

ASS. REC. BY:

REF:

CS/FCI19010643/Kgd3

N2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Henry Kao

of

FCI

Date/Time:

5:47pm @ 14/6/19

Estimated Cost:

Bill to:

OD ☒ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 52322

Insured:

SHA0209R

at Workshop m/s

Transcab

Tel:

62876666

of

No. 2 Amk St-63

Policy No:

Claim No:

D19003862MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/6/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(OS)

H.O.D. Endorsement:

Date/Time:

8:56am @ 17/6/19

Person Contacted:

Arenda

Vehicle ☒ IN/OUT

Date/Time

Action/Instruction

1st night

SHD 52322 - NBA / INC14001394 / y1

DOA: 13/01/2014

SHA0209R-C06/EDT15002608 / Alda 3p2-1

DOA: 6/2/15

19/6/19 @ 2:05pm revised to Henry by email.

2016

Q 2014.88

Summit

Cred to 24360.32, 92.67

ASS. (201 BY)

REF: FCI

## ASSIGNMENT

From

Date: 17/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD 5232 Z

at Workshop m/s

Trans Cab

of

No. 2 Amk St. 63

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.3.1

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

'Ds'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 5232 Z

Vt Regn:

12 / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius<sup>A</sup>

C.C.

1798

Colour

M.P. White 1st

A/C:

Insured / Std / NI / NA

Sp. Reading

33750

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTOKB 3FUX03078623

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

12/6/19

D.O.I.

18/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED JUN 2019

Date/Time, File Pass to?



Prel. Report

1) 24/6 10:55



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Workshop (\$

Survey Fee:

Transportation:

S + PS, SI

Photos

Others:

350

Report Format:

9p

Lump Sum / LBR (\$

2014.88



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003862MFSH

Date: 19 June 2019

Our Ref: CS/FCI19010643/Kqd3

The Motor Claims Department  
MS First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5232Z**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/06/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>26,375.20</u>
Revised Estimate Amount	: S\$ <u>1,364.48</u>
"Check" Items Amount	: S\$ <u>239.10</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

Date	13-06-2019	Our Ref No. D19003862MFSH
Accident Date	12-06-2019	Claim Type. Third Party
Insured Vehicle	SHA0209R	Third Party Vehicle. SHD5232Z
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 21 June 2019 6:03 PM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** FW: TP VEHICLE SHD 5232Z (DOA: 12/06/2019) -- AAD1906-109  
**Attachments:** image004.wmz; image001.wmz; image003.wmz; SHD5232 EST.pdf

Hi Shiau Chan

We confirmed COR amount \$2,014.88 (b4 GST)

Will send you the photo after I get from our workshop.

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Thursday, 20 June, 2019 3:53 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** RE: TP VEHICLE SHD 5232Z (DOA: 12/06/2019) -- AAD1906-109

Dear Wai Yin,

As per you requested.

Best Regards,  
**Shiau Chan (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Wai Yin <[waiyin.ng@transcab.com.sg](mailto:waiyin.ng@transcab.com.sg)>  
**Sent:** Thursday, 20 June 2019 3:30 PM  
**To:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** RE: TP VEHICLE SHD 5232Z (DOA: 12/06/2019) -- AAD1906-109

Hi Shiau Chan

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 19 June 2019 2:05 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Henry Kao Cai Jie'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19003862MFSH/1  
**Attachments:** CSFCI19010643Kqd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SHD 5232Z.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Monday, 17 June 2019 8:56 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Henry Kao Cai Jie' <[HenryKao@msfirstcapital.com.sg](mailto:HenryKao@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19003862MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 14 June 2019 5:47 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Henry Kao Cai Jie <[HenryKao@msfirstcapital.com.sg](mailto:HenryKao@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19003862MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

## PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

## Vehicle Details

Vehicle No.:	SHD5232Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B93010
Chassis No.:	JTDKB3FUX03078623
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	19 Dec 2018
First Registration Date:	19 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

## Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2026
PARF Rebate Amount:	\$10,685.00

## Intended COE Rebate Details

COE Expiry Date:	18 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,645.00
<b>Total Rebate Amount:</b>	<b>\$28,330.00</b>

## Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Jun 2019

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5232Z**

AAD1926-109

*Not Notified**Resurvey B4 paint  
82014.88*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD 5232Z**

JTDKB3FUX03078623

TOYOTA

PRIUS

12.6.19

**FIRST CAPITAL**

19/12/2018

**PART**

- |    |   |   |
|----|---|---|
| 1  | 1 | REAR BUMPER                                   |
| 2  | 1 | REAR BUMPER RE-INFORCEMENT                    |
| 3  | 1 | REAR BUMPER TOWING COVER                      |
| 4  | 1 | REAR BUMPER UNDER COVER (BLACK)               |
| 5  | 1 | REAR BUMPER SIDE RETAINER LH                  |
| 6  | 1 | REAR BUMPER SIDE RETAINER RH                  |
| 7  | 1 | REAR TAILGATE                                 |
| 8  | 1 | REAR TAILGATE OUTER GARNISH                   |
| 9  | 1 | COVER, REAR COMBINATION LAMP, RH              |
| 10 | 1 | COVER, REAR COMBINATION LAMP, RH              |
| 11 | 1 | GARNISH, BACK DOOR SIDE, LH                   |
| 12 | 1 | GARNISH, BACK DOOR SIDE, RH                   |
| 13 | 1 | MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH |
| 14 | 1 | MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH |
| 15 | 1 | BOARD ASSY, BACK DOOR TRIM                    |
| 16 | 1 | PANEL ASSY, BACK DOOR TRIM, UPPER             |
| 17 | 1 | REAR TAILGATE WEATHERSTRIP                    |
| 18 | 1 | REAR END PANEL                                |
| 19 | 1 | TAILLAMP LOWER RH                             |
| 20 | 1 | TAILLAMP UPPER RH                             |
| 21 | 1 | REAR BUMPER SIDE RH                           |
| 22 | 1 | REAR BUMPER SIDE LH                           |
| 23 | 1 | TAILLAMP LOWER LH                             |
| 24 | 1 | TAILLAMP UPPER LH                             |
| 25 | 1 | REAR FENDER RH                                |
| 26 | 1 | REAR FENDER LH                                |
| 27 | 1 | BOARD, BACK DOOR TRIM                         |
| 28 | 1 | PANEL SUB-ASSY, QUARTER, LH                   |
| 29 | 1 | PANEL, QUARTER WHEEL HOUSE, OUTER LH          |

**LIST**

\$	<i>Br/CM</i>	458.60	✓
\$	<i>Br</i>	318.80	✓
\$	<i>SL</i>	14.70	X
\$	<i>SL</i>	552.60	X
\$	<i>CM</i>	112.70	✓
\$	<i>SL</i>	112.70	X
\$	<i>N</i>	1,547.27	} X
\$	<i>SL</i>	905.10	
\$	<i>SL</i>	54.70	
\$	<i>SL</i>	54.70	
\$	<i>SL</i>	93.60	
\$	<i>SL</i>	93.60	
\$	<i>SL</i>	55.40	
\$	<i>SL</i>	55.40	
\$	<i>SL</i>	254.40	
\$	<i>SL</i>	51.20	
\$	<i>SL</i>	365.20	} X
\$	<i>N</i>	602.10	
\$	<i>SL</i>	548.40	
\$	<i>SL</i>	557.90	
\$	<i>SL</i>	232.00	
\$	<i>misc CM</i>	232.00	
\$	<i>misc SL</i>	548.40	
\$	<i>SL</i>	557.90	
\$	<i>N</i>	817.50	
\$	<i>N</i>	817.50	
\$	<i>SL</i>	220.70	} X
\$	<i>N</i>	836.70	
\$	<i>N</i>	290.50	



**Trans-cab Auto Services Pte Ltd**

AAD1906-109

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5232Z

- 30 1 PANEL SUB-ASSY, QUARTER, RH  
 31 1 PANEL, QUARTER WHEEL HOUSE, OUTER RH

\$	<i>nn</i>	836.70	X
\$	<i>nn</i>	290.50	X
<b>TOTAL</b>	<b>\$</b>	<b>12,489.47</b>	
<b>25%</b>	<b>\$</b>	<b>3,122.37</b>	
	<b>\$</b>	<b>9,367.10</b>	

**Special Nett**

- 1 1SET PARKING AID  
 2 1SET REAR BUMPER CLIP  
 3 2 REAR WINDSCREEN SEALANT  
 4 1 WINDSCREEN MOULDING  
 5 1 REAR WINDSCREEN INNER SPONGE SEAL  
 6 1 REAR TAILGATE TOYOTA LOGO  
 7 1 REAR TAILGATE WORDING 'PRIUS'  
 8 1 REAR TAILGATE WORDING 'HYBRID'  
 9 1 REAR TAILGATE STICKER 'TRANS-CAB'  
 10 1 REAR TAILGATE STICKER '6555-3333'  
 11 1 REAR BUMPER PROTECTOR  
 12 1 REAR WHEEL RIM  
 13 1 REAR WHEEL RIM COVER  
 14 1 SPARE WHEEL RIM  
 15 1 SPARE WHEEL RIM COVER

\$	<i>Phan</i>	700.00	<i>2001n</i>
\$	<i>nn</i>	22.00	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	100.00	
\$	<i>nn</i>	100.00	
\$	<i>nn</i>	47.00	
\$	<i>nn</i>	52.90	
\$	<i>nn</i>	53.50	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	100.00	
\$	<i>nn</i>	1,570.55	
\$	<i>nn</i>	175.80	
\$	<i>nn</i>	1,570.55	
\$	<i>nn</i>	175.80	
<b>TOTAL</b>	<b>\$</b>	<b>4,908.10</b>	

**TOTAL PARTS \$ 14,275.20****LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,500.00 *2001*

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1906-109

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5232Z

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	28d
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	5d
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	1d
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	4 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X

**TOTAL \$ 12,100.00****Over All Total \$ 26,375.20**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after (PART-BY-PART) Repair Days
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15 Days  
2 days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010643/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-06-2019		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 209R	Veh. Inspected	SHD 5232Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003862MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	14/06/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FUX03078623	Colour	M. P. WHITE / RED	
Odometer	33750	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/06/2019	Inspection Date	18/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5232Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	BENT / CRACKED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER TOWING COVER	SERVICEABLE	14.70	-
1	REAR BUMPER UNDER COVER (BLACK)	SERVICEABLE	552.60	-
1	REAR BUMPER SIDE RETAINER LH	CRACKED	112.70	112.70
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,547.27	-
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	905.10	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	GARNISH,BACK DOOR SIDE,LH	SERVICEABLE	93.60	-
1	GARNISH,BACK DOOR SIDE,RH	SERVICEABLE	93.60	-
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	SERVICEABLE	55.40	-
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	SERVICEABLE	55.40	-
1	BOARD ASSY,BACK DOOR TRIM	SERVICEABLE	254.40	-
1	PANEL ASSY,BACK DOOR TRIM, UPPER	SERVICEABLE	51.20	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	365.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	TAILLAMP LOWER RH	SERVICEABLE	548.40	-
1	TAILLAMP UPPER RH	SERVICEABLE	557.90	-
1	REAR BUMPER SIDE RH	SERVICEABLE	232.00	-
1	REAR BUMPER SIDE LH	MTG CRACKED	232.00	232.00
1	TAILLAMP LOWER LH	MTG CRACKED	548.40	548.40
1	TAILLAMP UPPER RH	SERVICEABLE	557.90	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	817.50	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	817.50	-
1	BOARD, BACK DOOR TRIM	SERVICEABLE	220.70	-
1	PANEL SUB-ASSY, QUARTER, LH	TO REPAIR SEE LABOUR	836.70	-

Report Ref No. CS/FCI19010643/Kqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	TO REPAIR SEE LABOUR	290.50	-
1	PANEL SUB-ASSY, QUARTER, RH	TO REPAIR SEE LABOUR	836.70	-
1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	TO REPAIR SEE LABOUR	290.50	-
	LESS 25% DISCOUNT		-3,122.37	-417.62
			9,367.10	1,252.88
	<b>SPECIAL NETT ITEMS</b>			
1	SET PARKING AID (SN)	SHORTED	700.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	22.00	22.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.00	-
1	REAR TAILGATE WORDING "PRIUS" (SN)	NOT NECESSARY	52.90	-
1	REAR TAILGATE WORDING "HYBRID" (SN)	NOT NECESSARY	53.50	-
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
1	REAR WHEEL RM (SN)	SERVICEABLE	1,570.55	-
1	REAR WHEEL RM COVER (SN)	SERVICEABLE	175.80	-
1	SPARE WHEEL RM (SN)	SERVICEABLE	1,570.55	-
1	SPARE WHEEL RM COVER (SN)	SERVICEABLE	175.80	-
			4,908.10	222.00
	<b>LABOUR</b>			
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR TAILGATE, REAR END PANEL, REAR FENDER RH, REAR FENDER LH, PANEL SUB-ASSY, QUARTER, LH, PANEL, QUARTER WHEEL HOUSE, OUTER LH, PANEL SUB-ASSY, QUARTER, RH AND PANEL, QUARTER WHEEL HOUSE, OUTER RH.		4,500.00	200.00

Report Ref No. CS/FCI19010643/Kqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	280.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			12,100.00	540.00
<b>GRAND TOTAL</b>			<b>26,375.20</b>	<b>2,014.88</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,014.88</b>

Report Ref No. CS/FCI19010643/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.