

ASS. REC. BY:

REF: CS/MSG 19010648 / UVd3

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Kwok Woon Choo

of MSG

Date/Time: 17.6.19 10.51a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 8184R

Insured:

at Workshop m/s Kan Fook Sing

Tel: 67479560

of MD 61 Defu Lany 12

Policy No: 9VPCB1450680

Claim No: MSC/V/19-000666

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 13.6.2019

(Client's Record)

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.6.19 11.34a.m

Person Contacted: Anita

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJV 8184R - x

18/6/19

Revert vehicle T/L via merimen

21/6/19

Submit uneconomical T/L - mv: \$10K (EST) LTA: \$6999 NV: \$3001

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MS16/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time

Action / Instruction

17/6/19

Indlu plus LTA 6999
after Repair m/s Tar next 3k. will check
Summ TOTAL 1055 Repairer 4/5 @ 4800

RECEIVED 21 JUN 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

☐: Preli. Report☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

200
11

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case:	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jun 2019 Sendback Est	14 Jun 2019 17:42 S\$12,774.15	17 Jun 2019 10:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	ABD RAHMAN BIN JOHAR, ID: S2000847D, Tel: +6594508554								
Vehicle Reg. No.:	SJV8184R	Date of Loss:	13/06/2019 20:00 - :59 [112 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / MSC/V/19-000666	Policy/Cover Note No.:	9VPCB1850680 (Comprehensive) Coverage: 10/02/2019 - 09/02/2020						
		Excess:	S\$500.00						
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, S39147 Defu Lane - Tel: 67479560								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/06/2019]								
Driver/Custodian:	RAIHANA BINTER ABD RAHMAN (35 / Female), NRIC: S8339479Z, Tel: +6594508554 Email: 3eyebodies@gmail.com								
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. to revert								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SJV8184R (MSC/V/19-000666)

OD

Jun 13 2019 8:00PM

[ABD RAHMAN BIN JOHAR]

Kan Fook Sing Motor Workshop

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 21/06/2019 10:49 AM.

To LKK_HQ

Subject Alert - Adj Mandate Revoked - SJV8184R - Claim Handler: Kwok Woon Choo

Revoked:total loss case. Please submit your bill.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Kwok Woon Choo	Date: 18 Jun 2019
Preliminary Advice	

Vehicle No	: SJV8184R	Accident Date	: 13/06/2019
Make	: HYUNDAI AVANTE	Policy No.	: 9VPCB1850680
Assignment Date	: 17/06/2019	Excess	: S\$500.00
Date of Inspection	: 17/06/2019	Est. Duration of Repair	: 0.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,774.15
Revised Amount	:S\$	10,160.05
Check Items (Estimated)	:S\$	1,145.10
Total	:S\$	11,305.15
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	6,999.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,001.00

Remarks

(X) The vehicle is not economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/06/2019 11:46
Date Of Accident	13/06/2019 20:00
Exact Location Of Accident	CTE - AFT BRADDELL EXT TOWARDS ANG MO KIO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV8184R
Insured/Policyholder	
Name Of Registered Owner	ABD RAHMAN BIN JOHAR
NRIC No	S2000847D
Email Address	3EYEBODIES@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82364473
Alternative Phone No	OFFICE-82364473

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	9VPCB1850680
Cover Note Number	

Driver

Name of Driver	RAIHANA BINTER ABD RAHMAN
NRIC No	S8339479Z
Date Of Birth	05/12/1983
Occupation	INDOOR
Date Of Driving Pass	06/06/2006
Driving Experience	13 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94508554
Fax Number	
Contact Number	
Email Address	3EYEBODIES@GMAIL.COM

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLA8024G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE HIRE

Name of Driver

NA

NRIC/Passport Number

Contact Number

98804998

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2


Passenger 1

NAME: : GRAB PASSANGER

GENDER: : FEMALE

Accident Sketch Plan Pg. 1

SKETCH PLAN



A: SJV8184R
B: SLX175K
C: SLA8024G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ① Saw brakelights of CAR B (SLX 175K); applied break - about 3 car apart
- ② Notice he wasn't moving after 2 seconds;
- ③ Applied harder (full) break but due to wet road the car was sliding on the tarmac. Vehicle was swerving a little due to sliding on the wet road.
- ④ Brake didn't apply and hit the vehicle B (SLX 175K)

INSURER: MCIS.

VEHICLE: SJV8184R.

DOA: 13/6/19

CLAIM TYPE: OD

WORKSHOP: KFS.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature] 14/6/2019

Policyholder's Signature
Date & Time:

[Signature] 14/6/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0847D
Vehicle Details	
Vehicle No.:	SJV8184R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	G4FC9U799893
Chassis No.:	KMH DU41BMAU964284
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,414.00
Original Registration Date:	10 Feb 2010
First Registration Date:	10 Feb 2010
Transfer Count:	0
Actual ARF Paid:	\$11,414.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Feb 2020
PARF Rebate Amount:	\$5,707.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$1,292.00
Total Rebate Amount:	\$6,999.00

The information contained herein is correct as at 17 Jun 2019

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

\$22K Depre, High Options Alpina B4 Coupe.



Agent Unit, High ARF With Hugh Savings From New, Depre Only \$22K! Done 48Kkm, StarAd



Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

Avante

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Avante		Any	Any	2010	Any	Any	Any	Available
	Hyundai	Avante 1.6A S	\$11,800	\$11,090 /yr	04-Jan-2010	1,591 cc	-	Sedan	Available
Best For Short Terms Usage Or Future COE Renewal! Cheaper Than Rental Car, High Car Body Value! Low Depreciation! Spacious, Reliable, Low Petrol Consumption, Trade In Welcome, Price Negotiable, Call O...									
Posted: 15-Jun-2019 Tags: 2010 Hyundai Avante, 2010 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6M	\$12,500	\$7,740 /yr	17-Jun-2010	1,591 cc	72,000 km	Sedan	Available
Posted: 08-Jun-2019 Tags: 2010 Hyundai Avante, 2010 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6M (New 5-yr COE)	\$25,800	\$5,150 /yr	28-Jan-2010	1,591 cc	143,419 km	Sedan	Available
Low Interest Rate. With New 5 Years COE. In House Financing Options Available. Buy With A Peace Of Mind. Low Mileage. 100% Genuine Mileage. No Chassis/Structural Damage. Immaculate Condition. All Trad...									
GOWHEELER Pte Ltd									
Posted: 08-Jun-2019 Tags: 2010 Hyundai Avante, 2010 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A	\$17,800	\$10,290 /yr	26-Aug-2010	1,591 cc	-	Sedan	Available
At It Best Condition For A Vehicle At Its Age, See For Yourself To Believe It. Paint Work Servicing And Repair All Done. No More Repair Needed. Very Healthy Engine And Efficient Fuel Throttle, Idea Fo...									
ABWIN (1994) Pte Ltd									
Posted: 24-May-2019 Tags: 2010 Hyundai Avante, 2010 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A S	\$21,800	\$10,660 /yr	31-Dec-2010	1,591 cc	-	Sedan	Available
100% Loan Available. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Test Report. Meet Our Friendly Consul...									
Classic Credit Pte Ltd									
Posted: 28-Apr-2019 Tags: 2010 Hyundai Avante, 2010 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A	\$13,800	\$14,430 /yr	07-Jan-2010	1,591 cc	-	Sedan	Available
Selling Cheap! Full Loan Available. Interior Is Maintained In Superbly Very Clean Condition. Cash/Loan Purchase Ok. Trade-In/Swap Car Welcome. Call Now!									
Posted: 24-Apr-2019 Tags: 2010 Hyundai Avante, 2010 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									

Compare

Kan Fook Sing Motor Workshop
61 Defu Lane 12
539147

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 14/06/2019 5:37 PM

Full Report

Registration: SJV8184R

Printed: 14/06/2019 5:37 PM

Summary Information

Claim

Location: Singapore (SG)

Work Provider:

MSIG Insurance
(Singapore) Pte Ltd

Printed by: Ryan Kan

Currency:

SGD

Claim Reference:

Date of Incident:

13/06/19

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer: HYUNDAI

Model: AVANTE (HD)

Sub Model: GLS

Model Sheet Number: 30 22 51

Registration: SJV8184R

VIN number:

Odometer:

Model Specs

FROM 02/2010

1.6 LTR 90 KW

EQUIPMENT GL

AIR CONDITIONING

4-SPEED AUTOMATIC

TWO COAT METALLIC

CENTRAL LOCKING

TWIN AIRBAGS

PREPARE OFF VEHICLE

FOG LAMPS

WHEELS 6J X 16 ALLOY

*not Allowed
when
renew
\$4155 \$500?
TOTAL 1055.
17/6/19
Tel: 62563561*

LKK Auto Consultant to be notified
the Repairer of the following:

- To resurvey before repair, spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kan Fook Sing Motor Workshop
61 Defu Lane 12
539147

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 14/06/2019 5:37 PM

Full Report

Registration: SJV8184R

Printed: 14/06/2019 5:37 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.		6.0	30.00
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	15.00
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		6.0	30.00
79110R0B)	R + R BONNET HINGES (BONNET REMOVED)		2.0	10.00
81182R00)	R + R FRONT BONNET CABLE		1.0	5.00
66300R0B	R + R BOTH FRONT WINGS		13.0	65.00
NO NUMBER	R + R LEFT FRONT WING BADGE		2.0	10.00

Kan Fook Sing Motor Workshop
61 Defu Lane 12
539147

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 14/06/2019 5:37 PM

Full Report

Registration: SJV8184R

Printed: 14/06/2019 5:37 PM

Code	Description	WU	Price SGD
NO NUMBER	R + R RIGHT FRONT WING BADGE	2.0	10.00
NO NUMBER	R + R FRONT PANEL	20.0	100.00
86111R00	R + R WINDSCREEN INCLUDES: R + R INTERIOR MIRROR, WIPER ARMS, WINDSCREEN FRAME COVER, ROOF STORAGE CONSOLE, SUN VISORS AND A-PILLAR TRIMS	20.0	100.00
84710R00)	R + R INSTRUMENT PANEL INCLUDES: R + R FRONT SEATS, GLOVE BOX, INSTRUMENT CLUSTER AND UPPER A-PILLAR TRIMS	19.0	95.00
84710R00)	RENEW INSTRUMENT PANEL (REMOVED)	1.0	5.00
84710RB1	ADD: PASSENGER AIRBAG	3.0	15.00
84610R00	R + R CENTRE CONSOLE	4.0	20.00
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	50.00
NO NUMBER	R + R CONDENSER-/EVAPORATOR PIPE	5.0	25.00
97763R00	R + R COMPRESSOR-EVAPORATOR	5.0	25.00
97762R00	R + R COMPRESSOR/CONDENSER PIPE	2.0	10.00
88810R00)	R + R LEFT FRONT SEAT BELT	2.0	10.00
88810R0R)	R + R RIGHT FRONT SEAT BELT	2.0	10.00
96600R0B)	R + R BOTH HORNS	1.0	5.00
95910R00)	R + R AIRBAG CONTROL UNIT	6.0	30.00
25300RA4	ADD/WORK FOR AUTOMATIC GEARBOX	1.0	5.00
28310R00)	R + R INTAKE MANIFOLD	3.0	15.00
28310R1G)	RENEW INTAKE MANIFOLD REMOVED	2.0	10.00
28138R00	R + R AIR INTAKE HOSE	2.0	10.00
56110R00	R + R STEERING WHEEL INCLUDES: R + R DRIVER AIRBAG	4.0	20.00
56140R00)	R + R STEERING COLUMN TRIM	1.0	5.00
93490R00)	R + R CONTACT RING	2.0	10.00
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	25.00
NN	R/RADIATOR AIR GUIDE R&R / NEW PARTS	15.0*	75.00X
Labour Cost		Hrs	WU
Panel / Mechanical Labour		17.00	170.0
Total of Labour			850.00

Kan Fook Sing Motor Workshop
61 Defu Lane 12
539147

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 14/06/2019 5:37 PM

Full Report

Registration: SJV8184R

Printed: 14/06/2019 5:37 PM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT		4.0	
	BONNET NEW PART PAINTING		24.0	
	L/F WING NEW PART PAINTING		10.0	
	R/F WING NEW PART PAINTING		10.0	
	BATTERY CARRIER SURFACE PAINT		4.0	
	FRONT BUMPER NEW PART PAINT K1R		10.0	
	LEFT FRONT DOOR SURFACE PAINT		8.0	
	RIGHT FRONT DOOR SURFACE PAINT		8.0	

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	4.23
0471	BONNET NEW PART PAINTING	78.43
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
1331	BATTERY CARRIER SURFACE PAINT	1.00
0283	FRONT BUMPER NEW PART PAINT K1R	47.23
1481	LEFT FRONT DOOR SURFACE PAINT	20.17
1482	RIGHT FRONT DOOR SURFACE PAINT	20.17

Labour Cost - Paint

	50.00 SGD/h	Hrs	WU	Price SGD
Factor				
Time Paint			78.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	10.80	108.0	540.00

Material Cost - Paint

	Price SGD
New Part Painting	114.55
New Part Painting - Plastic K1R	47.23
Surface-/Blend Paint	45.57
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	244.95

Kan Fook Sing Motor Workshop
61 Defu Lane 12
539147

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 14/06/2019 5:37 PM

Full Report

Registration: SJV8184R

Printed: 14/06/2019 5:37 PM

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	
				Price SGD	
0283	FRONT BUMPER	865112H000		Dij	180.00 ✓
0299	FRT BUMPER AIR GRILL	865612H001		Tuy	30.00 ✓
0315	FRT BUMPER ABSORBER	865202H010		Toi	48.00 ✓
0321	L/BUMPER MNTG REINF	865132H000		Ref	18.00 ✓
0322	R/BUMPER MNTG REINF	865142H000		Ref	18.00 ✓
0327	LEFT RETAINER	1491005000		Ref	18.00 ✓
0328	RIGHT RETAINER	1491005000		Ref	18.00 ✓
0340	FRT BUMPER SUPPORT	865302H010		D.S	105.00 ✓
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		Ref	15.00 ✓
0410	GRILLE	863512H500		320	180.00 ✓
0471	BONNET	664002H010		Buc	290.00 ✓
0475	LEFT BONNET HINGE	791102H000		Ref	22.00 ✓
0476	RIGHT BONNET HINGE	791202H000		Ref	22.00 ✓
0481	BONNET INSULATION	811252H000		Ref	85.00 ✓
0485	INSULATION MNTG KIT	8112637010		Ref	15.00 ✓
0493	BONNET LOCK	811302H900		Tuy	25.00 ✓
0499	FRONT BONNET CABLE	811902H100		Tuy	20.00 ✓
0561	LEFT HEADLAMP ASSY	921012H091		one	175.00 ✓
0562	RIGHT HEADLAMP ASSY	921022H091		one	175.00 ✓
0741	L/F WING	663112H022		Buc	130.00 ✓
0742	R/F WING	663212H022		Buc	130.00 ✓
0789	L/F WING CLAMP KIT	USE SINGLE PARTS		Ref	15.00 ✓
0790	R/F WING CLAMP KIT	USE SINGLE PARTS		Ref	15.00 ✓
0811	L/F WING BADGE	863162H000		Ref	0.00 ✓
0812	R/F WING BADGE	863162H000		Ref	0.00 ✓
0841	L/F WHEELHOUSE COVER	868112H010		Ref	30.00 ✓
0842	R/F WHEELHOUSE COVER	868122H010		Ref	30.00 ✓
1009	INNER FRT PANEL CPL	641012H000		D.S	280.00 ✓
1331	BATTERY CARRIER	371502H100			32.00 ?
1401	WINDSCREEN	861102H220		one	450.00 ✓
1411	WINDSCREEN BOND KIT	KNGKWI2			0.00 ?
1421	WINDSCREEN MOULDING	861312H000		Ref	40.00 ✓
1423	L/COWL MOULDING	861502H910			0.00 ?
1424	R/COWL MOULDING	861602H910			0.00 ?
4323	AIRBAG SYSTEM	REPLACE		NS	1,230.00 ✓
4325	PASSENGER AIRBAG	845302L900		NS	1,100.00 ✓

Kan Fook Sing Motor Workshop
61 Defu Lane 12
539147

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 14/06/2019 5:37 PM

Full Report

Registration: SJV8184R

Printed: 14/06/2019 5:37 PM

Code	Description	Part Number	Supplier	Price SGD
4331	INSTRUMENT PANEL	847102H8009PA		345 700.00 ✓
4465	AIR CON CONDENSER	976062H010		D.S 320.00 ✓
4481	COND/EVAPORATOR PIPE	977682L000		85.00 ?
4482	COMPR/EVAP PIPE	977642L000		145.00 ?
4484	COMPR/CONDENSER PIPE	977622H000		128.00 ?
4661	L/F SEAT BELT	888102H3009P		Am 350.00 ✓
4662	R/F SEAT BELT	888202H2009P		Am 350.00 ✓
7403	CONTACT RING	934902H000		Am 85.00 ✓
7405	DRIVER AIRBAG SYS	REPLACE		Am 1,230.00 ✓
7440	AIRBAG CONTROL UNIT	959102H000		Am 550.00 ✓
7449	L/F SHOCK SENSOR	959203K150		80.00 ?
7450	R/F SHOCK SENSOR	959203K150		80.00 ?
7755	L/RADIATOR AIR GUIDE	291352H000		D.S 15.00 ✓
7756	R/RADIATOR AIR GUIDE	291362H000		D.S 15.00 ✓
7761	RADIATOR	253102H050		D.S 210.00 ✓
7773	LWR RADIATOR HOSE	254152H001		23.00 ?
7776	UPPER RADIATOR HOSE	254142H000		Am 22.00 ✓
7789	FAN SHROUD CPL	253802H051		Am 145.00 ✓
7940	ENGINE COVER	292402B031		Am 145.00 ?
8221	INTAKE MANIFOLD	283112B000		150.00 ?
8389	AIR INTAKE HOSE	282111H000		65.00 ?
8390	AIR INTAKE HOUSING	282122H000		32.00 ?
9645	HIGH TONE HORN	966202H000		38.00 ?
9646	LOW TONE HORN	966102H000		38.00 ?
1000	BATTERY TOP BRKT	BTB		Am 30.00 ✓
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 9,972.00
u: Used parts				Addition(+10.00%) 997.20
Total				10,969.20

Extras

Code	Description	Price SGD
1001	FRT NUMBER PLATE FNP	30.00* ✓
1002	AIR CON GAS ACG	100.00* ✓
1003	FRT WINDSCREEN GUM FWG	40.00* ✓
Total Extras		170.00

Kan Fook Sing Motor Workshop
61 Defu Lane 12
539147

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 14/06/2019 5:37 PM

Full Report

Registration: SJV8184R

Printed: 14/06/2019 5:37 PM

Final Calculation

	SGD	SGD
Parts	9,972.00	
Addition(+10.00%)	997.20	
Total Parts		10,969.20
Labour Time Base 10 WU/h		
Total 170.0 WU X 50.00 SGD/h	850.00	
Total of Labour		850.00
Total Of Extras		170.00
Paint Work Time Base 10 WU/h		
Labour Cost 108.0 WU X 50.00 SGD/h	540.00	
Material Cost	244.95	
Total Paint Including Material		784.95
Repair Cost Excludes GST		12,774.15
GST (+7.0%)		894.19
Repair Cost Included GST		13,668.34
Deductions (Excludes GST)		
Deduction For Excess	-500.00	
Total Of Deductions (Excludes GST)		-500.00
Grand Total Excludes GST		12,274.15
GST (+7.0%)		859.19
Grand Total Included GST		13,133.34

12,274.15

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: KFSA100102
Version: 1810
Date calculated: 18/06/2019 2:37 PM

Full Report
Registration: SJV8184R
Printed: 18/06/2019 2:37 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	13/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	GLS
Model Sheet Number:	30 22 51
Registration:	SJV8184R
VIN number:	
Odometer:	

Model Specs

FROM 02/2010	AIR CONDITIONING	CENTRAL LOCKING	FOG LAMPS
1.6 LTR 90 KW	4-SPEED AUTOMATIC	TWIN AIRBAGS	WHEELS 6J X 16 ALLOY
EQUIPMENT GL	TWO COAT METALLIC	PREPARE OFF VEHICLE	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: KFSA100102
Version: 1810
Date calculated: 18/06/2019 2:37 PM


Full Report
Registration: SJV8184R
Printed: 18/06/2019 2:37 PM

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.		6.0	30.00
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	15.00
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		6.0	30.00
79110R0B)	R + R BONNET HINGES (BONNET REMOVED)		2.0	10.00
81182R00)	R + R FRONT BONNET CABLE		1.0	5.00
66300R0B	R + R BOTH FRONT WINGS		13.0	65.00
NO NUMBER	R + R LEFT FRONT WING BADGE		2.0	10.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: KFSA100102
 Version: 1810
 Date calculated: 18/06/2019 2:37 PM

Full Report
 Registration: SJV8184R
 Printed: 18/06/2019 2:37 PM

Code	Description	WU	Price SGD
NO NUMBER	R + R RIGHT FRONT WING BADGE	2.0	10.00
NO NUMBER	R + R FRONT PANEL	20.0	100.00
86111R00	R + R WINDSCREEN INCLUDES: R + R INTERIOR MIRROR, WIPER ARMS, WINDSCREEN FRAME COVER, ROOF STORAGE CONSOLE, SUN VISORS AND A-PILLAR TRIMS	20.0	100.00
84710R00)	R + R INSTRUMENT PANEL INCLUDES: R + R FRONT SEATS, GLOVE BOX, INSTRUMENT CLUSTER AND UPPER A-PILLAR TRIMS	19.0	95.00
84710R00)	RENEW INSTRUMENT PANEL (REMOVED)	1.0	5.00
84710RB1	ADD: PASSENGER AIRBAG	3.0	15.00
84610R00	R + R CENTRE CONSOLE	4.0	20.00
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	50.00
NO NUMBER	R + R CONDENSER-/EVAPORATOR PIPE	5.0	25.00
97763R00	R + R COMPRESSOR-EVAPORATOR	5.0	25.00
97762R00	R + R COMPRESSOR/CONDENSER PIPE	2.0	10.00
88810R00)	R + R LEFT FRONT SEAT BELT	2.0	10.00
88810R0R)	R + R RIGHT FRONT SEAT BELT	2.0	10.00
96600R0B)	R + R BOTH HORNS	1.0	5.00
95910R00)	R + R AIRBAG CONTROL UNIT	6.0	30.00
25300RA4	ADD/WORK FOR AUTOMATIC GEARBOX	1.0	5.00
28310R00)	R + R INTAKE MANIFOLD	3.0	15.00
28310R1G)	RENEW INTAKE MANIFOLD REMOVED	2.0	10.00
28138R00	R + R AIR INTAKE HOSE	2.0	10.00
56110R00	R + R STEERING WHEEL INCLUDES: R + R DRIVER AIRBAG	4.0	20.00
56140R00)	R + R STEERING COLUMN TRIM	1.0	5.00
93490R00)	R + R CONTACT RING	2.0	10.00
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	25.00
NN	R/RADIATOR AIR GUIDE R&R / NEW PARTS	15.0*	75.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		17.00	170.0
Total of Labour			850.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 18/06/2019 2:37 PM

Full Report

Registration: SJV8184R

Printed: 18/06/2019 2:37 PM

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	
				Price SGD	
0283	FRONT BUMPER	865112H000			180.00
0299	FRT BUMPER AIR GRILL	865612H001			30.00
0315	FRT BUMPER ABSORBER	865202H010			48.00
0321	L/BUMPER MNTG REINF	865132H000			18.00
0322	R/BUMPER MNTG REINF	865142H000			18.00
0327	LEFT RETAINER	1491005000			18.00
0328	RIGHT RETAINER	1491005000			18.00
0340	FRT BUMPER SUPPORT	865302H010			105.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS			15.00
0410	GRILLE	863512H500			180.00
0471	BONNET	664002H010			290.00
0475	LEFT BONNET HINGE	791102H000			22.00
0476	RIGHT BONNET HINGE	791202H000			22.00
0481	BONNET INSULATION	811252H000			85.00
0485	INSULATION MNTG KIT	8112637010			15.00
0493	BONNET LOCK	811302H900			25.00
0499	FRONT BONNET CABLE	811902H100			20.00
0561	LEFT HEADLAMP ASSY	921012H091			175.00
0562	RIGHT HEADLAMP ASSY	921022H091			175.00
0741	L/F WING	663112H022			130.00
0742	R/F WING	663212H022			130.00
0789	L/F WING CLAMP KIT	USE SINGLE PARTS			15.00
0790	R/F WING CLAMP KIT	USE SINGLE PARTS			15.00
0811	L/F WING BADGE	863162H000			0.00
0812	R/F WING BADGE	863162H000			0.00
1009	INNER FRT PANEL CPL	641012H000			280.00
1331	BATTERY CARRIER	371502H100			32.00
1401	WINDSCREEN	861102H220			450.00
1411	WINDSCREEN BOND KIT	KNGKWI2			0.00
1421	WINDSCREEN MOULDING	861312H000			40.00
1423	L/COWL MOULDING	861502H910			0.00
1424	R/COWL MOULDING	861602H910			0.00
4325	PASSENGER AIRBAG	845302L900			1,100.00
4331	INSTRUMENT PANEL	847102H8009PA			700.00
4465	AIR CON CONDENSER	976062H010			320.00
4481	COND/EVAPORATOR PIPE	977682L000			85.00
4482	COMPR/EVAP PIPE	977642L000			145.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: KFSA100102

Version: 1810

Date calculated: 18/06/2019 2:37 PM

Full Report

Registration: SJV8184R

Printed: 18/06/2019 2:37 PM

Code	Description	Part Number	Supplier	Price SGD
4484	COMPR/CONDENSER PIPE	977622H000		128.00
4661	L/F SEAT BELT	888102H3009P		350.00
4662	R/F SEAT BELT	888202H2009P		350.00
7403	CONTACT RING	934902H000		85.00
7405	DRIVER AIRBAG SYS	REPLACE		1,230.00
7440	AIRBAG CONTROL UNIT	959102H000		550.00
7449	L/F SHOCK SENSOR	959203K150		80.00
7450	R/F SHOCK SENSOR	959203K150		80.00
7755	L/RADIATOR AIR GUIDE	291352H000		15.00
7756	R/RADIATOR AIR GUIDE	291362H000		15.00
7761	RADIATOR	253102H050		210.00
7773	LWR RADIATOR HOSE	254152H001		23.00
7776	UPPER RADIATOR HOSE	254142H000		22.00
7789	FAN SHROUD CPL	253802H051		145.00
7940	ENGINE COVER	292402B031		145.00
8221	INTAKE MANIFOLD	283112B000		150.00
8389	AIR INTAKE HOSE	282111H000		65.00
8390	AIR INTAKE HOUSING	282122H000		32.00
9645	HIGH TONE HORN	966202H000		38.00
9646	LOW TONE HORN	966102H000		38.00
1000	BATTERY TOP BRKT	BTB		30.00
f: OEM Parts				0.00
n: Non-OEM Parts				8,682.00
u: Used parts				868.20
Savings				
Subtotal				
Addition(+10.00%)				
Total				9,550.20

Extras

Code	Description	Price SGD
1001	FRT NUMBER PLATE FNP	30.00*
1002	AIR CON GAS ACG	50.00*
1003	FRT WINDSCREEN GUM FWG	40.00*
Total Extras		120.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: KFSA100102
Version: 1810
Date calculated: 18/06/2019 2:37 PM

Full Report
Registration: SJV8184R
Printed: 18/06/2019 2:37 PM

Final Calculation

	SGD	SGD
Parts	8,682.00	
Addition(+10.00%)	868.20	
Total Parts		9,550.20
Labour Time Base 10 WU/h		
Total 170.0 WU X 50.00 SGD/h	850.00	
Total of Labour		850.00
Total Of Extras		120.00
Paint Work Time Base 10 WU/h		
Labour Cost 108.0 WU X 50.00 SGD/h	540.00	
Material Cost	244.95	
Total Paint Including Material		784.95
Repair Cost Excludes GST		11,305.15
GST (+7.0%)		791.36
Repair Cost Included GST		12,096.51
Deductions (Excludes GST)		
Deduction For Excess	-500.00	
Total Of Deductions (Excludes GST)		-500.00
Grand Total Excludes GST		10,805.15
GST (+7.0%)		756.36
Grand Total Included GST		11,561.51

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	14 Jun 2019	14 Jun 2019 17:42 S\$12,774.15	17 Jun 2019 10:57 Edit Adj Rpt	S\$10,160.05 Edit Estimates	S\$10,160.05 View Rpt	Pending for Survey Report

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ABD RAHMAN BIN JOHAR, ID: S2000847D, Tel: +6594508554		
Vehicle Reg. No.:	SJV8184R	Date of Loss:	13/06/2019 20:00 - :59 [112 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / MSC/V/19-000666	Policy/Cover Note No.:	9VPCB1850680 (Comprehensive) Coverage: 10/02/2019 - 09/02/2020
		Excess:	S\$500.00
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/07/2019]		
Driver/Custodian:	RAIHANA BINTER ABD RAHMAN (35 / Female) , NRIC: S8339479Z, Tel: +6594508554 Email: 3eyebodies@gmail.com		
Adj Asg. Remarks:	Car in, Survey & revert. Please contact us ASAP if you cannot attend this assignment, to revert		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (21/06/2019): Alert - Adj Mandate Revoked - SJV8184R - Claim Handler: Kwok Woon Choo

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJV8184R (MSC/V/19-000666)

OD

Jun 13 2019 8:00PM

[ABD RAHMAN BIN JOHAR]

Kan Fook Sing Motor Workshop

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports				1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	14/06/19 13:44	Accident Statement		Load HTM	
2	14/06/19 17:42	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/06/19 14:50	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	14/06/19 13:38	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	14/06/19 13:38	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	14/06/19 13:38	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	14/06/19 13:38	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	14/06/19 13:38	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	14/06/19 13:38	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	14/06/19 13:38	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/06/19 17:03	Odometer Reading		Load JPG	☒
2	17/06/19 17:03	Chassis Number		Load JPG	☒
3	17/06/19 17:04	Chassis Number		Load JPG	☒
4	17/06/19 17:04	Chassis Number		Load JPG	☒
5	17/06/19 17:04	Chassis Number		Load JPG	☒
6	17/06/19 17:04	Chassis Number		Load JPG	☒
7	17/06/19 17:04	Chassis Number		Load JPG	☒
8	17/06/19 17:04	Chassis Number		Load JPG	☒
9	17/06/19 17:04	Chassis Number		Load JPG	☒
10	17/06/19 17:04	Chassis Number		Load JPG	☒
11	17/06/19 17:04	Chassis Number		Load JPG	☒
12	17/06/19 17:04	Chassis Number		Load JPG	☒
13	17/06/19 17:04	Chassis Number		Load JPG	☒
14	17/06/19 17:04	Chassis Number		Load JPG	☒
15	17/06/19 17:04	Chassis Number		Load JPG	☒
16	17/06/19 17:04	Chassis Number		Load JPG	☒
17	17/06/19 17:04	Chassis Number		Load JPG	☒
18	17/06/19 17:04	Chassis Number		Load JPG	☒
19	17/06/19 17:04	Chassis Number		Load JPG	☒
20	17/06/19 17:04	Chassis Number		Load JPG	☒
21	17/06/19 17:04	Chassis Number		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
22	17/06/19 17:04	Chassis Number	 Load JPG	☒
23	17/06/19 17:04	Chassis Number	 Load JPG	☒
24	17/06/19 17:04	Chassis Number	 Load JPG	☒
25	17/06/19 17:04	Chassis Number	 Load JPG	☒
26	17/06/19 17:04	Chassis Number	 Load JPG	☒
27	17/06/19 17:04	Chassis Number	 Load JPG	☒
28	17/06/19 17:04	Chassis Number	 Load JPG	☒
29	17/06/19 17:04	Chassis Number	 Load JPG	☒
30	17/06/19 17:04	Chassis Number	 Load JPG	☒
31	17/06/19 17:04	Chassis Number	 Load JPG	☒
32	17/06/19 17:04	Chassis Number	 Load JPG	☒
33	17/06/19 17:04	Chassis Number	 Load JPG	☒
34	17/06/19 17:04	Chassis Number	 Load JPG	☒
35	17/06/19 17:04	Chassis Number	 Load JPG	☒
36	17/06/19 17:04	Chassis Number	 Load JPG	☒
37	17/06/19 17:04	Chassis Number	 Load JPG	☒
38	17/06/19 17:04	Chassis Number	 Load JPG	☒
39	17/06/19 17:04	Chassis Number	 Load JPG	☒
40	17/06/19 17:04	Chassis Number	 Load JPG	☒
41	17/06/19 17:04	Chassis Number	 Load JPG	☒
42	17/06/19 17:04	Chassis Number	 Load JPG	☒
43	17/06/19 17:04	Chassis Number	 Load JPG	☒
44	17/06/19 17:04	Chassis Number	 Load JPG	☒
45	17/06/19 17:04	Chassis Number	 Load JPG	☒
46	17/06/19 17:04	Chassis Number	 Load JPG	☒
47	17/06/19 17:04	Chassis Number	 Load JPG	☒
48	17/06/19 17:04	Chassis Number	 Load JPG	☒
49	17/06/19 17:04	Chassis Number	 Load JPG	☒
50	17/06/19 17:04	Chassis Number	 Load JPG	☒
51	17/06/19 17:04	Chassis Number	 Load JPG	☒
52	17/06/19 17:04	Chassis Number	 Load JPG	☒
53	17/06/19 17:04	Chassis Number	 Load JPG	☒
54	17/06/19 17:04	Chassis Number	 Load JPG	☒
55	17/06/19 17:04	Chassis Number	 Load JPG	☒
56	17/06/19 17:04	Chassis Number	 Load JPG	☒
57	17/06/19 17:04	Chassis Number	 Load JPG	☒
58	17/06/19 17:04	Chassis Number	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	14/06/19 13:43	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	14/06/19 13:43	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	14/06/19 13:43	nric & dl [Linked Accident Report Documents]	 Load TIF	
4	14/06/19 13:43	ci [Linked Accident Report Documents]	 Load TIF	
5	14/06/19 14:29	E-filed GIA report	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/06/19 15:40	Status of Driving Licence	 Load PDF	
2	15/06/19 15:44	PARF_COE Rebate Enquiry	 Load PDF	

Assessment Reports			1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/19 09:43	MARK ESTIMATE	Load PDF	
2	21/06/19 14:25	LTA REBATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	14/06/19 13:44	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	14/06/19 13:38	Accident Photo	Load JPG	☒
2	14/06/19 13:38	Accident Photo	Load JPG	☒
3	14/06/19 13:38	Accident Photo	Load JPG	☒
4	14/06/19 13:38	Accident Photo	Load JPG	☒
5	14/06/19 13:38	Accident Photo	Load JPG	☒
6	14/06/19 13:38	Accident Photo	Load JPG	☒
7	14/06/19 13:38	Accident Photo	Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	14/06/19 13:43	Accident Sketch Plan	Load TIF	
2	14/06/19 13:43	Accident Sketch Plan	Load TIF	
3	14/06/19 13:43	nric & dl	Load TIF	
4	14/06/19 13:43	ci	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19010648/UVD3S2

Date: 21/06/2019

REFERENCE

Insured/Claimant: ABD RAHMAN BIN JOHAR
Date of Loss: 13/06/2019

Policy No: 9VPCB1850680
Nature of Claim: OD

Claim No: MSC/V/19-000666

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV8184R**
Make & Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)
Reg. Date: 10/02/2010 (Man. Year: 2009)
Colour: White
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$10,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: G4FC9U799893
Chassis No: KMHU41BMAU964284
Odometer: 160411 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15
Front Left Side: Kumho 5 mm
Front Right Side: Kumho 5 mm
Rear Tyre Size: 185/65R15
Rear Left Side: Kumho 5 mm
Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,969.20	8,405.10	2,564.10	23.38
Miscellaneous Items	170.00	120.00	50.00	29.41
Labour	1,634.95	1,634.95	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,774.15	10,160.05	2,614.10	20.46
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	12,774.15	9,660.05	3,114.10	24.38
+ GST 7.00/7.00% (S\$)	894.19	676.20	217.99	24.38
Nett Amount (S\$)	13,668.34	10,336.25	3,332.09	24.38

INSPECTION

Date of Assignment: 17/06/2019 Present Location: Kan Fook Sing Motor Workshop (Defu)
Kan Fook Sing Motor Workshop (Defu)
Date Inspected: 17/06/2019 Inspected At: No. 61 Defu Lane 12
Singapore 539147
Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$1,145.10 NETT)

TOTAL LOSS ASPECT

Market Value :	\$10,000.00
OMV :	\$11,414.00
PARF Rebate (1) :	\$5,707.00
Quota Premium Paid :	\$19,989.00
COE Rebate (2) :	\$1,292.00
Total Rebate (1) + (2) = :	\$6,999.00

The total amount incurred will be Market Value \$10,000.00 minus Total Rebate \$6,999.00 = \$3,001.00 Before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2019)

Parts: 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJV8184R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/F WING BADGE (NPA) (WCP)	Necessary	-	*- F
2	1		*R/F WING BADGE (NPA) (WCP)	Necessary	-	*- F
3	1		*WINDSCREEN BOND KIT (NPA) (WCP)	*Check	-	*- F
4	1		*L/COWL MOULDING (NPA)(WCP)	*Check	-	*- F
5	1		*R/COWL MOULDING (NPA)(WCP)	*Check	-	*- F
6	1	NA	*AIRBAG CONTROL UNIT (WCP)	Activated	550.00 F	*550.00 F
7	1	NA	*AIRBAG SYSTEM (WCP)	No such part	1,230.00 F	*- F
8	1	NA	*AIR CON CONDENSER (WCP)	Distorted	320.00 F	*320.00 F
9	1	NA	*AIR INTAKE HOSE (WCP)	*Check	65.00 F	*- F
10	1	NA	*AIR INTAKE HOUSING (WCP)	*Check	32.00 F	*- F
11	1	NA	*BATTERY CARRIER (WCP)	*Check	32.00 F	*- F
12	1	NA	*BATTERY TOP BRKT (WCP)	Bent	30.00 F	*30.00 F
13	1	NA	*BONNET (WCP)	Buckled	290.00 F	*290.00 F
14	1	NA	*BONNET INSULATION (WCP)	Necessary	85.00 F	*85.00 F
15	1	NA	*BONNET LOCK (WCP)	Twisted	25.00 F	*25.00 F
16	1	NA	*COMPR/CONDENSER PIPE (WCP)	*Check	128.00 F	*- F
17	1	NA	*COMPR/EVAP PIPE (WCP)	*Check	145.00 F	*- F
18	1	NA	*COND/EVAPORATOR PIPE (WCP)	*Check	85.00 F	*- F
19	1	NA	*CONTACT RING (WCP)	Activated	85.00 F	*85.00 F
20	1	NA	*DRIVER AIRBAG SYS (WCP)	Activated	1,230.00 F	*1,230.00 F
21	1	NA	*ENGINE COVER (WCP)	*Check	145.00 F	*- F
22	1	NA	*FAN SHROUD CPL (WCP)	Cracked	145.00 F	*145.00 F
23	1	NA	*FRONT BONNET CABLE (WCP)	Jammed	20.00 F	*20.00 F
24	1	NA	*FRONT BUMPER (WCP)	Distorted	180.00 F	*180.00 F
25	1	NA	*FRT BUMPER ABSORBER (WCP)	Torn	48.00 F	*48.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1	NA	*FRT BUMPER AIR GRILL (WCP)	Twisted	30.00 F	*30.00 F
27	1	NA	*FRT BUMPER CLAMP KIT (WCP)	Necessary	15.00 F	*15.00 F
28	1	NA	*FRT BUMPER SUPPORT (WCP)	Distorted	105.00 F	*105.00 F
29	1	NA	*GRILLE (WCP)	Broken	180.00 F	*180.00 F
30	1	NA	*HIGH TONE HORN (WCP)	*Check	38.00 F	*- F
31	1	NA	*INNER FRT PANEL CPL (WCP)	Distorted	280.00 F	*280.00 F
32	1	NA	*INSTRUMENT PANEL (WCP)	Burst	700.00 F	*700.00 F
33	1	NA	*INSULATION MNTG KIT (WCP)	Necessary	15.00 F	*15.00 F
34	1	NA	*INTAKE MANIFOLD (WCP)	*Check	150.00 F	*- F
35	1	NA	*L/BUMPER MNTG REINF (WCP)	Bent	18.00 F	*18.00 F
36	1	NA	*L/F SEAT BELT (WCP)	Activated	350.00 F	*350.00 F
37	1	NA	*L/F SHOCK SENSOR (WCP)	*Check	80.00 F	*- F
38	1	NA	*L/F WHEELHOUSE COVER (WCP)	Not Necessary	30.00 F	*- F
39	1	NA	*L/F WING (WCP)	Buckled	130.00 F	*130.00 F
40	1	NA	*L/F WING CLAMP KIT (WCP)	Necessary	15.00 F	*15.00 F
41	1	NA	*L/RADIATOR AIR GUIDE (WCP)	Distorted	15.00 F	*15.00 F
42	1	NA	*LEFT BONNET HINGE (WCP)	Bent	22.00 F	*22.00 F
43	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	175.00 F	*175.00 F
44	1	NA	*LEFT RETAINER (WCP)	Bent	18.00 F	*18.00 F
45	1	NA	*LOW TONE HORN (WCP)	*Check	38.00 F	*- F
46	1	NA	*LWR RADIATOR HOSE (WCP)	*Check	23.00 F	*- F
47	1	NA	*PASSENGER AIRBAG (WCP)	Activated	1,100.00 F	*1,100.00 F
48	1	NA	*R/BUMPER MNTG REINF (WCP)	Bent	18.00 F	*18.00 F
49	1	NA	*R/F SEAT BELT (WCP)	Activated	350.00 F	*350.00 F
50	1	NA	*R/F SHOCK SENSOR (WCP)	*Check	80.00 F	*- F
51	1	NA	*R/F WHEELHOUSE COVER (WCP)	Not Necessary	30.00 F	*- F
52	1	NA	*R/F WING (WCP)	Bent	130.00 F	*130.00 F
53	1	NA	*R/F WING CLAMP KIT (WCP)	Necessary	15.00 F	*15.00 F
54	1	NA	*R/RADIATOR AIR GUIDE (WCP)	Distorted	15.00 F	*15.00 F
55	1	NA	*RADIATOR (WCP)	Distorted	210.00 F	*210.00 F
56	1	NA	*RIGHT BONNET HINGE (WCP)	Bent	22.00 F	*22.00 F
57	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	175.00 F	*175.00 F
58	1	NA	*RIGHT RETAINER (WCP)	Bent	18.00 F	*18.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1	NA	*UPPER RADIATOR HOSE (WCP)	Torn	22.00 F	*22.00 F
60	1	NA	*WINDSCREEN (WCP)	Cracked	450.00 F	*450.00 F
61	1	NA	*WINDSCREEN MOULDING (WCP)	Necessary	40.00 F	*40.00 F

F=Franchise part.

Sub Total (\$\$)	9,972.00	7,641.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	997.20	764.10
Total Parts (\$\$)	10,969.20	8,405.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIR CON GAS	100.00	50.00
2	1	FRT NUMBER PLATE (MISSING / BROKEN)	30.00	30.00
3	1	FRT WINDSCREEN GUM (NECESSARY)	40.00	40.00
Sub Total (S\$)			170.00	120.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	540.00	540.00
2	Total Paint Materials	New	244.95	244.95
3	Total Panel/Mechanical Labour	New	850.00	850.00
Gross Labour Cost (S\$)			1,634.95	1,634.95

Report was unsubmitted during this print-out.

< END OF ESTIMATES >