

SHC 3820U

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Remove/Refix Dashboard			\$ 450.00
	Remove/Refix Fuse Box			\$ 180.00
	Re-set Frt ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 3,630.00
	ESTIMATE TOTAL			\$ 18,876.96
	17/06/2019 @ 1200hr WKA Actual 2/Sum 6 dgs. 1 year LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				