

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Mr. Ynnul

of AIG

Date/Time: 17/6/19 10:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 7981E

Insured:

SLH 4630X

at Workshop in/s

Yap Lee Motor

Tel:

6844 1555

of

1 Kaki Bukit Ave 6 # 01-26 Autobay

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:06am @ 17/6/19

Person Contacted:

Shirley

Vehicle IN (OUT)

Date/Time

Action/Instruction

13/06/19

SIN 7981E-X

SLH 4630X-X

16/7@

Lump Sum \$3000/- , 5 days
(Red: 4186.95, 58%)

ASS. TAG. OF

Action

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SJN7981E Yr Regn: 2009, FebType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima c.c. 2362Colour: Gold A/C: Insured / Std / Nil / NASp. Reading: 190075 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: ACR500082652Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 26/06/19Survey held at Yap LeeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

COE Expiry: 30/09/28

RECEIVED 16 JUL 2019

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) 16th Typst.

2)

3)

4)

5)

6)

Final Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

250

11

261

PRE-REPAIR INSPECTION REQUEST – SJN7981E vs SLH4630X (OI) on D.O.A.: 13/06/2019

From: Hor, Yinnul
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tor
Sent: 6/17/2019 10:45:42 AM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: Monday, June 17, 2019 10:14 AM
To: Hor, Yinnul
Cc: Yap Lee Motor
Subject: [EXTERNAL] RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SJN7981E [OUR REF. TCL.GCN.RO.50381.19.YLM] YOUR REF. SLH 4630X
Importance: High

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sirs

We refer to your email of even date.

Our client is agreeable to appoint **Adrian Ling, LKK Auto Consultants** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **SJN 7981E**.

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

Venue : **Yap Lee Motor**
1 Kaki Bukit Avenue 6
#01-26 Autobay@Kaki Bukit (417883)

Contact Person : **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Without Prejudice

Your Reference : TCL GCN.RO.50381.19.YLM
Our Reference : SLH4630X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services

EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)

AIG

Claims Adjuster II, Singapore FNO, Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: Ruby Ong

Sent: Friday, 14 June 2019 4:42 PM

To: Hor, Yinrul <Yinrul.Hor@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SJN7981E [OUR REF. TCL.GCN.RO.50381.19.YLM]

Importance: High

Your ref: SLH 4630X
Our ref: TCL.GCN.ro.50381.19.ylm

WITHOUT PREJUDICE

14 June 2019

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: BONITA PANG YING CHYI

ACCIDENT INVOLVING SJN 7981E & SLH 4630X AT TRAFFIC LIGHT JUNCTION OF YISHUN STREET 11 & YISHUN AVENUE 5 ON 13 JUNE 2019 @ 2000HRS

We are instructed by Bonita Pang Ying Chyi to notify you of a road traffic accident on 13 June 2019 at about 2000hrs at traffic light junction of Yishun Street 11 & Yishun Avenue 5 involving our client's vehicle registration number SJN 7981E and vehicle registration number SLH 4630X driven by your insured/insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel: 6533 0212 ext 278
Fax: 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

MSMF10077823 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 14/06/2019 17:39
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/06/2019 17:39
 Date Of Accident 13/06/2019 20:00
 Exact Location Of Accident YISHUN ST 11 & YISHUN AVE 5 TRAFFIC LIGHT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJN7981E
Insured/Policyholder
 Name Of Registered Owner PANG YING CHYI BONITA
 NRIC No S7673894G
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-84993833
 Alternative Phone No OFFICE-84993833

Vehicle Particulars

Manufacturer TOYOTA
 Model ESTIMA
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number GA399483
 Cover Note Number

Driver

Name of Driver CHAN KONG HOENG
 NRIC No S6819290J
 Date Of Birth 23/05/1968
 Occupation INDOOR
 Date Of Driving Pass 10/06/1997
 Driving Experience 22 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +85-86889838
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address 21 CLOVER CLOSE
 Postcode 579262
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: DONALD CHAN DENG TIN
 GENDER: MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ACCIDENT HAPPENED AT YISHUN ST 11 AND YISHUN AVE 5 TRAFFIC LIGHT. I STOPPED AT THE TRAFFIC LIGHT AS TRAFFIC LIGHT IS RED. SUDDENLY, VEHICLE B COLLIDED ONTO THE REAR PORTION OF MY VEHICLE. THE DRIVER CLAIMED HE WAS LOOKING DOWN AND DID NOT KNOW MY VEHICLE HAD STOPPED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLH4630X
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver SELWIN SIM WEI SHENG
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/EPN No:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at Yishun St. 11 and
Yishun Ave 5 traffic light.

I stopped at the traffic light as traffic light
is red then suddenly vehicle B collide onto the
rear portion of my vehicle.

The driver claim he was looking down and
did not know my vehicle has stopped.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Bozida

Policyholder's Signature

Date & Time:

[Signature]

Driver's Signature
(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

REGISTRATION NO:

Sketch Plan #3 Pg. 1

LETTER OF UNDERTAKING

I/We, Bonita Pang Ying Chyi, the owner of vehicle no. STN7981E

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd. I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, Yap Lee Motor

Signed and Acknowledge by:

Bonita Pang

576 738946
Nric no. and signature of policyholder

Company Stamp

Date

YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883
Tel : 6844 1555 Fax. 6844 1311 Email : yap_lee_motor@singnet.com.sg

Date : 25-Jun-19

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #07-16
Singapore 079120

Your Reference : SLH 4630X

TP AIG

Denise

Owner Name : Bonita Pang Chyi
Accident Date : 13-Jun-19

ESTIMATE COST OF REPAIRS TO Toyota Estima SJN 7981E

<u>Quantity</u>	<u>Descriptions</u>	<u>Amount</u>
	<u>List Items</u>	
1	Rear Bumper <i>Replaced</i>	\$ 1,251.00 ✓
1	Rear Bumper Side Retainer <i>new</i>	\$ 110.00 ✓
1	Rear Bumper Reflector <i>new</i>	\$ 180.00 ✓
1	Rear End Panel <i>Replaced</i>	\$ 755.10 ✓
1	Rear End Panel Top Garnish <i>Replaced</i>	\$ 275.20 ✓
1	Rear End Panel Lock Sensor <i>new</i>	\$ 293.00 ✓ <i>242.40</i>
1	Rear End Panel Centre Garnish <i>new</i>	\$ 198.70 ✓
1	Tailgate <i>Repair</i>	\$ 1,281.40 ✓
1	Tailgate Weatherstrip <i>new</i>	\$ 318.70 ✓
1	Tailgate Lock <i>new</i>	\$ 349.80 ✓
1	Tailgate Lock Striker <i>new</i>	\$ 45.00 ✓
1	Tailgate Emblem-Logo <i>new</i>	\$ 48.70 ✓
1	Tailgate Emblem-Estima <i>new</i>	\$ 57.50 ✓
1	Tailgate Glass Moulding <i>new</i>	\$ 178.50 ✓
2	Rear Bumper Sponge <i>85x2 = 170</i>	\$ 5,342.60
	<i>cached</i>	
	Discount 25%	\$ 1,335.65
		\$ 4,006.95

To Be Continue/.....

YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883
Tel : 6844 1555 Fax. 6844 1311 Email : yap_lee_motor@singnet.com.sg

Date : 25-Jun-19

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #07-16
Singapore 079120

Your Reference : SLH 4630X

Owner Name : Bonita Pang Chyi
Accident Date : 13-Jun-19

ESTIMATE COST OF REPAIRS TO Toyota Estima SJN 7981E

<u>Quantity</u>	<u>Descriptions</u>	<u>Amount</u>
	<u>Nett Item :</u>	
1 set	Rear Bumper Clip <i>new</i>	\$ 30.00 <i>✓</i>
1 set	Rear Reverse Sensor <i>Not make</i>	\$ 300.00 <i>x</i>
1	Joint Sealant <i>RM</i>	\$ 150.00 <i>60.</i>
1	Windscreen Sealant <i>new</i>	\$ 150.00 <i>+</i>
		\$ 630.00

Sub-Total 4636.95

Labour And Miscellaneous Charges

Check Rear Wiring and Lightning System	\$ 60.00 <i>30</i>
Remove, Refit Rear Lining, Trim and Garnish	\$ 120.00 <i>40</i>
Remove and Renew Rear Reverse Sensor	\$ 120.00 <i>50</i>
Remove and Straighten Rear Exhaust	\$ 120.00 <i>+</i>
Remove and Refit Rear Windscreen	\$ 150.00 <i>x</i>
Transfer Parts, Attachment from Old Tailgate to New	\$ 180.00 <i>x</i>
Panel Beating on Affected Areas <i>1170</i>	\$ 900.00 <i>60</i>
Spray Painting on Affected Areas	\$ 800.00 <i>700</i>
Apply Anti Rust in Affected Areas	\$ 100.00 <i>50</i>

\$ 2,550.00

7314.45

Grand Total \$ 7,186.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin L
4/5 26/06/19
OSays

total 372.42
4/5 3K

3K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19010655/ATD3N2

Date: 18/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100487681-02
 Claimant Vehicle No: SJN7981E Insured Vehicle No: SLH4630X
 Date of Loss: 13/06/2019 Nature of Claim: TP Claim No: 2656690877SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN7981E
 Make & Model: TOYOTA ESTIMA, 2.4 E X (A) Engine No: 2AZF215601
 Reg. Date: 27/02/2009 (Man. Year: 2008) Chassis No: ACR500082652
 Colour: Gold Odometer: 190075 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,764.45	2,272.42	2,492.03	52.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,470.00	1,080.00	42.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,314.45	3,742.42	3,572.03	48.84
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,314.45	3,000.00	4,314.45	58.99

INSPECTION

Date of Assignment: 17/06/2019

Date Inspected: 26/06/2019 Inspected At:

Yap Lee Motor (HQ)
1 Kaki Bukit Avenue 6, #01-26 Autobay
@ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,251.00 FL	*1,251.00 FL
2	1		*REAR BUMPER SIDE RETAINER	Necessary	110.00 FL	*110.00 FL
3	1		*REAR BUMPER REFLECTOR	Not Necessary	180.00 FL	*- FL
4	1		*REAR END PANEL	Dented	755.10 FL	*755.10 FL
5	1		*REAR END PANEL TOP GARNISH	Deformed	275.20 FL	*275.20 FL
6	1		*REAR END PANEL LOCK SENSOR	Damaged	293.00 FL	*242.40 FL
7	1		*REAR END PANEL CENTRE GARNISH	Not Necessary	198.70 FL	*- FL
8	1		*TAILGATE	Repair	1,281.40 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	318.70 FL	*- FL
10	1		*TAILGATE LOCK	Not Necessary	349.80 FL	*- FL
11	1		*TAILGATE LOCK STRIKER	Not Necessary	45.00 FL	*- FL
12	1		*TAILGATE EMBLEM-LOGO	Necessary	48.70 FL	*48.70 FL
13	1		*TAILGATE EMBLEM-ESTIMA	Necessary	57.50 FL	*57.50 FL
14	1		*TAILGATE GLASS MOULDING	Not Necessary	178.50 FL	*- FL
15	2		*REAR BUMPER SPONGE	Cracked	170.00 FL	*170.00 FL
16	1		*SET REAR BUMPER XLIP	Necessary	30.00 FS	*30.00 FS
17	1		*SET REAR REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
18	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
19	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,142.60	2,999.90
- List Item Discount on L Items 25.00/25.00% (S\$)	1,378.15	727.48
Total Parts (S\$)	4,764.45	2,272.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING,TRIM AND GARNISH	New	120.00	40.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	New	120.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
6	TRANSFER PARTS,ATTACHMENT FROM OLD TAILGATE TO NEW	New	180.00	0.00
7	PANEL BEATING ON AFFECTED AREAS	New	900.00	600.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	700.00
9	APPLY ANTI RUST IN AFFECTED AREAS	New	100.00	50.00
Gross Labour Cost (S\$)			2,550.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >