



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:

India International Insurance Pte Ltd (HQ)

0

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/06/2019
Vehicle Reg. No.:	YP2969L	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MITSUBISHI FUSO, 10.7 D FV70HJA00064 (M)	Vehicle Reg. Date:	01/06/2016
Vehicle Colour:	WHITE		
Engine No:	4P10C24877	Chassis No:	FEB21EA20633
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	3,780.00
Miscellaneous Items	11.00
Labour	960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,751.00
+ GST 7.00% (\$\$)	332.57
Nett Amount (\$\$)	5,083.57

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 14 Jun 2019)**Parts:** N/A MITSUBISHI FUSO 10.7 D FV70HJA00064 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for YP2969L)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER COVER LH	25.00	0.00	*280.00 FL
2	1		*FRONT HEADLAMP LH	25.00	0.00	*980.00 FL
3	1		*FRONT SMALL LAMP LH	25.00	0.00	*210.00 FL
4	1		*FRONT SIGNAL LAMP LH	25.00	0.00	*230.00 FL
5	1		*FRONT CORNER PANEL LH	25.00	0.00	*280.00 FL
6	1		*FRONT ROUND MIRROR LH	25.00	0.00	*100.00 FL
7	1		*FRONT DOOR LH	25.00	0.00	*2,400.00 FL
8	1		*FRONT DOOR LOWER HINGE LH	25.00	0.00	*160.00 FL
9	1		*FRONT DOOR COMPANY LETTERING & LOGO STICKER	0	0.00	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,940.00
- List Item Discount on L Items (\$\$)	1,160.00
Total Parts (\$\$)	3,780.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO STRAIGHTEN LH FRONT DOOR PILLAR AND RENEW DAMAGED PARTS	New	300.00
2	TO REMOVE & TRANSFER ITEMS TO NEW LH FRONT DOOR	New	100.00
3	TO APPLY RUST PROOF ON AFFECTED AREAS	New	60.00
4	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	500.00
Gross Labour Cost (S\$)			960.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**
< END OF ESTIMATES >