

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67138415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000026**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJQ7517Y
KOH SENG SEON
BLK 549B SEGAR ROAD
#11-640
SINGAPORE 672549
CONTACT NO : 97575333

DATE : 17-JUN-2019
MAKE : TOYOTA
MODEL : COROLLA ALTIS 1.6 AUTO
CHASSIS NO : MR053ZEE106145849
ENGINE NO : 3ZZ4891032
SERVICE ADVISOR : ABBY LIM
PAGE : 1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	BOOT LID	W/Buc 909.70 ✓	
1	BOOT LID LAMP R/H	11 211.90 X	
1	BOOT LID LOCK	11 126.80 ✓	
1	BOOT LID OUTER CHOME MOULDING	11 223.21 X	
1	BOOT LID (TOYOTA) LOGO	11 45.67 ✓	
1	BOOT LID EMBLEM (COROLLA ALTIS)	11 45.67 ✓	
1	BOOT LID INNER TRIM	De/Torn 251.60 ✓	
2	BOOT LID INTER STOPPER	11 29.00 X	
1	REAR BOOT WEATHERSTRIP	11 194.70 ✓	
1	REAR END PANEL	11 590.60 ✓	
1	REAR END PANEL TOP GARNISH	11 202.70 ✓	
1	FENDER INNER TRIM R/H	De/Torn 378.40 ✓	
1	SPARE TYRE TOP BOARD	11 389.40 ✓	
1	TAIL LAMP R/H	11 414.10 ✓	
1	TAIL LAMP L/H	11 414.10 X	
1	TAIL LAMP PANEL R/H	11 129.24 X	
1	TAIL LAMP LOWER BRACKET R/H	11 45.70 X	
1	REAR BUMPER	Dis 523.90 ✓	
1	REAR BUMPER SPONGE	11 175.70 X	
1	REAR BUMPER BRACKET R/H	11 97.70 ✓	
1	REAR BUMPER SIDE RETAINER (LONG) o/s	11 57.80 ✓	
1	REAR BUMPER SIDE RETAINER (SHORT) o/s	11 46.95 ✓	
1	REAR BUMPER SIDE REFLECTOR	11 47.77 X	
1	BOOT LIT EMBLEM (1.6)	11 45.67 ✓	
Sub Total		5,597.98	0.00

SPECIAL NETT

10	BOOT LIT INNER TRIM CLIPS	11 50.00 ✓
----	---------------------------	------------

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67138415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000026**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJQ7517Y
KOH SENG SEON
 BLK 549B SEGAR ROAD
 #11-640
 SINGAPORE 672549
 CONTACT NO : 97575333

DATE : 17-JUN-2019
 MAKE : TOYOTA
 MODEL : COROLLA ALTIS 1.6 AUTO
 CHASSIS NO : MR053ZEE106145849
 ENGINE NO : 3ZZ4891032
 SERVICE ADVISOR : ABBY LIM
 PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
10	END PANEL TOP GARNISH CLIPS	11 50.00 X	
10	REAR BUMPER CLIPS	11 30.00 ✓	
10	FENDER INNER TRIM CLIPS	11 30.00 ✓	
1 set	REVERSE SENSOR	slub 250.00 200	
1	REVERSE CAMERA	11 380.00 X	
1	REAR END PANEL SEALANT	11 50.00 ✓	
1	BOOT LIT SEALANT	11 50.00 X	
10	TAIL LAMP SIDE CLIPS	11 50.00 X	
Sub Total		940.00	0.00

LABOUR

1	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA	1,000.00 800	
1	CHECK WIRING	50.00 30	
1	REMOVE AND REFIX BOOT LIT COMPONENT	100.00 60	
1	REMOVE AND REFIX EXHAUST PIPE	150.00 60	
1	REMOVE & REFIX SENSOR & TEST	80.00 50	
1	REMOVE AND REFIX CAMERA & TEST	100.00 50	
1	TO APPLY UNDERCOATING FOR RUST ROOFING	100.00 60	
1	SPRAY PAINTING ON ACCIDENT AREA	1,000.00 980	
Sub Total		2,580.00	0.00

SUB-TOTAL	9,117.98	0.00
GST - 7 %	638.26	0.00
TOTAL	9,756.24	0.00

ABWIN SERVICE PTE LTD

Prepared By

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-4321.36

25%

2-3241.02

S.N - 360.00

1640 - 2040.00

5641.02