

INS. CASE OWNER:

CC 4/ III 19010669 / T1 pa3

LKK: IDAC:

Surveyor:

MCH

DOI:

ASSIGNMENT

18/6/2019

Date / Time:

18/6/19

Registered in Merimen:

18/6/19

Pre-assign / CCU / FTE

Insured Vehicle No.:

SHD 3244C

Claim No.:

Name of Insured:

Comfort Transportation PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 10/06/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLQ 8767L

INSRS:

WSP: Teamwork garage

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SLQ 8767L - NA/LIP 19010390/64 - DOA 10/06/19
SHD 3244C - CC3/11/16002323/T1/18/06/19 - DOA 09/06/19
- CC3/11/16002323/T1/18/06/19 - DOA 16/07/19

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

22/8/19 - File -> Tautirih to finalise
1/11/19 - File -> type mandate
27/11/19 - File -> in letter to insurer
14/1/2020 - File pass to me to close.

ELIMINARY ADVICE Date/Time:

Sent By:

VALORIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$\$

(days) Reduction: %

Email Call

VAL SETTLEMENT

Date/Time:

Confirm with: Shm

Email Call

Liability:

%

(Agreed / Assessed) BOLA S/N No.: 28C4cc.011011

NO or B 28, Ass. Ltr

Repair Cost:

\$\$

16638.50

Cost of Rental (LOR):

\$\$

1600.00 (16 days) x \$100

Cost of Use (LOU):

\$\$

- (\$ x days)

Cost of Income (LOI):

\$\$

- (\$ x days)

LOU only LOR + LOU

LOU only

LOR + LOI [Tick only one]

LTA Search

\$\$

7.45

Medical:

\$\$

-

Disbursement:

\$\$

-

(e.g. Tow/ Independent)

Repair Cost:

\$\$

-

Total:

\$\$

18245.95

Global Sum \$\$: 18240.00

VAL PAYMENT

Date/Time:

Confirm with:

Email Call

Receipt 1:

\$\$

18240.00

Name 1:

Teamwork Garage Pte Ltd

Receipt 2: (Strike if N.A.)

\$\$

Name 2:

Receipt 3: (Strike if N.A.)

\$\$

Name 3:

COPY PRINT 14/01/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 1

3) Survey fee: \$600.00

ASSIGNMENT

From: _____ Date: 17/6/19

Estimated Cost: _____

OD: TP / RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLQ 8767L

at Workshop n/s: Teamwork Garage

of 53 ubi Ave 1 #01-24

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLQ 8767L (Reg: 2017 July)

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezel Hybrid cc 1496

Colour: Blach. AC: Insured / Std / NI / NA

Sp Reading: 14466 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RM 31230386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/60R16 R: 1 -

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 87K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or No

Lum Sum: 20% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 10/6/19	D.O.L. 18/6/19

Survey held at: Teamwork Garage.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	U s \$ 15550 (Reel \$ 13110.52 / 86%)
	13 + 20 + 1113 = 16

Date/Time, File Pass 1/1 : Prel. Report

1/1 : Final Report

Date/Time, File Return 1/1

3

Report Format: _____

Lump Sum / LE: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Advt Fee: Site Insp \$ Interview \$ Tech Insp \$ Wash cost \$

Survey Fee: _____

Transportation: _____

3 + RS of _____

Flare: _____

Other: _____

Other: _____

Rebate: 842,223



Pte Ltd

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com

India International Insurance Pte Ltd
 64 Cecil Street #05-00
 IOB Building
 Singapore 409711

Register number : 201015366H
 3RD PARTY CLAIM ESTIMATION

Vehicle number	SLQ8767L
Make / Model	HONDA/VEZEL
Chassis number	RU31230386
Accident date	10/6/19
Reference	1906-36

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE	1098.25 <i>bt</i>
4	TAILGATE GLASS MOULDING	140.00 <i>noi</i>
1	TAILGATE LOGO	58.00 <i>noi</i>
1	TAILGATE EMBLEM - VEZEL	58.04 <i>noi</i>
1	TAILGATE OUTER GARNISH	143.75 <i>x nn</i>
1	TAILGATE LOCK	86.25 ? / <i>OT</i>
1	TAILGATE LOCK STRIKER	40.25 ? <i>x nn</i>
1	TAILGATE RUBBER	120.75 ? <i>CRU</i>
1	TAILGATE LOCK STRIKER	45.21 <i>x repair</i>
2	TAILGATE DAMPER	448.50 <i>x nn</i>
1	TAILGATE INNER PULL COVER	35.73 ? <i>x nn</i>
1	TAILGATE INNER TRIM	224.25 <i>R / CRU</i>
2	TAILGATE INNER LAMP	609.50 ? <i>RH / LH / CRU</i>
1	REAR BUMPER	855.70 1024.95 <i>de</i>
2	REAR BUMPER RETAINER	64.40 <i>noi</i>
1	REAR BUMPER REINFORCEMENT	312.30 ? <i>x nn</i>
2	REAR BUMPER REFLECTOR	86.80 173.60 <i>LH-LH / RH-x nn</i>
1	REAR EXHAUST SILENCER	607.20 ? <i>photo</i>
2	REAR EXHAUST MOUNTING	35.90 ? <i>x nn</i>
2	REAR FENDER INNER TRIM	434.70 <i>x RH / LH / CR</i>
1	END PANEL	DD 585.20
1	END PAENL GARNISH	CRU 81.25
1	REAR FLOOR COMPARTMENT PANEL	DD 901.30
1	SPARE TYRE TOP BOARD	TN 447.39
1	SPARE TYRE UNDER COVER	CRU 355.20
2	REAR TAILLAMP	DR RH / LH / 966.00
2	REAR CORNER BUMPER	LH / RH / BR 580.24 <i>LH-LH / RH-?</i>
1	FRONT BUMPER	902.85 <i>de</i> 727.50
2	FRONT BUMPER SIDE GARNISH <i>(white each)</i>	RH / LH / DR 140.08
1	FRONT BUMPER LOWER GRILLE	DR 160.41
2	FRONT BUMPER RETAINER	64.60 <i>noi</i>
2	FRONT HEADLAMP	4105.50 <i>LH-LH / RH-?</i>
		1784.50 <i>CR</i>

Topline 97415149
-wp
18/6/19 p 530pm
lump sum
Repair cost to repair
tailgate mechanism
9 days

2	FRONT HEADLAMP BRACKET	120.10	
2	FOG LAMP	554.30 Xnn	
2	FOG LAMP COVER	179.40 Xnn	
1	FRONT BUMPER UNDER SPOILER	450.80	
1	FRONT BUMPER REINFORCEMENT	311.65 ?	
*1	FRONT GRILLE	1035.00	
1	FRONT GRILLE EMBLEM	35.01	
1	WIPER TANK	74.75 X NY	
1	AIRCON CONDENSER ASSY	718.54 X NY	
1	Front support panel X	18531.10	12089.27
	Less 20%	3706.22	9671.42
	Subtotal	14824.88	
	Balance C/F	14824.88	
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	14824.88	
1	FRONT NUMBER PLATE	70.00	45
1 SET	FRONT BUMPER CLIP	40.00	30mm
1	REAR NUMBER PLATE	70.00	X NY
1 SET	REAR REVERSE SENSOR	400.00	200mm
1 SET	REAR BUMPER CLIP	40.00	30mm
1 SET	REAR FENDER INNER TRIM CLIP	30.00	X NY
1	JOINT SEALANT	150.00	50V Ma
1	WINDSCREEN SEALANT	150.00	60mm
1	FLOOR INSULATOR	150.00	X NY
1	REAR REVERSE CAMERA	500.00	X NY 415
	Subtotal	1490.00	
	Balance C/F	16314.88	
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	16314.88	
1	CHECK ALL WIRING AND LIGHTNING SYSTEM	80.00	40
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	50.00	X
3	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00	60
4	REMOVE AND RENEW REAR REVERSE SENSOR	150.00	30
5	REMOVE AND RENEW REAR EXHAUST SILENCER	150.00	80
6	REMOVE AND RENEW FLOOR INSULATOR	150.00	X
7	REMOVE AND RENEW FUEL TANK	150.00	X
8	REMOVE AND REFIT REAR WINDSCREEN	150.00	120
9	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00	60
10	PANEL BEATING ON AFFECTED AREAS	1400.00	1200
11	SPRAY PAINTING ON AFFECTED AREAS	1600.00	1200
12	APPLY ANTI RUST ON AFFECTED AREAS	150.00	40 2830
	Subtotal	4430.00	
	Grand total	20744.88	



Pte Ltd

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com

India International Insurance Pte Ltd
 64 Cecil Street #05-00
 IOB Building
 Singapore 409711

Steve - 19/6/19

Register number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	SLQ8767L
Make / Model	HONDA/VEZEL
Chassis number	RU31230386
Accident date	10/6/19
Reference	1906-36

Qty Particulars

Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR AXLE X	1739.95 X un.
1	REAR BATTERY (HYBRID) (Lamp (CRV) / ACV (Air filter) / CRV	8154.60 dd ✓
		9894.55
	Less 20%	1978.91
	Subtotal	7915.64

6523.68

9671.42
 415
 2830
 6523.68
 19440.10
 4/58 15550 #
 13 days



Pte Ltd

India International Insurance Pte Ltd
 64 Cecil Street #05-00
 IOB Building
 Singapore 409711

Steve - 19/6/19

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	SLQ8767L
Make / Model	HONDA/VEZEL
Chassis number	RU31230386
Accident date	10/6/19
Reference	1906-36

Qty Particulars

Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR AXLE X	1739.95
1	REAR BATTERY (HYBRID) (Lower cover) - BCRV (Air duct) - CRV	8154.60
		9894.55
	Less 20%	1978.91
	Subtotal	7915.64

Battery (ML & charge pad)

Steve 25/6/19

Customer's consent is hereby notified
 to the following:
 • To provide estimate & parts during survey
 • To display damaged parts during survey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental services must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

28660.52



Pte Ltd

India International Insurance Pte Ltd
 64 Cecil Street #05-00
 IOB Building
 Singapore 409711

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 3RD PARTY CLAIM ESTIMATION

Vehicle number	SLQ8767L
Make / Model	HONDA/VEZEL
Chassis number	RU31230386
Accident date	10/6/19
Reference	1906-36

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE	1098.25 <i>bt</i>
4	TAILGATE GLASS MOULDING	140.00 <i>not</i>
1	TAILGATE LOGO	58.00 <i>not</i>
1	TAILGATE EMBLEM - VEZEL	58.04 <i>not</i>
1	TAILGATE OUTER GARNISH	143.75 x
1	TAILGATE LOCK	86.25 ?
1	TAILGATE LOCK STRIKER	40.25 ?
1	TAILGATE RUBBER	120.75 ?
1	TAILGATE LOCK STRIKER	45.21 x <i>Repaired</i>
2	TAILGATE DAMPER	448.50 x
1	TAILGATE INNER PULL COVER	35.73 ?
1	TAILGATE INNER TRIM	224.25 x
2	TAILGATE INNER LAMP	609.50 ?
1	REAR BUMPER	1024.95 <i>de</i>
2	REAR BUMPER RETAINER	64.40 <i>not</i>
1	REAR BUMPER REINFORCEMENT	312.30 ?
2	REAR BUMPER REFLECTOR	173.60 <i>LH on RH x</i>
1	REAR EXHAUST SILENCER	607.20 ? <i>photo</i>
2	REAR EXHAUST MOUNTING	35.90 ?
2	REAR FENDER INNER TRIM	434.70 x
1	END PANEL	585.20 ?
1	END PAENL GARNISH	81.25 ?
1	REAR FLOOR COMPARTMENT PANEL	901.30 <i>Rx</i>
1	SPARE TYRE TOP BOARD	447.39 ?
1	SPARE TYRE UNDER COVER	355.20 ?
2	REAR TAILLAMP	966.00 ?
2	REAR CORNER BUMPER	580.24 <i>LH - do RH - ?</i>
1	FRONT BUMPER	902.85 <i>de</i>
2	FRONT BUMPER SIDE GARNISH	140.08 x
1	FRONT BUMPER LOWER GRILLE	160.41 x
2	FRONT BUMPER RETAINER	64.60 <i>not</i>
2	FRONT HEADLAMP	4105.50 <i>LH x RH - ?</i>

Topline 97415419
wp
18/6/19 @ 530pm
lump sum
Requiring cost to repair
for the 1st 10 hours
9 days

1. The Policyholder must notify the Repairer of the following:
 • To ensure before/after spray painting
 • To ensure correct - 100% damage recovery
 • To ensure correct - 100% specification
 • To ensure correct - 100% "Paint Protection"
 • To ensure correct - 100% "Paint Protection"

2	FRONT HEADLAMP BRACKET		120.10	X
2	FOG LAMP		554.30	X
2	FOG LAMP COVER		179.40	X
1	FRONT BUMPER UNDER SPOILER		450.80	R ₂₀
1	FRONT BUMPER REINFORCEMENT		311.65	?
1	FRONT GRILLE		1035.00	new
1	FRONT GRILLE EMBLEM		35.01	new
1	WIPER TANK		74.75	X
1	AIRCON CONDENSER ASSY		718.54	X
1	Front Support Panel		18531.10	
		Less 20%	3706.22	
		Subtotal	14824.88	
		Balance C/F	14824.88	
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
		Balance B/F	14824.88	
1	FRONT NUMBER PLATE		70.00	new
1 SET	FRONT BUMPER CLIP		40.00	30 new
1	REAR NUMBER PLATE		70.00	X
1 SET	REAR REVERSE SENSOR		400.00	200 new
1 SET	REAR BUMPER CLIP		40.00	30 new
1 SET	REAR FENDER INNER TRIM CLIP		30.00	X
1	JOINT SEALANT		150.00	50?
1	WINDSCREEN SEALANT		150.00	60 new
1	FLOOR INSULATOR		150.00	X
1	REAR REVERSE CAMERA		500.00	X
		Subtotal	1490.00	
		Balance C/F	16314.88	
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
		Balance B/F	16314.88	
1	CHECK ALL WIRING AND LIGHTNING SYSTEM		80.00	40
2	REMOVE, RENEW CONDENSER AND TOP UP GAS		50.00	?
3	REMOVE, REFIT REAR LINING, TRIM AND GARNISH		200.00	60
4	REMOVE AND RENEW REAR REVERSE SENSOR		150.00	30
5	REMOVE AND RENEW REAR EXHAUST SILENCER		150.00	80
6	REMOVE AND RENEW FLOOR INSULATOR		150.00	X
7	REMOVE AND RENEW FUEL TANK		150.00	X
8	REMOVE AND REFIT REAR WINDSCREEN		150.00	120
9	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW		200.00	60
10	PANEL BEATING ON AFFECTED AREAS		1400.00	1200
11	SPRAY PAINTING ON AFFECTED AREAS		1600.00	1200
12	APPLY ANTI RUST ON AFFECTED AREAS		150.00	40
		Subtotal	4430.00	
		Grand total	20744.88	

LK- Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No legal modification(s) is allowed
 • All ancillary item(s) must be resurveyed and resurveyed to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H

India International Insurance Pte Ltd
 64 Cecil Street #05-00
 IOB Building
 Singapore 409711

REPAIR PERFORMA INVOICE
Vehicle number SLQ8767L
Make / Model HONDA/VEZEL
Chassis number RU31230386
Accident date 10/6/19
Reference 1906-36

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR AXLE	1739.95
1	REAR BATTERY (HYBRID)	8154.60
		9894.55
	Less 20%	1978.91
	Subtotal	7915.64

I, the undersigned hereby certify
 the accuracy of the following:
 • The vehicle is insured under policy number
 • The repair is necessary and the cost is reasonable
 • The repair is carried out by a qualified person
 • The repair is carried out in a "White Flag" shop
 • All bills are itemized and received
 • I agree to indemnify and hold the insurer harmless
 from all claims, damages, costs and expenses
 which may be incurred by the insurer in connection with this claim.
 Authorized by Insurer
 Signature: _____
 Date: _____

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	6722Z

Vehicle Details

Vehicle No.:	SLQ8767L
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	LEB5930397
Chassis No.:	RU31230386
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,349.00
Original Registration Date:	25 Jul 2017
First Registration Date:	25 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jul 2027
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	24 Jul 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$38,562.00
Total Rebate Amount:	\$42,312.00

The information contained herein is correct as at 11 Jun 2019

OK

ccy/m

v & m

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 17 June 2019 9:25 AM
To: Darren; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Pooi Chin Han Daniel
Subject: RE: OUR REF : 1906-36 // YOUR REF : SHD3244C ACCIDENTINVOLVINGSHD3244C AND SLQ8767L
Attachments: 2019_06_12_16_37_24.pdf

10:10am @ 17/6/19
person @ Dumen
vehicle in

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLQ8767L and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Darren [mailto:claims@teamworkgarage.com]
Sent: 14 June, 2019 6:17 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: OUR REF : 1906-36 // YOUR REF : SHD3244C ACCIDENTINVOLVINGSHD3244C AND SLQ8767L

Hi Gabriel,

We refer to your list of surveyor, we agree on LKK

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Motor Claim - III
Sent: Friday, 14 June 2019 1:25 PM

To: Darren

Subject: RE: OUR REF : 1906-36 // YOUR REF : SHD3244C ACCIDENT INVOLVINGSHD3244C AND SLQ8767L

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Darren [<mailto:claims@teamworkgarage.com>]

Sent: 14 June, 2019 10:57 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: OUR REF : 1906-36 // YOUR REF : SHD3244C ACCIDENT INVOLVINGSHD3244C AND SLQ8767L

Hi,

REMINDER

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: TEAMWORK

Sent: Wednesday, 12 June 2019 4:38 PM

To: motorclaim@iii.com.sg

Cc: TEAMWORK

Subject: OUR REF : 1906-36 // YOUR REF : SHD3244C ACCIDENT INVOLVINGSHD3244C AND SLQ8767L

WITHOUT PREJUDICE

OUR REF : 1901-06

YOUR REF : SHD3244C

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR SLQ8767L
ACCIDENT INVOLVING SHD3244C AND SLQ8767L ON 10.06.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Jun 2019 14:57	Cim Dtl Modified	Claimant's Name: -> -.	[A] Suwanna Te- Uttaruang
2	17 Jun 2019 14:57	Cim Veh Model Changed	(206024) ALPINA D5 BITURBO RHD 3.0 D (M).	[A] Suwanna Te- Uttaruang
3	17 Jun 2019 14:57	Cim Created	Reg No: SL8767L. Acct Date: 2019/06/10. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Teamwork Garage Pte Ltd (HQ)	[A] Suwanna Te- Uttaruang
4	17 Jun 2019 14:57	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Suwanna Te- Uttaruang
5	17 Jun 2019 14:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/26	[A] Suwanna Te- Uttaruang
6	17 Jun 2019 14:57	Adj Mandate Set	Approved;0.00.Reinsp:Adj decides.	[A] Suwanna Te- Uttaruang
7	17 Jun 2019 14:58	Label Added	(30653):Direct Settlement.	[A] Suwanna Te- Uttaruang
8	17 Jun 2019 14:58	Assignment 1st Accessed		[A] Suwanna Te- Uttaruang
9	17 Jun 2019 21:24	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] HOW MEI KWAN
10	17 Jun 2019 21:27	Cim Dtl Modified	Claimant's Name: - -> ROSET LIMOUSINE SERVICES PTE L. Claimant's ID: -> 2004067222.	[A] HOW MEI KWAN
11	17 Jun 2019 21:27	Cim Registration Modified	Reg No:SL8767L->SLQ8767L.	[A] HOW MEI KWAN
12	17 Jun 2019 21:27	Cim Veh Model Changed	(206024) -> (204907) HONDA VEZEL 1.5 HYBRID X (A).	[A] HOW MEI KWAN
13	20 Jun 2019 08:42	Adj Adjuster Assigned	BRYAN TANI -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
14	24 Jun 2019 10:25	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% (BOLA 28) Remarks: 4 vehicles chain collision wh ereby ID was the last car.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2180763	18/06/2019 08:40	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SLQ8767L	SHD3244C	11.77

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Jun 2019 14:57	Cim Dtl Modified	Claimant's Name: -> -.	[A] Suwanna Te- Uttaruang
2	17 Jun 2019 14:57	Cim Veh Model Changed	(206024) ALPINA D5 BITURBO RHD 3.0 D (M).	[A] Suwanna Te- Uttaruang
3	17 Jun 2019 14:57	Cim Created	Reg No: SL8767L. Acct Data: 2019/06/10. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Teamwork Garage Pte Ltd (HQ)	[A] Suwanna Te- Uttaruang
4	17 Jun 2019 14:57	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Suwanna Te- Uttaruang
5	17 Jun 2019 14:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/26	[A] Suwanna Te- Uttaruang
6	17 Jun 2019 14:57	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Suwanna Te- Uttaruang
7	17 Jun 2019 14:58	Label Added	(30653):Direct Settlement.	[A] Suwanna Te- Uttaruang
8	17 Jun 2019 14:58	Assignment 1st Accessed		[A] Suwanna Te- Uttaruang
9	17 Jun 2019 21:24	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] HOW MEI KWAN
10	17 Jun 2019 21:27	Cim Dtl Modified	Claimant's Name: - -> ROSET LIMOUSINE SERVICES PTE L. Claimant's ID: -> 200406722Z.	[A] HOW MEI KWAN
11	17 Jun 2019 21:27	Cim Registration Modified	Reg No:SL8767L->SLQ8767L.	[A] HOW MEI KWAN
12	17 Jun 2019 21:27	Cim Veh Model Changed	(206024) -> (204907) HONDA VEZEL 1.5 HYBRID X (A).	[A] HOW MEI KWAN
13	20 Jun 2019 08:42	Adj Adjuster Assigned	BRYAN TANI -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
14	24 Jun 2019 10:25	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% (BOLA 28) Remarks: 4 vehicles chain collision wh ereby ID was the last car.	[A] CHEW HSIAO TONG
15	24 Jun 2019 14:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/26. Mandate Remarks: We are agreeable to a D IRECT SETTLEMENT in this matter.	[I] Sundari Nagarajan
16	24 Jun 2019 14:37	Adj Mandate Set	Approved:0.00:We are agreeable to a DIRECT SETTLEMENT in this matter.	[I] Sundari Nagarajan

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2180763	18/06/2019 08:40	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SLQ8767L	SHD3244C	11.77

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 11 July 2019 8:33 AM
To: 'claims' (claims@teamworkgarage.com)
Subject: Your ref: SLQ 8767L *Our ref: CC4/III19010669/T1pa3 [ACCIDENT INVOLVING SHD 3244C(III)/ SLQ 8767L/ OTHERS ON 10/06/2019]

Your ref: **SLQ 8767L** **Without Prejudice**
Our ref: CC4/III19010669/T1pa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHD 3244C(III)/ SLQ 8767L/ OTHERS ON 10/06/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear subject to the BOLA guideline settlement and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Darren <claims@teamworkgarage.com>
Sent: Thursday, 11 July 2019 9:43 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: SLQ8767L HONDA VEZEL
Attachments: TEAMWORK ESTIMATE -8767 SUPP.xlsx; 3f9c5e85-05a1-47a9-ba3f-a9072cf311a2.jpg; 961f17bd-a1ff-4d8c-a4e6-5d021ab22336.jpg; 3095ac4c-2bd7-47bc-b268-f3ff60688f7e.jpg; 71046a7b-e5e9-4bab-b3a3-3354a3a79fb8.jpg; a46cdd4d-0929-4190-b0c4-56392d71e0e4.jpg; ed41c292-3d2a-42de-b5d9-8f9043b9b16c.jpg

Hi Hsiao Tong,

Please help to assists Taufikh to finalise this case.

Thank you

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Darren
Sent: Tuesday, 2 July 2019 5:43 PM
To: taufikh@lkkauto.com
Subject: SLQ8767L HONDA VEZEL

Hi Taufikh,

FYNA

Based on estimate calculation:

COR @ \$16000 (Included supplementary)
DOR @ We will like to counter propose Day of repair @ 16 Days

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Jun 2019 14:57	Cim Dtl Modified	Claimant's Name: -> -.	Suwanna Te- Uttaruang [A]
2	17 Jun 2019 14:57	Cim Veh Model Changed	(206024) ALPINA D5 BITURBO RHD 3.0 D (M).	Suwanna Te- Uttaruang [A]
3	17 Jun 2019 14:57	Cim Created	Reg No: SL8767L. Acct Date: 2019/06/10. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Teamwork Garage Pte Ltd (HQ)	Suwanna Te- Uttaruang [A]
4	17 Jun 2019 14:57	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	Suwanna Te- Uttaruang [A]
5	17 Jun 2019 14:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/26	Suwanna Te- Uttaruang [A]
6	17 Jun 2019 14:57	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	Suwanna Te- Uttaruang [A]
7	17 Jun 2019 14:58	Label Added	(30653):Direct Settlement.	Suwanna Te- Uttaruang [A]
8	17 Jun 2019 14:58	Assignment 1st Accessed		Suwanna Te- Uttaruang [A]
9	17 Jun 2019 21:24	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] HOW MEI KWAN
10	17 Jun 2019 21:27	Cim Dtl Modified	Claimant's Name: - -> ROSET LIMOUSINE SERVICES PTE L. Claimant's ID: -> 200406722Z.	[A] HOW MEI KWAN
11	17 Jun 2019 21:27	Cim Registration Modified	Reg No:SL8767L->SLQ8767L.	[A] HOW MEI KWAN
12	17 Jun 2019 21:27	Cim Veh Model Changed	(206024) -> (204907) HONDA VEZEL 1.5 HYBRID X (A).	[A] HOW MEI KWAN
13	20 Jun 2019 08:42	Adj Adjuster Assigned	BRYAN TANI -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
14	24 Jun 2019 10:25	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% (BOLA 28) Remarks: 4 vehicles chain collision wh ereby ID was the last car.	[A] CHEW HSIAO TONG
15	24 Jun 2019 14:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/26. Mandate Remarks: We are agreeable to a DIRECT SETTLEMENT in this matter.	[I] Sundari Nagarajan
16	24 Jun 2019 14:37	Adj Mandate Set	Approved:0.00:We are agreeable to a DIRECT SETTLEMENT in this matter.	[I] Sundari Nagarajan
17	20 Nov 2019 12:36	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
18	20 Nov 2019 12:36	Cim Dtl Modified	JPJ Reg. Date: -> 2017/07/25.	[A] JOANNE LEE KHANG MIN
19	20 Nov 2019 12:36	Cim Details Notified		[A] JOANNE LEE KHANG MIN
20	22 Nov 2019 10:13	Adj Mandate Request	Cur.Reg:18245.95:PODS Liability: 100% *Quantum: (a)CORw/GST: \$16,638.50 + (b) LOR(16days x \$100.00): \$1,600.00 + (c)LTA/GIA search fee: \$7.45 = Total: \$18,245.95 *Vehicle Model: Honda Vezel (1496cc) *13 recommendation repair days + 2Sunday + 1PRS	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

Print Received Message

This mail is associated with :

***SLQ8767L (MCT19060218)**
[SHD3244C]

TP

ROSET LIMOUSINE SERVICES PTE LTD

Jun 10 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Teamwork Garage Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/12/2019 11:56 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$18245.95) - SLQ8767L - Claim Handler: Pooi Chin Han Daniel

Approved:18245.95:Request TP WS to issue Tax invoice for Repairs in III's favour

Hsiao Tong (LKKAuto)

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Tuesday, 24 December 2019 11:40 AM
To: Hsiao Tong (LKKAuto)
Cc: Admin A; TEAMWORK
Subject: RE: OUR REF: 1906-36 // YOUR REF: SHD3244C
ACCIDENTINVOLVINGSHD3244CAND SLQ8767L //LKK REF: CC4/III19010669/T1pa3

WITHOUT PREJUDICE

Dear Hsiao Tong,

We refer to the offer below, it is acceptable.

Please let us have the DV soonest.

Thank you and have a nice day.

Regards,

Shu Shan

Teamwork Garage Pte Ltd

Blk 53 Ubi Avenue 1

#01-24

Paya Ubi Industrial Park

Singapore 408934

Tel: 6844 2475

Fax:6844 2474

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 24 December 2019 11:29 AM
To: Claims TeamworkGarage
Cc: Admin A
Subject: RE: OUR REF: 1906-36 // YOUR REF: SHD3244C ACCIDENTINVOLVINGSHD3244CAND SLQ8767L //LKK REF: CC4/III19010669/T1pa3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We are prepared to improve our offer at a global sum of \$18,240.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims TeamworkGarage <claims@teamworkgarage.com>

Sent: Monday, 23 December 2019 3:39 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Claims TeamworkGarage <claims@teamworkgarage.com>

Subject: RE: OUR REF: 1906-36 // YOUR REF: SHD3244C ACCIDENT INVOLVINGSHD3244CAND SLQ8767L //LKK REF: CC4/III19010669/T1pa3

WITHOUT PREJUDICE

Dear Sir/Madam ,

We refer to your offer dated 23rd December 2019.

We would like to counter propose the offer as mention :

Cost of Repair : \$ 16,638.50 (AGREED)

Loss of Rental : \$ 2,250 (\$150 x 15 Days , plus PRI & weekend)

Thank you ! 😊

Regards,

Tricia

Teamwork Garage Pte Ltd

Blk 53 Ubi Avenue 1

#01-24

Paya Ubi Industrial Park

Singapore 408934

Tel : 68442475

Fax : 68442474

From: Hsiao Tong (LKKAuto)

Sent: Monday, December 23, 2019 2:52 PM

To: Desmond

Cc: Admin A

Subject: RE: OUR REF: 1906-36 // YOUR REF: SHD3244C ACCIDENT INVOLVINGSHD3244CAND SLQ8767L //LKK REF: CC4/III19010669/T1pa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$18,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond <claims@teamworkgarage.com>

Sent: Wednesday, 11 December 2019 10:31 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Jia Le (LKK Auto) <JiaLe@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: Desmond <claims@teamworkgarage.com>

Subject: RE: OUR REF: 1906-36 // YOUR REF: SHD3244C ACCIDENT INVOLVINGSHD3244C AND SLQ8767L

Without Prejudice

Dear Sir/Madam,

We refer to above matter and LOD dated on 18TH Oct 2019 , we would like to remind due to date yet to receive any offer.

Hope to have your favourable offer soonest to settle the matter amicably.
Please forward to the case handler if this case does not belong to you.

Thank you for your understanding and blessed day ahead!

Regards,
Desmond
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel : 68442475
Fax : 68442474

From: Desmond
Sent: Wednesday, 20 November 2019 5:37 PM
To: 'Hsiao Tong (LKKAuto)'; Admin A; Admin-D (LKKAuto)
Cc: Desmond
Subject: RE: OUR REF: 1906-36 // YOUR REF: SHD3244C ACCIDENT INVOLVINGSHD3244C AND SLQ8767L

Without Prejudice

Dear Sir/Madam,

We refer to above matter and LOD dated on 18TH Oct 2019 , we would like to remind due to date yet to receive any offer.

Hope to have your favourable offer soonest to settle the matter amicably.
Please forward to the case handler if this case does not belong to you.

Thank you for your understanding and blessed day ahead!

Please ignore the previous email.

Regards,
Desmond
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel : 68442475
Fax : 68442474

From: Desmond
Sent: Wednesday, 20 November 2019 5:35 PM
To: 'Hsiao Tong (LKKAuto)'; Admin A; Admin-D (LKKAuto)
Cc: Desmond
Subject:

OUR REF: 1906-36 // YOUR REF: SHD3244C ACCIDENT INVOLVING SHD3244C AND SLQ8767L

Without Prejudice

Dear Sir/Madam,

We refer to above matter and LOD dated on 18TH Oct 2019 , we would like to remind due to date yet to receive any offer.

Hope to have your favourable offer soonest to settle the matter amicably.
Please forward to the case handler if this case does not belong to you.

Thank you for your understanding and blessed day ahead!

Regards,
Desmond
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel : 68442475
Fax : 68442474

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD18V12322 /VPZ /R00
Form	MZ406C
Date Of Issue	30-OCT-2018
1.Index Mark and Registration No. of Vehicle:	SLQ8767L
2.Chassis number of Vehicle:	RU31230386
3.Name of Policyholder:	ROSET LIMOUSINE SERVICES PTE LTD
4.Effective date of Commencement of Insurance for the purpose of the Act:	01-NOV-2018 00:00 AM
5.Date of Expiry of Insurance:	31-OCT-2019 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	
<p>Any person who is driving on the Policyholder's order or with their permission or to whom the vehicle is hired.</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.</p>	
7.Limitations as to use*:	
<p>A) Use for carriage of passengers or goods in connection with the Policyholder's business. B) Use for social, domestic, pleasure and business purposes of any person to whom the vehicle is hired. C) Use for the carriage of passengers for hire or reward under "Uber/Grabcar" by the person to whom the vehicle is hired.</p>	
8.Policy does not cover:	
<p>A) Use for racing, pace-making, reliability trial or speed-testing. B) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.</p> <p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.</p>	
<p>I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).</p>	
<p>For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers</p> 	
<p>_____ Authorised Signature</p>	
For Information only:	
COVERAGE :	Comprehensive, Unlimited Windscreen, Geographical Area - refer memorandum, Grabcar Extension
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Refer Memorandum - Section I S\$2000, Refer Memorandum - Section II S\$2000, Windscreen Excess S\$100
FINANCE COMPANY:	
PRODUCER NAME:	NEWSTATE STENHOUSE (S) PTE LTD



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475 Fax : 6844 2474
 E-mail : claims@teamworkgarage.com
 GST registered number : 201015366H

PROFOMA INVOICE - PI-2010

ROSET LIMOUSINE SERVICES PTE LTD
 C/O 53 Ubi Avenue 1 #01-24
 Paya Ubi Industrial Park
 Singapore 408934

Date : 18-Oct-19
 Vehicle number : SLQ8767L
 Make Model : HONDA VEZEL
 Accident date : 10.06.2019
 Reference number : 1903-36

Description		Amount SGD\$
Inclusive of supplying parts, labour, panel beating and spray painting		
Lump sum repair	:	15550.00
7% GST	:	1088.50
Grand total	:	16638.50
Singdollars: SIXTEEN THOUSAND SIX HUNDRED AND THIRTY-EIGHT DOLLAR ANS FIFTY CENTS		



Teamwork Garage Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jun 2019 Edit Reg		17 Jun 2019 00:00 Edit Adj Rpt	S\$15,550.00 Edit Estimates	S\$15,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	ROSET LIMOUSINE SERVICES PTE LTD , Co. Reg. No.: 200406722Z								
Vehicle Reg. No.:	SLQ8767L	Date of Loss:	10/06/2019 00:00 - :59 [22 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19060218	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHD3244C	Policy No. (Claimant):	SD18V12322/VPZ/R00						
		Excess:							
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (10/12/2019): Alert - Adj Mandate Approved (S\$18245.95) - SLQ8767L - Claim Handler: Pool Chin ... III_SG (24/06/2019): Alert - Adj Mandate Approved (S\$0.00) - SLQ8767L - Claim Handler: Pool Chin Han ... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ8767L (MCT19060218)
[SHD3244C]
TP
ROSET LIMOUSINE SERVICES PTE LTD
Jun 10 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Teamwork Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/06/19 10:24	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	24/06/19 10:24	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
60	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/06/19 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
63	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	22/11/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
148	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
149	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
150	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
151	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
152	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
153	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
154	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
155	22/11/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
156	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
157	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
158	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
159	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
160	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
161	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
162	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
163	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
164	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
165	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
166	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
167	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
168	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
169	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
170	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
171	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
172	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
173	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
174	22/11/19 10:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
175	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
176	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
177	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
178	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
179	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
180	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
181	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
182	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
183	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
184	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
185	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
186	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
187	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
188	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
189	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
190	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
191	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
192	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
193	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
194	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
195	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
196	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
197	22/11/19 10:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
198	22/11/19 10:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
199	22/11/19 10:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
200	22/11/19 10:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
201	22/11/19 10:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
202	22/11/19 10:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
203	22/11/19 10:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 21:25	ACKNOWLEDGEMENT EMAIL TO III DD 17.06.2019		Load PDF
2	17/06/19 21:25	TP GIA REPORT		Load PDF
3	21/06/19 10:08	TP ESTIMATE - MARKED		Load PDF
4	21/11/19 16:03	RENTAL RECEIPT		Load PDF
5	21/11/19 16:03	LTA SEARCH		Load PDF
6	21/11/19 16:03	LOD		Load PDF
7	22/11/19 10:11	PARF_COE REBATE		Load PDF

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
8	16/01/20 11:30	WORKSHOP INVOICE		Load PDF
9	16/01/20 11:30	AUTHORISATION TO ACT FORM		Load PDF
10	16/01/20 11:30	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	18/06/19 08:40	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19010669/T1PA3Q2

Date: 16/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLQ8767L	Insured Vehicle No :	SHD3244C
Date of Loss: 10/06/2019	Nature of Claim: TP	Claim No: MCT19060218

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8767L	Engine No:	LEB5930397
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31230386
Reg. Date:	25/07/2017 (Man. Year: 2016)	Odometer:	143166 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,340.52	16,610.10	7,730.42	31.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	2,830.00	1,600.00	36.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,770.52	19,440.10	9,330.42	32.43
Approved Total (Overridden) (S\$)		15,550.00		
(S\$)	28,770.52	15,550.00	13,220.52	45.95
+ GST 7.00/7.00% (S\$)	2,013.94	1,088.50	925.44	45.95
Nett Amount (S\$)	30,784.46	16,638.50	14,145.96	45.95
+ Car Rental (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		18,245.95		
Global Sum Settlement (S\$)		18,240.00		

INSPECTION

Date of Assignment:	17/06/2019	
Date Inspected:	18/06/2019	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	13.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$87,000.00(est) less LTA Rebate: \$42,312.00(est) = Nett Value :\$44,688.00(est)

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)	
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLQ8767L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,098.25 FL	*1,098.25 FL
2	4		*TAILGATE GLASS MOULDING	Necessary	140.00 FL	*140.00 FL
3	1		*TAILGATE LOGO	Necessary	58.00 FL	*58.00 FL
4	1		*TAILGATE EMBLEM -VEZEL	Necessary	58.04 FL	*58.04 FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	143.75 FL	*- FL
6	1		*TAILGATE LOCK	Bent	86.25 FL	*86.25 FL
7	1		*TAILGATE LOCK STRIKER	Not Necessary	40.25 FL	*- FL
8	1		*TAILGATE RUBBER	Crumpled	120.75 FL	*120.75 FL
9	1		*TAILGATE LOCK STRIKER	Repeated	45.21 FL	*- FL
10	2		*TAILGATE DAMPER	Not Necessary	448.50 FL	*- FL
11	1		*TAILGATE INNER PULL COVER	Not Necessary	35.73 FL	*- FL
12	1		*TAILGATE INNER TRIM	Crumpled	224.25 FL	*224.25 FL
13	2		*TAILGATE INNER LAMP	Broken	609.50 FL	*609.50 FL
14	1		*REAR BUMPER	Deformed	1,024.95 FL	*855.70 FL
15	2		*REAR BUMPER RETAINER	Necessary	64.40 FL	*64.40 FL
16	1		*REAR BUMPER REINFORCEMENT	Not Necessary	312.30 FL	*- FL
17	1		*REAR BUMPER REFLECTOR	N/S Cracked / O/SNot Necessary	173.60 FL	*86.80 FL
18	1		*REAR EXHAUST SILENCER	Bent	607.20 FL	*607.20 FL
19	2		*REAR EXHAUST MOUNTING	Not Necessary	35.90 FL	*- FL
20	2		*REAR FENDER INNER TRIM	Broken	434.70 FL	*434.70 FL
21	1		*END PANEL	Dented	585.20 FL	*585.20 FL
22	1		*END PANEL GARNISH	Crumpled	81.25 FL	*81.25 FL
23	1		*REAR FLOOR COMPARTMENT PANEL	Dented	901.30 FL	*901.30 FL
24	1		*SPARE TYRE TOP BOARD	Torn	447.39 FL	*447.39 FL
25	1		*SPARE TYRE UNDER COVER	Crumpled	355.20 FL	*355.20 FL
26	2		*REAR TAILLAMP	Broken	966.00 FL	*966.00 FL
27	2		*REAR CORNER BUMPER	Broken	580.24 FL	*580.24 FL
28	1		*FRONT BUMPER	Deformed	902.85 FL	*727.50 FL
29	2		*FRONT BUMPER SIDE GARNISH	Broken	140.08 FL	*140.08 FL
30	1		*FRONT BUMPER LOWER GRILLE	Broken	160.41 FL	*160.41 FL
31	1		*FRONT BUMPER RETAINER	Necessary	64.60 FL	*64.60 FL
32	1		*FRONT HEADLAMP	O/S Broken	4,105.50 FL	*1,784.50 FL
33	2		*FRONT HEADLAMP BRACKET	Broken	120.10 FL	*120.10 FL
34	2		*FOG LAMP	Not Necessary	554.30 FL	*- FL
35	2		*FOG LAMP COVER	Not Necessary	179.40 FL	*- FL
36	1		*FRONT BUMPER UNDER SPOILER	Repair	450.80 FL	*- FL
37	1		*FRONT BUMPER REINFORCEMENT	Dented	311.65 FL	*311.65 FL
38	1		*FRONT GRILLE	Cracked	1,035.00 FL	*385.00 FL
39	1		*FRONT GRILLE EMBLEM	Necessary	35.01 FL	*35.01 FL
40	1		*WIPER TANK	Not Necessary	74.75 FL	*- FL
41	1		*AIRCON CONDENDER ASSY	Not Necessary	718.54 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT NUMBER PLATE	Cut	70.00 FS	*45.00 FS
43	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
44	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
45	1		*SET REAR REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
46	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
47	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
48	1		*JOINT SEALANT	Necessary	150.00 FS	*50.00 FS
49	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
50	1		*FLOOR INSULATOR	Not Necessary	150.00 FS	*- FS
51	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
52	1		*REAR AXLE	Not Necessary	1,739.95 FL	*- FL
53	1		*REAR BATTERY (HYBRID)	Dented	8,154.60 FL	*8,154.60 FL

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (S\$)	30,025.65	20,658.87
- List Item Discount on L Items 20.00/20.00% (S\$)	5,685.13	4,048.77
Total Parts (S\$)	24,340.52	16,610.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	80.00	40.00
2	REMOVE,RENEW CONDENSER AND TOP UP GAS	New	50.00	0.00
3	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	60.00
4	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
5	REMOVE AND RENEW REAR EXHAUST SILENCER	New	150.00	80.00
6	REMOVE AND RENEW FLOOR INSULATOR	New	150.00	0.00
7	REMOVE AND RENEW FUEL TANK	New	150.00	0.00
8	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
9	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
10	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	1,200.00
11	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,200.00
12	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (S\$)			4,430.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >