

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 22X

AAD1906-121

*Not Authored
L/Sing & ?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 22X

WDD2120012B224483

MERCEDES BENZ

E 220 BLUETEC

12.6.19

AXA

16/12/2015

		PART		LIST	
1	1	Rear Bumper	\$	n 3,105.00	?
2	1	Rear Bumper Lower	\$	sn 1,080.00	X
3	1	Rear Bumper Reinforcement	\$	910.00	?
4	1	Rear Bumper Centre Pad	\$	sn 307.83	}
5	1	Rear Bumper Side Pad	\$	sn 186.33	
6	1	Rear Bumper Tow Hook Cover	\$	sn 42.00	
7	1	Rear Bumper Bracket	\$	n 22.50	
8	1	Rear Bumper Side Retainer Bracket	\$	n 132.00	
9	1	Rear Bumper Inner Frame	\$	sn 297.00	
10	1	Rear Bumper Bottom Bracket	\$	n 60.00	
11	1	Rear Bumper Top Bracket	\$	n 129.00	
12	1	Rear Bumper Side Holder Bracket	\$	n 135.00	
13	1	Rear Bumper Inner Bracket LH	\$	n 198.00	
14	1	Rear Bumper Inner Bracket RH	\$	n 198.00	
15	1	Rear Bumper Beam	\$	n 1,215.00	
16	1	Rear Bumper Beam Bracket LH	\$	n 307.50	
17	1	Rear Bumper Beam Bracket RH	\$	n 307.50	
18	1	Rear Bumper Bracket Centre	\$	sn 461.75	
19	1	Rear Bumper Tow Hook Cover	\$	sn 63.00	
20	1	Rear Bumper Retainer Bracket LH	\$	n 202.50	
21	1	Rear Bumper Retainer Bracket RH	\$	n 202.50	
22	1	Bootlid	\$	n 4,140.00	
23	1	Bootlid 'E220' Badge	\$	na 153.00	
24	1	Bootlid 'BLUETEC' Badge	\$	na 153.00	
25	1	Bootlid Centre Logo Badge	\$	na 153.00	

X

Trans-cab Auto Services Pte Ltd

AAD1906-121

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 22X

26	1	Bootlid Protector Garnish With Chrome	\$	Su	732.00	}
27	1	Bootlid Weatherstrip	\$	Su	360.00	
28	1	Bootlid Lock - Top	\$	n	300.00	
29	1	Bootlid Lock - Bottom	\$	n	216.00	
30	1	Bootlid Lock Actuator	\$	Su	420.00	
31	1	Bootlid Weatherstrip	\$	Su	240.00	
32	1	Bootlid Third Brake Lamp	\$	Su	577.50	
33	1	Rear End Panel Outer	\$	n	1,971.00	
34	1	Rear End Panel Inner	\$	n	324.00	
35	1	Rear End Panel Inner Trim	\$	Su	630.00	
36	1	Rear End Panel Inner Trim Flap	\$	Su	360.00	
37	1	Rear Lamp RH	\$	Su	1,170.00	
38	1	Rear Lamp Panel Outer RH	\$	n	382.95	
39	1	Rear Lamp LH	\$	Su	1,170.00	
40	1	Rear Lamp Panel Outer LH	\$	n	382.95	
41	1	Rear Luggage Floor Panel Tray	\$	Su	762.00	
42	1	Rear Luggage Floor Compartment Tray	\$	Su	116.00	
43	1	Rear Luggage Floor Panel Trim Board	\$	Su	420.00	
TOTAL			\$		24,695.81	
			10%	\$	2,469.58	
			\$		22,226.22	

Special Nett

1	1 SET	Rear Bumper Parking Sensor	\$	Su	1,200.00	X
2	1 SET	Bootlid Inner Trim Clip	\$	nn	90.00	X
3	1 SET	Rear End Panel Inner Trim Clip	\$	nn	90.00	X
4	1 SET	Rear Bumper Fastener Clip	\$		101.54	?
5	1 SET	Rear Fender Top Garnish Clip	\$	nn	90.00	X
6	1 SET	Rear Fender Inner Trim Clip	\$	nn	45.00	{
7	1 SET	License plate	\$	Su	225.00	X
8	1	Rear Windscreen Glass Sealant	\$	Wsu	225.00	X
9	1	Rear Windscreen Glass Inner Seal	\$	nn	180.00	{
10	1	Tyre Mechanical Jack	\$	Su	605.48	{
11	1	Tyre Mechanical Jack Holder Bracket	\$	n	177.98	X

Trans-cab Auto Services Pte Ltd

AAD1906-121

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 22X

12	1	Rear Bootlid 'DYNASTY' Sticker	\$	<i>nn</i> 33.75	X
TOTAL			\$	3,063.74	
GRAND TOTAL			\$	25,289.97	

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,500.00	<i>2009</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 120.00	X
Putty And Spray Painting Of The Affected Portion.	\$	5,500.00	<i>2501</i>
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	<i>nn</i> 270.00	X
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X
To Transfer Of Tire, Rim And On Wheel Balancing.	\$	<i>nn</i> 170.00	X
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1906-121

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 22X

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To Reinstall Rear Bumper Parking Sensor.	\$	170.00	?
To Reseal Sealant On Gap	\$	<i>nn</i> 120.00	X
To Supply And Re-Do Rear Luggage Floor Panel Insulation Padding.	\$	<i>5</i> 380.00	X
To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	<i>5</i> 170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>4</i> 170.00	X
To Repair And Realign Rear Exhaust Pipe.	\$	<i>5</i> 170.00	X
TOTAL	\$	13,850.00	
Over all total	\$	39,139.97	

(LUMP SUM) Repair Days

15-DAYS

1 - 2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: