

INS. CASE OWNER:

CC4/III 19010672 / Upa3

LKK:

IDAC:

Surveyor:

MARINS

DOI:

ASSIGNMENT

18/6/2019

Date / Time:

13/6/19

Registered in Merimen:

17/6/19

Pre-assign / CCU / FTE

Insured Vehicle No.:

SHA 3203L

Claim No.:

Name of Insured:

Comfort Transportation PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : \$:

D.O.A.:

13/06/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

STV 3156E

INSRS:

WSP: RICO 60

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

STV 3156E - NA/CT/19010572/h4 - DOA 13/06/2019
 - NA/CT/19010572/h3 - DOA 29/07/2017
 SHA 3203L - CC3/LER19024106/K14352 - DOA 28/12/2017
 - CC4/AXA 15011008/MT/302 - DOA 29/06/2015
 - CC4/III 17010916/K14352 - DOA 24/05/2017
 - CC4/III 19010630/Upa352 - DOA 09/09/2018

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

29/6/19 - OI part \$500 for private settlement?

27-05-19 TRY TO ARRIVE ON OFFER & ACCEPTABLE BEFORE PENNING DOWN THE TERM OF PRIVATE SETTLEMENT.

20/4/19 - III: There is a party system between OI & TP.
 Unable to withdraw TP claim
 - File -> MK to claim (exp)

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

1450

ELIMINARY ADVICE Date/Time:

Sent By:

VALIZATION

Date/Time:

Confirm with:

Confirm by:

Fair Cost:

\$:

(\$

days) Reduction:

%

Email

Call

VAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

al Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Fair Cost:

\$:

s of Rental (LOR):

\$:

(\$

days)

s of Use (LOU):

\$:

(\$

x

days)

s of Income (LOI):

\$:

(\$

x

days)

R only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

LTA Search

\$:

Final:

\$:

bursement:

\$:

(e.g. Tow/ Independent)

al Cost

\$:

ali:

\$:

Global Sum \$:

VAL PAYMENT

Date/Time:

Confirm with:

Email

Call

ec 1:

\$:

Name 1:

ec 2: (Strike if N.A.)

\$:

Name 2:

ec 3: (Strike if N.A.)

\$:

Name 3:

108/11/13 Wed

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GVA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 13980

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SVU 3156E

Yr Regn: 20/1/10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda stream

c.c 1799

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

216478

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRN686095200932

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/6/19

D.O.I.

18/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

2/5 Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7th. 19-1-2020 7th.

4/543000

(Real # 25844.47 90%).

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



Rico 60 Auto Services Pte Ltd - Blk 8, Kaki Bukit Avenue 4, #02-24

Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com

Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:

SJV 3156 E

MAKE & MODEL:

HONDA STREAM

MILEAGE:

TYRE:

CHASSIS NUM:

ATTN:				
NO.	DESCRIPTION - PARTS	QTY	PRICE	
1	REAR WINDSCREEN MOULDING	11	1 \$ 65.00	X
2	TAILGATE	11	1 \$ 903.20	X
3	TAILGATE WIPER	11	1 \$ 186.30	X
4	TAILGATE WIPER MOTOR	11	1 \$ 216.40	X
5	TAILGATE LOCK	11	1 \$ 109.40	X
6	TAILGATE CATCH	11	1 \$ 27.50	X
7	TAILGATE LOGO (HONDA)	11	1 \$ 21.90	X
8	TAILGATE EMBLEM (STREAM)	11	1 \$ 31.60	X
9	TAILGATE CENTER GARNISH	11	1 \$ 108.00	X
10	TAILGATE HANDLE SWITCH	11	1 \$ 50.00	X
11	TAILGATE CARPLATE LAMP (L+R)	11	2 \$ 131.20	X
12	TAILGATE INNER BOARD	11	1 \$ 141.00	X
13	TAILGATE INNER GARNISH CENTER	11	1 \$ 136.00	X
14	TAILGATE INNER GARNISH (L+R)	11	2 \$ 272.00	X
15	TAILGATE DAMPER (L+R)	11	2 \$ 474.40	X
16	TAILGATE HINGE (L+R)	11	2 \$ 187.20	X
17	TAILGATE STOPPER (L+R)	11	2 \$ 44.00	X
18	TAILGATE INNER HANDLE	11	1 \$ 25.00	X
19	TAILGATE INNER WIRE RUBBER PROTECTOR	11	2 \$ 40.00	X
20	TAILGATE WEATHER STRIP	11	1 \$ 121.60	X
21	TAIL LAMP (L+R)	11	2 \$ 1,434.00	X
22	TAIL LAMP PANEL (L+R)	11	2 \$ 583.96	X
23	REAR BUMPER	Deepcut	1 \$ 588.90	X
24	REAR BUMPER RETAINER (L+R) 35-20	0/5 best	2 \$ 117.60	12C
25	REAR BUMPER TOWING CAP	11	1 \$ 13.90	X
26	REAR BUMPER REINFORCEMENT BAR	NS	1	X
27	REAR BUMPER BEAM	NS	1	X
28	REAR BUMPER SPONGE	NS	1	X
29	REAR BUMPER BRACKET (L+R)	11	2 \$ 100.00	X
30	REAR FENDER (L+R) 858.30	0/1 30/500	2 \$ 1,716.60	12C
31	QUARTER WINDOW MOULDING (L+R) w/glass	11	2 \$ 375.00	X
32	REAR FENDER COWLING (L+R)	11	2 \$ 395.20	X
33	REAR FENDER INNER TRIM (UPPER) (L+R)	11	2 \$ 788.00	X
34	REAR FENDER INNER TRIM (LOWER) (L+R)	11	2	X
35	END PANEL	11	1 \$ 306.70	X
36	END PANEL TOP GARNISH	11	1 \$ 116.70	X
37	FLOOR PANEL	11	1 \$ 1,420.00	X
38	FLOOR PANEL TOP BOARD	11	1 \$ 238.40	X
39	FLOOR PANEL TOP BOARD TOP GARNISH	11	1 \$ 277.30	X
40	EXHAUST PIPE	11	1 \$ 978.20	X

18/6/19

not signed
n/c 3000
The 1st time

41	EXHAUST GASKET	11	1	\$	28.50	X
42	EXHAUST BRACKET (L+R)	11	2	\$	33.00	X
43	EXHAUST HEAT SHIELD	17	1	\$	42.10	X
44	SPARE TYRE BRACKET	17	1	\$	347.00	X
45	REAR ABSORBER (RH)	17	1			X
46	REAR LOWER ARM (RH)	17	1	\$	384.10	X
47	REAR THRUST ARM (RH)	17	1	\$	95.40	X
48	REAR KNUCKLE (RH)	17	1	\$	316.00	X
49	REAR KNUCKLE BEARING (RH)	17	1	\$	367.10	X
50	REAR BEARING HUB (RH)	17	1	\$	389.80	X
51	REAR UPPER LINK (RH)	17	1	\$	72.90	X
52	REAR AXLE (RH)	17	1			X

SUBTOTAL \$ 14,818.06

LESS 20% \$ 2,963.61

PARTS TOTAL \$ 11,854.45

SPECIAL NETT		QTY	PRICE	
1	TAILGATE SPOILER	11	1	\$ 2,000.00 X
2	TAILGATE SPOILER THIRD BRAKE LAMP	17	1	\$ 1,000.00 X
3	REAR WINDSCREEN SEALANT	11	1	\$ 120.00 X
4	REAR WINDSCREEN STICKER (WEBSITE)	17	1	\$ 300.00 X
5	REAR WINDSCREEN STICKER (CAR)	17	1	\$ 200.00 X
6	REAR WINDSCREEN STICKER (ASOBA9)	17	1	\$ 300.00 X
7	TAILGATE WIPER BLADE	17	1	\$ 80.00 X
8	TAILGATE INNER BOARD CLIP	17	10	\$ 100.00 X
9	TAILGATE EMBLEM (CHINESE WORD)	17	1	\$ 250.00 X
10	REAR CARPLATE	17	1	\$ 120.00 X
11	REVERSE CAMERA	17	1	\$ 850.00 X
12	REAR BUMPER CLIP	21	10	\$ 100.00 40
13	REVERSE SENSOR SET	17	4	\$ 600.00 X
14	REAR FENDER SEALANT	21	1	\$ 120.00 40
15	REAR FENDER QUARTER WINDOW SEALANT	2	2	\$ 120.00 X
16	REAR FENDER COWLING CLIP	17	10	\$ 100.00 X
17	END PANEL SEALANT	17	1	\$ 120.00 X
18	SPAREWHEEL PANEL SEALANT	17	1	\$ 120.00 X
19	EXHAUST CHROME TIP	17	1	\$ 400.00 X
20	REAR TYRE (RH)	17	1	\$ 600.00 X
21	REAR RIM (RH)	617	1	\$ 3,000.00 600
22	SPARE TYRE	17	1	\$ 600.00 X
23	SPARE TYRE RIM	17	1	\$ 800.00 X

SPECIAL NETT TOTAL \$ 9,000.00

LABOUR		QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1000	1	\$ 3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	720	1	\$ 2,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	50	1	\$ 250.00
4	TO RNR REAR WINDSCREEN	117	1	\$ 400.00
5	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	80	1	\$ 400.00

6	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	1	S	120.00
7	TO RNR REVERSE CAMERA AND TEST FUNCTION	11 X	1	S	120.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11 X	1	S	250.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	20	1	S	120.00
10	TO DO WATER LEAK TEST.	11 X	1	S	80.00
11	TO RNR FUEL TANK TO ASSIST WORK LOAD	conduct wheel alignment	60	1	S 250.00
				TOTAL	S 7,990.00
				GRAND TOTAL COST	S 28,844.45

PAGE 2 OF 2

LKK Auto Consultants hence notify the Reparer of the following:

- To receive labour and spray painting
- To ensure damaged parts during resurvey
- Parts to be replaced by performance
- This survey is on a "Without Prejudice" basis
- For the purpose of insurance claim
- Subject to approval from the insurance company

Acknowledged by Reparer

Signature:

Date:

P- 1482.40
 202
 P- 1185.92
 S.N 680.00
 10km 1980.00
 3865.82
 3276.73



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJV 3156 E
HONDA STREAM

not after
now
1/5/19
18/6/19
Zh/HK

ATTN	NO.	DESCRIPTION - PARTS	QTY	PRICE	
	1	REAR WINDSCREEN MOULDING	11	1	\$ 65.00 X
	2	TAILGATE	11	1	\$ 903.20 X
	3	TAILGATE WIPER	11	1	\$ 186.30 X
	4	TAILGATE WIPER MOTOR	11	1	\$ 216.40 X
	5	TAILGATE LOCK	11	1	\$ 109.40 X
	6	TAILGATE CATCH	11	1	\$ 27.50 X
	7	TAILGATE LOGO (HONDA)	11	1	\$ 21.90 X
	8	TAILGATE EMBLEM (STREAM)	11	1	\$ 31.60 X
	9	TAILGATE CENTER GARNISH	11	1	\$ 108.00 X
	10	TAILGATE HANDLE SWITCH	11	1	\$ 50.00 X
	11	TAILGATE CARPLATE LAMP (L+R)	11	2	\$ 131.20 X
	12	TAILGATE INNER BOARD	11	1	\$ 141.00 X
	13	TAILGATE INNER GARNISH CENTER	11	1	\$ 136.00 X
	14	TAILGATE INNER GARNISH (L+R)	11	2	\$ 272.00 X
	15	TAILGATE DAMPER (L+R)	11	2	\$ 474.40 X
	16	TAILGATE HINGE (L+R)	11	2	\$ 187.20 X
	17	TAILGATE STOPPER (L+R)	11	2	\$ 44.00 X
	18	TAILGATE INNER HANDLE	11	1	\$ 25.00 X
	19	TAILGATE INNER WIRE RUBBER PROTECTOR	11	2	\$ 40.00 X
	20	TAILGATE WEATHER STRIP	11	1	\$ 121.60 X
	21	TAIL LAMP (L+R)	11	2	\$ 1,434.00 X
	22	TAIL LAMP PANEL (L+R)	11	2	\$ 583.96 X
	23	REAR BUMPER	11	1	\$ 588.90
	24	REAR BUMPER RETAINER (L+R)	11	2	\$ 117.60 inc
	25	REAR BUMPER TOWING CAP	11	1	\$ 13.90 X
	26	REAR BUMPER REINFORCEMENT BAR	11	1	\$
	27	REAR BUMPER BEAM	11	1	\$
	28	REAR BUMPER SPONGE	11	1	\$
	29	REAR BUMPER BRACKET (L+R)	11	2	\$ 100.00 X
	30	REAR FENDER (L+R)	11	2	\$ 1,716.60 inc
	31	QUARTER WINDOW MOULDING (L+R) w/glass	11	2	\$ 375.00 X
	32	REAR FENDER COWLING (L+R)	11	2	\$ 395.20 X
	33	REAR FENDER INNER TRIM (UPPER) (L+R)	11	2	\$ 788.00 X
	34	REAR FENDER INNER TRIM (LOWER) (L+R)	11	2	\$
	35	END PANEL	11	1	\$ 306.70 X
	36	END PANEL TOP GARNISH	11	1	\$ 116.70 X
	37	FLOOR PANEL	11	1	\$ 1,420.00 X
	38	FLOOR PANEL TOP BOARD	11	1	\$ 238.40 X
	39	FLOOR PANEL TOP BOARD TOP GARNISH	11	1	\$ 277.30 X
	40	EXHAUST PIPE	11	1	\$ 978.20 X

41	EXHAUST MANSLET	1	\$	28.50
42	EXHAUST BRACKET (L+R)	2	\$	33.00
43	EXHAUST HEAT SHIELD	1	\$	42.10
44	SPARE TYRE BRACKET	1	\$	347.00
45	REAR ABSORBER (RH)	1		
46	REAR LOWER ARM (RH)	1	\$	384.10
47	REAR THRUST ARM (RH)	1	\$	95.40
48	REAR KNUCKLE (RH)	1	\$	316.00
49	REAR KNUCKLE BEARING (RH)	1	\$	367.10
50	REAR BEARING HUB (RH)	1	\$	389.80
51	REAR UPPER LINK (RH)	1	\$	72.90
52	REAR AXLE (RH)	1		
SUBTOTAL				\$ 14,818.06
LESS 20%				\$ 2,963.61
PARTS TOTAL				\$ 11,854.45
SPECIAL NETT				QTY PRICE
1	TAILGATE SPOILER	1	\$	2,000.00
2	TAILGATE SPOILER THIRD BRAKE LAMP	1	\$	1,000.00
3	REAR WINDSCREEN SEALANT	1	\$	120.00
4	REAR WINDSCREEN STICKER (WEBSITE)	1	\$	300.00
5	REAR WINDSCREEN STICKER (CAR)	1	\$	200.00
6	REAR WINDSCREEN STICKER (ASOBA9)	1	\$	300.00
7	TAILGATE WIPER BLADE	1	\$	80.00
8	TAILGATE INNER BOARD CLIP	10	\$	100.00
9	TAILGATE EMBLEM (CHINESE WORD)	1	\$	250.00
10	REAR CARPLATE	1	\$	120.00
11	REVERSE CAMERA	1	\$	850.00
12	REAR BUMPER CLIP	10	\$	100.00
13	REVERSE SENSOR SET	4	\$	600.00
14	REAR FENDER SEALANT	1	\$	120.00
15	REAR FENDER QUARTER WINDOW SEALANT	2	\$	120.00
16	REAR FENDER COWLING CLIP	10	\$	100.00
17	END PANEL SEALANT	1	\$	120.00
18	SPAREWHEEL PANEL SEALANT	1	\$	120.00
19	EXHAUST CHROME TIP	1	\$	400.00
20	REAR TYRE (RH)	1	\$	600.00
21	REAR RIM (RH)	1	\$	3,000.00
22	SPARE TYRE	1	\$	600.00
23	SPARE TYRE RIM	1	\$	800.00
SPECIAL NETT TOTAL				\$ 9,000.00
LABOUR				QTY PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1	\$	3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$	2,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$	250.00
4	TO RNR REAR WINDSCREEN	1	\$	400.00
5	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	1	\$	400.00

6	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	1	\$	120.00
7	TO RNR REVERSE CAMERA AND TEST FUNCTION	11X	1	\$	120.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11X	1	\$	250.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	20	1	\$	120.00
10	TO DO WATER LEAK TEST.	11X	1	\$	80.00
11	TO RNR FUEL TANK TO ASSIST WORK LOAD	Conduct wheel alignment	60	1	\$ 250.00
				TOTAL	\$ 7,990.00
				GRAND TOTAL COST	\$ 28,844.45

PAGE 2 OF 2

LESS Auto Care wants hence notify
the Repairer of the following:

- To not spray / blow off the spray painting
- To spray damaged parts following resurvey
- Please ensure correct to confirmation
- To ensure no "No Fault" or "No Fault" basis
- No fault found - no cost allowed
- Safety of the vehicle is the priority and
is subject to the repairer's high insurance company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 1615L

Vehicle Details

Vehicle No.: SJV3156E
Vehicle to be Exported: No
Intended Deregistration Date: 14 Jun 2019
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8L A
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: R18A13800933
Chassis No.: JHMRN68609S200932
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$25,671.00
Original Registration Date: 20 Jan 2010
First Registration Date: 20 Jan 2010
Transfer Count: 2
Actual ARF Paid: \$25,671.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Jan 2020
PARF Rebate Amount: \$12,835.00

Intended COE Rebate Details

COE Expiry Date: 19 Jan 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$19,190.00
COE Rebate Amount: \$1,145.00
Total Rebate Amount: \$13,980.00

The information contained herein is correct as at 14 Jun 2019

OK



Essential highlights for today's women



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2010 BMW 218i Gran Turismo Only \$12k Deprec!



1. For Two million 5 years old
warranty Full Agem Last 100k
Low Mileage Covered
AutoPrestige Gallery Wood

- Free VCOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SYTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

HONDA STREAM

Advanced Search

View	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	HONDA STREAM	Any	Any	2010	Any	Any	Any	Available
	Honda Stream 1.8A (New 5-yr COE)	\$39,800	\$7,950 /yr	19-Jan-2010	1,799 cc	124,462 km	MPV	Available
High Loan Available! \$3000 Drive-Away Only. Replaced Part With Receipt Proof. New Paintwork, Serviced And Maintained By Fussay Owner. High Trade In And Flexible Loan Package To Fit You. Call Our Friend!...								
Posted: 12-Jun-2019 Tags: 2010 Honda Stream, 2010 Honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A Sunroof	\$23,333	\$10,810 /yr	24-Jun-2010	1,799 cc	110,000 km	MPV	Available
No Need Repairs! 7 Seater Sunroof Spacious MPV. Inspection Paid And Done. Genuine Low Mileage. Converted From OPC. 2nd Family Car Only Used 12000km Yearly. Effectively Only 2 Registered Owners. Inter!...								
Posted: 11-Jun-2019 Tags: 2010 Honda Stream, 2010 Honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A	\$21,000	\$12,080 /yr	14-Jan-2010	1,799 cc	-	MPV	Available
One Owner Unit. Practical And Good Fuel Efficiency Family Car Ideal For Daily Drives. Car Is In Good Condition. Good For COE Extension. Must View. Selling Cheap! Hurry! View Now. Flexible Loan And Hig...								
Car Empire Automobiles Pte Ltd								
Posted: 10-Jun-2019 Tags: 2010 Honda Stream, 2010 Honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A RSZ	\$21,438	\$10,300 /yr	24-Mar-2010	1,799 cc	-	MPV	Available
Posted: 06-Jun-2019 Tags: 2010 Honda Stream, 2010 Honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Honda Stream 1.8A X \$26,800 \$12,090 /yr 12-Oct-2010 1,799 cc 96,000 km MPV Available

Perfect For Drivers Looking For Short Term Drive Without Compromising Space And Comfort. Immaculate Condition Coupled With Well Maintained. Good For Drivers With Kids Or Big Families. 100% Loan Availa...

Posted: 01-Jun-2019 Tags: 2010 Honda Stream, 2010 Honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

View: Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)

CC4/m

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 14 June 2019 5:15 PM
To: Rico 60; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Sherini Pillai
Subject: RE: PRI Arrangement for SJV 3156 E
Attachments: PRI.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJV3156E and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Rico 60 [mailto:claims@rico60.com]
Sent: 14 June, 2019 4:17 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: PRI Arrangement for SJV 3156 E

Dear Gabriel,

Please arrange Marcus from LKK Auto Consultants Pte Ltd.

Thank you.

Best Regards,

Elfphaine Tan



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M

TP : 01 - SITA 3203L
9am @ 17/6/19
person @ Ivonne
vehicle not in
arrange on 19/6/19
V & M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
#02-24, Singapore 415875
Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: enquiry@rico60.com

From: Motor Claim - III
Sent: Friday, 14 June 2019 4:04 PM
To: Rico 60
Subject: RE: PRI Arrangement for SJV 3156 E

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Rico 60 [<mailto:claims@rico60.com>]
Sent: 14 June, 2019 2:25 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: PRI Arrangement for SJV 3156 E

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SJV 3156 E
Your Insured – SHA 3203 L
DOA – 13/06/2019

Vehicle will only be in our workshop on 19/6/2019.

Thank you.

Best Regards,

Elfphaine Tan



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Jun 2019 15:09	Clim Dtl Modified	Claimant's Name: -> -.	[A] Suwanna Te-Uttaruang
2	17 Jun 2019 15:09	Clim Veh Model Changed	(204705) AUSTIN 7 848cc (A).	[A] Suwanna Te-Uttaruang
3	17 Jun 2019 15:09	Clim Created	Reg No: SJV3156E. Acct Date: 2019/06/13. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: RICO 60 AUTO SERVICES PTE LTD (HQ)	[A] Suwanna Te-Uttaruang
4	17 Jun 2019 15:09	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Suwanna Te-Uttaruang
5	17 Jun 2019 15:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/26	[A] Suwanna Te-Uttaruang
6	17 Jun 2019 15:09	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Suwanna Te-Uttaruang
7	17 Jun 2019 15:10	Assignment 1st Accessed		[A] LEE SU THING
8	17 Jun 2019 15:10	Label Added	(30653):Direct Settlement.	[A] Suwanna Te-Uttaruang
9	17 Jun 2019 21:16	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
10	20 Jun 2019 09:20	Clim Dtl Modified	Claimant's Name: - -> MS CAR CONCEPT LEASING.	[A] HOW MEI KWAN
11	20 Jun 2019 09:20	Clim Registration Modified	Acct Time:00:00:00->10:00:00.	[A] HOW MEI KWAN
12	20 Jun 2019 09:20	Clim Veh Model Changed	(204705) -> (201726) HONDA STREAM 1.8 L (A).	[A] HOW MEI KWAN
13	24 Jun 2019 10:18	Adj Mandate Request	Cur.Req:0.00:PODS Liability: TBA Remarks: Insured driver reported that he had paid \$500 to third party for private settlement. Kindly assist to check with ID if there is any proof on the private settlement. Thanks.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2180761	18/06/2019 08:38	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SJV3156E	SHA3203L	11.77

Print Received Message

This mail is associated with :

***SJV3156E (MCT19060406)
[SHA3203L]**

TP

MS CAR CONCEPT LEASING
Jun 13 2019 10:00AM

RICO 60 AUTO SERVICES PTE LTD

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/06/2019 11:29 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SJV3156E - Claim Handler: Sundari Nagarajan

Maintained: please look at page no. 7 of our ID's accident report which has the workshop's bill

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 11 July 2019 8:53 AM
To: Rico 60
Cc: Admin A
Subject: Your ref: SJV 3156E *Our ref: CC4/III19010672/Upa3 [ACCIDENT INVOLVING SHA 3203L(III) AND SJV 3156E ON 13/06/2019]
Attachments: POLICE REPORT_SHA3203L.pdf; Workshop Repair Bill.pdf

Your ref: **SJV 3156E** **Without Prejudice**
Our ref: CC4/III19010672/Upa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHA 3203L(III) AND SJV 3156E ON 13/06/2019

We refer to the above matter.

Attached here with a copy of our driver police report and workshop repair bill. According to our driver, he had paid \$500 for private settlement.

Kindly assist to check and confirm with your client.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Rico 60 <claims@rico60.com>
Sent: Friday, 26 July 2019 11:42 AM
To: Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: RE: Your ref: SJV 3156E *Our ref: CC4/III19010672/Upa3[ACCIDENT INVOLVING SHA 3203L(III) AND SJV 3156E ON 13/06/2019]

Dear Hsiao Tong,

Any updates on your end for this matter?

We have heard from our client that the hirer/driver took the money without knowing what it was for. Being a Malay in race, the documents sign upon cash received is in Chinese language. After being informed by the owner of the vehicle to return the money, he tried contacting your client for the refund but his calls were refused/unanswered.

Please kindly advice on how we should proceed on further for this case.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

* THE CASH INVOICE ISSUED BY LOW & TAN CLEARLY INDICATED THAT YOUR CLIENT HAS SENT AN HIS VEHICLE FOR REPAIR ^{AT 1.30 PM} ON 13-6-19 FOR \$200/-, IN ADDITION YOUR CLIENT HAS ACCEPTED ADDITIONAL CASH OF \$200/- MAKE IT A TOTAL OF \$400/- BEING ^{FULL} PRIVATE SETTLEMENT OF THIS MATTER. ^{INDIRECTLY} WE BELIEVE BEFORE THEY CONCLUDED THE TERM OF SETTLEMENT, MUCH OF THE NEGOTIATIONS WERE CONDUCTED ^{VERBALLY} IN LANGUAGE UNDERSTOOD BY YOUR CLIENT, OTHERWISE HE WOULD NOT COUNTER SIGNED AS ACCEPTANCE OF OUR CLIENTS OFFER. UNDER SUCH A CIRCUMSTANCE, THE MATTER IS DEEMED AS CLOSED AND WE ARE UNABLE TO ASSIST ANY FURTHER.

From: Rico 60

Sent: Thursday, 11 July 2019 10:00 AM

To: Hsiao Tong (LKKAuto)

Cc: Admin A

Subject: RE: Your ref: SJV 3156E *Our ref: CC4/III19010672/Upa3[ACCIDENT INVOLVING SHA 3203L(III) AND SJV 3156E ON 13/06/2019]

Dear Hsiao Tong,

We appreciate your response for this matter.

I refer to the second attached file in your attachment.

Will you be able to provide us with more information as to who signed the document.

Thank you.

Best Regards,
John Ong

Print Sent Message

This mail is associated with :

***SJV3156E (MCT19060406)
[SHA3203L]**

TP
MS CAR CONCEPT LEASING
Jun 13 2019 10:00AM

RICO 60 AUTO SERVICES PTE LTD

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 23/10/2019 12:49 PM.
To sundari@iii.com.sg
CC III_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Seek Instruction> MCT19060406

Dear Sirs/Mdm,

We refer to your below email.

We have informed third party repairer that our insured driver had paid \$500.00 to their client for private settlement. Third party repairer had checked with thier client and accodring to thier client, he took the \$500.00 from our driver, however the amount is not sufficient to repair his car and in the end he decided to submit insurance claim. Third party driver had tried to contact our driver to return back the money but our driver refused/unanswered his call.

In view of the above, kindly advise further instruction.

Thank you.

Hsiao Tong

<-- Original Message -->

From: III_SG

To: LKK_HQ

Sent On: 24/06/2019 11:29 AM

Subject: Alert - Adj Mandate Maintained - SJV3156E - Claim Handler: Sundari Nagarajan

Maintained:please look at page no. 7 of our ID's accident report which has the workshop's bill

Print Received Message

This mail is associated with :

***SJV3156E (MCT19060406)
[SHA3203L]**

TP

MS CAR CONCEPT LEASING
Jun 13 2019 10:00AM

RICO 60 AUTO SERVICES PTE LTD

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 25/10/2019 14:17 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SJV3156E - Claim Handler: Sundari Nagarajan

Maintained:there is a private settlement between our ID & TP. We are unable to entertain further claim from TP

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 31 October 2019 8:22 AM
To: Rico 60
Cc: Admin A
Subject: RE: Your ref: SJV 3156E *Ourref:CC4/III19010672/Upa3[ACCIDENTINVOLVING SHA 3203L(III) AND SJV 3156EON13/06/2019]

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We have seek further instruction from our principal. However we regret to inform you that we are unable to entertain further claim as there is a private settlement between your client and our driver.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rico 60 <claims@rico60.com>
Sent: Tuesday, 13 August 2019 12:29 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Your ref: SJV 3156E *Ourref:CC4/III19010672/Upa3[ACCIDENTINVOLVING SHA 3203L(III) AND SJV 3156EON13/06/2019]

Dear Mdm,

We hope this email finds you well.

Any updates for this matter?

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
#02-24, Singapore 415875
Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: claims@rico60.com

From: Rico 60
Sent: Tuesday, 6 August 2019 7:05 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: Your ref: SJV 3156E *Ourref:CC4/III19010672/Upa3[ACCIDENTINVOLVING SHA 3203L(III) AND SJV 3156EON13/06/2019]

Dear Hsiao Tong,

Any updates on this matter?

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
#02-24, Singapore 415875
Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: claims@rico60.com

From: Rico 60
Sent: Friday, 26 July 2019 11:42 AM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: Your ref: SJV 3156E *Our ref:CC4/III19010672/Upa3[ACCIDENTINVOLVING SHA 3203L(III) AND SJV 3156E ON13/06/2019]

Dear Hsiao Tong,

Any updates on your end for this matter?

We have heard from our client that the hirer/driver took the money without knowing what it was for. Being a Malay in race, the documents sign upon cash received is in Chinese language. After being informed by the owner of the vehicle to return the money, he tried contacting your client for the refund but his calls were refused/unanswered.

Please kindly advice on how we should proceed on further for this case.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Rico 60

Sent: Thursday, 11 July 2019 10:00 AM

To: [Hsiao Tong \(LKKAUTO\)](#)

Cc: [Admin A](#)

Subject: RE: Your ref: SJV 3156E *Our ref: CC4/III19010672/Upa3[ACCIDENTINVOLVING SHA 3203L(III) AND SJV 3156E ON 13/06/2019]

Dear Hsiao Tong,

We appreciate your response for this matter.

I refer to the second attached file in your attachment.

Will you be able to provide us with more information as to who signed the document.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: [Hsiao Tong \(LKKAUTO\)](#)

Sent: Thursday, 11 July 2019 8:53 AM

To: [Rico 60](#)

Cc: [Admin A](#)

Subject: Your ref: SJV 3156E *Our ref: CC4/III19010672/Upa3 [ACCIDENTINVOLVING SHA 3203L(III) AND SJV 3156E ON 13/06/2019]

Your ref: **SJV 3156E**

Without Prejudice

Our ref: CC4/III19010672/Upa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHA 3203L(III) AND SJV 3156E ON 13/06/2019

We refer to the above matter,

Attached here with a copy of our driver police report and workshop repair bill. According to our driver, he had paid \$500 for private settlement.

Kindly assist to check and confirm with your client.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jun 2019 Edit Reg		17 Jun 2019 00:00 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	MS CAR CONCEPT LEASING								
Vehicle Reg. No.:	SJV3156E	Date of Loss:	13/06/2019 10:00 - :59 [112 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19060406	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA3203L	Policy No. (Claimant):	DMHCSN1921281900						
		Excess:							
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (25/10/2019): Alert - Adj Mandate Maintained - SJV3156E - Claim Handler: Sundari Nagarajan III_SG (24/06/2019): Alert - Adj Mandate Maintained - SJV3156E - Claim Handler: Sundari Nagarajan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV3156E (MCT19060406)
[SHA3203L]
TP
MS CAR CONCEPT LEASING
Jun 13 2019 10:00AM
[COMFORT TRANSPORTATION PTE LTD]
RICO 60 AUTO SERVICES PTE LTD

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/06/19 10:14	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
3	24/06/19 10:14	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
4	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
9	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
10	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
11	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
12	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
13	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
14	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
15	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
16	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
17	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
18	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
19	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
20	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
21	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
22	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
23	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
24	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
25	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
26	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
27	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
28	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
29	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
30	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
31	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>
32	24/06/19 10:14	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/06/19 21:17	ACKNOWLEDGEMENT EMAIL TO III DD 17.06.2019		Load PDF	
2	17/06/19 21:17	NOTIFICATION FROM WORKSHOP		Load PDF	
3	20/06/19 09:22	TP GIA REPORT		Load PDF	
4	21/06/19 10:10	TP ESTIMATE - MARKED		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	18/06/19 08:38	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19010672/UPA3Q2

Date: 12/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SJV3156E Insured Vehicle No: SHA3203L
 Date of Loss: 13/06/2019 Nature of Claim: TP Claim No: MCT19060406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV3156E
 Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A13800933
 Reg. Date: 20/01/2010 (Man. Year: 2008) Chassis No: JHMRN68609S200932
 Colour: Black Odometer: 216478 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,854.45	1,865.92	21,988.53	92.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,990.00	1,980.00	6,010.00	75.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,844.45	3,845.92	27,998.53	87.92
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	31,844.45	3,000.00	28,844.45	90.58
+ GST 7.00/7.00% (\$\$)	2,229.11	210.00	2,019.11	90.58
Nett Amount (\$\$)	34,073.56	3,210.00	30,863.56	90.58
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 17/06/2019
 Date Inspected: 18/06/2019 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
 8, KAKI BUKIT AVENUE 4, #02-24,
 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV3156E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Not Necessary	65.00 FL	*- FL
2	1	*TAILGATE	Not Necessary	903.20 FL	*- FL
3	1	*TAILGATE WIPER	Not Necessary	186.30 FL	*- FL
4	1	*TAILGATE WIPER MOTOR	Not Necessary	216.40 FL	*- FL
5	1	*TAILGATE LOCK	Not Necessary	109.40 FL	*- FL
6	1	*TAILGATE CATCH	Not Necessary	27.50 FL	*- FL
7	1	*TAILGATE LOGO (HONDA)	Not Necessary	21.90 FL	*- FL
8	1	*TAILGATE EMBLEM (STREAM)	Not Necessary	31.60 FL	*- FL
9	1	*TAILGATE CENTER GARNISH	Not Necessary	108.00 FL	*- FL
10	1	*TAILGATE HANDLE SWITCH	Not Necessary	50.00 FL	*- FL
11	2	*TAILGATE CARPLATE LAMP (L+R)	Not Necessary	131.20 FL	*- FL
12	1	*TAILGATE INNER BOARD	Not Necessary	141.00 FL	*- FL
13	1	*TAILGATE INNER GARNISH CENTER	Not Necessary	136.00 FL	*- FL
14	2	*TAILGATE INNER GARNISH (L+R)	Not Necessary	272.00 FL	*- FL
15	2	*TAILGATE DAMPER (L+R)	Not Necessary	474.40 FL	*- FL
16	2	*TAILGATE HINGE (L+R)	Not Necessary	187.20 FL	*- FL
17	2	*TAILGATE STOPPER (L+R)	Not Necessary	44.00 FL	*- FL
18	1	*TAILGATE INNER HANDLE	Not Necessary	25.00 FL	*- FL
19	2	*TAILGATE INNER WIRE RUBBER PROTECTOR	Not Necessary	40.00 FL	*- FL
20	1	*TAILGATE WEATHER STRIP	Not Necessary	121.60 FL	*- FL
21	2	*TAIL LAMP (L+R)	Not Necessary	1,434.00 FL	*- FL
22	2	*TAIL LAMP PANEL (L+R)	Not Necessary	583.96 FL	*- FL
23	1	*REAR BUMPER	Deep Cut	588.90 FL	*588.90 FL
24	1	*REAR BUMPER RETAINER (L+R)	O/S Bent	117.60 FL	*35.20 FL
25	1	*REAR BUMPER TOWING CAP	Not Necessary	13.90 FL	*- FL
26	1	*REAR BUMPER REINFORCEMENT BAR (NPA)	No such part	0.00 FL	*- FL
27	1	*REAR BUMPER BEAM (NPA)	No such part	0.00 FL	*- FL
28	1	*REAR BUMPER SPONGE (NPA)	No such part	0.00 FL	*- FL
29	2	*REAR BUMPER BRACKET (L+R)	Not Necessary	100.00 FL	*- FL
30	1	*REAR FENDER (L+R)	O/S Badly Dented	1,716.60 FL	*858.30 FL
31	2	*QUARTER WINDOW MOULDING (L+R) (W/GLASS)	Not Necessary	375.00 FL	*- FL
32	2	*REAR FENDER COWLING (L+R)	Not Necessary	395.20 FL	*- FL
33	2	*REAR FENDER INNER TRIM (UPPER) (L+R)	Not Necessary	788.00 FL	*- FL
34	2	*REAR FENDER INNER TRIM (LOWER) (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
35	1	*END PANEL	Not Necessary	306.70 FL	*- FL
36	1	*END PANEL TOP GARNISH	Not Necessary	116.70 FL	*- FL
37	1	*FLOOR PANEL	Not Necessary	1,420.00 FL	*- FL
38	1	*FLOOR PANEL TOP BOARD	Not Necessary	238.40 FL	*- FL
39	1	*FLOOR PANEL TOP BOARD TOP GARNISH	Not Necessary	277.30 FL	*- FL
40	1	*EXHAUST PIPE	Not Necessary	978.20 FL	*- FL
41	1	*EXHAUST GASKET	Not Necessary	28.50 FL	*- FL
42	2	*EXHAUST BRACKET (L+R)	Not Necessary	33.00 FL	*- FL
43	2	*EXHAUST HEAT SHIELD	Not Necessary	42.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SPARE TYRE BRACKET	Not Necessary	347.00 FL	*- FL
45	1		*REAR ABSORBER (RH) (NPA)	Not Necessary	0.00 FL	*- FL
46	1		*REAR LOWER ARM (RH)	Not Necessary	384.10 FL	*- FL
47	1		*REAR THRUST ARM (RH)	Not Necessary	95.40 FL	*- FL
48	1		*REAR KNUCKLE (RH)	Not Necessary	316.00 FL	*- FL
49	1		*REAR KNUCKLE BEARING (RH)	Not Necessary	367.10 FL	*- FL
50	1		*REAR BEARING HUB (RH)	Not Necessary	389.80 FL	*- FL
51	1		*REAR UPPER LINK (RH)	Not Necessary	72.90 FL	*- FL
52	1		*REAR AXLE (RH) (NPA)	Not Necessary	0.00 FL	*- FL
53	1		*TAILGATE SPOILER	Not Necessary	2,000.00 FS	*- FS
54	1		*TAILGATE SPOILER THIRD BRAKE LAMP	Not Necessary	1,000.00 FS	*- FS
55	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
56	1		*REAR WINDSCREEN STICKER (WEBSITE)	Not Necessary	300.00 FS	*- FS
57	1		*REAR WINDSCREEN STICKER (CAR)	Not Necessary	200.00 FS	*- FS
58	1		*REAR WINDSCREEN STICKER (ASOBA9)	Not Necessary	300.00 FS	*- FS
59	1		*TAILGATE WIPER BLADE	Not Necessary	80.00 FS	*- FS
60	10		*TAILGATE INNER BOARD CLIP	Not Necessary	100.00 FS	*- FS
61	1		*TAILGATE EMBLEM (CHINESE WORD)	Not Necessary	250.00 FS	*- FS
62	1		*REAR CARPLATE	Not Necessary	120.00 FS	*- FS
63	1		*REVERSE CAMERA	Not Necessary	850.00 FS	*- FS
64	10		*REAR BUMPER CLIP	Necessary	100.00 FS	*40.00 FS
65	4		*SET REVERSE SENSOR	Not Necessary	600.00 FS	*- FS
66	1		*REAR FENDER SEALANT	Necessary	120.00 FS	*40.00 FS
67	2		*REAR FENDER QUARTER WINDOW SEALANT		120.00 FS	*- FS
68	10		*REAR FENDER COWLING CLIP	Not Necessary	100.00 FS	*- FS
69	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
70	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
71	1		*EXHAUST CHROME TIP	Not Necessary	400.00 FS	*- FS
72	1		*REAR TYRE (RH)	Not Necessary	600.00 FS	*- FS
73	1		*REAR RIM (RH)	Cut	3,000.00 FS	*600.00 FS
74	1		*SPARE TYRE	Not Necessary	600.00 FS	*- FS
75	1		*SPARE TYRE RIM	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,818.06	2,162.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,963.61	296.48
Total Parts (\$\$)	23,854.45	1,865.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS ,CUT /WELD ,KNOCK & REALIGN	New	3,600.00	1,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,400.00	720.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	50.00
4	TO RNR REAR WINDSCREEN	New	400.00	0.00
5	TO RNR UPHOLSTERY GARNISH AND ATTACHMENT PARTS	New	400.00	80.00
6	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	120.00	50.00
7	TO RNR REVERSE CAMERA AND TEST FUNCTION	New	120.00	0.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	120.00	20.00
10	TO DO WATER LEAK TEST	New	80.00	0.00
11	CONDUCT WHEEL ALIGNMENT	New	250.00	60.00
Gross Labour Cost (S\$)			7,990.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >