

ASS. REC. BY:

REF: CS/CT 19010673/ DSD/3/12

Special Instruction:

Surveyor: bryan

**ASSIGNMENT (Office)**

From (Person): ONG chin kiat

of CI

Date/Time: 17.6.19 14.39P M

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 72357

Insured: SGJ 223M

at Workshop m/s Chunni Motor

Tel: 6 5425119

of 10 AMK Industri Park 2A #03-19

Policy No: DMPCSN 30660718000

Claim No: SNM 1911 202760002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13.6.2019

CA / REV / REP. / REV 24 HRS

*"sup"*

H.O.D. Endorsement:

Date/Time: 17.6.19 2.55P M

Person Contacted: Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SHA 72357 - X	
	SGJ 223M - X	

REF:

ASSIGNMENT


COE 2023 Jan

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SHA7235T Yr Regn: Jan 2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai I40 C.C. 1685  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 691447 T/Radio: Insured / Std / NI / NA  
 Eng/No: D4FDEU449739  
 C/No: KMHLB41UMFU062715  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size: F: 205/60 R16  
 R: — — —  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Westlake  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 P/Bal. S mm R/Bal. S mm  
 L/Bal. S mm L/Bal. S mm  
 D.O.A. 13/06/2019 D.O.I. 18/06/2019  
 Survey held at Chunni AMC  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear O/S  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 86 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS \_\_\_\_\_  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT \_\_\_\_\_

Date / Time Action / Instruction  
China Taping 8GS 223M  
12/07/19 Invoice 1/5 10,300/- with 8 days of rev  
( \$ 1,615.10 Red - 39% )

RECEIVED 15 JUL 2019

Date/Time, File Pass to?  
15/07/19  
 1) Typ.st  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

: Preli. Report  
 : Final Report

Days Of Repair: 8  
 Resurvey No. of Trip: 2

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 10,300/- HS)

Survey Fee:

Transportation: \_\_\_\_\_  
 ) ...S + RS... \$  
 ) Photos \_\_\_\_\_  
 ) Others \_\_\_\_\_

220
TOTAL

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jun 2019		17 Jun 2019 14:39 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																																																																																																																										
<table border="1"> <thead> <tr> <th colspan="4">CLAIM SUBFOLDER DETAILS</th> <th>[Created by insurer]</th> </tr> </thead> <tbody> <tr> <td>Insured:</td> <td colspan="3">LIM CHEE HOU, ID: S73476081</td> <td></td> </tr> <tr> <td>Main Claimant:</td> <td colspan="3">COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R</td> <td></td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td>SHA7235T</td> <td>Date of Loss:</td> <td colspan="2">13/06/2019 23:00 - :59</td> </tr> <tr> <td>Claim Type:</td> <td>TP / SNM19D202760C02</td> <td>Policy/Cover Note No.:</td> <td colspan="2">DMPCSN30660718000 (Comprehensive)</td> </tr> <tr> <td>Vehicle Reg. No. (Insured):</td> <td>SGJ223M</td> <td>Policy No. (Claimant):</td> <td colspan="2">MCOM0015</td> </tr> <tr> <td></td> <td></td> <td>Excess:</td> <td colspan="2">S\$0.00</td> </tr> <tr> <td>Repairer:</td> <td colspan="4">Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="4">China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]</td> </tr> <tr> <td>Claimant's Insurer:</td> <td colspan="4">India International Insurance Pte Ltd (HQ) - Tel: 63476100</td> </tr> <tr> <td>Adjuster:</td> <td colspan="4">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/06/2019]</td> </tr> <tr> <td>Adj Asg. Remarks:</td> <td colspan="4">please assign Mr Henry Ng for SJE. thank you</td> </tr> <tr> <td colspan="4"></td> <td><a href="#">View All</a> <a href="#">Compose Case Mail</a></td> </tr> <tr> <td colspan="5"> <b>ASSOCIATED MAIL RECEIVED</b> </td> </tr> <tr> <td colspan="5">There are no mail for this case.</td> </tr> <tr> <td colspan="5"> <table border="1"> <thead> <tr> <th colspan="10">ALL ASSOCIATED TASKS</th> <th><a href="#">View All</a></th> <th><a href="#">Search Tasks</a></th> <th><a href="#">Create New Task</a></th> <th><a href="#">Complete</a></th> </tr> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> <th></th> <th></th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td colspan="14">No results.</td> </tr> </tbody> </table> </td> </tr> </tbody> </table>					CLAIM SUBFOLDER DETAILS				[Created by insurer]	Insured:	LIM CHEE HOU, ID: S73476081				Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R				Vehicle Reg. No.:	SHA7235T	Date of Loss:	13/06/2019 23:00 - :59		Claim Type:	TP / SNM19D202760C02	Policy/Cover Note No.:	DMPCSN30660718000 (Comprehensive)		Vehicle Reg. No. (Insured):	SGJ223M	Policy No. (Claimant):	MCOM0015				Excess:	S\$0.00		Repairer:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:				Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]				Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100				Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/06/2019]				Adj Asg. Remarks:	please assign Mr Henry Ng for SJE. thank you								<a href="#">View All</a> <a href="#">Compose Case Mail</a>	<b>ASSOCIATED MAIL RECEIVED</b>					There are no mail for this case.					<table border="1"> <thead> <tr> <th colspan="10">ALL ASSOCIATED TASKS</th> <th><a href="#">View All</a></th> <th><a href="#">Search Tasks</a></th> <th><a href="#">Create New Task</a></th> <th><a href="#">Complete</a></th> </tr> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> <th></th> <th></th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td colspan="14">No results.</td> </tr> </tbody> </table>					ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					No results.													
CLAIM SUBFOLDER DETAILS				[Created by insurer]																																																																																																																										
Insured:	LIM CHEE HOU, ID: S73476081																																																																																																																													
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R																																																																																																																													
Vehicle Reg. No.:	SHA7235T	Date of Loss:	13/06/2019 23:00 - :59																																																																																																																											
Claim Type:	TP / SNM19D202760C02	Policy/Cover Note No.:	DMPCSN30660718000 (Comprehensive)																																																																																																																											
Vehicle Reg. No. (Insured):	SGJ223M	Policy No. (Claimant):	MCOM0015																																																																																																																											
		Excess:	S\$0.00																																																																																																																											
Repairer:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:																																																																																																																													
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]																																																																																																																													
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100																																																																																																																													
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/06/2019]																																																																																																																													
Adj Asg. Remarks:	please assign Mr Henry Ng for SJE. thank you																																																																																																																													
				<a href="#">View All</a> <a href="#">Compose Case Mail</a>																																																																																																																										
<b>ASSOCIATED MAIL RECEIVED</b>																																																																																																																														
There are no mail for this case.																																																																																																																														
<table border="1"> <thead> <tr> <th colspan="10">ALL ASSOCIATED TASKS</th> <th><a href="#">View All</a></th> <th><a href="#">Search Tasks</a></th> <th><a href="#">Create New Task</a></th> <th><a href="#">Complete</a></th> </tr> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> <th></th> <th></th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td colspan="14">No results.</td> </tr> </tbody> </table>					ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					No results.																																																																																													
ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>																																																																																																																	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																																																																																																																					
No results.																																																																																																																														

MCDB1007/456 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 14/06/2019 10:54  
 SUBMITTED BY: Janet Lim Siang Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/06/2019 10:54
Date Of Accident	13/06/2019 23:20
Exact Location Of Accident	SHENTON WAY TWDS MCE NEARBY LAMPPOST 6
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7235T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	KANG MING THIAM
NRIC No	S1441638B
Date Of Birth	28/02/1960
Occupation	OUTDOOR
Date Of Driving Pass	03/07/1980
Driving Experience	38 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91186232
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 341 UBI AVENUE 1  
#10-915  
Postcode 400341  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
Weather Condillons CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1 NAME: : -  
GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: -  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SGJ223M  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver UNKNOWN  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name

Nature Of Damage

FRONT LH

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for Investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14.06.2019  
@ 10:30 hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**CHUNNI MOTOR WORK PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7235T

DATE : 14.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

*China Taipei*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>st</i>			\$ 2,174.90
	Boot Lid Lock Upper <i>NH</i>			\$ 102.60
	Boot Lid Lock Lower <i>NH</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>Nuc</i>			\$ 28.70
	Boot Lid CRDI Plate <i>Nuc</i>			\$ 27.90
	Boot Lid Lamp (RH) <i>crack</i>			\$ 565.60
	Boot Lid Trimboard <i>NH</i>			\$ 116.40
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00
	Bootlid Moulding <i>cut</i>			\$ 85.00
	Bootlid i40 Emblem <i>Nuc</i>			\$ 27.90
	Bootlid Lower Garnish <i>broken</i>			\$ 227.90
	Rear Bumper <i>broken</i>			\$ 553.00
	Rear Bumper Reinforcement <i>broken/crack</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>NH</i>	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>Nuc</i>			\$ 22.00
	Rear Bumper Bracket <i>broken</i>	\$	35.60	\$ 71.20
	Rear Bumper Sponge <i>trim</i>			\$ 118.40
	Rear Bumper Under Cover <i>distorted</i>			\$ 228.00
	Rear Bumper Reflector Lamp (RH) <i>broken</i>	\$	30.60	\$ 30.60
	Tail Lamp (RH) <i>crack</i>			\$ 697.80
	Rear Panel <i>Dented</i>			\$ 526.70
	Rear Panel Garnish <i>NH</i>			\$ 57.70
	Rear Panel Lower Panel <i>Dented</i>			\$ 495.50
	Spare Tyre Panel <i>Dented</i>			\$ 852.80
	Spare Tyre Panel Cushion <i>NH</i>			\$ 209.05
	Rear Towing Hook <i>NH</i>			\$ 94.60
	Member Assy- Rear Floor Centre <i>NH</i>			\$ 570.40
	Exhaust Pipe Insulator, RH <i>NH</i>			\$ 58.55
	Exhaust Silencer, RH <i>st</i>			\$ 967.70
	Exhaust Pipe Hanger, RH <i>NH</i>			\$ 58.55
	Exhaust Pipe Centre <i>NH</i>			\$ 730.10
	Rear Fender With Housing (RH) <i>Bnc</i>			\$ 4,736.80
	Rear Fender Inner Lining (RH) <i>NH</i>			\$ 169.30
	Rear Fender Air-Duct <i>NH</i>			\$ 51.60
	Rear Windscreen Moulding <i>Nuc</i>			\$ 28.30
			12895.10	
			10316.08	
	SUB TOTAL			\$ 15,317.25
	LESS 20%			\$ 3,063.45
	DISCOUNTED TOTAL			\$ 12,253.80

Handwritten checkmarks and 'X' marks in the right margin of the table.

SHA 7235T

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Comfort Logo & Tel No. Sticker <i>H/c</i>			\$ 30.00 <i>Nett ✓</i>
	Rear Bumper Reverse Sensor <i>D-w</i>			\$ 135.70 <i>Nett ✓</i>
	Rear Bumper Rubber Mat <i>slipment</i>			\$ 50.00 <i>Nett ✓</i>
	Rear Windscreen Sealant <i>H/c</i>			\$ 46.00 <i>Nett ✓</i>
			<i>261.70</i>	\$ 261.70
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>1,800.00</del> <i>1000/-</i>
	Spray Painting Charge			\$ <del>2,000.00</del> <i>800/-</i>
	Wiring Charge			\$ <del>50.00</del> <i>30/-</i>
	Tuff Kote			\$ <del>50.00</del> <i>40/-</i>
	Towing Charge			\$ 50.00 <i>42</i>
	Remove/Refix Cushion & Upholstery Rear			\$ <del>150.00</del> <i>80/-</i>
	Remove/Refix Rear Windscreen Glass			\$ <del>120.00</del> <i>80/-</i>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <i>40/-</i>
	Remove/Refix Exhaust Pipe			\$ <del>200.00</del> <i>60/-</i>
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 <i>42</i>
			<i>2130.00</i>	
	<b>TOTAL LABOUR</b>			\$ 4,020.00
	<b>ESTIMATE TOTAL</b>			\$ 16,535.50
				<i>16,915.10</i>
			<i>12707.78</i>	
			<i>supp 181.20</i>	
			<i>12888.98</i>	
			<i>1/10300/-</i>	

*18/06/2019 @ 1600hrs*  
*N/A Actual*  
*2/1/2019 8 days.*  
*Man*  
*JKK Auto*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**CHUNNI MOTOR WORK PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7235T (Supplementary)  
 MAKE :  
 MODEL : HYUNDAI i40

DATE : 19.06.2019  
 TEL : 6542 5119  
 FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Tail Lamp Quarter Panel (RH) <i>Paint</i>			S 226.50 ✓
	Rear Spare Tyre Bracket <i>HL</i>			S 248.00 X
	SUB TOTAL		<i>226.50</i>	S 474.50
	LESS 20%		<i>181.20</i>	S 94.90
	DISCOUNTED TOTAL			S 379.60
<p><i>Sign</i> <i>24/06/2019</i>  <i>2KK Auto</i></p> 				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119010673/DSD3N2

**Date:** 18/07/2019

#### REFERENCE

<b>Handling Insurer:</b> China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b> DMPCSN30660718000	
<b>Claimant Vehicle No :</b> SHA7235T	<b>Insured Vehicle No :</b> SGJ223M	
<b>Date of Loss:</b> 13/06/2019	<b>Nature of Claim:</b> TP	<b>Claim No:</b> SNM19D202760C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b> SHA7235T		
<b>Make &amp; Model:</b> HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	<b>Engine No:</b> D4FDEU449739	
<b>Reg. Date:</b> 15/01/2015 (Man. Year: 2014)	<b>Chassis No:</b> KMHLB41UMFU062715	
<b>Colour:</b> Blue	<b>Odometer:</b> 691447 km	
<b>Engine Capacity:</b> 1685 cc		
<b>Market Value/New Car Price:</b> N/A		
<b>Sum Insured (\$\$):</b> Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b> Yes	<b>Footbrake (Serviceable):</b> Yes
<b>Handbrake (Serviceable):</b> Yes	<b>Engine Modification:</b> No	<b>Pre-accident Condition:</b> Yes

#### CONDITION OF TYRES

<b>Front Tyre Size:</b> 205/60R16	<b>Rear Tyre Size:</b> 205/60R16
<b>Front Left Side:</b> West Lake 5 mm	<b>Rear Left Side:</b> West Lake 5 mm
<b>Front Right Side:</b> West Lake 5 mm	<b>Rear Right Side:</b> West Lake 5 mm

*The above values represent the remaining tyre treads depth.*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,895.10	10,758.98	2,136.12	16.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	2,130.00	1,890.00	47.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,915.10</b>	<b>12,888.98</b>	<b>4,026.12</b>	<b>23.80</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>10,300.00</b>		
	(\$\$)	16,915.10	10,300.00	6,615.10 39.11
	+ GST 7.00/7.00% (\$\$)	1,184.06	721.00	463.06 39.11
	<b>Nett Amount (\$\$)</b>	<b>18,099.16</b>	<b>11,021.00</b>	<b>7,078.16 39.11</b>

#### INSPECTION

<b>Date of Assignment:</b> 17/06/2019		
<b>Date Inspected:</b> 18/06/2019	<b>Inspected At:</b>	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047

**Estimated Period of Repair:** 8.0 days

**Adjuster:** BRYAN TANI

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA7235T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
2	1		*BOOT LID LOCK UPPER	Not Necessary	102.60 FL	*- FL
3	1		*BOOT LID LOCK LOWER	Not Necessary	31.70 FL	*- FL
4	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
5	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
6	1		*BOOT LID LAMP (RH)	Cracked	565.60 FL	*565.60 FL
7	1		*BOOT LID TRIMBOARD	Not Necessary	116.40 FL	*- FL
8	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
9	1		*BOOTLID MOULDING	Cut	85.00 FL	*85.00 FL
10	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
11	1		*BOOTLID LOWER GARNISH	Broken	227.90 FL	*227.90 FL
12	1		*REAR BUMPER	Broken	553.00 FL	*553.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Broken/Cracked	428.40 FL	*428.40 FL
14	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	160.60 FL	*- FL
15	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
16	2		*REAR BUMPER BRACKET	Broken	71.20 FL	*71.20 FL
17	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
18	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
19	1		*REAR BUMPER REFLECTOR LAMP (RH)	Broken	30.60 FL	*30.60 FL
20	1		*TAIL LAMP (RH)	Cracked	697.80 FL	*697.80 FL
21	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
22	1		*REAR PANEL GARNISH	Not Necessary	57.70 FL	*- FL
23	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
24	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
25	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
26	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
27	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
28	1		*EXHAUST PIPE INSULATOR,RH	Not Necessary	58.55 FL	*- FL
29	1		*EXHAUST SILENCER,RH	Bent	967.70 FL	*967.70 FL
30	1		*EXHAUST PIPE HANGER,RH	Not Necessary	58.55 FL	*- FL
31	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
32	1		*REAR FENDER WITH HOUSING (RH)	Buckled	4,736.80 FL	*4,736.80 FL
33	1		*REAR FENDER INNER LINING (RH)	Not Necessary	169.30 FL	*- FL
34	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
35	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
36	1		*TAIL LAMP QUARTER PANEL (RH)	Dented	226.50 FL	*226.50 FL
37	1		*REAR SPARE TYRE BRACKET	Not Necessary	248.00 FL	*- FL
38	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
39	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
40	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,000.00	800.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX EXHAUST PIPE	New	200.00	60.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,020.00</b>	<b>2,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >