

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7235T (Supplementary)

DATE : 19.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Tail Lamp Quarter Panel (RH) <i>Dental</i>			\$ 226.50 ✓
	Rear Spare Tyre Bracket <i>HL</i>			\$ 248.00 X
	SUB TOTAL		<i>226.50</i>	\$ 474.50
	LESS 20%		<i>181.20</i>	\$ 94.90
	DISCOUNTED TOTAL			\$ 379.60
	<p><i>[Signature]</i> 24/06/2019</p> <p><i>2 KK And</i></p> <p><i>[Signature]</i></p>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.