

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

14th JUNE 2019

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

JTDZS3E480J039699.

Accident date: 07th June 2019
Estimated repair cost for vehicle no: SMK8147X Toyota PRIUS '19

S/n	Qty	Items	U/price	Amount
				\$1,150.00 X
1	1	Front bonnet <i>Repis</i>		\$127.50 X
2	1	Front bonnet lock		\$145.10 X
3	1	bonnet inner rubber		\$114.00 X
4	1	Front bonnet lock cable		\$55.00 X
5	1	Front bonnet emble logo		\$289.40 X
6	1	Front windscreen moulding		\$236.50 X
7	1	Front windscreen rubber		\$30.00 X
8	1	Front windscreen ERP sticker		\$3,770.00 ✓
9	2	Front head lamp <i>cracked</i>	\$1,885.00	\$235.00 X
10	1	Front bumper top centre moulding <i>Neu</i>		\$1,050.00 ✓ 781
11	1	Front bumper <i>Distorted</i>		\$242.00 ✓
12	2	Front bumper side bracket <i>Damaged</i>	\$121.00	\$30.00 ✓
13	1	Front bumper clips <i>New</i>		\$650.00 X
14	2	Front bumper fog lamp <i>Neu</i>	\$325.00	\$155.00 ✓
15	1	Front bumper fog lamp cover <i>Neu</i>		\$635.00 ✓
16	1	Front bumper reinforcement <i>Bent.</i>		\$285.00 ✓
17	1	Front lower bumper grille <i>Distorted</i>		\$420.00 X
18	1	Front grille <i>Neu</i>		\$50.00 X
19	1	Front grille clips <i>New</i>		\$763.10 ✓
20	1	Front support panel <i>Distorted</i>		\$180.00 X
21	1	Front support panel top cover <i>Neu</i>		\$1,120.00 ✓
22	1	air cond condenser <i>Distorted</i>		\$761.00 ✓
23	1	radiator fan motor assy <i>cracked</i>		\$1,017.00 ✓
24	1	Front radiator <i>Distorted</i>		\$11,800.00 ✓ 4200 (SN)
25	1	front hybrid DC inverter ASSY converter <i>cracked</i>		\$950.00 X
26	1	wiring harness -complete set <i>Neu</i>		\$180.00 X
27	1	Front engine mounting - RH <i>Neu</i>		

28	1	Front engine mounting - LH	torn		\$185.00	✓
29	1	Front engine mounting - Front	torn		\$155.00	✓
30	1	Front engine mounting - Rear	new		\$145.00	+
31	1	Front wheel housing -LH	Rep		\$750.00	+
32	1	Front chassis -LH	Rep		\$880.00	+
33	1	Front horn	new		\$161.75	x
34	1	Front wiper tank	new		\$121.10	+
35	1	Front wiper tank motor	new		\$131.75	+
36	2	Front Fender	Distorted	\$752.20	\$1,504.40	✓
37	2	front fender inner garnish	torn	\$127.20	\$254.40	✓
38	8	front fender inner garnish clips	new	\$12.90	\$103.20	60
39	2	Front Lower Arm	LH Best	\$287.72	\$575.44	287.72
40	2	Front Knuckle Arm	LH Best	\$281.85	\$563.70	281.85
41	2	Front Knuckle Arm Bearing	LH Best	\$161.40	\$322.80	161.40
42	2	Front Shock Absorber	LH Best	\$485.00	\$970.00	485
43	2	front sport rim	LH ut		\$800.00	400
44	2	front tyre	new		\$600.00	x
45	1	front L/H door	Dented		\$1,071.50	✓
46	1	Front L/H Door Side Mirror	new		\$421.10	+
47	1	front LH door inner rubber	new		\$155.20	+
48	1	front LH door handle -outer	new		\$158.20	+
49	1	Front L/H Door top Molding	new		\$123.05	+
50	1	Front L/H door inner lock	new		\$289.90	+
51	1	Front L/H door inner trim board	new		\$472.20	+
52	1	Front L/H Door Inner Gear Motor Assy	new		\$425.20	+
53	1	Rear tail lamp -RH	new		\$640.10	+
54	2	Rear tail lamp clips	new	\$8.50	\$17.00	+
55	1	Rear tail lamp panel	new		\$285.00	+
56	1	Rear Bumper	Deformed		\$1,077.00	524
57	1	Rear Bumper side reflector	new		\$68.10	+
58	2	Rear Bumper Side Bracket	RH Best	\$55.60	\$111.20	55.60
59	1	Rear Bumper reverse sensor	new		\$350.00	+
60	2	Rear Bumper Bracket	new	\$68.40	\$136.80	+
61	8	Rear bumper clips	new	\$6.50	\$52.00	30
62	1	Rear R/H Fender	Rep		\$972.40	+
63	1	Rear fender inner trim board-RH	new		\$552.10	+
64	1	Rear R/H Shock Absorber	new		\$221.90	x
65	1	Rear R/H Bearing	new		\$591.60	x
66	10	Rear Rim-RH	new		\$450.00	x
67	1	Rear tyre -RH	new		\$300.00	x
68	1	rear R/H Lower Arm	new		\$287.72	x
69	1	rear R/H Knuckle Arm	new		\$281.85	x

Subtotal :- \$44,175.26

15014.67.

S.N: 4200

11261.00.

labour charges

To Remove & refix front air-cond condenser, Radiator fan motor & top up gas	\$250.00 120
To Check Wiring System	\$80.00 30
Diagnostic & computer reset	\$400.00 200
Tuff Kote	\$120.00 60
To Remove & refix cushion	\$150.00 40
to remove & Refix front & rear undercarriage	\$450.00 ✓
to Remove & install front chassis & cross member	\$380.00 150
Remove & refix front RH / LH engine & gear box mounting	\$300.00 200
WHeel alignment (computer)	\$150.00 80
To Remove & refix ^{centre} rear exhaust	200 120
To Remove & refix front windscreen	\$120.00 ✗
Gum	\$50.00 ✗
To Remove & refix reverse Sensor	5220. \$100.00 50
Towing charges	\$100.00 120
Panel beating	\$2,200.00 2000
Spray painting	\$2,200.00 1600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$7,050.00
Total:- \$51,225.26

Supplementary: 9988.02
Total: 30669.02
L/S: 2451c.
28 Days.

SMK 8147X Supplementary

Front Bumper Undercovers	torn	280.20	✓
Front Bumper Undercovers Clips	new	30	✓
Front Bumper Sparege	could	174.50	✓
Front Bumper Day Running Lamp LH.	new	972.80	✗
Front Fender Emblem x 02	new	121.2 x 2 = 242.40	✓
Engine Undercovers	Distorted	304.90	✓
Engine Undercover Clips	new	30	✓
Floor Panel Undercover x 02	torn	128.4 x 2 = 256.80	✓
Floor Panel Undercover Clips	new	50	✓
Steering Cross Member	Distorted	2485	✓
Steering Cross Member Bracket x 02	Best	95 x 2 = 190	✓
Engine Cross member	Distorted	1058.70	✓
Fuel Tank	cut	1159.40	✓
Fuel Tank Heat Shield	crushed	78.40	✓
Rear Cross member	Best	2151.40	✓
Rear LH wheel Hub	new	453.20	+
Rear Cross Rod	Best	159.60	✓
Front Anti Roll Bar	Best	348.80	✓
Front Anti Roll Bar Linkage x 02	LH Best	195 x 2 = 390	✓
		195	

Centre Exhaust Pipe. Bented 3804.30 ✓
 Centre Exhaust Heat Shield. Coped 95.90 ✓
 Air Con Condenser Air Guide x02 ^{LIA} Bented $35.4 \times 2 = 70.80$ ✓
 Oil Cooler ^{x1} _m 285.90 ✓
 Front Spare Rim Cover x02 ^{LH Missing} _{RH at} $70 \times 2 = 140$ (SN) ✓

13130.70 S.N: 140

9848.02.

Supplementary: 9988.02