

INS. CASE OWNER: OHAN KIAN HONG CC 3 / AG 190 10682 / Kha3<sup>SE</sup>

LKK:  
IDAC:

Surveyor: Kenneth DOI: 14/06/2019

Date / Time: 14/06/2019  
Registered in Merimen: 17/06/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : GBH 64159  
Name of Insured : Topgrid Pest Specialist PTE LTD  
Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A. : 13/06/2019  
Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_

Claim No. : 37119215379G  
Policy No. : \_\_\_\_\_  
Make / Model : \_\_\_\_\_  
Place of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_  
Driver Tel No. : \_\_\_\_\_ (V/L: YES NO)  
OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO  
Insured Liability : \_\_\_\_\_ % Final ? Yes / No

SHC 5991X




INSRS: Trans-cab  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/Time	STAGE	DATE / PIC
26/6/19	- BUS RECOVERED. OLD CHANGED CARS. with sent to OI	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final):
24/07/19	- OI CALLED IN. REQUESTED TP LAUNDRY LETTER. ADVISED TO LET AIG SETTLE 4 AWAITE DCB ISSUES. - FINALTERED. - ORIGINAL TP LOD IN	Notification Itr (if non-pickup): Call OI: <u>24/07/19 - HT</u> After call Itr to OI: <u>26/06/19 - JUMIN - DC</u>
15/08/19	- TP ACCEPTED OFFER. - ALL DOCS IN ORDER. - TO CLOSE.	Documentation Check List: Handler Typist Notification Itr (if non-pickup) After call Itr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD Payment Breakdown Form: Post-Repair Photos: Others:

RELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time: <u>15/08/19</u>	Confirm with: <u>WAI YIN</u>	Confirm by: _____	Email <input type="checkbox"/> Call <input type="checkbox"/>
Repair Cost:	<u>US \$ 3,250.00</u>	(3 days) Reduction: <u>91 %</u>		
FINAL SETTLEMENT	Date/Time: <u>15/08/19</u>	Confirm with: <u>WAI YIN</u>	Confirm by: _____	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u> (Agreed / Assessed)	BOLA S/N No. : <u>15</u>	If NO or B 28, Ass. Lia : <u>(OLD CHANGED CARS)</u>	
Repair Cost: (w/gst)	<u>\$ 3,177.50</u>			
Loss of Rental (LOR):	<u>\$ 290.97</u> (3 days) X <u>\$ 96.99</u>			
Loss of Use (LOU):	<u>\$ -</u> (\$ x days)			
Loss of Income (LOI):	<u>\$ -</u> (\$ x days)			
OR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
IA/LTA Search	<u>\$ 7.49</u>			
Medical:	<u>\$ -</u>			
Disbursement:	<u>\$ -</u> (e.g. Tow/Independent)			
Legal Cost	<u>\$ -</u>			
Total:	<u>\$ 3,775.96</u>	Global Sum <u>\$ 3,730.00</u>		
FINAL PAYMENT	Date/Time:	Confirm with:	Confirm by:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Fee 1:	<u>\$ 3,730.00</u>	Name 1: <u>TRANS-CAB AUTO SERVICES PTE LTD</u>		
Fee 2: (Strike if N.A.)	<u>\$ -</u>	Name 2: _____		
Fee 3: (Strike if N.A.)	<u>\$ -</u>	Name 3: _____		



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5991X**

AAD1906-127

*Not Authorized  
U/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHC 5991X**

VF1ABL15AUC280996

RENAULT

LATITUDE

13.6.19

**AIG**

18/12/2014

	<b>PART</b>		<b>LIST</b>
1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>Sh</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sh</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sh</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>Sh</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Sh</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Sh</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sh</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>Sh</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>Sh</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sh</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sh</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>Sh</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>Sh</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>Sh</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>Sh</i> 6.91
1	DOOR CASING REAR RH	\$	<i>Sh</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>Sh</i> 30.39
1	DOOR CASING CLIP	\$	<i>Sh</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Sh</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>Sh</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>Sh</i> 210.96

*X*

**Trans-cab Auto Services Pte Ltd**

**AAD1906-127**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5991X**

1	DOOR BLIND REAR RH	\$	Sm	741.80	}
1	DOOR WHEATHESTRIIP REAR RH	\$	Sm	410.66	
1	DOOR SEAL REAR RH	\$	Sm	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Sm	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	Sm	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	Sm	115.64	
1	DOOR PANEL FRT RH	\$	Bu	2,844.66	✓
1	DOOR HINGE UPPER RH	\$	N	261.28	✓
1	DOOR HINGE LOWER RH	\$	N	300.55	✓
1	DOOR CHECK FRT RH	\$	Sm	194.77	✓
1	DOOR LOCK FRT RH	\$	N	908.75	✓
1	DOOR CATCH FRT RH	\$	N	131.23	✓
1	DOOR HANDLE OUTER FRT RH	\$	Bu	477.76	✓
1	DOOR HANDLE COVER FRT RH	\$	M17	13.22	✓
1	DOOR HANDLE MODULE FRT RH	\$	Sm	133.60	}
1	DOOR REGULATOR FRT RH	\$	Sm	505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	Sm	796.46	
1	DOOR REGULATOR GUIDE FRT RH	\$	Sm	120.97	
1	DOOR WHEATHESTRIIP FRONT RH	\$	Sm	410.66	
1	DOOR MOULDING FRONT RH	\$	Sm	176.82	
1	DOOR FINISHER INNER FRONT RH	\$	Sm	323.44	
1	DOOR FINISHER FRONT RH	\$	Sm	423.10	
1	DOOR CASING FRONT RH	\$	Sm	1,509.06	
1	DOOR BLIND FRONT RH	\$	Sm	741.80	
1	DOOR SEAL FRONT RH	\$	Sm	162.02	
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	Sm	229.31	
1	DOOR WAIST SEAL OUTER FRONT RH	\$	Sm	334.69	
1	DOOR WAIST SEAL INNER FRONT RH	\$	Sm	115.64	
1	DOOR GRAB HANDLE FRONT RH	\$	Sm	210.96	
1	ROCKER PANEL INNER GARNISH RH	\$	Sm	466.51	
1	ROCKER PANEL INNER RH	\$	N	1,024.79	
1	ROCKER PANEL OUTER RH	\$	N	1,184.99	
1	ROCKER PANEL CENTER RH	\$	N	990.25	
1	DOOR MIRROR ASSY RH	\$	Sm	1,483.40	
1	DOOR MIRROR GLASS RH	\$	Sm	148.20	
1	DOOR MIRROR BACK COVER RH	\$	Sm	218.46	
1	DOOR HARNESS WIRE RH	\$	Sm	2,670.00	
1	BOOT REFLECTOR LAMP RH	\$	Sm	493.35	

**Trans-cab Auto Services Pte Ltd**

AAD1906-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5991X**

1	FENDER PANEL REAR RH	\$	3,299.13	}	X
1	FENDER PANEL INNER TRIM REAR RH	\$	671.45		
1	WHEELARCH REAR RH	\$	543.47		
1	BUMPER COVER REAR	\$	1,108.46		
1	BUMPER LOWER REAR	\$	768.84		
1	BUMPER BRACKET CTR REAR	\$	113.47		
1	BUMPER BRACKET SIDE RH REAR	\$	135.97		
1	BUMPER RETAINER RH REAR	\$	44.99		
1	BUMPER REFLECTOR RH	\$	43.61		
1	BUMPER BEAM REAR	\$	777.52		
1	BUMPER BEAM BRACKET RH REAR	\$	225.95		
1	TAILLAMP RH	\$	552.55		
1	TAILLAMP PANEL RH	\$	986.70		
1	EXHAUST REAR	\$	7,489.05		
1	EXHAUST CAP REAR	\$	230.49		
<b>TOTAL</b>		<b>\$</b>	<b>48,920.24</b>		
	<b>10%</b>	<b>\$</b>	<b>4,892.02</b>		
		<b>\$</b>	<b>44,028.22</b>		

**Special Nett**

1	REAR DOOR STICKER '6555-3333'	\$	300.00	base	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00	base	
1	FRONT DOOR STICKER 'Classic'	\$	80.00	15%	
1	DOOR CHECK BOLT	\$	22.69	}	X
1	DOOR GUIDE SCREW	\$	10.85		
1	DOOR HINGE BOLT	\$	10.85		
1	DOOR HINGE NUT RH	\$	14.60		
1	DOOR CHECK BOLT	\$	22.69		
1	DOOR CHECK NUT	\$	3.75		
1	DOOR LOCK SCREW L70Y	\$	6.12		
1	DOOR CATCH SCREW L70Y	\$	10.06		
1	FENDER INNER TRIM CLIP RH	\$	28.00		
1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00		
2	REAR WINDSCREEN SEALANT	\$	80.00		
1	WINDSCREEN MOULDING	\$	100.00		
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00		
1	REAR RIGHT TYRE	\$	300.00		
1	REAR RIGHT TYRE RIM	\$	380.00		

**Trans-cab Auto Services Pte Ltd**

AAD1906-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5991X**

1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	}	<i>X</i>
1SET	PARKING AID	\$	<i>sh</i> 700.00		
1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00		
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00		
1SET	BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00		
1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00		
1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00		
1	FRONT RIGHT TYRE	\$	<i>sh</i> 300.00		
1	FRONT RIGHT TYRE RIM	\$	<i>sh</i> 380.00		
<b>TOTAL</b>		<b>\$</b>	<b>3,186.63</b>		

**TOTAL PARTS \$ 47,214.85**

**LABOUR**

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>4000</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>4400</i>
To rust-proofing of the affected areas.	\$	170.00	<i>300</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00	<i>600</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd**

**AAD1906-127**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5991X**

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To repair and realign rear exhaust pipe.	\$	~ 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>2d</i>
To reinstall rear bumper parking sensor.	\$	~ 170.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	~ 380.00 X
<b>TOTAL</b>	<b>\$</b>	<b>16,070.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>63,284.85</b>

**LUMP SUM (REPAIR DAY)**

*20 DAYS*  
*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

#### Vehicle Details

Vehicle No.:	SHC5991X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002434
Chassis No.:	VF1ABL15AUC280996
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

#### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00

#### Intended COE Rebate Details

COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$22,674.00
<b>Total Rebate Amount:</b>	<b>\$32,047.00</b>

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Jun 2019

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jun 2019 <a href="#">Edit Reg</a>		14 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>TOPGRID PEST SPECIALIST PTE LTD</b> , Co. Reg. No.: A200510485H								
Main Claimant:	<b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	<b>SHC5991X</b>	Date of Loss:	13/06/2019 00:00 - :59 [53 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 3711921537SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBH6415G</b>	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	<b>Trans-cab Auto Services Pte Ltd ( )</b> No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 26/06/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (18/06/2019): Request To Upload TP GIA Report									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SHC5991X (3711921537SG)  
[GBH6415G]**

TP

**TRANS-CAB SERVICES PTE LTD  
Jun 13 2019 12:00AM  
[TOPGRID PEST SPECIALIST PTE LTD]  
Trans-cab Auto Services Pte Ltd**

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/> <input type="button" value="Upload Video"/> <input type="button" value="Upload Audio"/>			<b>View</b> <input type="button" value="View in Browser"/>
<b>Letters/Correspondences</b>			1 per page <input type="button" value="✓"/>
No:	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	(Draft)	<b>Third Party Express Settlement – Payment Breakdown</b>	<input type="button" value="1"/> <input type="button" value="Edit"/>
<b>Photos/Images</b>			3 per page <input type="button" value="✓"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	30/07/19 10:01	<b>Odometer Reading</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
2	30/07/19 10:01	<b>Chassis Number</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
3	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
4	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
5	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
6	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
7	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
8	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
9	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
10	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
11	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
12	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
13	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
14	30/07/19 10:01	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
<b>Documentation</b>			1 per page <input type="button" value="✓"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	21/06/19 10:31	<b>TP ESTIMATE - MARKED</b>	<input type="button" value="1"/> Load PDF
2	21/06/19 10:31	<b>TP GIA REPORT</b>	<input type="button" value="1"/> Load PDF
3	26/06/19 15:44	<b>Letter to OI</b>	<input type="button" value="1"/> Load PDF
4	27/09/19 10:43	<b>AUTHORISATION TO ACT</b>	<input type="button" value="1"/> Load PDF
5	27/09/19 10:43	<b>LOD</b>	<input type="button" value="1"/> Load PDF
6	27/09/19 10:43	<b>LTA SEARCH</b>	<input type="button" value="1"/> Load PDF
7	27/09/19 10:43	<b>RELEASE VOUCHER</b>	<input type="button" value="1"/> Load PDF
8	27/09/19 10:43	<b>RENTAL MILEAGE</b>	<input type="button" value="1"/> Load PDF
9	27/09/19 10:43	<b>RENTAL RECEIPT</b>	<input type="button" value="1"/> Load PDF
10	27/09/19 10:43	<b>WORKSHOP INVOICE</b>	<input type="button" value="1"/> Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	<b>Thumbnail</b> <b>Print</b>
1	18/06/19 10:17	<b>OI GIA REPORT</b>	<input type="button" value="1"/> Load PDF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	GBH6415G (Insd veh)	<b>Model:</b>	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A)
	SHC5991X (TP veh)		
<b>Date of Accident:</b>	13/06/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$		67,714.77
Final Repair Cost	: \$		3,730.00
Loss of Use	: \$		_____ days at \$0.00 per day
Rental (if any)	: \$		3 days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$		3,730.00
<b>Is Third Party Workshop GIA Registered?</b>		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO (Kindly indicate below)
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability _____ 100 _____ (%)	
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
		BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)	
		* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	_____		

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	: \$	3,730.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

27 Sep  
2019

\_\_\_\_\_  
Date

**Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/  
Bill (if any)**

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19010682/KHA3S2  
**Date:** 27/09/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SHC5991X **Insured Vehicle No :** GBH6415G  
Date of Loss: 13/06/2019 Nature of Claim: TP Claim No: 3711921537SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5991X**  
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C002434  
Reg. Date: 18/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC280996  
Colour: Metallic White/Red Odometer: 557148 km  
Engine Capacity: 1995 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Giti 8 mm Rear Left Side: Giti 8 mm  
Front Right Side: Giti 8 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,214.83	3,137.08	44,077.75	93.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,070.00	950.00	15,120.00	94.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>63,284.83</b>	<b>4,087.08</b>	<b>59,197.75</b>	<b>93.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
(S\$)	63,284.83	3,250.00	60,034.83	94.86
<b>+ GST 7.00/7.00% (S\$)</b>	4,429.94	227.50	4,202.44	94.86
<b>Nett Amount (S\$)</b>	<b>67,714.77</b>	<b>3,477.50</b>	<b>64,237.27</b>	<b>94.86</b>
<b>+ Car Rental (3.0 x S\$96.99/day) (S\$)</b>		290.97		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>3,775.96</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,730.00</b>		

### INSPECTION

Date of Assignment: 14/06/2019  
Date Inspected: 14/06/2019 Inspected At: Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111  
Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*-FL
2	1		*DOOR GUIDE REAR RH	Serviceable	176.82 FL	*-FL
3	1		*DOOR HINGE UPPER RH	Repair	274.50 FL	*-FL
4	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*-FL
5	1		*DOOR CHECK REAR LH/RH L70Y	Serviceable	203.06 FL	*-FL
6	1		*DOOR LOCK REAR RH	Repair	908.75 FL	*-FL
7	1		*DOOR HANDLE OUTER REAR RH	Serviceable	126.49 FL	*-FL
8	1		*DOOR HANDLE CAP REAR RH	Serviceable	35.52 FL	*-FL
9	1		*DOOR HANDLE SEAL REAR RH	Serviceable	7.89 FL	*-FL
10	1		*DOOR HANDLE COVER REAR RH	Serviceable	13.22 FL	*-FL
11	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.60 FL	*-FL
12	1		*DOOR REGULATOR REAR RH	Serviceable	1,135.10 FL	*-FL
13	1		*DOOR REGULATOR MOTOR REAR RH	Serviceable	893.75 FL	*-FL
14	1		*DOOR REGULATOR NUT REAR L70Y	Serviceable	12.43 FL	*-FL
15	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*-FL
16	1		*DOOR FINISHER REAR RH	Serviceable	423.10 FL	*-FL
17	1		*DOOR MOULDING REAR RH	Serviceable	176.82 FL	*-FL
18	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*-FL
19	1		*DOOR MOULDING SCREW L70Y	Serviceable	6.91 FL	*-FL
20	1		*DOOR CASING REAR RH	Serviceable	1,509.06 FL	*-FL
21	1		*DOOR WATER SHIELD REAR RH	Serviceable	30.39 FL	*-FL
22	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*-FL
23	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*-FL
24	1		*DOOR FINISHER INNER REAR RH	Serviceable	323.44 FL	*-FL
25	1		*DOOR FINISHER BRACKET INNER REAR RH	Repair	46.97 FL	*-FL
26	1		*DOOR FINISHER BRACKET INNER REAR RH	Repair	20.33 FL	*-FL
27	1		*DOOR FINISHER BRACKET INNER REAR RH	Repair	20.33 FL	*-FL
28	1		*DOOR FINISHER BRACKET INNER REAR RH	Repair	20.33 FL	*-FL
29	1		*DOOR GRAB HANDLE REAR RH	Serviceable	210.96 FL	*-FL
30	1		*DOOR BLIND REAR RH	Serviceable	741.80 FL	*-FL
31	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	410.66 FL	*-FL
32	1		*DOOR SEAL REAR RH	Serviceable	162.02 FL	*-FL
33	1		*DOOR GLASS RUNNER SEAL REAR RH	Serviceable	229.31 FL	*-FL
34	1		*DOOR WAIST SEAL OUTER REAR RH	Serviceable	334.69 FL	*-FL
35	1		*DOOR WAIST SEAL INNER REAR RH	Serviceable	115.64 FL	*-FL
36	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
37	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*-FL
38	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*-FL
39	1		*DOOR CHECK FRT RH	Serviceable	194.77 FL	*-FL
40	1		*DOOR LOCK FRT RH	Repair	908.75 FL	*-FL
41	1		*DOOR CATCH FRT RH	Repair	131.23 FL	*-FL
42	1		*DOOR HANDLE OUTER FRT RH	Broken	477.76 FL	*477.76 FL
43	1		*DOOR HANDLE COVER FRT RH	Missing	13.22 FL	*13.22 FL
44	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*-FL
45	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	*-FL
46	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*-FL
47	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*-FL
48	1		*DOOR WEATHERSTRIP FRONT RH	Serviceable	410.66 FL	*-FL
49	1		*DOOR MOULDING FRONT RH	Serviceable	176.82 FL	*-FL
50	1		*DOOR FINISHER INNER FRONT RH	Serviceable	323.44 FL	*-FL
51	1		*DOOR FINISHER FRONT RH	Serviceable	423.10 FL	*-FL
52	1		*DOOR CASING FRONT RH	Serviceable	1,509.06 FL	*-FL
53	1		*DOOR BLIND FRONT RH	Serviceable	741.80 FL	*-FL
54	1		*DOOR SEAL FRONT RH	Serviceable	162.02 FL	*-FL
55	1		*DOOR GLASS RUNNER SEAL FRONT RH	Serviceable	229.31 FL	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*DOOR WAIST SEAL OUTER FRONT RH	Serviceable	334.69 FL	*- FL
57	1		*DOOR WAIST SEAL INNER FRONT RH	Serviceable	115.64 FL	*- FL
58	1		*DOOR GRAB HANDLE FRONT RH	Serviceable	210.96 FL	*- FL
59	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
60	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
61	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
62	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
63	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
64	1		*DOOR MIRROR GLASS RH	Serviceable	148.20 FL	*- FL
65	1		*DOOR MIRROR BACK COVER RH	Serviceable	218.46 FL	*- FL
66	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	*- FL
67	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
68	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
69	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
70	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
71	1		*BUMPER COVER REAR	Serviceable	1,108.46 FL	*- FL
72	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
73	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
74	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
75	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
76	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
77	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
78	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
79	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
80	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
81	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
82	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
83	1		*REAR DOOR STICKER 6555-3333	Necessary	300.00 FS	*60.00 FS
84	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
85	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
86	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
87	1		*DOOR GUIDE SCREW	Serviceable	10.85 FS	*- FS
88	1		*DOOR HINGE BOLT	Serviceable	10.85 FS	*- FS
89	1		*DOOR HINGE NUT RH	Serviceable	14.60 FS	*- FS
90	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
91	1		*DOOR CHECK NUT	Serviceable	3.75 FS	*- FS
92	1		*DOOR LOCK SCREW L170Y	Serviceable	6.12 FS	*- FS
93	1		*DOOR CATCH SCREW L170Y	Serviceable	10.06 FS	*- FS
94	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
95	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
96	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
97	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
98	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
99	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
100	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
101	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
102	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
103	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
104	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
105	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
106	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
107	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
108	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
109	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
110	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>52,106.85</b>	<b>3,470.64</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>4,892.02</b>	<b>333.56</b>
<b>Total Parts (\$\$)</b>	<b>47,214.83</b>	<b>3,137.08</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	6,000.00	400.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	440.00
5	TO RUST-PROOFING OF THE AFFECTED PORTION.	New	170.00	30.00
6	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
7	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
8	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
9	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
11	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
12	TO DROP REAR EXHAUST PIPE, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
13	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
14	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
16	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	0.00
17	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>16,070.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >