

Trans-cab Auto Services Pte Ltd

AAD1906-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X*Not Authorized
U/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5991X

VF1ABL15AUC280996

RENAULT

LATITUDE

13.6.19

AIG

18/12/2014

	PART		LIST
1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>Lu</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Lu</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Lu</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>Lu</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Lu</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Lu</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Lu</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>Lu</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>Lu</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Lu</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Lu</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>Lu</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>Lu</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>Lu</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>Lu</i> 6.91
1	DOOR CASING REAR RH	\$	<i>Lu</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>Lu</i> 30.39
1	DOOR CASING CLIP	\$	<i>Lu</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Lu</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>Lu</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>N</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>Lu</i> 210.96

X

Trans-cab Auto Services Pte Ltd

AAD1906-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

1	DOOR BLIND REAR RH	\$	Sm	741.80	}
1	DOOR WHEATHESTRIIP REAR RH	\$	Sm	410.66	
1	DOOR SEAL REAR RH	\$	Sm	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Sm	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	Sm	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	Sm	115.64	}
1	DOOR PANEL FRT RH	\$	Bu	2,844.66	
1	DOOR HINGE UPPER RH	\$	N	261.28	X
1	DOOR HINGE LOWER RH	\$	N	300.55	X
1	DOOR CHECK FRT RH	\$	Sm	194.77	X
1	DOOR LOCK FRT RH	\$	N	908.75	X
1	DOOR CATCH FRT RH	\$	N	131.23	X
1	DOOR HANDLE OUTER FRT RH	\$	Bu	477.76	✓
1	DOOR HANDLE COVER FRT RH	\$	Mir	13.22	✓
1	DOOR HANDLE MODULE FRT RH	\$	Sm	133.60	}
1	DOOR REGULATOR FRT RH	\$	Sm	505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	Sm	796.46	
1	DOOR REGULATOR GUIDE FRT RH	\$	Sm	120.97	
1	DOOR WHEATHESTRIIP FRONT RH	\$	Sm	410.66	
1	DOOR MOULDING FRONT RH	\$	Sm	176.82	
1	DOOR FINISHER INNER FRONT RH	\$	Sm	323.44	
1	DOOR FINISHER FRONT RH	\$	Sm	423.10	
1	DOOR CASING FRONT RH	\$	Sm	1,509.06	
1	DOOR BLIND FRONT RH	\$	Sm	741.80	
1	DOOR SEAL FRONT RH	\$	Sm	162.02	
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	Sm	229.31	
1	DOOR WAIST SEAL OUTER FRONT RH	\$	Sm	334.69	
1	DOOR WAIST SEAL INNER FRONT RH	\$	Sm	115.64	
1	DOOR GRAB HANDLE FRONT RH	\$	Sm	210.96	
1	ROCKER PANEL INNER GARNISH RH	\$	Sm	466.51	
1	ROCKER PANEL INNER RH	\$	N	1,024.79	
1	ROCKER PANEL OUTER RH	\$	N	1,184.99	
1	ROCKER PANEL CENTER RH	\$	N	990.25	
1	DOOR MIRROR ASSY RH	\$	Sm	1,483.40	
1	DOOR MIRROR GLASS RH	\$	Sm	148.20	
1	DOOR MIRROR BACK COVER RH	\$	Sm	218.46	
1	DOOR HARNESS WIRE RH	\$	Sm	2,670.00	
1	BOOT REFLECTOR LAMP RH	\$	Sm	493.35	

Trans-cab Auto Services Pte Ltd

AAD1906-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

1	FENDER PANEL REAR RH	\$	4	3,299.13	}
1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	
1	WHEELARCH REAR RH	\$	Sm	543.47	
1	BUMPER COVER REAR	\$	Sm	1,108.46	
1	BUMPER LOWER REAR	\$	Sm	768.84	
1	BUMPER BRACKET CTR REAR	\$	Sm	113.47	
1	BUMPER BRACKET SIDE RH REAR	\$	Sm	135.97	
1	BUMPER RETAINER RH REAR	\$	Sm	44.99	
1	BUMPER REFLECTOR RH	\$	Sm	43.61	
1	BUMPER BEAM REAR	\$	N	777.52	
1	BUMPER BEAM BRACKET RH REAR	\$	N	225.95	
1	TAILLAMP RH	\$	Sm	552.55	
1	TAILLAMP PANEL RH	\$	N	986.70	
1	EXHAUST REAR	\$	N	7,489.05	
1	EXHAUST CAP REAR	\$	N	230.49	
TOTAL		\$		48,920.24	
10%		\$		4,892.02	
		\$		44,028.22	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	N	300.00	base
1	FRONT DOOR STICKER 'Trans-Cab'	\$	N	80.00	base
1	FRONT DOOR STICKER 'Classic'	\$	N	80.00	15sm
1	DOOR CHECK BOLT	\$	Sm	22.69	}
1	DOOR GUIDE SCREW	\$	Sm	10.85	
1	DOOR HINGE BOLT	\$	Sm	10.85	
1	DOOR HINGE NUT RH	\$	Sm	14.60	
1	DOOR CHECK BOLT	\$	Sm	22.69	
1	DOOR CHECK NUT	\$	Sm	3.75	
1	DOOR LOCK SCREW L70Y	\$	Sm	6.12	
1	DOOR CATCH SCREW L70Y	\$	Sm	10.06	
1	FENDER INNER TRIM CLIP RH	\$	na	28.00	
1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
2	REAR WINDSCREEN SEALANT	\$	na	80.00	
1	WINDSCREEN MOULDING	\$	na	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	REAR RIGHT TYRE	\$	Sm	300.00	
1	REAR RIGHT TYRE RIM	\$	N	380.00	

Trans-cab Auto Services Pte Ltd

AAD1906-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	}	
1SET	PARKING AID	\$	<i>sn</i> 700.00		
1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00		
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00		
1SET	BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00		
1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00		
1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00		
1	FRONT RIGHT TYRE	\$	<i>sn</i> 300.00		
1	FRONT RIGHT TYRE RIM	\$	<i>sn</i> 380.00		
TOTAL		\$	3,186.63		
TOTAL PARTS		\$	47,214.85		

LABOUR

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>400</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>440</i>
To rust-proofing of the affected areas.	\$	170.00	<i>30</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00	<i>60</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1906-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To repair and realign rear exhaust pipe.	\$	na	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	na	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	2d
To reinstall rear bumper parking sensor.	\$	na	170.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	na	380.00	X
TOTAL	\$		16,070.00	
Over All Total	\$		63,284.85	

LUMP SUM (REPAIR DAY)

~~20 DAYS~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: