



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Corna Roberto ADDRESS : 26 Bukit Batok East Avenue 2 #17-08 Singapore 659920 TEL : 94653635		WIP : 43302 EXCESS : DATE: 15-Jun-19	
VEH NO :	SMF1150H	DATE IN :		CONTACT PERSON :	Jobi 63310682
CHASSIS NO :	JM6BN22A8K0251674	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	29-Oct-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MB63B-50-031BBB		\$ 866.80
2	RETAINER RHS	1	MB63B-50-0T1B		\$ 15.50
3	CLIP, FRONT BUMPER	12	MC274-50-133		\$ 44.40
4	FASTENER, FRONT BUMPER	2	MB45A-56-146A		\$ 6.00
5	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5		\$ 5.80
6	SEAL RUBBER, FRONT BUMPER	2	MB63B-50-2G2		\$ 4.80
7	RIVET, FRONT BUMPER	4	MTK21-50-355		\$ 36.80
8	RIVET, FRONT BUMPER	4	MS51S-51-833		\$ 16.00
9	FASTENER, FRONT BUMPER	8	MGD7A-50-EA1		\$ 25.60
10	HEADLAMP RHS	1	MBAAR-51-031H		\$ 3,778.60
11	CLIP, HEADLAMP	2	MDR61-50-133		\$ 13.00
12	RIVET, HEADLAMP	1	MB092-51-833		\$ 3.50
13	CORD SHORT, HEADLAMP	1	MBAAR-51-0K6		\$ 123.10
TOTAL PARTS					\$ 4,939.90
LESS 10%					\$ 493.99
TOTAL PARTS COST					\$ 4,445.91
Labour Description					
1	MZ-BR-FRONT1	TO REPLACE FRONT BUMPER. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			990 \$ 1,320.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.			\$ 1,260.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			150 \$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150 \$ 250.00

5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6		TO SUPPLY BRILA PREMIUM COATING. (invoice?)	NETT	\$ 250.00
7	MZ-BR-SUNDRI	SUNDRIES. 20	NETT	\$ 100.00
TOTAL LABOUR			\$ -	\$ 3,780.00
TOTAL PARTS			\$ -	\$ 4,445.91
TOTAL			\$ -	\$ 8,225.91
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue

Hp 90010068

4-5 days

19/06/19 @ 1030

Resay before paid