

## TRANS EUROKARS PTE LTD



# ESTIMATE COST OF REPAIRS

43302 WIP: Mr Corna Roberto INDIA INTERNATIONAL INSURANCE P/L NAME: EXCESS: ADDRESS: 26 Bukit Batok East Avenue 2 64 CECIL STREET 15-Jun-19 DATE: #17-08 #04-#05 IOB BUILDING Singapore 659920 SINGAPORE 049711 94653635 TEL: MOTOR CLAIMS ATTN.: FAX: lobi 63310682 CONTACT PERSON: SMF1150H DATE IN: VEH NO : THIRD PARTY CLAIM TYPE OF CLAIM: MILEAGE: JM68N22A8K0251674 CHASSIS NO: POLICY NO.: DATE REG.: 29-Oct-18 MAZDA3 MODEL: NATURE OF WORKS **Parts Description** PRICES HEVISED QTY NO 866.80 MB638-50-031888 1 FRONT BUMPER 1. 15.50 MB638-50-0T18 ysuc 1 RETAINER RHS 2 \$ 44,40 MC274-50-133 12 CLIP, FRONT BUMPER 6.00 5 MB45A-56-146A Ne 1 2 FASTENER, FRONT BUMPER 4 5.80 5 MGHP9-50-025 GROMMET, FRONT BUMPER 2 5 4.80 2 MB63B-50-2G2 SEAL RUBBER, FRONT BUMPER 5 Ś 36.80 MTK21-50-355 4 RIVET, FRONT BUMPER RL 16.00, 5 MSS1S-S1-833 4 RIVET, FRONT BUMPER × 25.60 MGD7A-50-EA1 H FASTENER, FRONT BUMPER 9 m 3,778.60 5 MBAAR-S1-031H 7 1 HEADLAMP RHS 13.00 MDR61-50-133 2 MA CLIP, HEADLAMP 11 5 3.50 MB092-51-833 12 RIVET, HEADLAMP 123.10 MBAAR-S1-0K6 1 CORD SHORT, HEADLAMP 13 4,939.90 TOTAL PARTS 493.99 **LESS 10%** 4,445.91 TOTAL PARTS COST **Labour Description** TO REPLACE FRONT BUMPER. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED 990 MZ-BR-FRONT1 BY THE ACCIDENT. 1 TO RESPRAY FRONT BUMPER AND FRONT FENDER RH. 2 MZ-SP-SFRT07 150-MZ-BR-CAVITY TO CARRY-OUT BODY CAVITY PRESERVATION 3 MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 150. 4

5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS			180		35000
5		TO SUPPLY BRILA PREMIUM COATING: (1001CE?)			NETT		250.00
,	MZ-BR-SUNDRI	SUNDRIES.	20		NETT	5	10000
-			TOTAL LABOUR	Ś		5	3,780.0
			TOTAL PARTS	\$	-	5	4,445.9
			TOTAL	5		\$	8,225.9
			LESS EXCESS	5		5	
			TOTAL AFTER EXCESS	5			
			GST 7%	\$		5	- 1-
			GRAND TOTAL	5		5	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT, TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**Authorised Signature** 

TRANS EUROKARS PTE LTD

4p 90010068

4-5 days 5 days
19/06/19@1030
Resy before put

LXX Auto Consultants hence notify the Repairer of the following:

- . To resurvey at long latter species paint
- . To display among partial during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Projudice" basis
- . No illegal modification(s) is a roused
- Supplementary item(x) must be recurveyed and it subject to final approval from Insurance Company

Advocated by Requirer

Signature.

Date:



#### TRANS EUROKARS PTE LTD



### FINALISED COST OF REPAIRS

43302 Mr Corna Roberto WIP: INDIA INTERNATIONAL INSURANCE P/L NAME: EXCESS: 26 Bukit Batok East Avenue 2 64 CECIL STREET ADDRESS: 15-Jun-19 DATE: #04-#05 IOB BUILDING SINGAPORE 049711 Singapore 659920 ATTN.: MOTOR CLAIMS TEL: 94653635 FAX: Jobi 63310682 CONTACT PERSON: SMF1150H DATE IN: VEH NO : THIRD PARTY CLAIM TYPE OF CLAIM: JM68N22A8K0251674 MILEAGE: CHASSIS NO: POLICY NO.: MODEL: **MAZDA3** DATE REG.: 29-Oct-18 NATURE OF WORKS Parts Description REVISED PRICES QTY NO 866.80 866.80 5 FRONT BUMPER 1 MB638-50-031888 1 15:50 MB63B-50-0T1B 1 2 RETAINER RHS 44.40 \$ 44.40 MC274-50-133 12 CLIP, FRONT BUMPER 3 6.00 S 6.00 FASTENER, FRONT BUMPER 2 MB45A-56-146A 4 5.80 \$ 5.80 MGHP9-50-025 GROMMET, FRONT BUMPER 2 5 \$ 4.80 5 4.80 2 MB63B-50-2G2 SEAL RUBBER, FRONT BUMPER 36.80 36.80 \$ MTK21-50-355 7 RIVET, FRONT BUMPER 4 \$ 16.00 16.00 RIVET, FRONT BUMPER 4 MS515-51-833 8 25.60 \$ \$ MGD7A-50-EA1 25.60 8 q FASTENER, FRONT BUMPER MBAAR-51-031H 3,778.60 1 HEADLAMP RHS 13.00 \$ CLIP, HEADLAMP 2 MDR61-50-133 11 \$ 3.50 1 MB092-51-833 RIVET, HEADLAMP 123.10 MBAAR-51-0K6 CORD SHORT, HEADLAMP 1 13 1,006.20 5 4,939.90 TOTAL PARTS 493.99 LESS 10% 100.62 TOTAL PARTS COST \$ 905.58 4,445.91 Labour Description TO REPLACE FRONT BUMPER. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED \$ 990.00 \$ 1,320.00 MZ-BR-FRONT1 1 BY THE ACCIDENT. MZ-SP-SFRT07 TO RESPRAY FRONT BUMPER AND FRONT FENDER RH. \$ 1,260.00 1,260.00 2 MZ-BR-CAVITY TO CARRY-OUT BODY CAVITY PRESERVATION. 150.00 250.00 3 \$ 150.00 250.00 MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 4 5 1B0.00 S 350.00 MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. 5

6		TO SUPPLY BRILA PREMIUM COATING.  DRI SUNDRIES.		\$	250.00	\$	250.00
7	MZ-BR-SUNDRI			\$	20.00	s	100.00
_			TOTAL LABOUR	5	3,000.00	\$	3,780.00
			TOTAL PARTS	\$	905.58	5	4,445.91
			TOTAL	5	3,905.58	\$	8,225.91
			LESS EXCESS	5	9	S	
			TOTAL AFTER EXCESS	5	3,905.58		
			GST 7%	5	273.39	\$	
			GRAND TOTAL	\$	4,178.97	5	

### REMARKS:

<sup>5</sup> REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

#### Rasul (LKKAuto)

From: catherinechua@eurokars.com.sg
Sent: Thursday, 11 July, 2019 10:44 AM

To: Rasul (LKKAuto)

Cc: jobithomas@eurokars.com.sg

Subject: RE: SMF1150H - FINALIZATION OF COR

Dear Rasul

Brila coating was installed by our workshop at the point of purchase and we have therefore sent you the extract of our Internal Invoice to prove thus.

The re-coating was also done by our workshop and we will bill it to the Insurance company in our final repair invoice.

We hope that the above explanation suffices.

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 D: (65) 6603 6121 F: (65) 6476 7417

E: catherinechua@mazda.com.sq

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurakars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Rasul (LKKAuto) < Rasul@lkkauto.com>

Sent: 11 July 2019 10:19 AM

To: Catherine Chua <<u>catherinechua@eurokars.com.sg</u>>
Cc: Jobi Thomas <<u>iobithomas@eurokars.com.sg</u>>
Subject: RE: SMF1150H - FINALIZATION OF COR

Hi Catherine,

Kindly forward to me the invoice for the coating 250. The other copy that you forward to me doesn't show any amount

Best Regards.

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Save the Earth- Print only when necessary-

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]

Sent: Wednesday, 10 July, 2019 3:14 PM

To: Rasul (LKKAuto)

Cc: jobithomas@eurokars.com.sg; CS A Team; Admin A

Subject: SMF1150H - FINALIZATION OF COR

Dear Rasul

Our COR computation with 84 paint photos is attached for your agreement.

COR: \$3905.58 before GST

5 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards



Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 D: (65) 6603 6121 F: (65) 6476 7417

E: catherinechua@mazda.com.sq

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <mazdacanon@mazda.com.sg>

Sent: 10 July 2019 2:39 PM

To: Catherine Chua <catherinechua@eurokars.com.sg>

Subject: Attached Image