CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHB 4962S (Supplementary)

DATE: 19.06.2019 TEL : 6542 5119

· FIVIINDAT (40

MODEL	: HYUNDAI i40	FAX	FAX: 6542 6039		
Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Spare Tyre Bracket Deutsch			\$ 248.00	
	SUB TO			\$ 248.00	
	LESS	1 1		\$ 49.6	
	DISCOUNTED TO	TAL		\$ 198.4	
			¥		
	1			-	
	7406	119			
	JEK AD	'			
				H. H	
0.00					
	1 2 1 2 2				
i.					
			· ·		
	2.7	,			
	6		2		
	. \				
	`.		-		
				i i	
				*	

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.