



Pte Ltd

AIG Singapore
78 Shenton Way
Singapore 079120

Tanpin 974 1541
WP
18/6/19 C545
Lumpsum
Resurvey before repair
6 days

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	SLW369Z
Make / Model	AUDI/A3
Chassis number	WAUZZZ8V9J1034190
Accident date	12 June 2019
Reference	1906-53

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER de	
2	REAR BUMPER BRACKET RH new LY ✓	
2	REAR BUMPER RETAINER RH new RH ✓	
1	REAR BUMPER REFLECTOR RH new ✓	
1	REAR BUMPER UNDER GARNISH cut ✓	
1	REAR TAILLAMP RH ad ✓	
1	REAR RH FENDER bf ✓ dismantle photo ✗	
1	REAR WINDSCREEN MOULDING new ✓	
4	REAR RH FENDER AIR VENT ?	
1	REAR RH FENDER INNER TRIM ✗	
4	PDC SENSOR new ✓	
4	SENSOR HOLDER new ✓	
		0.00
	Less 5%	0.00
	Subtotal	0.00
	Balance C/F	0.00
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	Balance B/F	0.00
1 SET	REAR BUMPER CLIP	40.00 30 new ✓
1	REAR FENDER INNER TRIM CLIP	20.00 ✗
1	JOINT SEALANT	150.00 60
1	WINDSCREEN SEALANT	150.00 60w ✓
	Subtotal	360.00
	Balance C/F	360.00
LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	360.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	300.00 180
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
4	REMOVE, REFIT TRIM, LINING AND GARNISH	200.00 60
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 120
6	PANEL BEATING ON AFFECTED AREAS	1400.00 700
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 500
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	3610.00
	Grand total	3970.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: