

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 19 Jun 2019

Preliminary Advice

Insured Vehicle No	: GBH5280J	Accident Date	: 13/06/2019
TP Vehicle No	: SKC4018C	Assignment Date	: 18/06/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 6
Date of Inspection	: 18/6/2019		
Inspection At	: WEI LEE MOTOR WORKS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,640.29
Revised Amount	:S\$	5,090.68
Check Items (Estimated)	:S\$	109.05
Total	:S\$	5,199.73
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.