

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119010737/KTD3E2

Date: 08/05/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN13100419066
Claimant Vehicle No :	SLV6280K	Insured Vehicle No :	GW1748R
Date of Loss:	01/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202646

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV6280K	Engine No:	2ZR0A29624
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W60J008222
Reg. Date:	05/01/2018 (Man. Year: 2017)	Odometer:	28217 km
Colour:	Metallic Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	645.00	645.00	0.00	0.00
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	54.60	54.60	0.00	0.00
Paintwork Labour	341.07	413.70	-72.63	-21.29
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,140.67	1,213.30	-72.63	-6.37
+ GST 7.00/7.00% (S\$)	79.85	84.93	-5.08	-6.36
Nett Amount (S\$)	1,220.52	1,298.23	-77.71	-6.37

INSPECTION

Date of Assignment:	18/06/2019 Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	24/06/2019 Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2020)
Parts: M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV6280K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		645.00 F	*645.00 F
					Total Parts (S\$)	645.00
						645.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
			Sub Total (\$\$)	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TOTAL PAINT INCLUDING MATERIAL	New	341.07	413.70
Labour Items				
2	TOTAL OF LABOUR	New	54.60	54.60
			Gross Labour Cost (\$\$)	395.67
				468.30

Report was unsubmitted during this print-out.

< END OF ESTIMATES >