

ASS. REC. BY:

REF: (S)CT1 19010737 / K1 d3

Special Instruction:

Miriam

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ong chin kiat of CT1 Date/Time: 18.6.19 11:35 a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 6280K Insured: GW 1748R

at Workshop m/s Kai Huat Tel: 64538110

of 160 Sin Ming Drive #04-01

Policy No: DMCVSN 13100419066 Claim No: SNM1902064 b

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 1.6.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 18.6.19 11:43 a.m Person Contacted: Jenny Vehicle IN/OUT

H.O.D. Endorsement:

Date/Time	Action/Instruction	Estimate	(✓)
	SLV 6280K - X		
	GW 1748R - CB / CT1 15012429 / RI hass 2		
	part by part	\$1213.30	(Red: 37263:23)

D.O.A. 14/06/2015.



# Lai Huat (Meng Kee) Motor Pte Ltd

160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming  
Autocity  
575722

Claim Reference: TP-GW 1748R  
Assessment number: 70567  
Version: 1810  
Date calculated: 06/06/2019 5:48 PM

Full Report  
Registration: SLV 6280K  
Printed: 06/06/2019 5:49 PM

## Summary Information

### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GW 1748R	Date of Incident:	01/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

## Vehicle Details

### Vehicle

Manufacturer: TOYOTA  
Model: WISH(ZGE21L/ZGE2)  
Sub Model: BASE MODEL  
Model Sheet Number: 70 W2 01  
Registration: SLV 6280K  
VIN number:  
Odometer:

### Model Specs

AIR CONDITIONING	FROM 10/2017	XENON HEADLAMPS	FOG LAMPS
1.8 LTR 95 KW	CVT AUTO GEARBOX	TWO COAT METALLIC	PREPARE OFF VEHICLE

## Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
670051	RENEW LEFT FRONT DOOR INCLUDES: R + R AND ALIGN LEFT FRONT DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		13.0	54.60
	<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
	<b>Panel / Mechanical Labour</b>		1.30	13.0
	<b>Total of Labour</b>			<b>54.60</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No further work is allowed
- Work must be resurveyed and approved by the approval from Insurance Company

*Not Authorized*  
*Recovery B4 pain*  
*2 days*

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: TP-GW 1748R  
 Assessment number: 70567  
 Version: 1810  
 Date calculated: 06/06/2019 5:48 PM

Full Report  
 Registration: SLV 6280K  
 Printed: 06/06/2019 5:49 PM

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	LEFT FRONT DOOR NEW PART PAINTING	18.0
	L/F DOOR OUT HANDLE NEW PART PAINT K1R	3.0
	R/F WING SURFACE PAINT	6.0

**Paint Material Per Part**

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	52.63
1565	L/F DOOR OUT HANDLE NEW PART PAINT K1R	0.98
0742	R/F WING SURFACE PAINT	10.46

**Labour Cost - Paint**

	Factor	Hrs	WU	Price SGD
	42.00 SGD/h		27.0	
		2.50	25.0	105.00
		0.50	5.0	21.00
<b>Total</b>	<b>10 WU/h</b>	<b>5.70</b>	<b>57.0</b>	<b>239.40</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	52.63
New Part Painting - Plastic K1R	0.98
Surface-/Blend Paint	10.46
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>101.67</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
1481	LEFT FRONT DOOR	67002 0M040		B1	450.00 ✓
1565	L/F DOOR OUT HANDLE	69211 0M901		nu	145.00 ✓
1659	L/F DOOR TRIM REAR	75756 0M010		nu	50.00 ?
f: OEM Parts	<b>Savings</b>				0.00
n: Non-OEM Parts	<b>Subtotal</b>				645.00
u: Used parts					

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: TP-GW 1748R  
 Assessment number: 70567  
 Version: 1810  
 Date calculated: 06/06/2019 5:48 PM

Full Report  
 Registration: SLV 6280K  
 Printed: 06/06/2019 5:49 PM  
 100.00

**Total** **745.00**

**Extras**

Code	Description	Price SGD
1000	GLASS COATING SPRAY CERAMIC	300.00*
	<b>Total Extras</b>	<b>300.00</b>

WM. x ?

**Final Calculation**

	SGD	SGD
<b>Parts</b>	645.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		<b>745.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 13.0 WU X 42.00 SGD/h	54.60	
<b>Total of Labour</b>		<b>54.60</b>
<b>Total Of Extras</b>		<b>300.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 57.0 WU X 42.00 SGD/h	239.40	281.40
Material Cost	101.67	132.30
<b>Total Paint Including Material</b>		<b>341.07</b>
<b>Repair Cost Excludes GST</b>		<b>1,440.67</b>
GST (+7.0%)		100.85
<b>Repair Cost Included GST</b>		<b>1,541.52</b>

1585.93

7263

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS