

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 18 Jun 2019

Preliminary Advice

Vehicle No	: SFF9993Y	Accident Date	: 13/06/2019
Make	: HONDA ODYSSEY	Policy No.	: A29071964QMY
Assignment Date	: 18/06/2019	Excess	: S\$1,000.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 8 days
Inspection At	: Sme Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15 Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s & n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 19,119.95
Revised Amount	:S\$ 11,800.25
Check Items (Estimated)	:S\$ 4,577.45
Total	:S\$ 16,377.70
 Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 110,000.00
COE / PARF Rebate	:S\$ 67,914.00
Salvage Value	:S\$
Margin for Repair	:S\$ 42,086.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.