

Standard

ASS. REC. BY:

REF: CS/MSG/9010740 / Ucd 30 Special Instruction:

Surveyor: MURRAY

ASSIGNMENT (Office)

From (Person): Pauline Soh Li Ping of MS24 Date/Time: 18.6.19 10:34 AM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFF 99939 Insured:

at Workshop m/s SINE MOTOR Tel: 67476106

of 1 Kaki Bukit Ave 6, #02-15

Policy No: A290719640MY Claim No:

Sum Insured: Excess: \$ 000 00

Make of Veh: D.O.A. 13.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 18.6.19 10:57am Person Contacted: Dai Ying Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SFF 99939 - NBI INC 100/0554/L4	DOA - 15/06/2019
18/06/19	@ 16:16 pm revised TA to Pauline Soh Li Ping via memo.	
18/06/19	@ 16:19 pm mandate requested authorise repair to Pauline.	
18/06/19	@ 18:56 pm mandate approved by Jocelyn Ng via memo.	
19/06/19	@ 10:50 am inform CIA to Sebastian (owner) via email.	

(08/11/13) wet

ASS. REG. BY: MARCUS

REF:

CS/MSG 190107401 USD3

MSIC/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SFF 99931

at Workshop m/s

sne.

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: 1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

110k.

IDAC Accident Rpt:

Consistent? : Yes or No

GI / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

1.131

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A67914

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFF99931

Yr Regn:

2, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Odyssey EXV 2356

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

51611

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMR C1890AC 209093

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/35-219

R:

BS / DUN / EXNOVA / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/6/19

D.O.I.

18/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L7 015 & 115 Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Typ. full repair

cost plus 10% or 15%
L7 w/screen No studs.

RECEIVED 22 AUG 2019

19/6/19 @ 10:48 am checked with Sebastian, Cost plus 10%.

20/8/19 P/P # 15174.10 confirmed with ALLYING
(F 4,656.95 Rev - 24%)

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

8

1) 24/8/19
Typ. 4☒

Final Report

Resurvey No. of Trip:

3

Survey Fee:

200

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

Lump Sum 11.B. (\$ 15,174.10)

TOTAL

211

marini waf

ASS. REC. BY: MARINIS

REF:

MS101

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SFF 99931

at Workshop m/s

Sue

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: 1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

110k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Vail.: Yes or No

CA / REV / REP. / 24 HRS

LA 67914

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

743. full repaircost plus 10% or 15%

Veh No:

SFF99931

Yr Regn:

2, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Car

Make:

Honda Odyssey EXV 2356

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

51611

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMR C1890AC 209093

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F: 245/35-19

R:

BS / DUN / EXNOVA / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/6/19

D.O.I.

18/6/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Lt o/s & n/s R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) \$ + RB \$



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019 17:13		18 Jun 2019 10:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA CHUAN HOE, ID: S7524202F, Tel: +6591189993, Email: NOEMAIL		
Vehicle Reg. No.:	SFF9993Y	Date of Loss:	13/06/2019 11:00 - :59 [5 Months and 12 Days From LTA Reg Date (Mon Yr)]
Claim Type:	OD	Policy/Cover Note No.:	A29071964QMY (Comprehensive) Coverage: 13/02/2019 - 12/02/2020
		Excess:	S\$1,000.00
Repairer:	Sme Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Soh Li Ping]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/06/2019]		
Driver/Custodian:	CHUA CHUAN HOE (43 / Male), NRIC: S7524202F, Tel: +6591189993 Email: NOEMAIL		
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	4202F

Vehicle Details

Vehicle No.:	SFF9993Y
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	K24W72013712
Chassis No.:	JHMRC1890GC209093
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,901.00
Original Registration Date:	13 Feb 2017
First Registration Date:	13 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$36,662.00 18331

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Feb 2027
PARF Rebate Amount:	\$27,496.00

Intended COE Rebate Details

COE Expiry Date:	12 Feb 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,807.00
COE Rebate Amount:	\$40,418.00
Total Rebate Amount:	\$67,914.00

The information contained herein is correct as at 18 Jun 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4202F

Vehicle Details

Vehicle No.: SFF9993Y
Vehicle to be Exported: No
Intended Deregistration Date: 18 Jun 2019
Vehicle Make: HONDA
Vehicle Model: ODYSSEY 2.4 EXV-S CVT SR
Primary Colour: White
Manufacturing Year: 2016
Engine No.: K24W72013712
Chassis No.: JHMRC1890GC209093
Maximum Power Output: 129.0 kW (172 bhp)
Open Market Value: \$31,901.00
Original Registration Date: 13 Feb 2017
First Registration Date: 13 Feb 2017
Transfer Count: 0
Actual ARF Paid: \$36,662.00 *1f331*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Feb 2027
PARF Rebate Amount: \$27,496.00

Intended COE Rebate Details

COE Expiry Date: 12 Feb 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$52,807.00
COE Rebate Amount: \$40,418.00
Total Rebate Amount: \$67,914.00

The information contained herein is correct as at 18 Jun 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

New 5 Years Renewal Coe Honda Stream Rsz 1.8A

3.18% p.a. \$0 Admin Fees @ Gv
Finance, 2 Years
Warranty: \$2500 Down Monthly
From \$638
Gv Credit Pte Ltd - StarAd

Free VICOM evaluation

Free grooming and 6 months maintenance

In-house workshop ensures quality service

Member of SVTA and hire purchase association

100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by Date Posted

20 results/page

6 vehicles

Odyssey

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Odyssey		Any	Any	2017	Any	Any	Any	Available
	Honda	Odyssey 2.4A EX-S 8-Seater	\$126,888	\$13,550 /yr	04-Sep-2017	2,356 cc	34,000 km	MPV	Available
Promo Loan Interest At 2.28%. Extremely Well Maintained, Fully Agent Maintained And Come With First Five Years Of Agent Warranty. This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View...									
Posted: 16-Jun-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EX-S	\$121,500	\$12,590 /yr	01-Dec-2017	2,356 cc	-	MPV	Available
Elegant Grey MPV, Serviced By Agent In April 2019, Agent Warranty Till Dec 2022, With Electric Tailgate And 2 Power Sliding Doors, One Owner Only, Very Well Maintained, Easy Financing, Flexible In Hou...									
Prime Motor & Leasing									
Posted: 16-Jun-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EX-S	\$115,000	\$12,490 /yr	09-Jun-2017	2,356 cc	29,500 km	MPV	Available
Consignment Unit. Warranty Till 2022. Loan Interest At 2.28%, Extremely Well Maintained And Fully Agent Maintained. This Beast Does Not Just Look Beautiful, It's 100% Accident-Free. View To Believe! U...									
Posted: 04-Jun-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EX-S	\$113,888	\$12,960 /yr	09-Jan-2017	2,356 cc	20,240 km	MPV	Available
Accident Free. Direct Owner (1). Serviced At About 5000km Intervals At AD With Last Servicing At 19350km With 2 More Free Servicing Left. 8 Seater Premium Spice Purple With 5 Years Extended Warranty. ...									
Posted: 03-Jun-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
Car Buying Car Selling Car Ownership Car Aftermarket On The Move Lifestyle									
	Honda	Odyssey 2.4A EXV-S Sunroof	\$125,888	\$13,090 /yr	21-Sep-2017	2,356 cc	42,000 km	MPV	Available
Agent Unit! 1 Careful Owner! Low Mileage! High Loans Up To 80% Of The Car Price With Lowest Interest Rates From 2.28%. Whatsapp To View Now! By Appointment Only!									
360 VR Cars									
Posted: 14-May-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EX-S	\$116,800	\$13,290 /yr	20-Jan-2017	2,356 cc	39,000 km	MPV	Available
1 Owner, Servicing Is Done With Kah Motors.									
Posted: 13-Apr-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									

Compare

Save this search criteria, to get email alerts whenever a match is found.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 18 July 2019 3:37 PM
To: peiyong@smemotor.com.sg
Cc: SUR; 'Sebastian Kong'
Subject: RE: SFF 9993Y OD (MSIG) DOA - 13/06/2019
Attachments: SUPP.pdf

Dear Pei Ying,

Supplementary approved by MSIG.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 19 June 2019 10:50 AM
To: peiyong@smemotor.com.sg
Cc: SUR <sur@lkkauto.com>; 'Sebastian Kong' <sebastian@smemotor.com.sg>
Subject: SFF 9993Y OD (MSIG) DOA - 13/06/2019

Dear Pei Ying,

As instructed by our client, please proceed to repair the insured vehicle **SFF 9993Y (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 19 June 2019 10:50 AM
To: peiyang@smemotor.com.sg
Cc: SUR; 'Sebastian Kong'
Subject: SFF 9993Y OD (MSIG) DOA - 13/06/2019

Dear Pei Ying,

As instructed by our client, please proceed to repair the insured vehicle **SFF 9993Y (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

*SFF9993Y (596733)
OD
Jun 13 2019 11:00AM
[CHUA CHUAN HOE]
Sme Motor Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 21/08/2019 15:19 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15174.10) - SFF9993Y - Claim Handler: Pauline Soh Li Ping

Approved:15174.10.

DOCUMENTS SUMMARY
There are no documents.

View Received Message

This mail is associated with :

***SFF9993Y (596733)**

OD

Jun 13 2019 11:00AM

[CHUA CHUAN HOE]

Sme Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 18/07/2019 10:09 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12461.35) - SFF9993Y - Claim Handler: Pauline Soh Li Ping

Approved:12461.35:A If C. Check items to be verified and confirmed.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SFF9993Y (596733)**

OD

Jun 13 2019 11:00AM

[CHUA CHUAN HOE]

Sme Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 18/06/2019 18:36 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11800.25) - SFF9993Y - Claim Handler: Pauline Soh Li Ping

Approved:11800.25:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 21 Aug 2019

Preliminary Advice

Vehicle No	: SFF9993Y	Accident Date	: 13/06/2019
Make	: HONDA ODYSSEY	Policy No.	: A29071964QMY
Assignment Date	: 18/06/2019	Excess	: S\$1,000.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 8 days
Inspection At	: Sme Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15 Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s & n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,831.05
Revised Amount	:S\$	15,174.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,174.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	67,914.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,086.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 18 Jul 2019

Preliminary Advice

Vehicle No	: SFF9993Y	Accident Date	: 13/06/2019
Make	: HONDA ODYSSEY	Policy No.	: A29071964QMY
Assignment Date	: 18/06/2019	Excess	: S\$1,000.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 8 days
Inspection At	: Sme Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15 Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s & n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,831.05 (inclusive supp)
Revised Amount	:S\$	12,461.35 (inclusive supp)
Check Items (Estimated)	:S\$	4,577.45
Total	:S\$	17,038.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	67,914.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,086.00

Remarks

(X) The vehicle is economical for repair. Supplementary amount is \$ 661.10.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 18 Jun 2019

Preliminary Advice

Vehicle No	: SFF9993Y	Accident Date	: 13/06/2019
Make	: HONDA ODYSSEY	Policy No.	: A29071964QMY
Assignment Date	: 18/06/2019	Excess	: S\$1,000.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 8 days
Inspection At	: Sme Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15 Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s & n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,119.95
Revised Amount	:S\$	11,800.25
Check Items (Estimated)	:S\$	4,577.45
Total	:S\$	16,377.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	67,914.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,086.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/06/2019 14:02
Date Of Accident	13/06/2019 11:55
Exact Location Of Accident	CTE (AYE) AFTER ORCHARD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFF9993Y
Insured/Policyholder	
Name Of Registered Owner	CHUA CHUAN HOE
NRIC No	S7524202F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91189993
Alternative Phone No	OFFICE-91189993

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29071964QMY
Cover Note Number	

Driver

Name of Driver	CHUA CHUAN HOE
NRIC No	S7524202F
Date Of Birth	14/08/1975
Occupation	INDOOR
Date Of Driving Pass	21/01/1994
Driving Experience	25 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91189993
Fax Number	
Contact Number	OFFICE-91189993
Email Address	NOEMAIL

Address	23 AMK AVE 9 #11-11
Postcode	569787
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJV6910A
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

YN2489R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SLA2344Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

IMPORTANT NOTES

1. This report is prepared by the insurers of the vehicle(s) involved in this accident.
2. This report is completed by the Insurers and/or the Author(s) of this report.
3. When a claimant makes a claim, the insurer is required to provide a copy of this report to the claimant and to the claimant's insurer.
4. The report will be made available to the claimant's insurer for use in determining the claimant's liability under the policy.
5. Any false statement may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the handing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). The Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to my enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:



- (A) - SFF 97134
- (B) - LINENOW
- (C) - SJV 67104
- (D) - YN 3472
- (E) - SLA 3244

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS DRIVING ALONG CTE (AVE) AFTER (CROWD) ROAD EXT. VEHICLE B
 SUMMER) ESCAPE, I TRY TO SWERVE TO RIGHT BUT MY VEHICLE LEFT SIDE
 HIT CRUISED VEHICLE B FROM RIGHT AND HIT INTO VEHICLE C (IN)
 FRONT LANE - RESULT VEHICLE C HIT ALSO VEHICLE D / E

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature
 Date & Time:

Driver's Signature
 (If driver is not the owner/owner)
 Date & Time:

Reporting Officer/Investigator's Signature
 Name:
 NO. & Date:

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #01-15 Autobay@KakiBukit Singapore 417883
 TEL: 67475106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

not Adjust
haha
7.4k p/b 3rd party
Excess B10:
cost price:

M/S: MSIG INSURANCE (SINGAPORE) PTE. LTD.

4 Shenton Way, #21-01

SGX Centre 2

Singapore 068807

TEL: 68277888

FAX: 68277800

ATTN: Motor Claim Department

Your Ref No: 19/MSIG/OD-302 (06)

Claim Type: Own Damage

Estimate No: EST0004897

Date: 17 Jun 2019

Policy No: A29071964QMY

Veh Reg No: SFF9993Y

Make/Model: HONDA ODYSSEY

Reg. Date: 13/02/2017

Estimate Repair Cost to Vehicle No :SFF9993Y

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Parts				
1 FRT WINDSCREEN	Che	1PC	1,950.00	—
2 FRT WINDSCREEN MOULDING	neu	1PC	55.00	—
3 FRT WINDSCREEN SIDE MOULDING-LH	Che	1PC	0.0000	—
4 FRT WIPER CORNER GARNISH-LH	De	1PC	35.00	—
5 FRT WIPER GARNISH	De/	1PC	125.00	—
6 FRT BONNET	3 u/c	1PC	480.00	—
7 FRT BONNET GARNISH		1PC	70.00	?
8 FRT BONNET HINGE	neu	2PC	80.00	—
9 FRT BONNET INSULATOR	Tail	1PC	65.00	—
10 FRT BONNET INSULATOR CLIP	neu	8PC	16.00	—
11 FRT GRILLE (TOP)		1PC	180.00	?
12 FRT GRILLE CLIP		4PC	8.00	?
13 FRT GRILLE CHROME-TOP (BIG)		1PC	180.00	?
14 FRT BUMPER	Dis	1PC	450.00	—
15 FRT BUMPER RETAINER	neu	2PC	24.00	—
16 FRT BUMPER CLIP	neu	10PC	20.00	—
17 FRT BUMPER REINFORCEMENT	neu	1PC	220.00	—
18 FRT BUMPER BEAM (BELOW HEADLAMP)	M/SCM	2PC	70.00	1PC
19 HEADLAMP	n/s cre	2PC	3,000.00	1PC
20 HEADLAMP SUPPORT PANEL	n	1PC	300.00	OK
21 BATTERY COVER		1PC	20.00	?
22 FRT FENDER	neu/Deu	2PC	720.00	—
23 FRT FENDER COWLING	Tail	2PC	160.00	—
24 FRT FENDER COWLING CLIP	neu	20PC	40.00	—
25 FRT FENDER TOP GARNISH LH	Tail	1PC	35.00	—
26 FRT FENDER GLASS LH	3.10	1PC	300.00	—
27 FRT FENDER INNER REAR GARNISH LH	Che	1PC	40.00	—
28 WHEEL HOUSING PANEL LH		1PC	680.00	?
29 WHEEL HOUSING PANEL JOINT LH		1PC	0.0000	?
30 SIDE MIRROR COVER LH	m. j	1PC	55.00	—
31 'A' PILLAR LH	neu	1PC	620.00	OK
32 RESONATOR BOX		1PC	90.00	?
33 BATTERY BRACKET		1PC	35.00	?
34 FRT FENDER TOP CHROME		2PC	130.00	?
35 FOG LAMP GARNISH RH	Che	1PC	55.00	—
36 AIR CLEANER BOX ASSY		1PC	150.00	?
37 DASHBOARD		1PC	650.00	?
38 SIDE MIRROR GLASS LH	Che	1PC	680.00	?
39 AIRCON CONDENSER	n. j	1PC	480.00	X

SME Motor Pte Ltd

1 Kaki Bukit Ave 4, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442358 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S: MSIG INSURANCE (SINGAPORE) PTE. LTD.

4 Shenton Way, #21-01

SGX Centre 2

Singapore 068807

TEL: 68277888

FAX: 68277800

ATTN: Motor Claim Department

Your Ref No: 19/MSIG/OD-302 (06)

Claim Type: Own Damage

Estimate No: EST0004897

Date: 17 Jun 2019

Policy No: A29071964QMY

Veh Reg No: SFF9993Y

Make/Model: HONDA ODYSSEY

Reg. Date: 13/02/2017

Estimate Repair Cost to Vehicle No :SFF9993Y

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 RADIATOR		1 PC	700.00	X
41 FRT DOOR OUTER MOULDING (CHROME) LH		1 PC	75.00	
42 SUPPORT PANEL BRACKET		2 PC	70.00	?
			13,113.00	
	Add 15%		1,966.95	15,079.95

Special Net

43 FRT WINDSCREEN GUM	1 PC	60.00	40
44 ERP BRACKET	1 PC	25.00	20
45 FRT FENDER GLASS	2 PC	120.00	30
46 BATTERY	1 PC	180.00	100
47 RADIATOR COOLANT	1 PC	25.00	X
			410.00

Labour

48 WIRE CHECKING	1 UNIT	20.00	✓
49 REMOVE & REFIX AIRCON AND GAS	1 UNIT	100.00	✓
50 REMOVE & REFIX FRT WINDSCREEN	1 UNIT	120.00	✓
51 REMOVE & REFIX DASHBOARD	1 UNIT	250.00	?
52 REMOVE & REFIX 2PCS FENDER GLASS	1 UNIT	240.00	60
53 LABOUR CHARGE	1 UNIT	1,400.00	1100
54 SPRAY PAINTING	1 UNIT	1,500.00	1200
			3,630.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FOUR HUNDRED FIFTY EIGHT AND CENTS THIRTY FIVE ONLY

- No final modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount Before Excess SS 19,119.95

Add GST @ 7% 1,338.40

Total Amount payable SS 20,458.35

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

19/6/19
not Arthur
hkn
T. k. p. k. k. k.
priority
Excess 1100
cost price?

M/S: MSIG INSURANCE (SINGAPORE) PTE. LTD.
4 Shenton Way, #21-01
SGX Centre 2
Singapore 068807
TEL: 68277888 FAX: 68277800
ATTN: Motor Claim Department
Your Ref No: 19/MSIG/OD-302 (06)
Claim Type: Own Damage

Estimate No: EST0004897
Date: 17 Jun 2019
Policy No: A29071964QMY
Veh Reg No: SFF9993Y
Make/Model: HONDA ODYSSEY

Reg. Date: 13/02/2017

Estimate Repair Cost to Vehicle No :SFF9993Y

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Parts				
1 ✓ FRT WINDSCREEN		1 PC	1,950.00	—
2 ✓ FRT WINDSCREEN MOULDING		1 PC	55.00	—
3 ✓ FRT WINDSCREEN SIDE MOULDING -LH		1 PC	0.0000	—
4 ✓ FRT WIPER CORNER GARNISH -LH		1 PC	35.00	—
5 ✓ FRT WIPER GARNISH		1 PC	125.00	—
6 ✓ FRT BONNET		1 PC	480.00	—
7 FRT BONNET GARNISH		1 PC	70.00	X
8 ✓ FRT BONNET HINGE		2 PC	80.00	—
9 ✓ FRT BONNET INSULATOR		1 PC	65.00	—
10 ✓ FRT BONNET INSULATOR CLIP		8 PC	16.00	—
11 FRT GRILLE (TOP)		1 PC	180.00	X
12 FRT GRILLE CLIP		4 PC	8.00	X
13 FRT GRILLE CHROME -TOP (BIG)		1 PC	180.00	X
14 ✓ FRT BUMPER		1 PC	450.00	—
15 ✓ FRT BUMPER RETAINER		2 PC	24.00	—
16 ✓ FRT BUMPER CLIP		10 PC	20.00	—
17 ✓ FRT BUMPER REINFORCEMENT		1 PC	220.00	—
18 ✓ FRT BUMPER BEAM (BELOW HEADLAMP)		2 PC	70.00	1 PC 35
19 ✓ HEADLAMP		2 PC	3,000.00	—
20 HEADLAMP SUPPORT PANEL		1 PC	300.00	X
21 ✓ BATTERY COVER		1 PC	20.00	—
22 ✓ FRT FENDER		2 PC	720.00	—
23 ✓ FRT FENDER COWLING		2 PC	160.00	—
24 ✓ FRT FENDER COWLING CLIP		20 PC	40.00	—
25 ✓ FRT FENDER TOP GARNISH LH		1 PC	35.00	—
26 ✓ FRT FENDER GLASS LH		1 PC	300.00	—
27 ✓ FRT FENDER INNER REAR GARNISH LH		1 PC	40.00	—
28 ✓ WHEEL HOUSING PANEL LH		1 PC	680.00	—
29 ✓ WHEEL HOUSING PANEL JOINT LH		1 PC	0.0000	—
30 ✓ SIDE MIRROR COVER LH		1 PC	55.00	—
31 ✓ A' PILLAR LH		1 PC	620.00	—
32 RESONATOR BOX		1 PC	90.00	X
33 BATTERY BRACKET		1 PC	35.00	X
34 ✓ FRT FENDER TOP CHROME LH		2 PC	130.00	1 PC
35 ✓ FOG LAMP GARNISH RH		1 PC	55.00	—
36 AIR CLEANER BOX ASSY		1 PC	150.00	X
37 DASHBOARD		1 PC	650.00	X
38 ✓ SIDE MIRROR GLASS LH		1 PC	680.00	—
39 AIRCON CONDENSER		1 PC	480.00	X

10355

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST: 201119451E RCB NO: 201119451E

M/S : MSIG INSURANCE (SINGAPORE) PTE. LTD.
4 Shenton Way, #21-01
SGX Centre 2
Singapore 068807
TEL: 68277888 FAX: 68277800
ATTN: Motor Claim Department
Your Ref No: 19/MSIG/OD-302 (06)
Claim Type: Own Damage

Estimate No: EST0004897
Date: 17 Jun 2019
Policy No: A29071964QMY
Veh Reg No: SFF9993Y
Make/Model: HONDA ODYSSEY

Reg. Date: 13/02/2017

Estimate Repair Cost to Vehicle No :SFF9993Y

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 RADIATOR	11	1 PC	700.00	X
41 FRT DOOR OUTER MOULDING (CHROME) LH	321	1 PC	75.00	-
42 SUPPORT PANEL BRACKET	11	2 PC	70.00	X
	10		13,113.00	
	Add 15%		1,966.95	15,079.95

Special Net

43 FRT WINDSCREEN GUM	111	1 PC	60.00	40
44 ERP BRACKET	111	1 PC	25.00	20
45 FRT FENDER GLASS	111	2 PC	120.00	30
46 BATTERY	111	1 PC	180.00	100
47 RADIATOR COOLANT	111	1 PC	25.00	X
				410.00

Labour

48 WIRE CHECKING	1 UNIT	20.00	✓
49 REMOVE & REFIX AIRCON AND GAS	1 UNIT	100.00	✓
50 REMOVE & REFIX FRT WINDSCREEN	1 UNIT	120.00	✓
51 REMOVE & REFIX DASHBOARD	1 UNIT	250.00	✓
52 REMOVE & REFIX 2PCS FENDER GLASS	1 UNIT	240.00	60
53 LABOUR CHARGE	1 UNIT	1,400.00	1100
54 SPRAY PAINTING	1 UNIT	1,500.00	1200
			3,630.00

LEK Auto Consultants hence notify the Repairer of the following:
• To re-survey before/after spray painting
• To deliver damaged parts during re-survey
• Penalties are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification is allowed
• Supplementary items must be resurveyed and is subject to final approval from Insurance Company

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FOUR HUNDRED FIFTY EIGHT AND CENTS THIRTY FIVE ONLY

Acknowledged by Repairer
Signature:
Date:

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

2-10831
15%
2-11914-10
15-190-07
15-3070-00
15174.10

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST: 201119451E RCB NO: 201119451E

M/S : MSIG INSURANCE (SINGAPORE) PTE. LTD.

4 Shenton Way, #21-01

SGX Centre 2

Singapore 068807

TEL: 68277888

FAX: 68277800

ATTN: Motor Claim Department

Your Ref No: 19/MSIG/OD-302 (06)

Claim Type: Own Damage

Estimate No: EST0004897

Date: 16 Jul 2019

Policy No: A29071964QMY

Veh Reg No: SFF9993Y

Make/Model: HONDA ODYSSEY

Reg. Date: 13/02/2017

Estimate Repair Cost to Vehicle No :SFF9993Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
<u>Supplementary Parts to Repair</u>				
Parts				
1 LH HEADLAMP PANEL <i>bulb</i>		1 PC	35.00	<i>A</i>
2 FOG LAMP GARNISH LH <i>for</i>		1 PC	55.00	<i>A</i>
3 BATTERY TRAY <i>one</i>		1 PC	15.00	<i>A</i>
4 LH GEARBOX MOUNTING <i>to in</i>		1 PC	210.00	<i>A</i>
5 AIR HOSE <i>to in</i>		1 PC	60.00	<i>A</i>
6 WINDSCREEN MOULDING CLIPS <i>one</i>		4 PC	26.00	<i>A</i>
			401.00	
	Add 10%		40.10	441.10
Labour				
7 REMOVE & REFIX FRT LH UNDERCARRIAGE		1 UNIT	150.00	<i>120 A</i>
8 REMOVE & REFIX ENGINE MOUNTING		1 UNIT	60.00	<i>40 A</i>
9 WHEEL ALIGNMENT		1 UNIT	60.00	<i>✓ A</i>
				270.00
				<i>661.10</i>
			Amount Before Excess	S\$ 711.10
			GST Amount	S\$ 49.78
			Total Amount payable	S\$ 760.88

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
 DAIHATSU / KIA / SUZUKI / HONDA
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1886 FAX: 6291 7717
 Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE.6
 #02-15/16/17/18 AUTOBAY @KAKI BUKIT
 SINGAPORE 417883
 ODY
 GARY

NO: HLI9063576
 PAGE: 1
 DATE: 03/08/2019
 A/C CODE: LDSM446
 TERMS: CR
 P/O NO: SFF9993Y

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
Our D/O No: HDO9004809						
1	H74270-T6A-000	TOP COWL,LH	H2K45	1	35.00	4 35.00
2	H74210-T6A-000	TOP COWL,CTR	HU3-80	1	125.00	5 125.00
3	H60100-T6A-000ZZ	BONNET	HU3-16	1	480.00	6 480.00
4	H60120-T6A-000ZZ	BINNET HINGE RH	H2A30	1	40.00	8 40.00
5	H60170-T6A-000ZZ	BONNET HINGE LH	H2A3	1	40.00	8 40.00
6	H74141-T6A-000	BONNET INSULATOR	HU3-32	1	65.00	9 65.00
7	H04711-T6A-900ZZ	FR BUMPER	HU3-TOP6	1	450.00	14 450.00
8	H71130-T6A-300ZZ	FR.REINFORCEMENT(305ZZ)	HU3-32S-2	1	220.00	17 220.00
9	H33150-T6A-Q11	FR.HEADLAMP LH	HU3-40	1	1,500.00	17 1,500.00
10	H60210-T6A-300ZZ	FR.FENDER RH	HU3-27	1	360.00	22 360.00
11	H60260-T6A-300ZZ	FR.FENDER LH	HU3-48	1	360.00	22 360.00
12	H74100-T6A-000	FR.FDR.COWLING RH	HU3-53	1	80.00	23 80.00
13	H74150-T6A-000	FR.FDR.COWLING LH	HU3-50	1	80.00	23 80.00
14	H74206-T6A-000	FR.FDR.TOP GARN.LH	H2K1	1	35.00	25 35.00
15	H73370-T6A-013	FR.QTR.GLASS LH(003/315)	HU3-TOP3	1	300.00	26 300.00
16	H74155-T6A-000	FR.FDR.ENCLOSURE LH	H2J3	1	40.00	27 40.00
17	H76251-T6A-J01ZF	FR.MIRROR COVER LH	H2K54	1	55.00	30 55.00
18	H76258-T6A-Q01	FR.DR.MIRROR LH(Q02)	HU3-62S	1	680.00	38 680.00
19	H04645-T6A-300ZZ	FR.PILLAR PANEL LH	HU3017	1	620.00	31 620.00
20	H72450-T6A-003	FR.DR.OUT.MLDG LH	HDS	1	75.00	41 75.00
21	H71104-T6A-921	FR.FOG LAMP COVER RH	H2K50	1	55.00	52 55.00

Our D/O No: HDO9004811

Print / LSK / 3/8/2019 1:34:16 PM

Cont'd





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

NO: HLI9063576
PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
1	H71193-T6A-003	FR.SIDE RETAINER RH	1	12.00	15 12.00
2	H71198-T6A-003	FR.SIDE RETAINER LH	1	12.00	15 12.00
3	H71190-T6A-003	FR.BPR.BEAM LH	1	35.00	18 35.00
4	H33100-T6A-Q11	FR.HEADLAMP RH	1	1,500.00	19 1,500.00
5	H17252-5X6-J00	AIR TUBE	1	60.00	55 60.00
6	H60483-T6A-300ZZ	SUPPORT PANEL BRACKET LH	1	35.00	51 35.00
7	H50850-T6A-J01	GEAR BOX MTG LH	1	210.00	54 210.00
8	H31531-T6A-J00	BATTERY COVER	1	20.00	21 20.00
9	H31521-T6A-J00	BATTERY TRAY	1	15.00	53 15.00
10	H72465-T6A-003	FR.FDR.CORNER MLDG.LH	1	65.00	34 65.00
11	H71109-T6A-921	FR.FOG LAMP COVER LH	1	55.00	35 55.00
Our D/O No: HDO9004812					
1	H73163-T6A-003	FRONT W/S MOULDING LH	1	130.00	3 130.00
Our D/O No: HDO9004818					
1	H60750-T6A-320ZZ	FR.WHEELHOUSING LH	1	680.00	28 680.00
2	H60713-T6A-300ZZ	FR.W/HOUSE UP.MEMBER LH	1	250.00	29 250.00
Our D/O No: HDO9004825					
1	H91570-TA0-003	ROOF MOULDING CLIP	3	6.50	56 19.50
2	H91571-TA0-003	ROOF MOULDING CLIP	1	6.50	56 6.50
3	H73111-T6A-013	FRONT W/S	1	1,900.00	1 1,900.00
4	H73150-T6A-003	FR.W/S.MLDG.	1	55.00	2 55.00
5	H91501-S1K-003	INSULATOR CLIP	8	2.00	10 16.00
6	H91503-SZ3-003	CLIP BUMPER	10	2.00	16 20.00
7	H91501-TR0-003	CLIP COWLING	20	2.00	24 40.00
TOTAL QUANTITY:			79	TOTAL	SIN 10,831.00
				ADD GST @ 7%	758.17
				GRAND TOTAL	<u>SIN 11,589.17</u>

Print / LSK / 3/8/2019 1:34:18 PM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST: 201119451E RCB NO: 201119451E

M/S: MSIG INSURANCE (SINGAPORE) PTE. LTD.
 4 Shenton Way, #21-01
 SGX Centre 2
 Singapore 068807
 TEL: 68277888 FAX: 68277800
 ATTN: Motor Claim Department
 Your Ref No: 19/MSIG/OD-302 (06)
 Claim Type: Own Damage

Estimate No: EST0004897
 Date: 16 Jul 2019
 Policy No: A29071964QMY
 Veh Reg No: SFF9993Y
 Make/Model: HONDA ODYSSEY

Reg. Date: 13/02/2017

Estimate Repair Cost to Vehicle No :SFF9993Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
Parts				
1 LH HEADLAMP PANEL <i>3.5ml</i>		1 PC	35.00	✓
2 FOG LAMP GARNISH LH <i>5.5ml</i>		1 PC	55.00	✓
3 BATTERY TRAY <i>5.5ml</i>		1 PC	15.00	✓
4 LH GEARBOX MOUNTING <i>70.00</i>		1 PC	210.00	✓
5 AIR HOSE <i>70.00</i>		1 PC	60.00	✓
6 WINDSCREEN MOULDING CLIPS <i>6.00</i>		4 PC	26.00	✓
			401.00	
	Add 10%		40.10	441.10
Labour				
7 REMOVE & REFIX FRT LH UNDERCARRIAGE		1 UNIT	150.00	120
8 REMOVE & REFIX ENGINE MOUNTING		1 UNIT	60.00	40
9 WHEEL ALIGNMENT		1 UNIT	60.00	✓
				220
				220.00

Parts 10,831
 +10% 11,914.10
 SN 190
 LC 3070
 15,174.10

Amount Before Excess	S\$ 711.10
GST Amount	S\$ 49.78
Total Amount payable	S\$ 760.88

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

15/08/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019		18 Jun 2019 10:34 Edit Adj Rpt	\$515,174.10 Edit Estimates	\$515,174.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: CHUA CHUAN HOE , ID: S7524202F, Tel: +6591189993, Email: NOEMAIL									
Vehicle Reg. No.: SFF9993Y		Date of Loss: 13/06/2019 11:00 - :59 [28 Months From LTA Reg Date (Man Yr)]							
Claim Type: OD / 596733		Policy/Cover Note No.: A29071964QMY (Comprehensive) Coverage: 13/02/2019 - 12/02/2020							
Excess: S\$1,000.00									
Repairer: Sme Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15, 417883 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Soh Li Ping]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/07/2019]									
Driver/Custodian: CHUA CHUAN HOE (43 / Male), NRIC: S7524202F, Tel: +6591189993 Email: NOEMAIL									
Adj Asg. Remarks: Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (21/08/2019): Alert - Adj Mandate Approved (\$515174.10) - SFF9993Y - Claim Handler: Pauline So... - MSIG_SG (18/07/2019): Alert - Adj Mandate Approved (\$512461.35) - SFF9993Y - Claim Handler: Pauline So... - MSIG_SG (18/06/2019): Alert - Adj Mandate Approved (\$511800.25) - SFF9993Y - Claim Handler: Pauline So...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFF9993Y (596733)
OD
Jun 13 2019 11:00AM
[CHUA CHUAN HOE]
Sme Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Video						1 per page		☒	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)					Thumbnail	Print	
1	14/06/19 14:08	Video - Accident [Linked Accident Report Documents]					Load AVI		
Assessment Reports						1 per page		☒	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)					Thumbnail	Print	
1	14/06/19 14:24	Accident Statement					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	18/06/19 16:16	Adjuster Immediate Advice					Load HTM		
2	18/07/19 09:44	Adjuster Immediate Advice					Load HTM		
3	21/08/19 12:09	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	18/06/19 16:37	General View					Load JPG	☒	
2	18/06/19 16:37	General View					Load JPG	☒	
3	18/06/19 16:37	General View					Load JPG	☒	
4	18/06/19 16:37	General View					Load JPG	☒	
5	18/06/19 16:37	General View					Load JPG	☒	
6	18/06/19 16:37	General View					Load JPG	☒	
7	18/06/19 16:37	General View					Load JPG	☒	
8	18/06/19 16:37	General View					Load JPG	☒	
9	18/06/19 16:37	General View					Load JPG	☒	
10	18/06/19 16:37	General View					Load JPG	☒	
11	18/06/19 16:37	General View					Load JPG	☒	
12	18/06/19 16:37	General View					Load JPG	☒	
13	18/06/19 16:37	General View					Load JPG	☒	
14	18/06/19 16:37	General View					Load JPG	☒	
15	18/06/19 16:37	General View					Load JPG	☒	
16	18/06/19 16:37	General View					Load JPG	☒	
17	18/06/19 16:37	General View					Load JPG	☒	
18	18/06/19 16:37	General View					Load JPG	☒	
19	18/06/19 16:37	General View					Load JPG	☒	
20	18/06/19 16:37	General View					Load JPG	☒	
21	18/06/19 16:37	General View					Load JPG	☒	
22	18/06/19 16:37	General View					Load JPG	☒	
23	18/06/19 16:37	General View					Load JPG	☒	
24	18/06/19 16:37	General View					Load JPG	☒	
25	18/06/19 16:37	General View					Load JPG	☒	
26	18/06/19 16:37	General View					Load JPG	☒	
27	18/06/19 16:37	General View					Load JPG	☒	
28	18/06/19 16:37	General View					Load JPG	☒	

Video			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
29	18/06/19 16:37	General View	 Load JPG	☒
30	18/06/19 16:37	General View	 Load JPG	☒
31	18/06/19 16:37	General View	 Load JPG	☒
32	18/06/19 16:37	General View	 Load JPG	☒
33	18/06/19 16:37	General View	 Load JPG	☒
34	18/06/19 16:37	General View	 Load JPG	☒
35	18/06/19 16:37	General View	 Load JPG	☒
36	18/06/19 16:37	General View	 Load JPG	☒
37	18/06/19 16:37	General View	 Load JPG	☒
38	18/06/19 16:37	General View	 Load JPG	☒
39	18/06/19 16:37	General View	 Load JPG	☒
40	18/06/19 16:37	General View	 Load JPG	☒
41	18/06/19 16:37	General View	 Load JPG	☒
42	18/06/19 16:37	General View	 Load JPG	☒
43	18/06/19 16:37	General View	 Load JPG	☒
44	18/06/19 16:37	General View	 Load JPG	☒
45	18/06/19 16:37	General View	 Load JPG	☒
46	18/06/19 16:37	General View	 Load JPG	☒
47	18/06/19 16:37	General View	 Load JPG	☒
48	18/06/19 16:37	General View	 Load JPG	☒
49	18/06/19 16:37	General View	 Load JPG	☒
50	18/06/19 16:37	General View	 Load JPG	☒
51	18/06/19 16:37	General View	 Load JPG	☒
52	18/06/19 16:37	General View	 Load JPG	☒
53	18/06/19 16:37	General View	 Load JPG	☒
54	18/06/19 16:37	General View	 Load JPG	☒
55	18/06/19 16:37	General View	 Load JPG	☒
56	18/06/19 16:37	General View	 Load JPG	☒
57	18/06/19 16:37	General View	 Load JPG	☒
58	18/06/19 16:37	General View	 Load JPG	☒
59	18/06/19 16:37	General View	 Load JPG	☒
60	18/06/19 16:37	General View	 Load JPG	☒
61	18/06/19 16:37	General View	 Load JPG	☒
62	18/06/19 16:37	General View	 Load JPG	☒
63	18/06/19 16:37	General View	 Load JPG	☒
64	18/06/19 16:37	General View	 Load JPG	☒
65	18/06/19 16:37	General View	 Load JPG	☒
66	18/06/19 16:37	General View	 Load JPG	☒
67	18/06/19 16:37	General View	 Load JPG	☒
68	18/06/19 16:37	General View	 Load JPG	☒
69	18/06/19 16:37	General View	 Load JPG	☒
70	18/06/19 16:37	General View	 Load JPG	☒
71	18/06/19 16:37	General View	 Load JPG	☒
72	18/06/19 16:37	General View	 Load JPG	☒
73	18/06/19 16:37	General View	 Load JPG	☒
74	18/06/19 16:37	General View	 Load JPG	☒
75	18/06/19 16:37	General View	Load JPG	☒
76	18/06/19 16:37	General View	Load JPG	☒
77	18/06/19 16:37	General View	Load JPG	☒
78	18/06/19 16:37	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
79	18/06/19 16:37	General View	 Load JPG	☒
80	18/06/19 16:37	General View	 Load JPG	☒
81	18/06/19 16:37	General View	 Load JPG	☒
82	18/06/19 16:37	General View	 Load JPG	☒
83	18/06/19 16:37	General View	 Load JPG	☒
84	18/06/19 16:37	General View	 Load JPG	☒
85	18/06/19 16:37	General View	 Load JPG	☒
86	18/06/19 16:37	General View	 Load JPG	☒
87	18/06/19 16:37	General View	 Load JPG	☒
88	18/06/19 16:37	General View	 Load JPG	☒
89	18/06/19 16:37	General View	 Load JPG	☒
90	18/06/19 16:37	General View	 Load JPG	☒
91	18/06/19 16:37	General View	 Load JPG	☒
92	18/06/19 16:37	General View	 Load JPG	☒
93	18/06/19 16:37	General View	 Load JPG	☒
94	18/06/19 16:37	General View	 Load JPG	☒
95	18/06/19 16:37	General View	 Load JPG	☒
96	18/06/19 16:37	General View	 Load JPG	☒
97	18/06/19 16:37	General View	 Load JPG	☒
98	18/06/19 16:37	General View	 Load JPG	☒
99	18/06/19 16:37	General View	 Load JPG	☒
100	18/06/19 16:37	General View	 Load JPG	☒
101	18/06/19 16:37	General View	 Load JPG	☒
102	18/06/19 16:37	General View	 Load JPG	☒
103	18/06/19 16:37	General View	 Load JPG	☒
104	18/06/19 16:37	General View	 Load JPG	☒
105	18/06/19 16:37	General View	 Load JPG	☒
106	18/06/19 16:37	General View	 Load JPG	☒
107	18/06/19 16:37	General View	 Load JPG	☒
108	18/06/19 16:37	General View	 Load JPG	☒
109	18/06/19 16:37	General View	 Load JPG	☒
110	18/06/19 16:37	General View	 Load JPG	☒
111	18/06/19 16:37	General View	 Load JPG	☒
112	18/06/19 16:37	General View	 Load JPG	☒
113	18/06/19 16:37	General View	 Load JPG	☒
114	18/06/19 16:37	Odometer Reading	 Load JPG	☒
115	18/06/19 16:38	Chassis Number	 Load JPG	☒
116	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
117	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
118	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
119	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
120	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
121	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
122	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
123	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
124	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
125	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
126	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
127	24/06/19 17:45	Reinspection Photo	 Load JPG	☒
128	24/06/19 17:45	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
129	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
130	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
131	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
132	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
133	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
134	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
135	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
136	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
137	17/07/19 17:03	Reinspection Photo	 Load JPG	☒
138	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
139	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
140	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
141	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
142	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
143	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
144	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
145	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
146	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
147	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
148	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
149	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
150	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
151	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
152	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
153	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
154	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
155	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
156	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
157	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
158	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
159	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
160	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
161	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
162	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
163	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
164	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
165	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
166	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
167	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
168	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
169	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
170	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
171	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
172	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
173	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
174	18/07/19 07:58	Reinspection Photo	 Load JPG	☒
175	18/07/19 07:58	Reinspection Photo	Load JPG	☒
176	18/07/19 07:58	Reinspection Photo	Load JPG	☒
177	18/07/19 07:58	Reinspection Photo	Load JPG	☒
178	18/07/19 07:58	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
179	18/07/19 07:58	Reinspection Photo		☒
180	18/07/19 07:58	Reinspection Photo		☒
181	18/07/19 07:58	Reinspection Photo		☒
182	18/07/19 07:58	Reinspection Photo		☒
183	18/07/19 07:58	Reinspection Photo		☒
184	18/07/19 07:58	Reinspection Photo		☒
185	18/07/19 07:58	Reinspection Photo		☒
186	18/07/19 07:58	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/06/19 17:18	Estimate + IC + DL + CI		☒
2	17/06/19 17:19	PARF/COE Rebate		☒
3	17/06/19 17:19	Vehicle Transfer Fee		☒
4	17/06/19 17:21	Singapore Accident Statement - SJV6910A		☒
5	17/06/19 17:21	Singapore Accident Statement - YN2489R		☒
6	17/06/19 17:21	Singapore Accident Statement - SLA2344Y		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/19 16:17	ESTIMATE.pdf		☒
2	18/07/19 09:38	SUPP.pdf		☒
3	21/08/19 12:05	ESTIMATE & SUPP MARKED.pdf		☒
4	05/09/19 09:33	Parts Invoice		☒

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	14/06/19 14:08	Video - Accident		☒
Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	04/09/19 01:31	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	14/06/19 14:20	Accident Photo		☒
2	14/06/19 14:20	Accident Photo		☒
3	14/06/19 14:20	Accident Photo		☒
4	14/06/19 14:20	Accident Photo		☒
5	14/06/19 14:20	Accident Photo		☒
6	14/06/19 14:20	Accident Photo		☒
7	14/06/19 14:20	Accident Photo		☒
8	14/06/19 14:20	Accident Photo		☒
9	14/06/19 14:20	Accident Photo		☒
10	14/06/19 14:20	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	14/06/19 14:08	Sketch Plan		☒
2	14/06/19 14:08	Sketch Plan #2		☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19010740/USD3E2

Date: 05/09/2019

REFERENCE

Insured/Claimant:	CHUA CHUAN HOE	Policy No:	A29071964QMY	Claim No:	596733
Date of Loss:	13/06/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF9993Y	Engine No:	K24W72013712
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Chassis No:	JHMRC1890GC209093
Reg. Date:	13/02/2017 (Man. Year: 2016)	Odometer:	51611 km
Colour:	White		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,388.10	12,104.10	4,284.00	26.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	3,070.00	830.00	21.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,288.10	15,174.10	5,114.00	25.21
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	19,288.10	14,174.10	5,114.00	26.51
+ GST 7.00/7.00% (S\$)	1,350.17	992.19	357.98	26.51
Nett Amount (S\$)	20,638.27	15,166.29	5,471.98	26.51

INSPECTION

Date of Assignment:	18/06/2019	Inspected At:	Sme Motor Pte Ltd (HQ)
Date Inspected:	18/06/2019		1 KAKI BUKIT AVE6, #02-15
			Singapore 417883
Estimated Period of Repair:	8.0 days		

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2019)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFF9993Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT WINDSCREEN (WCP)	Cracked	1,950.00 F	*1,900.00 F
2	1		*FRT WINDSCREEN MOULDING (WCP)	Necessary	55.00 F	*55.00 F
3	1		*FRT WINDSCREEN SIDE MOULDING - LH (WCP)	Cut	130.00 F	*130.00 F
4	1		*FRT WIPER CORNER GARNISH - LH (WCP)	Deformed	35.00 F	*35.00 F
5	1		*FRT WIPER GARNISH (WCP)	Deformed / Warped	125.00 F	*125.00 F
6	1		*FRT BONNET (WCP)	Buckled	480.00 F	*480.00 F
7	1		*FRT BONNET GARNISH (WCP)	Not Necessary	70.00 F	*- F
8	2		*FRT BONNET HINGE (WCP)	Bent	80.00 F	*80.00 F
9	1		*FRT BONNET INSULATOR (WCP)	Torn	65.00 F	*65.00 F
10	8		*FRT BONNET INSULATOR CLIP (WCP)	Necessary	16.00 F	*16.00 F
11	1		*FRT GRILLE (TOP) (WCP)	Not Necessary	180.00 F	*- F
12	4		*FRT GRILLE CLIP (WCP)	Not Necessary	8.00 F	*- F
13	1		*FRT GRILLE CHROME - TOP (BIG) (WCP)	Not Necessary	180.00 F	*- F
14	1		*FRT BUMPER (WCP)	Distorted	450.00 F	*450.00 F
15	2		*FRT BUMPER RETAINER (WCP)	Bent	24.00 F	*24.00 F
16	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
17	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	220.00 F	*220.00 F
18	1		*FRT BUMPER BEAM (BELOW HEADLAMP) (WCP)	N/S Cracked	70.00 F	*35.00 F
19	2		*HEADLAMP (WCP)	Cracked	3,000.00 F	*3,000.00 F
20	1		*HEADLAMP SUPPORT PANEL (WCP)	Repair	300.00 F	*- F
21	1		*BATTERY COVER (WCP)	Cracked	20.00 F	*20.00 F
22	2		*FRT FENDER (WCP)	Bent / Buckled	720.00 F	*720.00 F
23	2		*FRT FENDER COWLING (WCP)	Torn	160.00 F	*160.00 F
24	20			Necessary	40.00 F	*40.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRT FENDER COWLING CLIP (WCP)			
25	1		*FRT FENDER TOP GARNISH LH (WCP)	Torn	35.00 F	*35.00 F
26	1		*FRT FENDER GLASS LH (WCP)	Broken	300.00 F	*300.00 F
27	1		*FRT FENDER INNER REAR GARNISH LH (WCP)	Cut	40.00 F	*40.00 F
28	1		*WHEEL HOUSING PANEL LH (WCP)	Badly Dented	680.00 F	*680.00 F
29	1		*WHEEL HOUSING PANEL JOINT LH (WCP)	Badly Dented	250.00 F	*250.00 F
30	1		*SIDE MIRROR COVER LH (WCP)	Missing	55.00 F	*55.00 F
31	1		*A PILLAR LH (WCP)	Badly Dented	620.00 F	*620.00 F
32	1		*RESONATOR BOX (WCP)	Not Necessary	90.00 F	*- F
33	1		*BATTERY BRACKET (WCP)	Not Necessary	35.00 F	*- F
34	1		*FRT FENDER TOP CHROME (WCP)	N/S Cut	130.00 F	*65.00 F
35	1		*FOG LAMP GARNISH RH (WCP)	Cut	55.00 F	*55.00 F
36	1		*AIR CLEANER BOX ASSY (WCP)	Not Necessary	150.00 F	*- F
37	1		*DASHBOARD (WCP)	Not Necessary	650.00 F	*- F
38	1		*SIDE MIRROR GLASS LH (WCP)	Cracked	680.00 F	*680.00 F
39	1		*AIRCON CONDENSER (WCP)	Not Necessary	480.00 F	*- F
40	1		*RADIATOR (WCP)	Not Necessary	700.00 F	*- F
41	1		*FRT DOOR OUTER MOULDING (CHROME) LH (WCP)	Bent	75.00 F	*75.00 F
42	2		*SUPPORT PANEL BRACKET (WCP)	Not Necessary	70.00 F	*- F
43	1		*FRT WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
44	1		*ERP BRACKET	Necessary	25.00 FS	*20.00 FS
45	2		*FRT FENDER GLASS SEALANT	Necessary	120.00 FS	*30.00 FS
46	1		*BATTERY	Dented	180.00 FS	*100.00 FS
47	1		*RADIATOR COOLANT	Not Necessary	25.00 FS	*- FS
48	1		*LH HEADLAMP PANEL (WCP)	Bent	35.00 F	*35.00 F
49	1		*FOG LAMP GARNISH LH (WCP)	Scratched	55.00 F	*55.00 F
50	1		*BATTERY TRAY (WCP)	Cracked	15.00 F	*15.00 F
51	1		*LH GEARBOX MOUNTING (WCP)	Torn	210.00 F	*210.00 F
52	1		*AIR HOSE (WCP)	Torn	60.00 F	*60.00 F
53	4		*WINDSCREEN MOULDING CLIPS (WCP)	Cracked	26.00 F	*26.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	14,304.00	11,021.00
+ Margin on L,N Items 15.00/10.00% (\$\$)	2,084.10	1,083.10
Total Parts (\$\$)	16,388.10	12,104.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	20.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX FRT WINDSCREEN	New	120.00	120.00
4	REMOVE & REFIX DASHBOARD	New	250.00	250.00
5	REMOVE & REFIX 2PCS FENDER GLASS	New	240.00	60.00
6	LABOUR CHARGE	New	1,400.00	1,100.00
7	SPRAY PAINTING	New	1,500.00	1,200.00
8	REMOVE & REFIX FRT LH UNDERCARRIAGE	New	150.00	120.00
9	REMOVE & REFIX ENGINE MOUNTING	New	60.00	40.00
10	WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (S\$)			3,900.00	3,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >