

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 26 May 2020

Preliminary Advice

Vehicle No	: SDK6776A	Accident Date	: 30/05/2019
Make	: FORD MUSTANG	Policy No.	: 28824089QMY
Assignment Date	: 18/06/2019	Excess	: S\$1,500.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 8.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,446.00	
Revised Amount	:S\$	19,050.00	(INCLUSIVE OF CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	19,050.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	83,242.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,758.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON CHECK ITEMS.