

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. ANG SENG HOCK JONATHAN
BLK 183 BISHAN STREET 13 #16-299
S 570183Attention : Motor Claim Department
Contact : 91542209

Estimate : ES000951

Date : 17/06/2019
Vehicle Num. : SLZ 6729M
Make/Model : HONDA CIVIC 1.8 LA
Chassis/Eng# :
Accident Date : 14/06/2019
Claim No. :
Reference :
Policy No. :TPA 19
VIC

JHMF01630AS200135

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	TRUNKLID <i>Dented</i>		830.00 <i>683</i>
2.	1 PC	TRUNKLID LOCK <i>Dented</i>		97.10 ✓
3.	1 PC	TRUNKLID LOGO <i>all</i>		36.40 ✓
4.	2 PCS	REAR LAMPS <i>cracked</i>	404.80	809.60 <i>560.8</i>
5.	1 PC	REAR BUMPER <i>Dented</i>		901.20 <i>38</i>
6.	2 PCS	REAR BUMPER SIDE RETAINER <i>new</i>	23.20	46.40 ✓
7.	2 PCS	REAR BUMPER BRACKET <i>new</i>	20.50	41.00 ✓
8.	1 PC	REAR END PANEL <i>Dented</i>		469.50 <i>316.60</i>
9.	1 PC	REAR END PANEL TOP GARNISH <i>Dented</i>		87.50 ✓
10.	1 PC	REAR SPARE TYRE PANEL <i>new</i>		1,058.80 ✓
11.	8 PCS	REAR BUMPER CLIPS <i>new</i>	3.50	28.00 ✓
12.	2 PCS	TRUNKLID HINGES <i>new</i>	195.00	390.00 ✓
13.	2 PCS	TRUNKLID REFLECTOR <i>cracked</i>	408.40	816.80 <i>404.1</i>
14.	1 PC	TRUNKLID WEATHERSTRIP <i>new</i>		97.40 ✓
15.	1 PC	TRUNKLID CIVIC EMBLEM <i>new</i>		28.80 ✓
16.	1 PC	TRUNKLID I-VTEC EMBLEM <i>new</i>		33.70 ✓
17.	1 PC	TRUNKLID 1.8 EMBLEM <i>new</i>		25.40 ✓
		<i>Spare Tyre Panel Top Cover</i> <i>new</i>		
		List Total S\$:		5,797.60
		20.00% Discount S\$:		1,159.52
		<i>2 PCS Tailor Panel</i> <i>Dented</i> <i>194.3</i>		4,638.08
1.	1 SET	SPECIAL NETT ITEMS : REAR BUMPER SENSOR <i>Dented</i>		250.00 <i>200</i>

CONTINUE / ...

3793.90

3035.12

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. ANG SENG HOCK JONATHAN
BLK 183 BISHAN STREET 13 #16-299
S 570183

Attention : Motor Claim Department

Contact : 91542209

Estimate : ES000951

Date : 17/06/2019

Vehicle Num. : SLZ 6729M

Make/Model : HONDA CIVIC 1.8 LA

Chassis/Eng# :

Accident Date : 14/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1 PC	REAR NUMBER PLATE		20.00
3.	1 PC	REAR NUMBER PLATE HOLDER		25.00
Special Nett Total S\$:				295.00
LABOUR :				
KNOCKING, CUTTING, JACKING WELDING ETC				1,800.00
SPRAY PAINTING				1,600.00
TO CHECK WIRING AND SYSTEM FUNCTION				120.00
TO APPLY RUST-PROOFING ON AFFECTED AREA				200.00
REMOVE & REFIX FENDER INNER TRIM FOR FACILIATER REPAIR				500.00
Labour Total S\$:				4,220.00
To remove reverse sensor				50.00

Total S\$: 9,153.08

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

blkl: SLZ 6729M
4/5: 4150

06 Days