

REF:

REF:

NSI INC 19010748/ NSd302

Apprval:

NAR

Inc

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: 563 68279

Policy No. 510779016 (22/02/2019-21/02/2020)

Claims No. MT/1049479-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bol. or Market Value: XXXX

IVAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHD 3445P Yr Regn: 29 SEP 2016

Type: M.Car / M.Cycle / BUS / Van / Lorry (Taxi) Prime Mover /

Truck / Tractor or

Make: HYUNDAI 140 c.c. 1,65

Colour BLUE A/C: Insured / Std / Nil / NA

Sp. Reading 329,261 T/Radio: Insured / Std / Nil / NA

Eng/Ho: \_\_\_\_\_

C/No: KM1XLB41UMG4093671

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modl: Nil / SIRIm / STD / ARIm or

Tyre Siz: F: 205/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE (F), HANKOOK (R)

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bol. 6 mm R/Bol. 5 mm

L/Bol. 6 mm L/Bol. 5 mm

D.O.A. 16/6/19 U.O.A. 17/6/19

Survey held at CDK LYANKE

Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

SHD 3445P - (C3/CAI15013437/H1134392)

DOA - 05/08/2015

SGJ 68279 - NSI INC 19009961 / K19 d3

DOA - 02/06/2019

17/7/19 Estmt 4/5 \$4000 4 Days. (On Behalf)  
( \$ 7,040.74 Rep - 62% )

RECEIVED 22 JUL 2019

19/7/2019

Date/Time, File Pass to?

22/07/19

1) Type

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format:

Lump Sum / I.B.I. (\$) 4,400/- 4/5

☐ : Prelim Report

☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee: 160

Transportation:

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) S + HS \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_) Photos \_\_\_\_\_

☐ : Tech. Invo (\$ \_\_\_\_\_) \_\_\_\_\_

☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

160

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No.(For Motor)  Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5107701016		TAN KIM YEOW	S1523348F	GPC	drivo CLASSIC	SGJ6827G	SGJ6827G	22/02/2019	21/02/2020

Date/Time: 17.06.2019 09:12

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3930511

JC NO.: 305303847

OMER  
S COMFORT TRANSPORTATION PTE LTD  
OMER NO. 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)  
JUNT CARD NO.


REGN NO.: SHD3445P	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 16.06.2019 09:35
YR OF MANU. 29.09.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU093671	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 16.06.2019  
NATURE: 3P 16.06.19/B

NTUC

S/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip		Exit Pass	
No.: SHD3445P	FZ NTUC	Vehicle No.: SHD3445P	
Signature/Date	Name of Service Advisor	Date	
turned to Service Reception upon collection		To be kept by Security Guard	

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1051903-002	SMRT TAXIS PTE LTD	SHB 5685K	FBM 6006C	03/07/2019	22:30	\$ 4,933.18	\$ 2,535.59
2	MT/1049479-002	COMFORT TRANSPORTATION PTE LTD	SHD 3445P	SGJ 6827G	16/06/2019	00:50	\$ 11,440.74	\$ 4,400.00

Claim received from LKK Auto

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/06/2019 07:40
Date Of Accident	16/06/2019 00:50
Exact Location Of Accident	BRADDELL RD TURNING BISHAN RD.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3445P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	SOON KIAN TORN
NRIC No	S1181829C
Date Of Birth	10/10/1956
Occupation	OUTDOOR
Date Of Driving Pass	24/11/1984
Driving Experience	34 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98434536
Fax Number	
Contact Number	
EMail Address	SOONKIAN TORN@HOTMAIL.COM

Address	184 08-309.BISHAN STREET 13
Postcode	570184
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE ATTACH.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ6827G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KIM YEOW
NRIC/Passport Number	S1523348F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/6/2019 at about 0050 hrs, I vehicle A was driving, my taxi along braddell road turning into Bishan Road. traffic light and stop at the junction A few second later vehicle B came from behind Collected onto vehicle A rear portion. no one was injured at that time

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CO REG NO 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

16/6/19  
Jackson Her.  
CSO


Reporting Centre Personnel's Signature  
Name:

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:



- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.









ME (U) TRANSPORTATION PTE LTD  
 Policyholder's Signature:   
 Date & Time: \_\_\_\_\_  
 CO REG. NO. 199303821R Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: \_\_\_\_\_

16/6/19  
 Jackson Heng  
 CSO





Reporting Centre Personnel's Signature  
 Name: \_\_\_\_\_  
 NRIC/FIN No.: \_\_\_\_\_











## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHD 3445P

DATE 17/6/2019 10:45

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 2,174.90
	Boot Lid Lock Upper			\$ 102.60
	Boot Lid Lock Lower			\$ 31.70
	Boot Lid 'H' Emblem			\$ 28.70
	Boot Lid CRDI Plate			\$ 27.90
	Bootlid Moulding			\$ 85.00
	Bootlid i40 Emblem			\$ 27.90
	Bootlid Lower Garnish			\$ 227.90
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Sponge			\$ 103.50
	Rear Bumper Under Cover			\$ 228.00
	Rear Bumper Reflector Lamp, RH			\$ 30.60
	Rear Panel			\$ 526.70
	Rear Panel Garnish			\$ 57.70
	Rear Panel Lower Panel			\$ 89.40
	Rear Fender (LH/RH)		\$ 2,171.40	\$ 4,342.80
	Rear Windscreen Moulding			\$ 28.30
	<b>SUB TOTAL</b>			<b>\$ 9,348.80</b>
	<b>LESS 20%</b>			<b>\$ 1,869.76</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 7,479.04</b>
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant			\$ 46.00
				<b>\$ 511.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,800.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 80.00
	<b>TOTAL LABOUR</b>			<b>\$ 3,450.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 11,440.74</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NTUC / REAR

(FZ)

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUB TOTAL

LESS 20%

DISCOUNTED TOTAL

Boot Lid Comfort Logo &amp; Tel No. Sticker

Rear Bumper Reverse Sensor

Rear Bumper Rubber Mat

Rear Bumper Advertisement Logo

Rear Fender Advertisement Logo (LH/RH)

Rear Windscreen Sealant

**Labour Charge**

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Kote

Remove/Refix Cushion &amp; Upholstery Rear

Remove/Refix Rear Windscreen Glass

Remove/Refix Reverse Sensor

**TOTAL LABOUR****ESTIMATE TOTAL**

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305303847  
Date : 24.06.2019

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM


To : LKK  
Attn : NAZ  
Vehicle Reg No. : SHD3445P  
Date of Accident : 16.06.2019


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SGJ6827G
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$0.00
  - (b) Labour Charges \$0.00
  - Total for Part-By-Part Repair Cost \$0.00
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$4,400.00  
Final Lumpsum Repair cost \$4,400.00

3. Estimated normal period for repairs: 4 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :   
Name : FAUZY BIN MOKHTAR  
Tel : 62148319  
Fax : 65468156

Signature :   
Name : Kaim (on Behalf Naz)  
Date : 17/7/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19010748/Nsd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 08-08-2019	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGJ 6827G	Veh. Inspected	SHD 3445P	
Policy No.	5107701016	Coverage (\$)	0.00	
Claim No.	MT/1049479-002	Excess (\$)	0.00	
Assign From		Assign Date	17/06/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093671	Colour	BLUE	
Odometer	329261	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/06/2019	Inspection Date	17/06/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3445P**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOT LID	BUCKLED	2,174.90	2,174.90
1	BOOT LID LOCK UPPER	JAMMED	102.60	102.60
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	SERVICEABLE	27.90	-
1	BOOTLID LOWER GARNISH	TO REPAIR SEE LABOUR	227.90	-
1	REAR BUMPER	CRACKED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	BENT	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	BENT	160.60	160.60
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	CRACKED	71.20	71.20
1	REAR BUMPER SPONGE	CRACKED	103.50	103.50
1	REAR BUMPER UNDER COVER	CRACKED	228.00	228.00
1	REAR BUMPER REFLECTOR LAMP, RH	SERVICEABLE	30.60	-
1	REAR PANEL	DEFORMED	526.70	526.70
1	REAR PANEL GARNISH	SERVICEABLE	57.70	-
1	REAR PANEL LOWER PANEL	TO REPAIR SEE LABOUR	89.40	-
2	REAR FENDER (LH/RH) @\$2171.40	TO REPAIR SEE LABOUR	4,342.80	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	28.30	-
	LESS 20% DISCOUNT		-1,869.76	-885.50
			<b>7,479.04</b>	<b>3,542.00</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00

Report Ref No. NS/INC19010748/Nsd3e2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			511.70	465.70
	<b>LABOUR</b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER, BOOTLID LOWER GARNISH, REAR PANEL LOWER PANEL AND REAR FENDER (LH/RH).		1,800.00	600.00
	SPRAY PAINTING CHARGE.		1,200.00	800.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	NOT NECESSARY	150.00	-
	REMOVE / REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			3,450.00	1,500.00
<b>GRAND TOTAL</b>			<b>11,440.74</b>	<b>5,507.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>4,400.00</b>

Report Ref No. NS/INC19010748/Nsd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.