

INSURANCE

INS. CASE OWNER:

Peter

CC 4/ASA 1901 0753, 11/9/2019

LKK:

IDAC:

Surveyor:

Taufik

DOI:

ASSIGNMENT

8/11/19

Date / Time:

18/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

EW 3633 Z

Name of Insured:

YEN HAN KIONG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

12/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: YEN YEE LM

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S 1mo 2006 (120069)

Policy No.:

GA 15154

Make / Model:

MERLEDES

Place of Accident:

LIE MONTI HUS 9.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGB 62994



INSRS:

WSP:

Tel:

Liability:

RMKS:

moon meny



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE/ PIC
19/6	CAV OI, aware to claim & NCD issue, agreed to settle - Email LOR & Liability clearance email to TP. (Pending driver)	Non-Reporting Itr (1st):	
11/7	Pending finalized of final est.	Non-Reporting Itr (2nd):	
10/10	Rec LOR to TP (Pending LOD)	Non-Reporting Itr (Final):	
14/2	LOD in, to CTE mandate.	Notification Itr (if non-pickup):	
20/2	Pending mandate approval	Call OI:	7 CPL 19/6/19
20/2	offer offer \$4500 (Pending acceptance)	After call Itr to OI:	
20/2	TP reject offer, propose \$4500 (not opt) for LOR. CTE HRA instruction.	Documentation Check List: Handler Typist	
26/2	offer offer \$4500 (Pending acceptance)	Notification Itr (if non-pickup):	☒
27/2	offer offer \$4500, DV send (Pending DV)	After call Itr to OI:	☒
27/2	DV in, Pending LOR.	Authorisation To Act:	☒
	LOA in, file pass ME to close.	Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time: 10/10/19 / 12:00PM - Confirm with: MS HONG		Confirm by: TAUFIK	
Repair Cost: LG	SS 2900.00	(4 days) Reduction: \$500.00	by
FINAL SETTLEMENT Date/Time: 20/2/2020 Confirm with: MS HONG		Email ☒ Call ☒	
Final Liability:	SS 100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost: (W/MS)	SS 4177.00	If NO or B 28, Ass. Lia:	
Loss of Rental (LOR):	SS 449.40	OI rear ended TP.	
Loss of Use (LOU):	SS -	(3 days) x \$149.80	(W/MS)
Loss of Income (LOI):	SS -	(5 x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search:	SS 3.00	1) Claim status: Normal/Reject/Private Settle	
Medical:	SS -	2) Report Format: TP	
Disbursement:	SS -	(i.e. Tow/ Independent)	
Legal Cost:	SS -	3) Survey fee: \$250.	
Total:	SS 4624.40	Global Sum SS: 4620.00	
FINAL PAYMENT Date/Time:		Confirm with: Email ☒ Call ☒	
Payee 1:	SS 4620.00	Name 1:	MOON MENY MOTOR Pte Ltd
Payee 2 (Strike if N.A.)	SS -	Name 2:	/
Payee 3 (Strike if N.A.)	SS -	Name 3:	

COPY SENT 4/3/2020

AXA

9

①

Woon Meng.



#89K

4

20

Which is better

SGB 62994

2015 Oct.

①

Toyota Harrier

1982

white

113998.

254 600038197.

①

②

③

④

255/55R18

①

INSURANCE (GUYANA) LTD. (GUYANA) LTD. (GUYANA) LTD.

TOYOTA

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Form

Woon Meng Bkt Bkt

4s \$3900/- (red = \$5200.23/57%)

Car Type (Car/Truck)

☐ First Report
☐ Final Report

Days Of Repair

Resurvey No. of Trip

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

☐ First Report
☐ Final Report

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

Car Type

SG 284 Maxima

Woon Meng Motor Pte Ltd

Office 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungai Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng@singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP Claim

To : AXA Insurance Singapore Pte Ltd
Motor Claims Dept

Date : 08 Jul 2019

Dear Sirs :

Fax : 68804838

RE : ESTIMATE COST FOR TOYOTA HARRIER ZSU60 2.0 - SGB6299Y
ACCIDENT INVOLVING SGB6299Y AND EW3633Z ON 13.06.2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 1,385.60 <i>de</i>
2	Rear bumper retainer @\$85.7ea	1pc	\$ 171.40 <i>Xun</i>
3	Rear bumper spoiler	1pc	171.40
4	Rear bootlid	1pc	\$ 2,378.60 <i>bt</i>
5	Rear bootlid absorber @\$1431.6ea.	2pcs	\$ 2,863.20 <i>run</i>
6	Rear bootlid hinge @\$87.2ea	2pcs	\$ 174.40 <i>run</i>
7	Rear bootlid lock	1pc	\$ 974.80 <i>Xun</i>
8	Emblem.	1pc	\$ 75.60 <i>u</i>
9	Harrier	1pc	\$ 78.90 <i>u</i>
10	Oseko toyopet	1pc	445.00
12	Rear rubber	1pc	\$ 445.00 <i>Xun</i>
13	Rear end panel.	1pc	\$ 892.80 <i>692 H</i>
			\$ 9,440.30
			\$ (2,360.07)
			\$ 7,080.23
Sum Carried Forward			

Less 25%

4610.70
3458.02.

Ceci

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP Claim

To : AXA Insurance Singapore Pte Ltd
Motor Claims Dept

Date : 08 Jul 2019

Dear Sirs :

Fax : 68804838

RE : ESTIMATE COST FOR TOYOTA HARRIER ZSU60 2.0 - SGB6299Y
ACCIDENT INVOLVING SGB6299Y AND EW3633Z ON 13.06.2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>	
1	Rear bumper	1pc	\$ 1,385.60	de
2	Rear bumper retainer @\$85.7ea	1pc	\$ 171.40	Xun
3	Rear bumper spoiler	1pc		
4	Rear bootlid	1pc	\$ 2,378.60	bt
5	Rear bootlid sbsober @\$1431.6ea.	2pcs	\$ 2,863.20	xun
6	Rear bootlid hinge @\$87.2ea	2pcs	\$ 174.40	xun
7	Rear bootlid lock	1pc	\$ 974.80	Xun
8	Emblem.	1pc	\$ 75.60	we
9	Harrier	1pc	\$ 78.90	we
10	Osaka/toyopet	1pc		
12	Rear rubber	1pc	\$ 445.00	Xun
13	Rear end panel.	1pc	\$ 892.80	Rx
			\$ 9,440.30	3918.70
			\$ (2,360.07)	
			\$ 7,080.23	2939.02
Sum Carried Forward				
	Less 25%			

Email to Ms Hany 7/10.

Woon Meng Motor Pte Ltd

Office 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel: 63268523
 (Email Address : woonmeng@singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP Claim

To : AXA Insurance Singapore Pte Ltd
 Motor Claims Dept

Date : 08 Jul 2019

Dear Sirs :

Fax : 68804838

RE : ESTIMATE COST FOR TOYOTA HARRIER ZSU60 2.0 - SGB6299Y
ACCIDENT INVOLVING SGB6299Y AND EW3633Z ON 13.06.2019

ITEMS	DESCRIPTION	QTY	PRICE	
1	Rear bumper	1pc	\$ 1,385.60	de
2	Rear bumper retainer @\$85.7ea	1pc	\$ 171.40	Xun
3	Rear bumper spoiler	1pc		
4	Rear bootlid	1pc	\$ 2,378.60	bt
5	Rear bootlid sbsober @\$1431.6ea.	2pcs	\$ 2,863.20	run
6	Rear bootlid hinge @\$87.2ea	2pcs	\$ 174.40	xun
7	Rear bootlid lock	1pc	\$ 974.80	Xun
8	Emblem.	1pc	\$ 75.60	w
9	Harrier	1pc	\$ 78.90	w
10	Osaka/toyopet	1pc		
11	Rear rubber	1pc	\$ 445.00	Xun
12	Rear end panel.	1pc	\$ 892.80	Ry
			\$ 9,440.30	3918.70
			\$ (2,360.07)	
			\$ 7,080.23	2939.02
Sum Carried Forward				
	Less 25%			

Sum Carried Forward

\$ 7,080.23

- 14 Rear windscreen sealant.
15 Rear sensor.

2pcs \$ 40.00 *40*
1set \$ 220.00 *200.00*
240

Labour Charge & Misc

To remove, replace & install damaged parts. }

\$ 750.00 *500*

To R & R rear windscreen glass

\$ 150.00 *120*

To R & R tailgate mechanism

\$ 100.00 *60*

To remove & repair wiring and check.

\$ 60.00 *30*

To putty & spray painting.

\$ 700.00 *500*

Total

\$ 9,100.23 *1210*

All prices quoted are subjected to 7% GST

This is a computer generated document. No signature is required.

Taufik 47493749

WP

17/19 & 4pm

4 days

Repair after repair

Taufik @ 11/11/19

2739.02

240

1210

4389.02

1/5/3500

4 days #

MSK Auto Consultants hence notify**Be Recipient of the following:**

- To repair before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary demand for the repair cost and is subject to final approval from the insurance company

Acknowledged by P. 1/1/19

Signature:

Date:

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP Claim

To : AXA Insurance Singapore Pte Ltd
Motor Claims Dept

Date : 08 Jul 2019

Dear Sirs :

Fax : 68804838

RE : ESTIMATE COST FOR TOYOTA HARRIER ZSU60 2.0 - SGB6299Y
ACCIDENT INVOLVING SGB6299Y AND EW3633Z ON 13.06.2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 1,385.60 <i>de</i>
2	Rear bumper retainer @\$85.7ea	1pc	\$ 171.40 <i>?</i>
3	Rear bumper spoiler	1pc	<i>ant</i>
4	Rear bootlid	1pc	\$ 2,378.60 <i>bt</i>
5	Rear bootlid sbsober @\$1431.6ea.	2pcs	\$ 2,863.20 <i>x</i>
6	Rear bootlid hinge @\$87.2ea	2pcs	\$ 174.40 <i>x</i>
7	Rear bootlid lock	1pc	\$ 974.80 <i>?</i>
8	Emblem.	1pc	\$ 75.60 <i>us</i>
9	Harrier	1pc	\$ 78.90 <i>us</i>
10	Osako/toyopet	1pc	<i>us</i>
12	Rear rubber	1pc	\$ 445.00 <i>?</i>
13	Rear end panel.	1pc	\$ 892.80 <i>R.Y</i>
			\$ 9,440.30
		Less 25%	\$ (2,360.07)
Sum Carried Forward			\$ 7,080.23

Sum Carried Forward

\$ 7,080.23

14 Rear windscreen sealant.

2pcs \$ 40.00

15 Rear sensor.

1set	\$	220.00
------	----	--------

Labour Charge & Misc

To remove, replace & install damaged parts.

\$ 750.00

To R & R rear windscreen glass

\$ 150.00

To R & R tailgate mechanism

\$ 100.00

To remove & repair wiring and check.

\$ 60.00

To putty & spray painting.

\$ 700.00

Total

\$ 9,100.23

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Tanjung 97495749
'wp'

2/7/19 4p

4 days

Reamy for repair

transfer to the bank

LUX Auto Consultants hence notify

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval

Acknowledged by Publishers

Signature: _____

Digital:

Service Request Details

Claim

S9M01QOE

Reference

None 

Loss Date

June 13, 2019

Report Date

Jun 14, 2019 12:00:00 AM

Request Date

June 18, 2019

Due Date

June 25, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

SGB6299Y

p. mdm Heng

T: 10 17 9.17

v. Alt

E: ✓

YUJUEI
TOYOTA

Service Address

...

Primary Contact/Insured

YEW CHIN KIONG
101 CASHEW ROAD, CASHEW HEIGHTS CONDOMINIUM, #07-01, 679672, Singapore
98480558
EFIX_YCK@YAHOO.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Heng Sew Sow <woonmeng@singnet.com.sg>
Sent: Monday, 17 June, 2019 5:35 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Accident involving SGB6299Y & EW3633Z On 13.06.19
Attachments: 20190617171908.pdf

Categories: Shailendra

Dear Sir/Madam

We refer to the above accident

Kindly be advised that we will be assisting our client, owner of vehicle no: SGB6299Y to submit a third party claim against your insured vehicle. We would like to proceed with direct settlement.
Please arrange for your surveyor to liaise with us for an inspection on our client's Vehicle at your earliest convenience.

Location : 50, Bukit Batok St 23 # 01- 06 Midview Building (S) 659578

Thank you.

Woon Meng Motor Pte Ltd
Tel : 63161131
Fax : 63167050



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/02/2020

Survey Details:

Date of loss	13-Jun-19
Date of appointment	18-Jun-19
Date of survey	8-Jul-19
Location of survey	WOON MENG MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGB 6299Y
Make and Model	TOYOTA HARRIER ZSU60 2.0
Date of registration	6/10/2015
Excess	
Market Value	\$89,000
Part Rebate	\$59,825
Nett Loss	\$29,175

Repair details:

Initial Estimate	\$ 9,100.23
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,698.02
Check items (estimate)	\$ -
Labour	\$ 1,210.00
Total	\$ 4,908.02
Lump Sum(if applicable)	\$ 3,900.00
Number of days for repair	4

Remarks:[illegible]

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 4,173.00	W/GST
Loss of use	\$ -	
Loss of rental (W/GST)	\$ 577.80	3days x \$192.60
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 4,752.80	

**<MANDATE IA> - S9M01QOE {ACCIDENT INVOLVING EW 3633Z (OI) & SGB 6299Y (TP) ON 13/06/2019}**

Type

Question

Message

LIABILITY; 100% BOLA 527 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE, AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$4752.80 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 20/02/2020

[Reply](#)



Pls proceed DS with below revised quantum

Type

🔗 Question

Message

COR: \$4173.00 (as proposed); LOR: \$385.20 (\$128.40/day for 3 days). LTA: \$2.00 . Total: \$4560.20

Reply



Pls offer up to \$149.80/day LOR for 2000CC

Type

🔔 Question

Message

COR: \$4173.00 (as proposed); LOR: up to \$449.40 (\$149.80/day for 3 days). LTA: \$2.00 . Total: \$4624.40

Reply



Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578
Tel: +6563161131 / +6563161151 FAX: +6563167050
Workshop: 42, Sungei Kadut Ave Singapore 729666 Tel: +6563628523
Email: woonmeng@singnet.com.sg
Co Reg No. 200603678M GST Reg No. 20-0603678M

AXA Insurance Singapore Pte Ltd
8 Shenton Way # 27 - 01
27- 01 AXA Tower
Singapore 068811

6 Feb 2020

Attn: Motor Claim Dept.

Dear Sirs

DIRECT SETTLEMENT FOR REPAIR OF TOYOTA HARRIER ZSU60 - SGB6299Y

RE : ACCIDENT INVOLVING SGB6299Y & EW3633Z
ALONG CLEMENTI AVE 6 ON 13.06.19

We have been given the full authority to act on behalf of Tan Kian Hing, registered owner of motor vehicle no. SGB6299Y, which was involved and damaged in the above accident.

We were told that the said accident was caused solely due to the negligence of your insured driver. Therefore, we are compelled to claim against you for the losses incurred as follows:-

1)	Cost of repairs.	\$ 4,173.00
2)	Car rental	\$ 577.80
3)	LTA search	\$ 2.00
	TOTAL AMOUNT:-	<u>\$ 4,752.80</u>

We have told our client that this matter is strictly on a DIRECT SETTLEMENT basis. If you do not dispute liability, please arrange to let us have your payment for the sum of S/D : FOUR THOUSAND SEVEN HUNDRED FIFTY TWO AND CENTS EIGHTY ONLY in full and final settlement for our client's claim.

We enclose herewith the GIA report, Surveyor's report and the invoices for your attention.

We look forward to your early favourable reply.

Yours faithfully,

.....
Chong Han Woon



Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578
Tel: +6563161131 / +6563161151 FAX: +6563167050
Workshop: 42, Sungai Kadut Ave Singapore 729666 Tel: +6563628523
Email: woonmeng@singnet.com.sg
Co Reg No 200603678M GST Reg No. 20-0603678M

TAX INVOICE NO: WM2020/C04423/feb/TP

Date : 06 Feb 2020

AXA Insurance Singapore Pte Ltd
8 Shenton Way # 27 - 01
27- 01 AXA Tower
Singapore 068811

Attn Motor Claims Department

Dear Sirs

RE : REPAIR COST FOR TOYOTA HARRIER ZSU60 - SGB6299Y
ACCIDENT INVOLVING SGB6299Y & EW3633Z ON 13.06.2019

<u>ITEM</u>	<u>DESCRIPTION</u>	<u>PRICE</u>
1	Lump sum repair cost	\$ 3,900.00
		\$ 3,900.00
	ADD GST 7%	\$ 273.00
	TOTAL AMOUNT S\$	\$ 4,173.00

S/D : Four Thousand One Hundred And Seventy Three Only.

This is a computer-generated document. No signature is required.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19010753/T1ga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 10-03-2020	
ATTN:PETER			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	EW 3633Z	Veh. Inspected	SGB 6299Y	
Policy No.	GA152954	Coverage (\$)	0.00	
Claim No.	S9M01QOE	Excess (\$)	0.00	
Assign From		Assign Date	18/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZSU600038197	Colour	WHITE	
Odometer	113998	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	MICHELIN	6 mm	
L/H Front Tyre	235/55 R18	MICHELIN	6 mm	
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2019	Inspection Date	08/07/2019	
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGB 6299Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,385.60	1,385.60
2	REAR BUMPER RETAINER @\$85.70 (CONSISTENT)	NOT NECESSARY	171.40	-
1	REAR BOOTLID (CONSISTENT)	BENT	2,378.60	2,378.60
2	REAR BOOTLID ABSORBER @\$1431.60 (CONSISTENT)	NOT NECESSARY	2,863.20	-
2	REAR BOOTLID HINGE @\$87.20 (CONSISTENT)	NOT NECESSARY	174.40	-
1	REAR BOOTLID LOCK (CONSISTENT)	NOT NECESSARY	974.80	-
1	EMBLEM (CONSISTENT)	NECESSARY	75.60	75.60
1	HARRIER (CONSISTENT)	NECESSARY	78.90	78.90
1	REAR RUBBER (CONSISTENT)	NOT NECESSARY	445.00	-
1	REAR END PANEL (CONSISTENT)	BENT	892.80	692.00
	LESS 25% DISCOUNT		-2,360.08	-1,152.68
			7,080.22	3,458.02
<u>SPECIAL NETT ITEMS</u>				
2	REAR WINDSCREEN SEALANT (CONSISTENT) (SN)	NECESSARY	40.00	40.00
1	SET REAR SENSOR (CONSISTENT) (SN)	NOT WORKING	220.00	200.00
			260.00	240.00
<u>LABOUR</u>				
	TO REMOVE ,REPLACE & INSTALL DAMAGED PARTS.		750.00	500.00
	TO R&R REAR WINDSCREEN GLASS .		150.00	120.00
	TO R&R TAILGATE MECHANISM .		100.00	60.00
	TO REMOVE & REPAIR WIRING AND CHECK .		60.00	30.00
	TO PUTTY & SPRAY PAINTING .		700.00	500.00
			1,760.00	1,210.00
GRAND TOTAL			9,100.22	4,908.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CC4/ASM19010753/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SYM01QOE

Reference

CCA/ASM19010753/TT1ga3u2

Loss Date

13 June 2019

Report Date

14 Jun 2019 12:00:00 AM

Request Date

4 December 2019

Due Date

Vendor Name

LKH AUTO CONSULTANTS PTE LTD (TPV)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SCB6299Y

Make

TPVD

Model

TOYOTA

Service Address

...

Primary Contact/Insured

YEW CHIN KIONG

101 CASHEW ROAD, CASHEW HEIGHTS CONDOMINIUM, #07-01, 679672, Singapore 98480558

EFFX_YCK@YAHOO.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (8).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LKKAdjustment14 (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 TP FINAL LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 PARF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 GIA SEARCH INV.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 MANDATE IA DD 20022020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 tp-la 6299.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	9 July 2019
 PRI FROM WORKSHOP WITH TP CIA SGB62999.mng	Letters and Correspondence	Workshop	KUNMAR Shailendra	18 June 2019