

Cecilia

## Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050  
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523  
( Email Address : woonmeng @singnet.com.sg )  
Co Reg No. 200603678M GST Reg No. 20-0603678M

### Estimate

### TP Claim

To : AXA Insurance Singapore Pte Ltd  
Motor Claims Dept

Date : 08 Jul 2019

Dear Sirs :

Fax : 68804838

RE : ESTIMATE COST FOR TOYOTA HARRIER ZSU60 2.0 - SGB6299Y  
ACCIDENT INVOLVING SGB6299Y AND EW3633Z ON 13.06.2019

| <u>ITEMS</u>        | <u>DESCRIPTION</u>                | <u>QTY</u> | <u>PRICE</u>  |          |
|---------------------|-----------------------------------|------------|---------------|----------|
| 1                   | Rear bumper                       | 1pc        | \$ 1,385.60   | de       |
| 2                   | Rear bumper retainer @\$85.7ea    | 1pc        | \$ 171.40     | Xun      |
| 3                   | <del>Rear bumper spoiler</del>    | 1pc        |               | ad       |
| 4                   | Rear bootlid                      | 1pc        | \$ 2,378.60   | bl       |
| 5                   | Rear bootlid sbsober @\$1431.6ea. | 2pcs       | \$ 2,863.20   | xun      |
| 6                   | Rear bootlid hinge @\$87.2ea      | 2pcs       | \$ 174.40     | xun      |
| 7                   | Rear bootlid lock                 | 1pc        | \$ 974.80     | Xun      |
| 8                   | Emblem.                           | 1pc        | \$ 75.60      | us       |
| 9                   | Harrier                           | 1pc        | \$ 78.90      | u        |
| 10                  | <del>Osaka/toyopet</del>          | 1pc        |               | ux       |
| 12                  | Rear rubber                       | 1pc        | \$ 445.00     | Xun      |
| 13                  | Rear end panel.                   | 1pc        | \$ 892.80     | RY       |
|                     |                                   |            | \$ 9,440.30   | 3918.70. |
|                     |                                   |            | \$ (2,360.07) |          |
|                     |                                   |            | \$ 7,080.23   | 2939.02  |
| Sum Carried Forward |                                   |            |               |          |
|                     | Less 25%                          |            |               |          |

Email to Mrs Henry 7/10.

|                                             |                          |      |                    |        |
|---------------------------------------------|--------------------------|------|--------------------|--------|
| <b>Sum Carried Forward</b>                  |                          |      | <b>\$ 7,080.23</b> |        |
| 14                                          | Rear windscreen sealant. | 2pcs | \$ 40.00           | u✓     |
| 15                                          | Rear sensor.             | 1set | \$ 220.00          | 200mm✓ |
|                                             |                          |      |                    | 240.   |
| <b><u>Labour Charge &amp; Misc</u></b>      |                          |      |                    |        |
| To remove, replace & install damaged parts. |                          | }    | \$ 750.00          | 500.   |
| To R & R rear windscreen glass              |                          | }    | \$ 150.00          | 120    |
| To R & R tailgate mechanism                 |                          |      | \$ 100.00          | 60.    |
| To remove & repair wiring and check.        |                          |      | \$ 60.00           | 30.    |
| To putty & spray painting.                  |                          |      | \$ 700.00          | 500    |
| <b>Total</b>                                |                          |      | <b>\$ 9,100.23</b> | 1210.  |

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Taufik 97495749  
 'wp'  
 8/7/19 4pm  
 4 days.  
 Repairing after repair  
 taufik e khandan

2939.02  
 240  
 1210

4389.02

1/3/3500  
 4 days #

**Link Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer  
 Signature:  
 Date: