

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP Claim

To : AXA Insurance Singapore Pte Ltd
Motor Claims Dept

Date : 08 Jul 2019

Dear Sirs :

Fax : 68804838

RE : ESTIMATE COST FOR TOYOTA HARRIER ZSU60 2.0 - SGB6299Y
ACCIDENT INVOLVING SGB6299Y AND EW3633Z ON 13.06.2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 1,385.60 <i>de</i>
2	Rear bumper retainer @\$85.7ea	1pc	\$ 171.40 ?
3	Rear bumper spoiler	1pc	<i>ant</i>
4	Rear bootlid	1pc	\$ 2,378.60 <i>bt</i>
5	Rear bootlid sbsober @\$1431.6ea.	2pcs	\$ 2,863.20 <i>x</i>
6	Rear bootlid hinge @\$87.2ea	2pcs	\$ 174.40 <i>x</i>
7	Rear bootlid lock	1pc	\$ 974.80 ?
8	Emblem.	1pc	\$ 75.60 <i>we</i>
9	Harrier	1pc	\$ 78.90 <i>we</i>
10	Osako/toyopet	1pc	<i>we</i>
12	Rear rubber	1pc	\$ 445.00 ?
13	Rear end panel.	1pc	\$ 892.80 <i>RY</i>
			\$ 9,440.30
		Less 25%	\$ (2,360.07)
Sum Carried Forward			\$ 7,080.23

Sum Carried Forward**\$ 7,080.23**

14	Rear windscreen sealant.	2pcs	\$	40.00	all ✓
15	Rear sensor.	1set	\$	220.00	200 mm ✓

Labour Charge & Misc

To remove, replace & install damaged parts.	}	\$	750.00	500.
To R & R rear windscreen glass	}	\$	150.00	120
To R & R tailgate mechanism		\$	100.00	60.
To remove & repair wiring and check.		\$	60.00	30.
To putty & spray painting.		\$	700.00	500

Total**\$ 9,100.23**

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Taufik 97495749
'wp'
8/7/19 e 4pm
4 days.
Resurvey after repair
taufik e lkhairi

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: