

12/05/2005

ASS. REC. BY:

Surveyor: Tan Hui

REF: CS/CT119010769/T15d3<sup>sr</sup>

Special Instruction:

From (Person): Chong Boon Sen

ASSIGNMENT (Office)

of CT1

Date/Time: 18/6/19 @ 10.24am

Estimated Cost:

Bill to:

OD / CT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 3585A

Insured: XD 7742R

at Workshop in/s

Kah Motor

Tel: 8288 6309

of

No. 255 Alexandra Road

Policy No:

Claim No:

SNM19D202796

Sum Insured:

Excess:

D.O.A. 17/06/2019.

Make of Veh:  
(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 10:40am @ 18/6/19

Person Contacted:

Jack

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>3MA 3585A - X</u>
	<u>XD 7742R - CS3/AXA 13024415 / Agby 2-1</u>
	<u>DoA: 24/12/2013</u>
<u>25/10/19</u>	<u>@ 15:40pm - checked with Jack (owner),</u> <u>pending liability from Insurance. Owner convert</u> <u>to OD claim.</u>

ASS. REG. BY:

REF:

CT1

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Side

Veh No:

SMA 3585A

Vr Regn:

2018, June.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c.

1597

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

12360

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC5650JT000819

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

29/7/19 C/Am

Survey held at

Hah Motor Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 25 OCT 2019

Date/Time, File Pass to?

25/10/19

1)

Typh

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + P3 \$

Photos

Other:

TOTAL

Report Format:

Prel:

Lump Sum / L.R. (\$)

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 18 June 2019 10:24 AM  
**To:** Jack Ng  
**Cc:** assignments  
**Subject:** RE: ACCIDENT BETWEEN SMA 3585 A AND YOUR INSURED XD 7742 R / OUR REF: SNM19D202796

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Jack Ng [<mailto:jackng@honda.com.sg>]  
**Sent:** Tuesday, 18 June, 2019 10:06 AM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: ACCIDENT BETWEEN SMA 3585 A AND YOUR INSURED XD 7742 R / OUR REF: SNM19D202796

Dear Boon Sen,

Kindly assist to arrange LKK to survey this case.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

*Jack Ng*

*Hp: 8288 6309*

*Email: [Jackng@honda.com.sg](mailto:Jackng@honda.com.sg)*

BODY REPAIR AND PAINT CENTRE  
255 Alexandra Road Singapore 159937  
DID : +65 6514 5481 FAX : +65 6362 5015  
Kah Motor Co. Sdn. Bhd.  
(A MEMBER OF ORIENTAL HOLDING BERHAD)  
Website: [www.honda.com.sg](http://www.honda.com.sg)



Visit our  
Facebook page

Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Sent:** Tuesday, June 18, 2019 10:04 AM  
**To:** Jack Ng <[jackng@honda.com.sg](mailto:jackng@honda.com.sg)>  
**Subject:** RE: ACCIDENT BETWEEN SMA 3585 A AND YOUR INSURED XD 7742 R / OUR REF: SNM19D202796

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

### Chong Boon Sen

Claims Executive  
Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Claims Dept of CTI  
**Sent:** Tuesday, 18 June, 2019 9:47 AM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [jackng@honda.com.sg](mailto:jackng@honda.com.sg); Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>  
**Cc:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>  
**Subject:** FW: ACCIDENT BETWEEN SMA 3585 A AND YOUR INSURED XD 7742 R

Dear Boon Sen,

Claim registered. SNM19D202796  
File with OIC – Boon Sen - 63896171

**From:** Jack Ng [<mailto:jackng@honda.com.sg>]  
**Sent:** Tuesday, 18 June 2019 9:22 AM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>  
**Subject:** ACCIDENT BETWEEN SMA 3585 A AND YOUR INSURED XD 7742 R

Dear al,

Kindly assist to register for direct settlement, attached is the GIA report.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

*Jack Ng*

*Hp: 8288 6309*

*Email: [jackng@honda.com.sg](mailto:jackng@honda.com.sg)*

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: [www.honda.com.sg](http://www.honda.com.sg)



Visit our  
Facebook page



**Please consider the environment before printing this email**

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/06/2019 18:25
Date Of Accident	17/06/2019 10:10
Exact Location Of Accident	JURONG ISLAND HIGHWAY TOWARDS JURONG ISLAND
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA3585A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ERIC NG PENG YUI
NRIC No	S7312609F
Email Address	ERIC_NG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97562447
Alternative Phone No	OFFICE-97562447

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	ERIC NG PENG YUI
NRIC No	S7312609F
Date Of Birth	31/03/1973
Occupation	INDOOR
Date Of Driving Pass	04/11/1996
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97562447
Fax Number	
Contact Number	OFFICE-97562447
Email Address	ERIC_NG@GMAIL.COM

No. Of Passenger (Including Driver)



**SINGAPORE  
POLICE FORCE**



T/20190617/2044

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

2 of 3  
Report No. T/20190617/2044

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ERIC NG PENG YUI	ID No.	S7312609F
Related Vehicle	SMA3585A (Car)	Contact No.	97562447
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17/06/2019 at about 10.12am, while I was driving my vehicle of reg no. SMA3585A along the Jurong Island Highway towards the direction of Jurong Island, my vehicle was involved in a hit and run accident.


2. At that point of time, I was driving towards the car lanes which is at the left side of the entrances to the multiple lanes waiting to enter the Jurong Island. While I was at the queue, suddenly this lorry of reg no. XD7742R came from behind and his vehicle left portion then side swipe my vehicle right portion. The said lorry continued to hit my car for quite a while and I horn. It drive off when it reached the check point. As a result, my vehicle sustained dents at the left side rear portion. I could not stop my vehicle because there was a queue behind.

3. No one was injury in the accident. My vehicle in-built vehicle camera had capture that the lorry driving towards my right side and it had also captured the vehicle reg no. However, I strongly believed that there are many cameras installed at the entrances to the Jurong Island.

Sketch Plan #2 Pg. 1

Vehicle Number: \_\_\_\_\_

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIARMC V4-1-1 (Final) 01-01-2013



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT19003299	<b>Page</b>	1
<b>Registration No</b>	: SMA3585A	<b>Date</b>	: 27. Jul 2019		
<b>Chassis No</b>	: MRHFC5650JT000819	<b>Customer No.</b>	: WZC008		
<b>Model</b>	: CIVIC 1.6 VTI YM2018	<b>Svc Advisor</b>	:		
<b>Owner's Name</b>	: ERIC NG PENG YUI	<b>Engine No</b>	: R16B25500908		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 27. Jul 2019 8:45:37 AM		
<b>Date of Accident</b>	: 17/6/2019	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	<del>OWN DAMAGE CLAIMS-J/NO:</del> POLICY/CLAIMS NO: OWNER:ERIC NG PENG YUI ACC DATE:17/06/2019 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20 <i>de</i>		617.20	43.20	660.40
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	18.00 <i>?</i>		18.00	1.26	19.26
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40 <i>nei</i>		10.40	0.73	11.13
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40 <i>nei</i>		10.40	0.73	11.13
91505-TM8-003	CLIP,BUMPER	22	2.30 <i>nei</i>		50.60	3.54	54.14
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	711.60 <i>bt</i>		711.60	49.81	761.41
42700-TEA-T61	DISKALUMINIUM WHEEL	1	297.80 <i>mtb</i>		297.80	20.85	318.65
73227-TEA-003	RUBBER CWINDOWSHIELD DAM	1	17.20 <i>nei</i>		17.20	1.20	18.40
73525-SYY-000	RUBBERRR QTR W/SHIELD	3	9.70 <i>nei</i>		29.10	2.04	31.14
91501-S70-003	FASTENER BW/SHIELD	2	5.30 <i>nei</i>		10.60	0.74	11.34
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80 <i>nei</i>		7.60	0.53	8.13
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	2.90 <i>nei</i>		5.80	0.41	6.21
73125-SR3-000	RUBBER, W/SHIELD	1	12.60 <i>nei</i>		12.60	0.88	13.48
73126-SR3-000	RUBBER, W/SHIELD	1	14.40 <i>nei</i>		14.40	1.01	15.41
BO-WS-SEALANT	WINDSCREEN SEALANT (N)-	2	60.00 <i>nei</i>		120.00	8.40	128.40
<b>Sum Item</b>					<b>1933.30</b>	<b>135.33</b>	<b>2,068.63</b>
BOSUN	SUNDRIES	<i>incl</i> 1	100.00 <i>50</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR RHS REAR FENDER	1	150.00 <i>20</i>		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00 <i>280</i>		380.00	26.60	406.60

Printed on 29/7/2019 10:09:25 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE	<b>Document No.</b>	: SQT19003299	<b>Page</b>	2
	3 ANSON ROAD #16-00	<b>Date</b>	: 27. Jul 2019		
	SPRINGLEAF TOWER	<b>Customer No.</b>	: WZC008		
	SINGAPORE 079909	<b>Svc Advisor</b>	:		
<b>Registration No</b>	: SMA3585A	<b>Engine No</b>	: R16B25500908		
<b>Chassis No</b>	: MRHFC5650JT000819	<b>Date   Time</b>	: 27. Jul 2019 8:45:37 AM		
<b>Model</b>	: CIVIC 1.6 VTI YM2018	<b>Surveyor Name</b>	:		
<b>Owner's Name</b>	: ERIC NG PENG YUI	<b>Survey Date</b>	:		
<b>Ins Policy No.</b>	:	<b>Authorisation Date</b>	:		
<b>Date of Accident</b>	: 17/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC011R	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	450.00	✓	450.00	31.50	481.50
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00	✓	380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	580	800.00	56.00	856.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	800.00	580	800.00	56.00	856.00
BODAMKIT	WINDSCREEN DAM KIT.	1	200.00	150	200.00	14.00	214.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN (N)	1	560.00	✓	560.00	39.20	599.20
BKFE22R	CUT & RENEW RR R FENDER. RENEW ALL DAMAGE PARTS	1	5000.00	2520	5000.00	350.00	5350.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	3500.00	900	3500.00	245.00	3745.00
Sum Labor					12320.00	862.40	13,182.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 14,253.30 997.73 15,251.03

Total (Inclusive of GST) 15,251.03

Surf Lkkauto.com

Resurvey before paint

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 29/7/2019 10:09:25 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019		30 Jul 2019 12:00 <a href="#">Edit Adj Rpt</a>	<b>S\$8,485.30</b> <a href="#">Edit Estimates</a>	<b>S\$8,485.30</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	<b>YONG LEI SERVICES PTE LTD</b> , Co. Reg. No.: 201109858C		
Vehicle Reg. No.:	<b>SMA3585A</b>	Date of Loss:	17/06/2019 10:00 - :59 [12 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM19D202796C02</b>	Policy/Cover Note No.:	DMCVSN17343819022
Vehicle Reg. No. (Insured):	<b>XD7742R</b>	Policy No. (Claimant):	DMCVSN1734381902
		Excess:	S\$0.00
Repairer:	<b>Kah Motor Co Sdn Bhd (ALEXANDRA)</b> 255 ALEXANDRA ROAD, - Alexandra - Tel:		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Claimant's Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 08/08/2019]		

[View All](#)[Compose Case Mail](#)

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date    Priority    Type    Task Group    Subject    Handler    Assigned By    Completed On    Created On    Done?

No results.



## Claim Documents

**\*SMA3585A (SNM19D202796C02)**  
[XD7742R]

TP

**YONG LEI SERVICES PTE LTD**

Jun 17 2019 10:00AM

[-]







**Kah Motor Co Sdn Bhd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/06/19 16:41	<b>Accident Statement</b>	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/06/19 16:39	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	26/06/19 16:39	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	26/06/19 16:39	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	26/06/19 16:39	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	26/06/19 16:39	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	26/06/19 16:39	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	25/10/19 15:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/06/19 16:40	<b>Sketch Plan</b> [Linked Accident Report Documents]	Load TIF	
2	26/06/19 16:41	<b>ci,ic,di</b> [Linked Accident Report Documents]	Load TIF	

## Linked Accident Report Documents

			View	View in Browser ▼
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/06/19 16:41	<b>Accident Statement</b>	 Load HTM	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/06/19 16:39	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
2	26/06/19 16:39	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
3	26/06/19 16:39	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
4	26/06/19 16:39	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
5	26/06/19 16:39	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
6	26/06/19 16:39	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/06/19 16:40	<b>Sketch Plan</b>	 Load TIF	
2	26/06/19 16:41	<b>cl,lc,dl</b>	 Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset Save Print
There are no document checklists configured.	
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) </div> <div> Show Remarks To: <input type="checkbox"/> Handling Insurer  Note: Remarks are private unless you show it to other parties. </div>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119010769/T1SD3S2  
 Date: 30/10/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN17343819022  
 Claimant Vehicle No: SMA3585A Insured Vehicle No: XD7742R  
 Date of Loss: 17/06/2019 Nature of Claim: TP Claim No: SNM19D202796C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMA3585A Engine No: R16B25500908  
 Make & Model: HONDA CIVIC, 1.6 VTI (A) Chassis No: MRHFC5650JT000819  
 Reg. Date: 04/06/2018 (Man. Year: 2018) Odometer: 12360 km  
 Colour: Grey  
 Engine Capacity: 1597 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16  
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,233.30	2,115.30	118.00	5.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,020.00	6,370.00	5,650.00	47.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,253.30</b>	<b>8,485.30</b>	<b>5,768.00</b>	<b>40.47</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>997.73</b>	<b>593.97</b>	<b>403.76</b>	<b>40.47</b>
<b>Nett Amount (S\$)</b>	<b>15,251.03</b>	<b>9,079.27</b>	<b>6,171.76</b>	<b>40.47</b>

## INSPECTION

Date of Assignment: 30/07/2019  
 Date Inspected: 29/07/2019 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)  
 Estimated Period of Repair: 7.0 days 255 ALEXANDRA ROAD  
 Singapore -

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

OWNER CONVERT TO OD CLAIM.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$18.00 NETT)

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2019)
<b>Parts:</b>	143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA3585A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY,RR.BUMPER	Deformed	617.20 FS	*617.20 FS
2	1		*GARNISHR.FR.BUMPER SIDE	*Check	18.00 FS	*- FS
3	1		*SPACERR.FR.BUMPER SIDE	Necessary	10.40 FS	*10.40 FS
4	1		*SPACERL.FR.BUMPER SIDE	Necessary	10.40 FS	*10.40 FS
5	1		*CLIP, BUMPER	Necessary	50.60 FS	*50.60 FS
			22pcs			
6	1		*PANEL SETR.RR.OUTSIDE	Bent	711.60 FS	*711.60 FS
7	1		*DISKALUMINIUM WHEEL	Cut	297.80 FS	*297.80 FS
8	1		*RUBBER CWINDSHEILD DAM	Necessary	17.20 FS	*17.20 FS
9	3		*RUBBERRR QTR W/SHIELD	Necessary	29.10 FS	*29.10 FS
10	2		*FASTENER BW/SHIELD	Necessary	10.60 FS	*10.60 FS
11	2		*FASTENER AW/SHIELD	Necessary	7.60 FS	*7.60 FS
12	2		*CLIP, WINDSHIELD UPPER	Necessary	5.80 FS	*5.80 FS
13	1		*RUBBER, W/SHIELD	Necessary	12.60 FS	*12.60 FS
14	1		*RUBBER, W/SHIELD	Necessary	14.40 FS	*14.40 FS
15	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
16	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
17	1		*WINDSCREEN DAM KIT	Necessary	200.00 FS	*150.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>2,233.30</b>	<b>2,115.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY JOINT SEALANT FOR RHS REAR FENDER.	New	150.00	120.00
2	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.	New	380.00	280.00
3	RESET & CALIBRATE SMART ENTRY SYSTEM.	New	450.00	450.00
4	REMOVE & REINSTALL REVERSE SENSORS.	New	380.00	380.00
5	REMOVE & INSTALL REAR COMPARTMENT LININGS.	New	800.00	580.00
6	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.	New	800.00	580.00
7	REMOVE & INSTALL RR. WINDSCREEN.	New	560.00	560.00
8	CUT & RENEW RR R FENDER. RENEW ALL DAMAGE PARTS.	New	5,000.00	2,520.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	3,500.00	900.00
Gross Labour Cost (\$\$)			12,020.00	6,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >