

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R**AAD1906-057***Not Authored*
1/1/19 \$16000
17/8/19

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD 272R

VF1ABL15AUC282421

RENAULT

LATITUDE

7.6.19

CHINA TAIPING

22/3/2016

PART

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	RADIATOR GRILLE
15	1	RADIATOR GRILLE BADGE 'RENAULT'
16	1	RADIATOR GRILLE FRAME
17	1	FRAME FULL SUPPORT PANEL
18	1	FRAME FULL SUPPORT BRACKET
19	1	FRONT BRACE PANEL
20	1	HORN
21	1	HORN BRACKET
22	1	HEADLAMP LH
23	1	HEADLAMP RH
24	1	HEADLAMP PANEL FRT LH
25	1	HEADLAMP PANEL FRT RH
26	1	BONNET
27	1	BONNET INSULATOR
28	1	BONNET STRUT LH

LIST

\$	<i>miy</i>	1,259.42	✓
\$	<i>miy</i>	181.75	✓
\$	<i>miy</i>	394.68	✓
\$	<i>CM</i>	151.41	✓
\$	<i>miy</i>	123.88	✓
\$	<i>CM</i>	150.77	✓
\$	<i>miy</i>	123.88	✓
\$	<i>miy</i>	472.83	✓
\$	<i>miy</i>	266.80	✓
\$	<i>miy</i>	207.21	✓
\$	<i>miy</i>	207.21	✓
\$	<i>B</i>	914.08	✓
\$	<i>miy</i>	28.61	✓
\$	<i>miy</i>	1,707.78	✓
\$	<i>miy</i>	225.36	✓
\$	<i>CM</i>	1,353.75	✓
\$	<i>CM</i>	615.90	✓
\$	<i>B</i>	89.79	✓
\$	<i>B</i>	177.22	✓
\$	<i>SL</i>	314.17	X
\$	<i>N</i>	40.45	X
\$	<i>Bu</i>	1,184.43	✓
\$	<i>ngcm</i>	1,184.43	✓
\$	<i>DJI</i>	152.15	✓
\$	<i>B</i>	152.15	✓
\$	<i>Bu</i>	1,941.63	✓
\$	<i>Refom</i>	405.73	✓
\$	<i>Pu</i>	88.61	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R**AAD1906-057**

29	1	BONNET STRUT RH	\$	<i>Pu</i>	88.61	—
30	1	BONNET HINGE LH	\$	<i>Bu</i>	348.31	—
31	1	BONNET HINGE RH	\$	<i>D.1</i>	348.31	—
32	1	BONNET LOCK	\$	<i>Bu</i>	305.48	—
33	1	BONNET CABLE	\$	<i>Pu</i>	119.19	7 X
34	1	BONNET CABLE COVER	\$	<i>Pu</i>	161.03	X
35	1	BONNET SEAL OUTER	\$	<i>miy</i>	92.36	—
36	1	BONNET SEAL INNER	\$	<i>Pu</i>	157.28	X
37	1	FENDER PANEL FRT LH	\$	<i>Bu</i>	783.83	—
38	1	WHEELARCH FRT LH	\$	<i>cm</i>	278.84	—
39	1	FENDER BRACKET LOWER LH	\$	<i>n</i>	15.79	X
40	1	FENDER INSULATOR LH	\$	<i>Pu</i>	130.84	X
41	1	FENDER PANEL FRT RH	\$	<i>Bu</i>	130.84	—
42	1	WHEELARCH FRT RH	\$	<i>cm</i>	278.84	—
43	1	FENDER BRACKET LOWER RH	\$	<i>n</i>	36.11	X
44	1	FENDER INSULATOR RH	\$	<i>Pu</i>	130.84	X
45	1	WHEEL HOUSING PANEL FRNT RH	\$	<i>R Pu</i>	4,682.09	7 X
46	1	DOOR PANEL FRT RH	\$	<i>n</i>	2,844.66	X
47	1	DOOR HINGE UPPER RH	\$	<i>n</i>	261.28	X
48	1	DOOR HINGE LOWER RH	\$	<i>n</i>	300.55	X
49	1	DOOR CHECK FRT RH	\$	<i>n</i>	194.77	X
50	1	DOOR CATCH FRT RH	\$	<i>n</i>	131.23	X
51	1	DOOR WHEATHESTRIIP FRONT RH	\$	<i>Pu</i>	410.66	X
52	1	WIPER RESERVOIR	\$	<i>Pu</i>	348.25	Y
53	1	WIPER RESERVOIR NECK	\$	<i>SVC Pu</i>	136.11	7 X
54	1	WIPER RESERVOIR MOTOR	\$	<i>SVC Pu</i>	270.06	7 X
55	1	AIR CLEANER LOWER	\$	<i>SVC Pu</i>	271.26	7 X
56	1	AIR CLEANER HOSE	\$	<i>SVC Pu</i>	175.85	7 X
57	1	BASE BATTERY TRAY	\$	<i>SVC Pu</i>	363.40	7 X
58	1	AIR CLEANER BOX	\$	<i>SVC Pu</i>	464.20	X
59	1	TURBO DUCT	\$	<i>SVC Pu</i>	1,027.80	7 X
60	1	A/C HEATER VALVE	\$	<i>Pu</i>	484.50	X
61	1	SUBFRAME OUTER FRT	\$	<i>SVC Pu</i>	2,652.45	7 X
62	1	SUBFRAME BRACKET OUTER LH	\$	<i>n</i>	92.36	X
63	1	SUBFRAME BRACKET OUTER RH	\$	<i>n</i>	92.36	X
64	1	ENGINE UNDERTRAY	\$	<i>Pu</i>	564.98	7 X
65	1	A/C CONDENSER	\$	<i>Pu</i>	2,020.37	—
66	1	A/C CONDENSER GARNISH LH UPPER	\$	<i>cm</i>	39.67	—

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R**AAD1906-057**

67	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	X
68	1	A/C CONDENSER GARNISH LH	\$	58.81	X
69	1	A/C CONDENSER GARNISH RH	\$	59.60	X
70	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	R 208.39	X
71	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	svc 658.72	X
72	1	A/C PIPE COMPRESSOR	\$	334.29	X
73	1	A/C PIPE	\$	svc 658.72	X
74	1	A/C COMPRESSOR	\$	2,684.61	X
75	1	AIR COOLER	\$	svc 792.60	X
76	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	X
77	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	X
78	1	TRANSMISSION COOLER	\$	1,219.30	X
79	1	TRANSMISSION COOLER PAD	\$	svc 17.96	X
80	1	RADIATOR	\$	1,202.20	X
81	2	RADIATOR STUD UPPER	\$	14.41	X
82	2	RADIATOR BUSH UPPER	\$	50.12	X
83	2	RADIATOR MTG LOWER	\$	55.85	X
84	1	RADIATOR FAN COWLING	\$	svc 820.54	X
85	1	RADIATOR FAN MOTOR LH	\$	svc 967.36	X
86	1	RADIATOR FAN MOTOR RH	\$	svc 1,479.46	X
87	1	RADIATOR TANK	\$	324.62	X
88	1	RADIATOR HOSE UPPER	\$	svc 240.56	X
89	1	RADIATOR HOSE LOWER	\$	svc 491.18	X
90	1	RADIATOR TANK HOSE	\$	svc 61.18	X
91	1	AUTO COMPUTER	\$	5,032.17	X
92	1	INJECTION COMPUTER	\$	4,706.30	X
93	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	R 5,154.52	X
94	1	STEERING PUMP ELECTRIC L70Y	\$	2,306.90	X
95	1	STEERING PINION RACK L70Y	\$	4,413.11	X
96	1	LOWER ARM LH L70Y	\$	685.76	X
97	1	KNUCKLE ARM LH L70Y	\$	846.98	X
98	1	ABSORBER FRT LH L70Y	\$	360.54	X
99	1	DRIVESHAFT LH	\$	1,747.45	X
100	1	STABILIZER BAR FRT	\$	604.65	X
101	1	LOWER ARM RH L70Y	\$	685.76	X
102	1	KNUCKLE ARM RH L70Y	\$	846.98	X
103	1	ABSORBER FRT RH L70Y	\$	360.54	X
104	1	DRIVESHAFT RH	\$	1,747.45	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R**AAD1906-057**

105 2 STABILIZER LINK FRT

106 1 ENGINE WIRING HARNESS

	\$	117.22 X
	\$	4,084.54 X
TOTAL	\$	82,881.72
10%	\$	8,288.17

\$ 74,593.55

Special Nett

1	1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	✓
2	1SET BUMPER CLIP FRT	\$	nn	66.00	✓
3	1 BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	X
4	1 BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	X
5	1 BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	X
6	1 BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	X
7	1 FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	6000
8	1 FRONT DOOR STICKER 'Classic'	\$	nn	80.00	1500
9	1SET RADIATOR GRILLE SCREW	\$	nn	16.00	} X
10	1SET BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
11	1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
12	2 FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
13	2 FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
14	1 Windscreen moulding	\$	nn	120.00	} X
15	1 FRONT WINDSCREEN SEALANT	\$	nn	253.80	
16	1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
17	1SET Front licence plate with holder	\$	his	80.00	4500
18	1SET WHEELARCH CLIP FRT LH	\$	nn	30.50	—
19	1SET WHEELARCH CLIP FRT RH	\$	nn	30.50	—
20	1 Front left tyre	\$	nn	330.00	} X
21	1 Front left tyre rim	\$	nn	380.00	
22	1 Front right tyre	\$	nn	330.00	
23	1 Front right tyre rim	\$	nn	380.00	
24	6 BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
25	2 BONNET STRUT L70Y	\$	nn	88.61	} X
26	2 BONNET CABLE CLIP L70Y	\$	nn	6.31	
27	2 BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
TOTAL		\$	2,675.88		

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R**AAD1906-057****TOTAL PARTS \$ 77,269.43****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	9,000.00	1400
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	nn X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Putty and spray painting of the affected portion.	\$	9,000.00	1540
To check steering geometry and computer wheel alignment	\$	220.00	60
To remove and refit air bag system and reset vehicle warning indicators.	\$	480.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	200
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	250
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of front windscreen fittings and conduct water seepage test	\$	200.00	nn X
To vacuum, replace, refix and recharge air condenser	\$	380.00	100

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD1906-057**SHD 272R**

To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To rust-proofing of the affected areas.	\$	170.00	1501
To Check Electrical Lighting Concerned.	\$	170.00	301
To replace, refix and top up coolant for radiator	\$	170.00	501
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	Agua 380.00	X
Towing Fees.	\$	150.00	501
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	4 380.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	4 380.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	4 440.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4 380.00	X
TOTAL		\$ 25,280.00	
Over All Total		\$ 102,549.43	
Repair Days (LUMP SUM)		30 DAYS	

12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from

Acknowledged by Repairer

Signature:

Date: