

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN MUN CHUAN
NO 28 JLN PENDEKAR 4
TMN UNGKU TUN AMINAH
81300 SKUDAI JOHOR

TP EQ
Xico Tony

Date :28.06.2019
Vehicle No :JRM 9137
Make/Model :NISSAN SERENA
Accident date :09.06.2019

| No | DESCRIPTION | Qty | Amount (\$) |
|-------------------|-----------------------------------------------------------|-----|------------------------|
| <u>List Items</u> | | | |
| 1 | Front bumper fod lamp @ \$ 387.70 <i>lt cracked.</i> | 2 | \$ 775.4 <i>285</i> |
| 2 | Front bumper fod lamp cover @ \$ 156.10 <i>not new</i> | 2 | \$ 312.2 <i>x</i> |
| 3 | Front bumper clips (1set) <i>new</i> | 1 | \$ 66.30 |
| 4 | Front grille <i>{ not new</i> | 1 | \$ 447.5 <i>x</i> |
| 5 | Front grille logo <i>{ not new</i> | 1 | \$ 88.7 <i>x</i> |
| 6 | Front LH fender <i>dented</i> | 1 | \$ 814.1 <i>689.</i> |
| 7 | Front LH fender inner shield <i>behind</i> | 1 | \$ 146 <i>✓</i> |
| 8 | Rear windscreen rubber <i>new</i> | 1 | \$ 140.8 <i>✓</i> |
| 9 | Rear tailgate <i>distorted</i> | 1 | \$ 3204.5 <i>-1380</i> |
| 10 | Rear tailgate hinge @ \$ 112.20 | 2 | \$ 224.4 <i>x</i> |
| 11 | Rear tailgate shock absorber @ \$ 236.60 <i>{ not nec</i> | 2 | \$ 473.2 <i>x</i> |
| 12 | Rear tailgate inner handle <i>not new</i> | 1 | \$ 66 <i>x</i> |
| 13 | Rear tailgate weather strip <i>cut</i> | 1 | \$ 237.1 <i>✓</i> |
| 14 | Rear tailgate wiper motor <i>{ not nec</i> | 1 | \$ 791.2 <i>x</i> |
| 15 | Rear tailgate wiper arm <i>{ not nec</i> | 1 | \$ 94.7 <i>x</i> |
| 16 | Rear tailgate wiper arm cover | 1 | \$ 19.2 <i>x</i> |
| 17 | Rear tailgate Nissan emblem <i>{ new</i> | 1 | \$ 71.6 <i>✓</i> |
| 18 | Rear tailgate S Hybrid emblem | 1 | \$ 70 <i>✓</i> |
| 19 | Rear tailgate Highway emblem (1 set) <i>{ nec</i> | 1 | \$ 105.4 <i>✓</i> |
| 20 | Rear tailgate Star emblem (1 set) | 1 | \$ 71.6 <i>✓</i> |
| 21 | Rear tailgate camera <i>not nec</i> | 1 | \$ 960 <i>x</i> |
| 22 | Rear RH lamp bulbs @ \$ 8.40 <i>cracked</i> | 4 | \$ 33.6 <i>✓</i> |
| 23 | Rear bumper <i>deformed</i> | 1 | \$ 989.4 <i>758</i> |
| 24 | Rear bumper side holder @ \$ 67.40 <i>RH damaged</i> | 2 | \$ 134.8 <i>67.40</i> |
| 25 | Rear bumper reverse sensor @ \$ 352.80 <i>not new</i> | 2 | \$ 705.6 <i>x</i> |
| 26 | Rear RH fender inner shield <i>not new</i> | 1 | \$ 119 <i>x</i> |
| 27 | Rear RH fender inner garnish <i>cracked</i> | 1 | \$ 525 <i>✓</i> |
| 28 | Rear RH fender inner top garnish <i>behind</i> | 1 | \$ 215.6 <i>✓</i> |
| 29 | Rear end panel <i>dented</i> | 1 | \$ 2148 <i>715</i> |
| 30 | Rear RH fender lower air vent <i>not new</i> | 1 | \$ 46.8 <i>x</i> |
| 31 | Rear RH inner fender <i>Repair</i> | 1 | \$ 1363.8 <i>x</i> |
| 32 | Rear RH jack holder <i>bent</i> | 1 | \$ 210.5 <i>✓</i> |

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN MUN CHUAN
NO 28 JLN PENDEKAR 4
TMN UNGKU TUN AMINAH
81300 SKUDAI JOHOR

Date :28.06.2019
Vehicle No :JRM 9137
Make/Model :NISSAN SERENA
Accident date :09.06.2019

| No | DESCRIPTION | Qty | Amount (\$\$) |
|----|-------------------------------------|-----|----------------------------------------|
| 33 | Rear spare tyre well | 1 | \$ 2262.5 x |
| 34 | Rear spare tyre well insulation | 1 | \$ 358.3 x |
| 35 | Rear spare tyre top board | 1 | \$ 718.3 x |
| 36 | Front supper panel | 1 | \$ 821.8 x |
| 37 | Rear windscreen solar film | 1 | \$ 240 ✓ |
| 38 | Front bumper | 1 | \$ 1169.2 795 |
| 39 | Front bumper sponge | 1 | \$ 318.1 85 |
| 40 | Front bumper side holder @ \$ 42.20 | 2 | \$ 84.4 42.20 LH Damaged |
| 41 | Front bumper reinforcement | 1 | \$ 866.4 x |
| 42 | Front LH head lamp | 1 | \$ 985 ✓ |
| 43 | Rear windscreen | 1 | \$ 1687.6 1140.40 Shattered |
| 44 | Rear tailgate upper lock | 1 | \$ 197.2 ✓ |
| 45 | Rear tailgate lower lock | 1 | \$ 66 x |
| 46 | Rear tailgate inner board | 1 | \$ 724.8 525 cracked |
| 47 | Rear RH lamp | 1 | \$ 905.4 515 smashed |
| 48 | Rear RH lamp top housing | 1 | \$ 237.7 x Repair |
| 49 | Rear RH lamp lower housing | 1 | \$ 222.1 ✓ Dented |
| 50 | Rear bumper reflector @ \$ 76.90 | 2 | \$ 153.8 76.90 RHT cracked |
| 51 | Rear bumper clips | 1 | \$ 68 30 Nec |
| 52 | Rear RH fender | 1 | \$ 1606.8 1348 Distorted |
| 53 | Rear RH fender centre garnish | 1 | \$ 316.8 ✓ cracked |
| 54 | Rear RH fender roller | 1 | \$ 268.9 x |
| 55 | Rear RH fender quarter glass | 1 | \$ 861.5 x |
| 56 | Rear end panel inner top garnish | 1 | \$ 198 x Nec |
| 57 | Rear RH safety belt | 1 | \$ 916.3 x |
| | | | \$ 31924.6 |
| | Less 10% Disc | | \$ 3192.5 |
| | Total | | \$ 28732.1 |

12270.20

11043.18

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN MUN CHUAN
NO 28 JLN PENDEKAR 4
TMN UNGKU TUN AMINAH
81300 SKUDAI JOHOR

Date :28.06.2019
Vehicle No :JRM 9137
Make/Model :NISSAN SERENA
Accident date :09.06.2019

| No | Description | Qty | Amount (\$) |
|--------------------|-----------------------------------------------------|------|-------------------------|
| Labour Cost | | | |
| 1 | Towing fee | | \$ 150 120 |
| 2 | To supply rear windsceen sealant | | \$ 50 ✓ |
| 3 | Remove & reinstall rear windscreen | | \$ 300 120 |
| 4 | Remove & reinstall cushion + roof lining | | \$ 300 120 |
| 5 | Remove & reinstall safety belt | | \$ 100 60 |
| 6 | Remove & reinstall camera | | \$ 80 50 |
| 7 | Remove & reinstall air con fill in gas | | \$ 150 X |
| 8 | Remove, replace & repair consistent to the accident | | \$ 2800 1800 |
| 9 | Respray painting | 4000 | \$ 2200 1500 |
| 10 | To check wiring | | \$ 150 60 |
| 11 | Tuff kote | | \$ 150 120 |
| Total | | | \$ 6430 |
| Grand Total | | | \$ 35162.1 |

K Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 15043.18
H/S : 12K
15 Days.