

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX5092D
CHAY WENG TECK
BLK 7 SIMEI ST 4
05-01
SINGAPORE 529864
TEL : FAX :
PH : 90708319
ATTN :

ESTIMATE BILL

Number : EB00005183
Date : 15/06/2019
Case No : AD00010487
Vehicle No : SKC1823P
Chassis : KNAFW411LA5186248
Year of Mfr : 2009
Policy No :
Model : KIA CERATO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	HEADLAMP LH <i>che</i>	1.0	467.00	0	467.00
List Price - Parts Sub Total					467.00
2	FRONT FENDER LH - REPAIR <i>nx</i>	1.0			
3	FRONT BUMPER - REPAIR <i>nx</i>	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					467.00
4	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	400.00	0	400.00
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
6	ANTI-RUST COATING	1.0	80.00	0	80.00
7	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					1,020.00
LUK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modifications is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: <i>not Alred</i> <i>24/7/19</i> <i>24/5/19</i> <i>800</i>					<i>467</i> <i>12</i> <i>479</i> <i>1020</i>
SINGAPORE DOLLARS : ONE THOUSAND FIVE HUNDRED NINETY-ONE AND CENTS NINE ONLY			Less Excess		0.00
			SUBTOTAL		1,487.00
			GST 7.00%		104.09
			TOTAL		1,591.09

Date of accident : 06/06/2019 02:50 PM. Place : ECP INTO UPPER EAST COAST ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE