

# Kp 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

HNT,  
 (LKK)  
 24/06/19  
 Mon

13/06/2019

Owner: MKM CAR LEASING PTE LTD

Not Authorized  
 11/12/19 @ 3200L 4-12/19  
 Penny After Payer

## ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLV172D

|                                      |                                         |    |              |       |
|--------------------------------------|-----------------------------------------|----|--------------|-------|
| 1pc                                  | rear tailgate                           | 12 | \$ 1,218.45  | ✓     |
| 1pc                                  | rear tailgate outer garnish             | 12 | \$ 371.25    | X     |
| 1pc                                  | rear tailgate "TOYOTA" logo             | 12 | \$ 61.10     | X     |
| 1pc                                  | rear tailgate "PRIUS" emblem            | 12 | \$ 63.90     | ✓     |
| 1pc                                  | rear tailgate "HYBRID" emblem           | 12 | \$ 61.10     | ✓     |
| 1set                                 | rear tailgate windscreen glass moulding | 12 | \$ 182.28    | ✓     |
| 1pc                                  | rear tailgate inner lock                | 12 | \$ 374.45    | X     |
| 1pc                                  | rear tailgate inner rubber              | 12 | \$ 381.90    | X     |
| 1pc                                  | rear tailgate inner garnish             | 12 | \$ 781.90    | X     |
| 1pc                                  | rear LH taillamp                        | 12 | \$ 581.90    | ✓     |
| 2pcs                                 | rear taillamp lower bracket @\$132.25   | 12 | \$ 264.50    | ✓     |
| 1pc                                  | rear bumper                             | 12 | \$ 981.90    | ✓     |
| 2pcs                                 | rear bumper side retainer @\$132.45     | 12 | \$ 264.90    | ✓     |
| 2pcs                                 | rear bumper side reflector @\$181.50    | 12 | \$ 363.00    | X     |
| 1pc                                  | rear end panel                          | 12 | \$ 781.10    | X     |
| 1pc                                  | rear end panel outer sensor             | 12 | \$ 260.00    | X     |
| 1pc                                  | rear end panel inner garnish            | 12 | \$ 374.85    | X     |
| 1pc                                  | rear float panel                        | 12 | \$ 981.50    | X     |
| 1pc                                  | rear float panel garnish                | 12 | \$ 585.20    | ✓     |
| 1pc                                  | rear LH fender inner garnish            | 12 | \$ 758.85    | X     |
|                                      |                                         |    | \$ 9,694.03  |       |
| less 25%                             |                                         |    | \$ 2,423.51  |       |
|                                      |                                         |    | \$ 7,270.52  |       |
| 1set                                 | rear parking sensor                     | 12 | \$ 280.00    | 2005m |
| 1set                                 | rear number plate & casing              | 12 | \$ 50.00     | X     |
| remove & refix rear windscreen glass |                                         |    | \$ 120.00    | ✓     |
| sealant                              |                                         |    | \$ 80.00     | 405m  |
| tuffkote                             |                                         |    | \$ 120.00    | 30L   |
| wiring                               |                                         |    | \$ 80.00     | 20L   |
| spray painting                       |                                         |    | \$ 1,000.00  | 600L  |
| labour charges                       |                                         |    | \$ 1,000.00  | 500L  |
| Total                                |                                         |    | \$ 10,000.52 |       |

LKK Auto Consultants hence notify  
 Repairer of the following:  
 • To resurvey before after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

