

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8619Y

MAKE :

MODEL : HYUNDAI IONIQ

CHINA

DATE 13/6/2019 15:35

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X m</i>			\$ 459.40
	Rear Bumper Centre Moulding Assy <i>—</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>X</i>			\$ 47.50
	Rear Bumper Stay <i>?</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>?</i>		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips <i>—</i>			\$ 22.00
	Rear Bumper Reflector Lamp (LH) <i>X</i>			\$ 31.90
	SUB TOTAL			\$ 1,216.35
	LESS 20%			\$ 243.27
	DISCOUNTED TOTAL			\$ 973.08
	Labour Charge			
	Panel Beating			\$ 400.00 <i>200</i>
	Spray Painting Charge			\$ 350.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	Towing Charge			\$ 60.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 1,030.00
	ESTIMATE TOTAL			\$ 2,003.08
	<div><p><i>Kahin 11/11/19</i></p><p><i>14/6/19 1045h</i></p><p><i>2 Dy,</i></p><p><i>P/P</i></p><p><i>After Repair p/bt</i></p><p><i>Larry Ng</i></p></div>			
	<div><p>LKK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<p>Acknowledged by Repairer</p><p>Signature:</p><p>Date:</p></div>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				