

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740150W, GST Reg. No. M3-0020081-X



FINAL REPORT

Estimate No. : b1 51607
Date Estimated : 18/06/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -

Tan YunXin, Melissa (Chen Yunxin, Melis
28A Jalan Lempeng
#13-12

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 128808

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MLEAGE
SLV620C	VB97282	21/12/2017	218iA/2	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dented areas caused by the accident	850.00 /	10.00	765.00
To respray rear bumper	934.00 /	10.00	840.60
To check electrical wiring systems and lightings at the rear section for proper function	150.00 /	10.00	135.00
Sundries	80.00 /	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
SET MOUNTS PDC SENSOR REAR	58.60 /	1.00	3.00	56.84
REAR BUMPER CARRIER	416.45 /	1.00	3.00	403.96
REAR BUMPER TRIM STRIP (LINE SPORT)	90.49 /	1.00	3.00	87.78
REAR BUMPER PANEL PRIMED (LINES)	1,018.95 /	1.00	3.00	988.38
(DG/SL) ADHESIVE SET K6	53.05 /	1.00	3.00	51.46

SUPPLEMENTARY ITEMS

Total Labour :	1,820.60
Total Parts :	1,588.42
Total Labour & Parts :	3,409.02
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,409.02
GST @7%:	238.63
Grand Total :	3,647.65

Mon 24/06 @ 9am

SLV620C

SER

Dear Dealer

Performance Motors Limited

A Siew Doozy Motors Company
Co./Reg. No. 197921559W GST Reg. No. MO-0020081-2
Toll-Free Number: 1800-2255269

311, Alexandra Road
Siew Doozy Performance Centre
Singapore 159944
Fax: 64794773

289, Kengong Xiang Road
East Coast Centre
Singapore 438140
Fax: 43445773

311, Alexandra Road
Siew Doozy Performance Centre
Singapore 159944
Fax: 64794773

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

On:

GST REG. NO : M2 - 0020081

18 JUN 2019

ESTIMATE

Estimate No. : b1 51607 Page No. : 1 of 4
Date Estimated : 18/06/2019
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -

Tan YunXin, Melissa (Chen Yunxin, Melis
28A Jalan Lempeng
#13-12

Singapore 128808

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV620C	VB97282	21/12/2017	218iA/2	0

DESCRIPTION

To replace rear bumper & attachments including to knock out dented area caused by the accident

850 1,275.00

To respray rear bumper

979 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

0 80.00

Total Labour 1: 2,570.00

DESCRIPTION

SET MOUNTS PDC SENSOR REAR

QTY	PRIC	VALUE
1	58.60	58.60

REAR BUMPER CARRIER

1	416.45	416.45
---	--------	--------

REAR BUMPER CENTRE GUIDE

1	48.35	48.35
---	-------	-------

REAR BUMPER TRIM STRIP (LINE SPORT)

1	90.50	90.50
---	-------	-------

REAR BUMPER PANEL PRIMED (BA

1	1,018.95	1,018.95
---	----------	----------

RR FLAP TOWING EYE PRIMED

1	38.95	38.95
---	-------	-------

DECOUPLING RING PDC TORQUE CONVERTER

2	5.05	10.10
---	------	-------

PDC SENSOR MINERALWEISS (A96

2	368.80	737.60
---	--------	--------

(DG/SL) ADHESIVE SET K8

1	53.05	53.05
---	-------	-------

Total Parts : 2,472.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Repair Site: Claim Site:

Date & Time: 14/6/19, 11:00am Excess \$:

Surveyor's Name: Steve Sign:

Surveyor's Tel: 8339 8873 Authorized: Yes / No

Authorized Date: Time:

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PMS: Yes / No

Surveyor's E-mail:

Labour 1 : 2,570.00

Parts : 2,472.55

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 352.98

Grand Total : 5,395.53

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **