

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMH4398E
Chassis No : MRHFC5650JT002418
Model : CIVIC 1.6 VTI YM2018
Owner's Name : ANGELA TAN CHYE YUN
Ins Policy No. :
Date of Accident : 15/6/2019

Document No. : SQT19002670 Page 6
Date : 18. Jun 2019
Customer No. : WZM003
Svc Advisor : NG SIN HAI
Engine No : R16B25502840
Date | Time : 18. Jun 2019 8:54:33 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
72910-TEA-T01	MOLDING ASSYR.RR.DOOR ? ✓ <i>new</i>	1	25.20	✓ 18.90	25.20	1.76	26.96
72925-TBA-A01	MOLDING ASSYR.RR.DOOR SASH ? ✓ <i>new</i>	1	29.20	✓ 21.90	29.20	2.04	31.24
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH ? ✓ <i>cut</i>	1	28.30	✓ 21.22	28.30	1.98	30.28
72721-TEA-T01	GARNISHR.RR.DOOR QUARTER OUT ?	1	23.50		23.50	1.65	25.15
72956-TEA-T01	GARNISHR.RR.CENTER CORNER ?	1	1.30		1.30	0.09	1.39
65610-TEA-T00ZZ	FRAME COMP,R.RR.FLOOR ? } <i>X'sure</i>	1	685.90		685.90	48.01	733.91
65660-TEA-T00ZZ	FRAME COMP,L.RR.FLOOR ?	1	685.90		685.90	48.01	733.91
64350-TEA-T00ZZ	SUPPORT COMPR.RR.SHELF ?	1	48.90		48.90	3.42	52.32
64750-TEA-T00ZZ	SUPPORT COMPL.RR.SHELF ?	1	48.90		48.90	3.42	52.32
64330-TEC-U10ZZ	WHEELHOUSE COMPR.RR <i>repair</i>	1	256.30		256.30	17.94	274.24
64730-TEC-U00ZZ	WHEELHOUSE COMPL.RR X	1	256.30		256.30	17.94	274.24
64301-TEA-T00ZZ	PANELR.RR.INSIDE ?	1	212.00		212.00	14.84	226.84
64701-TEA-T00ZZ	OANELL.RR.INSIDE ?	1	211.80		211.80	14.83	226.63
64320-TEA-305ZZ	EXTSN COMPR.RR.W/ARCH RFCMNT ? } <i>X'sure</i>	1	37.10		37.10	2.60	39.70
64720-TEA-305ZZ	EXTSN COMPL.RR.W/ARCH RFCMNT ?	1	37.10		37.10	2.60	39.70
66501-TEA-T00ZZ	STIFFENERRR.SHELF FR. ?	1	42.40		42.40	2.97	45.37
66500-TET-H00ZZ	SHELF COMPRR.PARCEL ?	1	244.50		244.50	17.12	261.62
90108-S0A-003	BOLT FLANGE 6X15 ?	6	2.00		12.00	0.84	12.84
65550-TEA-T00ZZ	PAN COMPSPARE TIRE X	1	216.70		216.70	15.17	231.87
66100-TEC-307ZZ	PANEL SETRR. X <i>repeated</i>	1	243.10		243.10	17.02	260.12
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE X <i>repeated</i>	1	26.70		26.70	1.87	28.57
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE ?	1	26.70		26.70	1.87	28.57
63321-TEA-T00ZZ	GUTTERR.RR.UPPER ?	1	29.40		29.40	2.06	31.46
63322-TEA-T00ZZ	ADAPTERR.RR.COMBINATION LIGHT ?	1	60.70		60.70	4.25	64.95
63721-TEA-T00ZZ	GUTTERL.RR.UPPER ? } <i>X'sure</i>	1	29.40		29.40	2.06	31.46
63722-TEA-T00ZZ	ADAPTERL.RR.COMBINATION LIGHT ?	1	60.70		60.70	4.25	64.95
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE ? } <i>533.70</i>	1	711.60		711.60	49.81	761.41
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE ?	1	711.60		711.60	49.81	761.41
75450-TEA-T01	OUTLET ASSYR.RR.AIR ? } <i>6.15</i>	1	8.10		8.10	0.57	8.67

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.