

SS. REC. BY:

REF: CS/MSG/19010295/ R/vd302

Special Instruction:

Surveyor: Rusu**ASSIGNMENT (Office)**From (Person): Pauline Thomof msigDate/Time: 18.6.19 4:23 p.m

Estimated Cost: _____

Bill to: _____

CD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 4398EInsured: SMH 7196Bat Workshop m/s Kah motorTel: 64715419of 255 Alexandra RoadPolicy No: 29112616 mcy

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 15.6.19

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement: _____

Date/Time: 18.6.19 2:23 p.mPerson Contacted: Sim HaiVehicle IN/OUT

Date/Time	Action/Instruction
	<u>Ishtmatl (✓)</u>
	<u>SMH 4398E -x</u>
	<u>SMH 7196B -x</u>
<u>19/6/19</u>	<u>Sand preli revised via merimen</u>
<u>18/7/19</u>	<u>Final fig \$27,034.08 confirmed by email (Ref 37,309.53, 58/19)</u>

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SMH 4398E**
 at Workshop m/s **KAT MOTOR**
 of **255, ALEXANDRA RD**
 Insured: **MSIA**

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: **94K**

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMH 4398E** Yr Regn: **2019 / JAN**Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **HONDA CIVIC 1.6 VTI** c.c. **1597**Colour: **BLUG** A/C: Insured / Std / NI / NASp. Reading: **006511** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **MRHFC5650J T002418**Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: **215/55R16**R: **~**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. **6** mm R/Bal. **6** mmL/Bal. **6** mm L/Bal. **6** mmD.O.A. **18/06/19**D.O.I. **18/06/19**Survey held at **KAT MOTOR**Des. of Damages: Frt / Rear / ☒ O/S / ☒ N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 8 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) **18/7 - typist**Report Format: **merimen**Lump Sum / I.B.I: (\$) **27,034.08**Days Of Repair: **23**Resurvey No. of Trip: **2**Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

300**11****311**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Int Auth'd	Status
Main	(Not Notified)		18 Jun 2019 14:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	BlueCar East Asia Pte Ltd, Co. Reg. No.: 201617259H								
Main Claimant:	ANGELA TAN CHYE YUN, ID: S7341669H								
Vehicle Reg. No.:	SMH4398E	Date of Loss:	15/06/2019 00:00 - 59 [4 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29112616MCY (Comprehensive) Coverage: 30/01/2019 - 31/12/2019						
Vehicle Reg. No. (Insured):	SMH7196B	Policy No. (Claimant):							
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/06/2019]								
Adj Asg. Remarks:	Car In, request survey ASAP.Liab: dispute (OI NR) Contact: Sin Hai @ 6471 5419 on WP. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Pauline Tham	Date: 19 Jun 2019
Preliminary Advice	

Insured Vehicle No	: SMH7196B	Accident Date	: 15/06/2019
TP Vehicle No	: SMH4398E	Assignment Date	: 18/06/2019
Make	: HONDA CIVIC	Est. Duration of Repair	: 23
Date of Inspection	: 18/6/2019		
Inspection At	: KAH MOTOR CO SDN BHD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s and n/s body parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	60,289.50
Revised Amount	:S\$	19,842.20
Check Items (Estimated)	:S\$	18,262.90
Total	:S\$	38,105.10
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Wednesday, 19 June 2019 2:23 PM
To: Ng Sin Hai
Cc: Veron Chen (LKKAUTO)
Subject: SMH 4398E DOA : 15/06/19

Hi Sin Hai,

Just to inform that repair limit for this case is 54K


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1669H
Vehicle Detail	
Vehicle No.:	SMH4398E
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	R16B25502840
Chassis No.:	MRHFC5650JT002418
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,890.00
Original Registration Date:	23 Jan 2019
First Registration Date:	23 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$19,890.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jan 2029
PARF Rebate Amount:	\$14,917.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,501.00
COE Rebate Amount:	\$24,459.00
Total Rebate Amount:	\$39,376.00

The information contained herein is correct as at 19 Jun 2019

OK

94000

39,376

54,624

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/06/2019 20:42
Date Of Accident	15/06/2019 17:15
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH4398E
Insured/Policyholder	
Name Of Registered Owner	ANGELA TAN CHYE YUN
NRIC No	S7341669H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91736206
Alternative Phone No	OFFICE-91736206

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10898271
Cover Note Number	

Driver

Name of Driver	ANGELA TAN CHYE YUN
NRIC No	S7341669H
Date Of Birth	13/11/1973
Occupation	INDOOR
Date Of Driving Pass	19/10/2005
Driving Experience	13 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91736206
Fax Number	
Contact Number	OFFICE-91736206
Email Address	NOEMAIL

Address S

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1

NAME: : ANG WEISHAN

GENDER: : FEMALE

Passenger 2

NAME: : FOO MEITING

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMH7196B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE HIRE

Name of Driver



NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLH5858A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

Vehicle Number: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____



Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Vehicle Number: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20190615/2146

A : SMH4378E

B : SMH 7196B

C : SLH 5858A

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



**SINGAPORE
POLICE FORCE**



T/20190615/2146

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

1 of 4

Report No. T/20190615/2146

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/06/2019 19:37		Vide Report No.:		Station Diary No.: 124	
Informant's Particulars					
Name of Informant: ANGELA TAN CHYE YUN			Address: APT BLK 102 SPOTTISWOODE PARK ROAD #07-82 SINGAPORE 080102		
ID Type / ID No.: NRIC NO / S7341669H			Contact No.: Home/Office: Mobile: 91736206		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 45	Date of Birth: 13/11/1973	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: IT MANAGER		Driving Licence Information: Class:		Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/06/2019 17:15	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Along PIE before Bedok North Avenue 3 exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLH5858A	Car				Seriously Damaged	0
SMH4398E	Car	HONDA	CIVIC 1.6 VTI CVT	Blue	Seriously Damaged	2
SMH7196B	Car				Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20190615/2146

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

2 of 4
Report No. T/20190615/2146

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMH4398E	AVIVA LTD	10898271	23/01/2019	22/01/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	TAN SWEE JUN, DARREN		ID No.	S8237099D
Related Vehicle	SLH5858A (Car)		Contact No.	97607598
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	ANGELA TAN CHYE YUN		ID No.	S7341669H
Related Vehicle	SMH4398E (Car)		Contact No.	91736206
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	EDDY ZULKARNEAN BIN OSMAN		ID No.	S9142141J
Related Vehicle	SMH7196B (Car)		Contact No.	93687103
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190615/2146

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

3 of 4

Report No. T/20190615/2146

CONTINUATION OF REPORT

Brief Details.

On the 15/06/2019 at about 1716hrs, I was driving my vehicle SMH4398E with two of my friends onboard, travelling along the middle lane of PIE, travelling towards Tampines. The traffic volume was rather heavy and slow moving. As I continued straight, a blue SG vehicle SMH7196B travelling slightly in front of my vehicle along the leftmost lane suddenly moved into my lane and the front right portion of the blue SG vehicle collided with the front left portion of my vehicle. The large impact caused my vehicle to swerved into the first lane. A third vehicle SLH5858A that was travelling along the first lane could not stop in time and collided into my vehicle. After the collisions, all of the drivers stopped and alighted from their vehicles. The other two vehicles did not have any passengers on board, and no one was visibly injured. As all the vehicles were rather badly damaged, we called for the traffic police.

Shortly after, the traffic police arrived and interviewed all the involved parties. I handed over my memory card that contained footages of the accident to the officer. We were then advised to lodge a traffic accident report vide G/20190615/0167.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999



T/20190615/2146

4 of 4


Report No. T/20190615/2146

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 LIM WEI SIANG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 15/06/2019 19:37
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	Classification Of Case:
Authentication Stamp NP168	

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification Number: S7341669H

NAME: ANGELA TAN CHYE YUN (ANGELA CHEN CAYUN)

Valid Until: 13 Nov 1973

Issue Date: 14 Apr 2007

9914517538

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7341669H



Name
ANGELA TAN CHYE YUN
(CHEN CAIYUN)
陳彩雲

Race
CHINESE

Date of birth
13-11-1973

Country of birth
SINGAPORE



Sex
F

IC7341669H

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

PAGE THREE

Class 2 Motor Cars < 3000kg with < 7 passengers, as driver 19 Oct 2006
of the driver, and other motor vehicles < 3000kg

License No: 573418090

HP 425A

8000490



Serial No. 87341669H



Date of Birth
21-04-2007

Address
APT BLK 102 SPOTTERWOODS PARK ROAD
#07-02
SINGAPORE 080102



Aviva Ltd., 4 Shenton Way, #01-01/02/03/04, Singapore 068807. Tel: (65) 6801 9900. www.aviva.com.sg

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189 OF THE REVISED EDITION)
IN FORCE IN SINGAPORE
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1966 (EDITION
REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

CERTIFICATE NUMBER: 10893271

1) VEHICLE REGISTRATION NO.
CHASSIS NO.
ENGINE NO.

SAH4798E
MRHFC545017002418
R16B25502840

2) NAME OF INSURED

FAMILY NAME
GIVEN NAME

TAN
CHYE YUN ANGELA

3) EFFECTIVE DATE OF COMMENCEMENT OF INSURANCE FOR THE
PURPOSE OF THE ACT

23-Jan-2019 00:00hours

4) DATE OF EXPIRY OF INSURANCE

22-Jan-2021 23:59hours

5) PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE

Any driver

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss.

Please refer to the policy document for full terms and conditions.

6) LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the insured's business. The Policy does not cover use for hire or reward, livery or driving tests, racing, speed-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 25 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

NAMED DRIVER

7) FINANCE COMPANY

OCBC BANK LIMITED

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia), or any amendment, act or acts passed in substitution thereof.

Issued in Singapore: 24-Jan-2019 at 14:21hours

Aviva Ltd.

IMPORTANT NOTE:

- If you want to cancel your policy at any time, you will need to return the certificate to us.
- You MUST report all accidents to us within 24 hours of the occurrence regardless of whether you intend to claim on your own policy or not, or whether your car is damaged or not. Should you fail to do so, your No Claims Discount could be affected and your claim may be prejudiced.

Nishit Majumdar
Chief Executive Officer

In case of accident or windscreen damage, please call 6333 2222 (24 hours) immediately.

ORIGINAL



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMH4398E
Chassis No : MRHFC5650JT002418
Model : CIVIC 1.6 VTI YM2018
Owner's Name : ANGELA TAN CHYE YUN
Ins Policy No. :
Date of Accident : 15/6/2019

Document No. : SQT19002670 Page 1
Date : 18. Jun 2019
Customer No. : WZM003
Svc Advisor : NG SIN HAI
Engine No : R16B25502840
Date | Time : 18. Jun 2019 8:54:33 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
60261-TBA-A00ZZ	PANELL FENDER <i>huc</i>	1	248.90	✓ 186.67	248.90	17.42	266.32
74151-TEA-T00	FENDER L FR INNER <i>de</i>	1	51.10	✓ 38.32	51.10	3.58	54.68
60263-TBA-A00ZZ	BRACKET AL FR FENDER <i>re</i>	1	29.40	✓ 22.05	29.40	2.06	31.46
60266-TEM-M00ZZ	STAY, L FR FENDER UPPER <i>re</i>	1	18.10	✓ 13.57	18.10	1.27	19.37
74155-TEA-T00	ENCLOSURE L FR FENDER <i>re</i>	1	8.90	✓ 6.67	8.90	0.62	9.52
74295-TEA-T00	PAD L FR FENDER PARTITION <i>? X sue</i>	1	44.10		44.10	3.09	47.19
91501-TR0-003	CLIP INNER FENDER <i>re</i>	22	2.80	✓ 46.20	61.60	4.31	65.91
33150-TEC-Q01	HEADLIGHT ASSYL <i>con</i>	1	585.70	✓ 439.27	585.70	41.00	626.70
34350-TET-H01	LIGHT ASSYL SIDE TURN <i>re</i>	1	33.10	✓ 24.82	33.10	2.32	35.42
71101-TEA-T00ZZ	FACE FR BUMPER <i>de</i>	1	579.90	✓ 434.92	579.90	40.59	620.49
71102-TBA-A10	GRILLE FR BUMPER LOWER <i>? X sue</i>	1	36.10		36.10	2.53	38.63
71190-TEA-T00	BEAM L FR BUMPER UPPER <i>? ✓ bt</i>	1	26.70	✓ 20.02	26.70	1.87	28.57
71140-TEA-T00	BEAM R FR BUMPER UPPER <i>? X sue</i>	1	26.70		26.70	1.87	28.57
71198-TEA-T01	SPACER L FR BUMPER SIDE <i>re</i>	1	10.40	✓ 7.80	10.40	0.73	11.13
71193-TEA-T01	SPACER R FR BUMPER SIDE <i>re</i>	1	10.40	✓ 7.80	10.40	0.73	11.13
71206-TEA-T00	PLATE L FR BUMPER SIDE INDUCTN <i>? X sue</i>	1	44.00		44.00	3.08	47.08
71108-TEA-T00	GARNISH L FR BUMPER SIDE <i>scr</i>	1	18.00	✓ 13.50	18.00	1.26	19.26
91505-TM8-003	CLIP BUMPER <i>re</i>	16	2.30	✓ 27.60	36.80	2.58	39.38
71130-TEA-T00	BEAM COMP FR BUMPER <i>? X sue</i>	1	345.90		345.90	24.21	370.11

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMH4398E
Chassis No : MRHFC5650JT002418
Model : CIVIC 1.6 VTI YM2018
Owner's Name : ANGELA TAN CHYE YUN
Ins Policy No. :
Date of Accident : 15/6/2019

Document No. : SQT19002670
Date : 18. Jun 2019
Customer No. : WZM003
Svc Advisor : NG SIN HAI
Engine No : R16B25502840
Date | Time : 18. Jun 2019 8:54:33 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71150-TEA-T00	BEAM COMPFR BUMPER CENTER UPP ? x suc	1	214.80		214.80	15.04	229.84
71410-TEA-T01	BULKHEAD ASSYFR. ? H ✓	1	525.90 ✓ 394-42		525.90	36.81	562.71
60947-TEA-T00ZZ	SUPPORTL FR. SIDE FRAME ?	1	31.10		31.10	2.18	33.28
60921-TBA-A00ZZ	BRACKETL FR. SUB FRAME FR. ?	1	32.60		32.60	2.28	34.88
60919-TEA-T00ZZ	FLANGEL FR. BUMPER BEAM EXTENS ?	1	34.20		34.20	2.39	36.59
60922-TEA-T00ZZ	PLATEL FR. SIDE FRAME ?	1	31.10		31.10	2.18	33.28
71129-TEA-T01	EXTENSION ASSYL FR. GRILLE ?	1	85.60		85.60	5.99	91.59
71121-TEA-T01	BASE FR. GRILLE CHROME ? ✓ cut	1	73.80 ✓ 55-35		73.80	5.17	78.97
71125-TEA-T01	MOLDINGFR. GRILLE ? x suc	1	100.40		100.40	7.03	107.43
75700-TBA-A00	EMBLEM ? ✓ ne	1	15.00 ✓ 11-25		15.00	1.05	16.05
90301-ST0-003	NUTPUSH 3MM ? ✓ ne	2	2.10 ✓ 3-15		4.20	0.29	4.49
44305-TEA-T01	DRIVESHAFT ASSY, R. ?	1	927.90		927.90	64.95	992.85
51611-TEA-T01	ABSORBER UNTR. FR. SHOCK ?	1	231.60		231.60	16.21	247.81
51684-TBA-A01	RUBBER R. FR. SPRING MOUNT LOWER ?	1	4.20		4.20	0.29	4.49
51401-TEA-T01	SPRING, R. FR. ? x suc	1	44.30		44.30	3.10	47.40
51670-TEA-T01	RUBBER COMPFR. SHOCK ABS MTG ?	1	38.20		38.20	2.67	40.87
51402-TEX-R01	RUBBER R. FR. SPRING MOUNT UPPER ?	1	7.70		7.70	0.54	8.24
51350-TEA-T00	ARM COMPFR. FR. LOWER ? x suc	1	215.40		215.40	15.08	230.48
51220-TEA-T01	JOINT COMPFR. LOWER BALL ? ✓ H	1	47.70 ✓ 55-T1		47.70	3.34	51.04
51211-TEA-T10	KNUCKLER FR. ?	1	141.10		141.10	9.88	150.98
51320-TBA-A02	LINK COMP, FR. STABILIZER ?	1	21.70		21.70	1.52	23.22
51300-TEA-T01	STABILIZER COMPFR. ?	1	141.10		141.10	9.88	150.98
51308-TEA-T00	BRACKET STABILIZER HOLD ?	1	4.10		4.10	0.29	4.39
53620-TEC-Q01	BOX ASSY, POWER STEERING GEAR ?	1	1916.10		1916.10	134.13	2050.23
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X ?	1	45.00		45.00	3.15	48.15
32131-TEA-R00	SUB CORDRR. BUMPER CORNER SENS ?	1	28.10		28.10	1.97	30.07
39670-TEX-Y01	SENSOR UNIT PARKING ?	1	62.50		62.50	4.38	66.88
39680-TEX-Y41ZT	SENSOR ASSY, PARKING ?	4	145.80		583.20	40.82	624.02
33500-TEA-T01	TAILLIGHT ASSY. Mij ✓	1	261.40 ✓ 196-05		261.40	18.30	279.70

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance. Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581
 Registration No : SMH4398E
 Chassis No : MRHFC5650JT002418
 Model : CIVIC 1.8 VTI YM2018
 Owner's Name : ANGELA TAN CHYE YUN
 Ins Policy No. :
 Date of Accident : 15/6/2019

Document No. : SQT19002670 Page 3
 Date : 18. Jun 2019
 Customer No. : WZM003
 Svc Advisor : NG SIN HAI
 Engine No : R16B25502840
 Date | Time : 18. Jun 2019 8:54:33 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33550-TEA-T01	TAILLIGHT ASSYL <i>X</i>	1	281.30		281.30	19.69	300.99
34150-TEX-Y01	LIGHT ASSYR.LID <i>X</i> } <i>sur</i>	1	122.30		122.30	8.56	130.86
34155-TEX-Y01	LIGHT ASSYL.LID <i>X</i>	1	122.30		122.30	8.56	130.86
68500-TEA-N00ZZ	LID COMP TRUNK <i>repair</i>	1	486.20		486.20	34.03	520.23
68610-TEA-T10ZZ	HINGE COMPR.TRUNK <i>X</i>	1	44.80		44.80	3.14	47.94
68660-TEA-T10ZZ	HINGE COMPL.TRUNK <i>X</i> } <i>sur</i>	1	44.80		44.80	3.14	47.94
74851-TEA-003	LOCK ASSYTRUNK <i>X</i>	1	74.30		74.30	5.20	79.50
74865-TEA-T01	WEATHERSTRIPTRUNK LID <i>X</i>	1	70.00		70.00	4.90	74.90
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE <i>repair</i>	1	100.60		100.60	7.04	107.64
75722-TBA-A00	EMBLEM SETRR. <i>new</i> ✓ <i>8.85</i>	1	11.80		11.80	0.83	12.63
75725-TEA-T01	EMBLEMRR. <i>new</i> ✓ <i>8.35</i>	1	11.00		11.00	0.77	11.77
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>new</i> ✓ <i>463.90</i>	1	617.20		617.20	43.20	660.40
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>new</i> ✓ <i>37.30</i>	1	36.40		36.40	2.55	38.95
71503-TEA-T00	GARNISH R.RR.BUMPER SIDE <i>new</i> ✓ <i>6.30</i>	1	8.40		8.40	0.59	8.99
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>new</i> ✓ <i>1.72</i>	1	2.30		2.30	0.16	2.46
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE <i>X</i> } <i>sur</i>	1	7.80		7.80	0.55	8.35
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER ? <i>X</i>	1	164.70		164.70	11.53	176.23
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE ? <i>X</i>	1	2.30		2.30	0.16	2.46
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>new</i> ✓ <i>8.62</i>	1	11.50		11.50	0.81	12.31
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>new</i> ✓ <i>8.62</i>	1	11.50		11.50	0.81	12.31
91505-TM8-003	CLIP,BUMPER <i>new</i> ✓ <i>12.87</i>	7	2.30		16.10	1.13	17.23
66100-TEC-307ZZ	PANEL SETRR. <i>repair</i>	1	243.10		243.10	17.02	260.12
65550-TEA-T00ZZ	PAN COMPSPARE TIRE <i>X</i>	1	216.70		216.70	15.17	231.87
84640-TEA-Z01ZA	LINING ASSYRR.PANEL <i>X</i>	1	50.30		50.30	3.52	53.82
84521-TEA-Q01ZA	LID ASSYSPARE TIRE <i>X</i> } <i>sur</i>	1	60.20		60.20	4.21	64.41
84542-TET-H00	BOX COMPTOOL <i>X</i>	1	38.00		38.00	2.66	40.66
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE <i>X</i>	1	48.90		48.90	3.42	52.32
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE <i>X</i>	1	48.90		48.90	3.42	52.32
72841-SH3-315	OILSHEET <i>X</i>	3	40.70		122.10	8.55	130.65

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SMH4398E

Chassis No : MRHFC5650JT002418

Model : CIVIC 1.6 VTI YM2018

Owner's Name : ANGELA TAN CHYE YUN

Ins Policy No. :

Date of Accident : 15/6/2019

Document No. : SQT19002670

Date : 18. Jun 2019

Customer No. : WZM003

Svc Advisor : NG SIN HAI

Engine No : R16B25502840

Date | Time : 18. Jun 2019 8:54:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 4

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE ? <i>x 800</i>	1	26.70		26.70	1.87	28.57
71101-TEA-T00ZZ	FACEFR.BUMPER <i>X repeated</i>	1	579.90		579.90	40.59	620.49
71102-TBA-A10	GRILLEFR.BUMPER LOWER <i>X repeated</i>	1	36.10		36.10	2.53	38.63
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE <i>scr /</i>	1	18.00		18.00	1.26	19.26
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE <i>X repeated</i>	1	18.00		18.00	1.26	19.26
71193-TEA-T01	SPACERR.FR.BUMPER SIDE <i>X repeated</i>	1	10.40		10.40	0.73	11.13
71198-TEA-T01	SPACERL.FR.BUMPER SIDE <i>X repeated</i>	1	10.40		10.40	0.73	11.13
91505-TM8-003	CLIP,BUMPER <i>X repeated</i>	16	2.30		36.80	2.58	39.38
71121-TEA-T01	BASE,FR.GRILLE CHROME <i>X repeated</i>	1	73.80		73.80	5.17	78.97
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE <i>X repeated</i>	1	85.60		85.60	5.99	91.59
71125-TEA-T01	MOLDINGFR.GRILLE <i>X repeated</i>	1	100.40		100.40	7.03	107.43
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE <i>X repeated</i>	1	85.60		85.60	5.99	91.59
74146-TEA-T00	RUBBERHOOD SEAL <i>na /</i>	1	27.60		27.60	1.93	29.53
75700-TBA-A00	EMBLEM <i>X repeated</i>	1	15.00		15.00	1.05	16.05
90301-ST0-003	NUTPUSH 3MM <i>X repeated</i>	2	2.10		4.20	0.29	4.49
74110-TEA-T00	COVER ASSY,ENGINE UNDER ? <i>X</i>	1	213.20		213.20	14.92	228.12
71130-TEA-T00	BEAM COMPFR.BUMPER ? <i>X</i>	1	345.90		345.90	24.21	370.11
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP ? <i>X</i>	1	214.80		214.80	15.04	229.84
71410-TEA-T01	BULKHEAD ASSYFR <i>X repeated</i>	1	525.90		525.90	36.81	562.71
80100-TBA-A01	CONDENSER ASSY ? <i>X</i>	1	704.40		704.40	49.31	753.71
19010-5FA-Z01	RADIATOR COMP ? <i>X</i>	1	1100.50		1100.50	77.04	1177.54
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 ? <i>na /</i>	6	23.20		139.20	9.74	148.94
80525-TBA-A01	SENSOR ASSYAMBIENT ? <i>X</i>	1	40.10		40.10	2.81	42.91
91555-TBA-K01	CLIPAMBIENT SENSOR ? <i>X</i>	1	5.40		5.40	0.38	5.78
60100-TEA-T00ZZ	HOOD COMPENGINE <i>bt /</i>	1	598.70		598.70	41.91	640.61
80050-TG7-000	LABLE AIR CON <i>na /</i>	1	0.80		0.80	0.06	0.86
19043-5AA-E00	LABEL, COOLANT INFORMATION ? <i>na /</i>	1	10.00		10.00	0.70	10.70
71140-TEA-T00	BEAMR.FR.BUMPER UPPER ? <i>X</i>	1	26.70		26.70	1.87	28.57
33100-TEC-Q01	HEADLIGHT ASSY,R. ? <i>X</i>	1	585.70		585.70	41.00	626.70

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMH4398E
Chassis No : MRHFC5650JT002418
Model : CIVIC 1.6 VTI YM2018
Owner's Name : ANGELA TAN CHYE YUN
Ins Policy No. :
Date of Accident : 15/6/2019

Document No. : SQT19002670 Page 5
Date : 18. Jun 2019
Customer No. : WZM003
Svc Advisor : NG SIN HAI
Engine No : R16B25502840
Date | Time : 18. Jun 2019 8:54:33 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71190-TEA-T00	BEAML.FR.BUMPER UPPER ? x see	1	26.70		26.70	1.87	28.57
33150-TEC-Q01	HEADLIGHT ASSYL. can't repeated	1	585.70		585.70	41.00	626.70
60211-TBA-A00ZZ	PANELR.FENDER blue ✓	1	248.90	✓ 186.67	248.90	17.42	266.32
60213-TBA-A00ZZ	BRACKET AR.FR.FENDER ✓	1	29.40	✓ 23.15	29.40	2.06	31.46
60261-TBA-A00ZZ	PANELL.FENDER x repeated	1	248.90		248.90	17.42	266.32
60263-TBA-A00ZZ	BRACKET AL.FR.FENDER x repeated	1	29.40		29.40	2.06	31.46
90853-SJA-A00	RIVET 4.8MM new ✓	10	1.90	✓ 14.25	19.00	1.33	20.33
74101-TEA-T00	FENDERR.FR INNER ? x see	1	51.10		51.10	3.58	54.68
74151-TEA-T00	FENDERL.FR INNER ? x repeated	1	51.10		51.10	3.58	54.68
91501-TR0-003	CLIP INNER FENDER x repeated	22	2.80		61.60	4.31	65.91
67010-TEA-T00ZZ	PANEL COMPR.FR.DOR can't repair	1	784.20		784.20	54.89	839.09
67410-T2M-T02ZZ	HINGER.FR.DOR UPPER ?	1	38.40		38.40	2.69	41.09
67420-T2M-T02ZZ	HINGER.FR.DOR LOWER ?	1	39.30		39.30	2.75	42.05
72340-TEA-T01	CHECKER COMPFR.DOR ?	1	13.50		13.50	0.95	14.45
72328-TEA-T01	SEALR.FR.DOR LOWER ?	1	8.20		8.20	0.57	8.77
72336-TEA-T01	SEALR.FR.DOR FR.GAP ?	1	12.50		12.50	0.88	13.38
72425-TBA-A01	MOLDING ASSYR.FR.DOR SASH ?	1	26.50		26.50	1.86	28.36
72430-TEA-T01	GARNISH ASSYR.FR.DOR SASH ?	1	13.70		13.70	0.96	14.66
72430-TEA-T01	GARNISH ASSYR.FR.DOR SASH ?	1	13.70		13.70	0.96	14.66
72410-TEA-T01	MOLDING ASSYR.FR.DOR ? ✓ cut ✓	1	24.00	✓ 18	24.00	1.68	25.68
76208-TEA-T02	MIRROR ASSY.R. scr ✓	1	254.30	✓ 190.72	254.30	17.80	272.10
76201-TBA-A11ZN	CAP.R.SKULL ? x see	1	59.90		59.90	4.19	64.09
67050-TEA-T00ZZ	PANEL COMPL.FR.DOR bt ✓	1	784.20	✓ 588.15	784.20	54.89	839.09
72465-TBA-A01	MOLDING ASSYL.FR.DOR SASH ? ✓ cut ✓	1	26.50	✓ 14.87	26.50	1.86	28.36
72456-TEA-T01	GARNISHR.FR.CENTER CORNER ? x see	1	1.60		1.60	0.11	1.71
72470-TEA-T01	GARNISH ASSYL.FR.DOR SASH ? ✓ cut ✓	1	13.70	✓ 10.37	13.70	0.96	14.66
72450-TEA-T01	MOLDING ASSYL.FR.DOR ? ✓ cut ✓	1	24.00	✓ 18	24.00	1.68	25.68
67510-TEA-T00ZZ	PANELR.RR.DOR blue ✓	1	717.50	✓ 538.12	717.50	50.23	767.73
72828-TEA-T01	SEALRR.DOR LOWER ? (3PCS) ✓	1	6.20	✓ 4.30	6.20	0.43	6.63

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD.
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SMH4398E

Chassis No : MRHFC5650JT002418

Model : CIVIC 1.6 VTI YM2018

Owner's Name : ANGELA TAN CHYE YUN

Ins Policy No. :

Date of Accident : 15/6/2019

Document No. : SQT19002670

Date : 18 Jun 2019

Customer No. : WZM003

Svc Advisor : NG SIN HAI

Engine No : R16B25502840

Date | Time : 18 Jun 2019 8:54:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 6

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
72910-TEA-T01	MOLDING ASSY.RR.DOOR ? <i>✓</i>	1	25.20 <i>✓ 18.90</i>		25.20	1.76	26.96
72925-TBA-A01	MOLDING ASSY.RR.DOOR SASH ? <i>✓</i>	1	29.20 <i>✓ 21.90</i>		29.20	2.04	31.24
72930-TEA-T01	GARNISH ASSY.RR.DOOR SASH ? <i>✓</i>	1	28.30 <i>✓ 21.32</i>		28.30	1.98	30.28
72721-TEA-T01	GARNISHR.RR.DOOR QUARTER OUT ?	1	23.50		23.50	1.65	25.15
72956-TEA-T01	GARNISHR.RR.CENTER CORNER ?	1	1.30		1.30	0.09	1.39
65610-TEA-T00ZZ	FRAME COMP.R.RR.FLOOR ? <i>X sus</i>	1	685.90		685.90	48.01	733.91
65660-TEA-T00ZZ	FRAME COMP.L.RR.FLOOR ?	1	685.90		685.90	48.01	733.91
64350-TEA-T00ZZ	SUPPORT COMPR.RR.SHELF ?	1	48.90		48.90	3.42	52.32
64750-TEA-T00ZZ	SUPPORT COMPL.RR.SHELF ?	1	48.90		48.90	3.42	52.32
64330-TEC-U10ZZ	WHEELHOUSE COMPR.RR <i>repair</i>	1	256.30		256.30	17.94	274.24
64730-TEC-U00ZZ	WHEELHOUSE COMPL.RR <i>X</i>	1	256.30		256.30	17.94	274.24
64301-TEA-T00ZZ	PANELR.RR.INSIDE ?	1	212.00		212.00	14.84	226.84
64701-TEA-T00ZZ	OANELL.RR.INSIDE ?	1	211.80		211.80	14.83	226.63
64320-TEA-305ZZ	EXTSN COMPR.RR.W/ARCH RFCMNT ? <i>X sus</i>	1	37.10		37.10	2.60	39.70
64720-TEA-305ZZ	EXTSN COMPL.RR.W/ARCH RFCMNT ?	1	37.10		37.10	2.60	39.70
66501-TEA-T00ZZ	STIFFENERRR.SHELF FR. ?	1	42.40		42.40	2.97	45.37
66500-TET-H00ZZ	SHELF COMPRR.PARCEL ?	1	244.50		244.50	17.12	261.62
90108-S0A-003	BOLT FLANGE 6X15 ?	6	2.00		12.00	0.84	12.84
65550-TEA-T00ZZ	PAN COMSPARE TIRE <i>X</i>	1	216.70		216.70	15.17	231.87
66100-TEC-307ZZ	PANEL SETRR. <i>X reported</i>	1	243.10		243.10	17.02	260.12
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE <i>X reported</i>	1	26.70		26.70	1.87	28.57
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE ?	1	26.70		26.70	1.87	28.57
63321-TEA-T00ZZ	GUTTERR.RR.UPPER ?	1	29.40		29.40	2.06	31.46
63322-TEA-T00ZZ	ADAPTERR.RR.COMBINATION LIGHT ?	1	60.70		60.70	4.25	64.95
63721-TEA-T00ZZ	GUTTERL.RR.UPPER ? <i>X sus</i>	1	29.40		29.40	2.06	31.46
63722-TEA-T00ZZ	ADAPTERL.RR.COMBINATION LIGHT ?	1	60.70		60.70	4.25	64.95
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE ? <i>✓ 533.70</i>	1	711.60		711.60	49.81	761.41
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE ? <i>✓</i>	1	711.60		711.60	49.81	761.41
75450-TEA-T01	OUTLET ASSYRR.AIR ? <i>✓ 6.15</i>	1	8.10		8.10	0.57	8.67

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SMH4398E

Chassis No : MRHFC5650JT002418

Model : CIVIC 1.6 VTI YM2018

Owner's Name : ANGELA TAN CHYE YUN

Ins Policy No. :

Date of Accident : 15/6/2019

Document No. : SQT19002670

Date : 18. Jun 2019

Customer No. : WZM003

Svc Advisor : NG SIN HAI

Engine No : R16B25502840

Date | Time : 18. Jun 2019 8:54:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 7

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
68500-TEA-N00ZZ	LID COMP TRUNK <i>X repeated</i>	1	486.20		486.20	34.03	520.23
68610-TEA-T10ZZ	HINGE COMPR. TRUNK <i>X repeated</i>	1	44.80		44.80	3.14	47.94
68660-TEA-T10ZZ	HINGE COMPL TRUNK <i>X repeated</i>	1	44.80		44.80	3.14	47.94
74177-TR0-A01	CUSHIONHOOD ? <i>X } sue</i>	2	3.70		7.40	0.52	7.92
74829-S84-A00	STOPPER TRUNK LID <i>X } sue</i>	2	4.60		9.20	0.64	9.84
74851-TEA-003	LOCK ASSYTRUNK <i>X repeated</i>	1	74.30		74.30	5.20	79.50
74862-TEA-003	STRIKERTRUNK LID <i>X sue</i>	1	7.10		7.10	0.50	7.60
74865-TEA-T01	WEATHERSTRIPTRUNK LID <i>X repeated</i>	1	70.00		70.00	4.90	74.90
74871-TBA-A00	SPRINGR. TRUNK OPEN <i>X</i>	1	35.40		35.40	2.48	37.88
74872-TBA-A00	SPRINGL. TRUNK OPEN <i>X</i>	1	35.40		35.40	2.48	37.88
74873-T2A-003	CLIPTRUNK OPEN STAY GATE <i>X } sue</i>	1	2.00		2.00	0.14	2.14
74880-TEA-T01	CABLETRUNK OPEN <i>X</i>	1	19.80		19.80	1.39	21.19
74890-TEA-T11ZB	GARNISH ASSYRR. LICENSE <i>X repeated</i>	1	100.60		100.60	7.04	107.64
74895-TEX-Y01	GARNISH ASSYR. TRUNK HINGE <i>X } sue</i>	1	15.40		15.40	1.08	16.48
74896-TEX-Y01	GARNISH ASSYL. TRUNK HINGE <i>X } sue</i>	1	15.40		15.40	1.08	16.48
75701-TBA-A10	EMBLEM, H-MARK <i>X</i>	1	12.20		12.20	0.85	13.05
90101-TA0-000	BOLT-WASHER 6X16 ?	2	2.50		5.00	0.35	5.35
90102-STK-A00	BOLT WASHER 5X12 ?	1	2.00		2.00	0.14	2.14
90108-S0A-003	BOLT FLANGE 6X15 ?	4	2.00		8.00	0.56	8.56
90109-SM4-000	BOLT SPECIAL ?	4	2.10		8.40	0.59	8.99
90301-ST0-003	NUTPUSH 3MM ?	2	2.10		4.20	0.29	4.49
90308-SZW-003	NUTGARNISH ?	1	3.90		3.90	0.27	4.17
90667-SWZ-003ZV	CLIP, TRIM, 7MM NH900L ?	2	2.60		5.20	0.36	5.56
90856-TR0-A01	PLUGTRUNK DRAIN ?	1	0.40		0.40	0.03	0.43
73211-TEA-T02	GLASS SET, RR. WINDSHIELD ? <i>X</i>	1	932.10		932.10	65.25	997.35
73227-TEA-003	RUBBER C WINDSHIELD DAM <i>X an</i>	1	17.20		17.20	1.20	18.40
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>X an</i>	3	9.70		29.10	2.04	31.14
91501-S70-003	FASTENER BW/SHIELD <i>X an</i>	2	5.30		10.60	0.74	11.34
91536-SS0-J01	FASTENER AW/SHIELD <i>X an</i>	2	3.80		7.60	0.53	8.13

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SMH4398E

Chassis No : MRHFC5650JT002418

Model : CIVIC 1.6 VTI YM2018

Owner's Name : ANGELA TAN CHYE YUN

Ins Policy No. :

Date of Accident : 15/6/2019

Document No. : SQT19002670

Date : 18 Jun 2019

Customer No. : WZM003

Svc Advisor : NG SIN HAI

Engine No : R16B25502840

Date | Time : 18 Jun 2019 8:54:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 8

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91568-TF0-003	CLIP,WINDSHIELD UPPER <i>Handwritten: 2.90</i>	2	2.90	✓ 4.35	5.80	0.41	6.21
73125-SR3-000	RUBBER, W/SHIELD <i>Handwritten: 12.60</i>	1	12.60		12.60	0.88	13.48
73126-SR3-000	RUBBER, W/SHIELD <i>Handwritten: 14.40</i>	1	14.40		14.40	1.01	15.41
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>Handwritten: 60.00</i>	2	60.00	✓ 120	120.00	8.40	128.40
73500-TEA-T01	GLASS ASSY. QUARTER WINDSHIEL <i>Handwritten: 136.60</i>	1	136.60	✓ 102.45	136.60	9.56	146.16
Sum Item					28329.50	1,983.14	30,312.64
					<i>Handwritten: 28329.50</i>		
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00	✓	250.00	17.50	267.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
Sum Ext. Service					430.00	30.10	460.10
BG52R	REPLACE RR. R QTR GLASS.(N)	1	320.00	✓	320.00	22.40	342.40
BO-TOW	TOWING SERVICES (MBBS)(AFTER OFFICE HOUR)	1	180.00	✓	180.00	12.60	192.60
BOSUN	SUNDRIES	1	100.00	✓ 50	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	✓	180.00	12.60	192.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	380.00	✓	380.00	26.60	406.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	330.00	✓	330.00	23.10	353.10
BMU12R	REMOVE & REPLACE FR UNDERCARRIAGE PARTS.(N)	1	1680.00	✓ 560?	1680.00	117.60	1797.60
BMU01R	REMOVE & REPLACE RR UNDERCARRIAGE PARTS.(N)	1	1680.00	✓ 560? X 17	1680.00	117.60	1797.60
BKBH01R	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS	1	5000.00	✓ 1680 2040	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	✓ 1350 3250	3000.00	210.00	3210.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00	✓	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	✓	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BOJSE	SEALANT FOR RHR FENDER	1	80.00	✓	80.00	5.60	85.60
BOJSE	SEALANT FOR LHR FENDER	1	80.00	X 3	80.00	5.60	85.60
BOJSE	SEALANT FOR RHS SILL PANEL	1	80.00	X 3	80.00	5.60	85.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	X 3	80.00	5.60	85.60

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SMH4398E

Chassis No : MRHFC5650JT00241B

Model : CIVIC 1.6 VTI YM2018

Owner's Name : ANGELA TAN CHYE YUN

Ins Policy No. :

Date of Accident : 15/6/2019

Document No. : SQT19002670 Page 9

Date : 18. Jun 2019

Customer No. : WZM003

Svc Advisor : NG SIN HAI

Engine No : R16B25502840

Date | Time : 18. Jun 2019 8:54:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00	X	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓	180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	1120.00	✓	1120.00	78.40	1198.40
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	560.00	X	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	X	560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL.	1	9000.00	✓	9000.00	630.00	9630.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	5000.00	✓	5000.00	350.00	5350.00
BKOT00R	REMOVE AND RENEW TRUNK SPOILER	1	180.00	✓	180.00	12.60	192.60
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	560.00	✓	560.00	39.20	599.20
BKBU01R	REMOVE AND RENEW WHEELS/RIMS	1	200.00	✓	200.00	14.00	214.00
Sum Labor					31530.00	2,207.10	33,737.10

Survey By RASUL - Hp 90010068Date & Time 18/06/19 @ 1730

Excess

Status

Signature [Signature]

Total Amount 60,289.50 4,220.34 64,509.84

Total (Inclusive of GST) 64,509.84

64,343.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 18/6/2019 10:03:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

64,343.61



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHFC5650JT002418
License No: SMH4398E
Mileage: 2570
Engine No: R16B25502840

Document No: SVO19040010
Printed By: SHNG
Order Date: 24. June 2019
Order Time: 2:30:23 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (JINO:)						
	OWNER:ANGELA TAN CHYE YUN						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY LABOUR AND ITEMS						
60261-TBA-A00ZZ	PANELL.FENDER	1	248.90	25	186.67	13.07	199.74
74151-TEA-T00	FENDERL.FR.INNER	1	51.10	25	38.32	2.68	41.00
60263-TBA-A00ZZ	BRACKET AL.FR.FENDER	1	29.40	25	22.05	1.54	23.59
60266-TEM-M00ZZ	STAY, L. FR. FENDER UPPER	1	18.10	25	13.57	0.95	14.52
74155-TEA-T00	ENCLOSUREL.FR.FENDER	1	8.90	25	6.67	0.47	7.14
91501-TR0-003	CLIP,INNER FENDER	22	2.80	25	46.20	3.23	49.43
33150-TEC-306	HEADLIGHT ASSY,L.	1	585.70	25	439.27	30.75	470.02
34350-TET-H01	LIGHT ASSYL.SIDE TURN	1	33.10	25	24.82	1.74	26.56
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	26.70	25	20.02	1.40	21.42
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
91505-TM8-003	CLIP,BUMPER	16	2.30	25	27.60	1.93	29.53
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	73.80	25	55.35	3.87	59.22
75700-TBA-A00	EMBLEM	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
51220-TEA-T01	JOINT COMPFR.LOWER BALL	1	47.70	25	35.77	2.50	38.27
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
75722-TBA-A00	EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71503-TEA-T00	GARNISH R.RR.BUMPER SIDE	1	8.40	25	6.30	0.44	6.74
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
74146-TEA-T00	RUBBERHOOD SEAL	1	27.60	25	20.70	1.45	22.15
71410-TEA-T01	BULKHEAD ASSYFR.	1	525.90	25	394.42	27.61	422.03
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	25	104.40	7.31	111.71
60100-TEA-T00ZZ	HOOD COMPENGINE	1	598.70	25	449.02	31.43	480.45
80050-TG7-000	LABLE AIR CON	1	0.80	25	0.60	0.04	0.64
19043-SAA-E00	LABEL, COOLANT INFORMATION	1	10.00	25	7.50	0.53	8.03
60211-TBA-A00ZZ	PANELLR.FENDER	1	248.90	25	186.67	13.07	199.74
60213-TBA-A00ZZ	BRACKET AR.FR.FENDER	1	29.40	25	22.05	1.54	23.59
90853-SJA-A00	RIVET4.8MM	10	1.90	25	14.25	1.00	15.25
72410-TEA-T01	MOLDING ASSYR.FR.DOOR	1	24.00	25	18.00	1.26	19.26



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3683 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHFC5650JT0024 18
License No: SMH4398E
Mileage: 2570
Engine No: R16B25502840

Document No: SVO19040010
Printed By: SHNG
Order Date: 24. June 2019
Order Time: 2:30:23 PM
Service Advisor: NG SIN HAI

76208-TEA-T02	MIRROR ASSY,R.	1	254.30	25	190.72	13.35	204.07
67050-TEA-T00ZZ	PANEL COMPL.FR.DOOR	1	784.20	25	588.15	41.17	629.32
72465-TBA-A01	MOLDING ASSYL.FR.DOOR SASH	1	26.50	25	19.87	1.39	21.26
72470-TEA-T01	GARNISH ASSYL.FR.DOOR SASH	1	13.70	25	10.27	0.72	10.99
72450-TEA-T01	MOLDING ASSYL.FR.DOOR	1	24.00	25	18.00	1.26	19.26
67510-TEA-T00ZZ	PANELR.RR.DOOR	1	717.50	25	538.12	37.67	575.79
72828-TEA-T01	SEALRR.DOOR LOWER	2	6.20	25	9.30	0.65	9.95
72910-TEA-T01	MOLDING ASSYR.RR.DOOR	1	25.20	25	18.90	1.32	20.22
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER	1	29.20	25	21.90	1.53	23.43
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH	1	28.30	25	21.22	1.49	22.71
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	711.60	25	533.70	37.36	571.06
75450-TEA-T02	OUTLET ASSY,RR.AIR	1	8.20	25	6.15	0.43	6.58
73227-TEA-003	RUBBER C WINDSHIELD DAM	1	17.20	25	12.90	0.90	13.80
91501-S70-003	FASTENER BW/SHIELD	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	2.90	25	4.35	0.30	4.65
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL	1	136.60	25	102.45	7.17	109.62
67550-TEA-T00ZZ	PANELLRR.DOOR	1	717.50	25	538.12	37.67	575.79
60262-TBA-A00ZZ	STAYL.FENDER LOWER	1	17.20	25	12.90	0.90	13.80
72950-TEA-T01	MOLDING ASSY,L.RR.DOOR	1	25.20	25	18.90	1.32	20.22
72965-TEA-T01	MOLDING ASSY,L.RR.DR INNER	1	56.70	25	42.52	2.98	45.50
72970-TEA-T01	GARNISH ASSYL.RR.DOOR SASH	1	28.30	25	21.22	1.49	22.71
72368-TEA-T01	SEALL.FR.DOOR LOWER	1	8.20	25	6.15	0.43	6.58
71850-TEA-T01ZB	GARNISH ASSY,L.SIDE SILL	1	117.80	25	88.35	6.18	94.53
74552-TEA-T00	FENDERR.RR INNER	1	63.00	25	47.25	3.31	50.56
77930-TEA-B21	SENSOR ASSYFR.CRASH	1	71.40	25	53.55	3.75	57.30
17230-SFE-M00	CHAMBER ASSYRESONATOR	1	51.00	25	38.25	2.68	40.93
42700-TEA-T61	DISKALUMINIUM WHEEL	2	297.80	25	446.70	31.27	477.97
32108-TEA-N20	WIRE HARNESS REAR	1	116.80	25	87.60	6.13	93.73
51216-TEA-T10	KNUCKLEL.FR.	1	141.10	25	105.82	7.41	113.23
51360-TEA-T02	ARM COMP,L.FRL.LOWER	1	233.90	25	175.42	12.28	187.70
44300-TEA-T51	BEARING ASSYFR.HUB	1	73.90	25	55.42	3.88	59.30
44600-TBC-A00	HUB ASSYFR.	1	73.90	25	55.42	3.88	59.30
33505-TEA-T01	REFLECTOR ASSYR.RR.	1	7.20	25	5.40	0.38	5.78
71504-TBA-A00	COVERR.FINISHER	1	11.90	25	8.92	0.62	9.54
			SUM PARTS:		7,404.08	518.28	7,922.36
BG52R	0701	1	320.00		320.00	22.40	342.40
	REPLACE RR. R QTR GLASS.(N)						
BO-TOW	0701	1	180.00		180.00	12.60	192.60
	TOWING SERVICES (MBBS)(AFTER OFFICE HOUR)						
BOSUN	0701	1	50.00		50.00	3.50	53.50
	SUNDRIES						
BML011	1438	1	180.00		180.00	12.60	192.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BMC01D	1438	1	380.00		380.00	26.80	406.80
	REMOVE & INSTALL RADIATOR WITH FITTINGS.						
	PRESSURE TEST COOLING SYSTEM.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHFC5650JT002418
License No: SMH4398E
Mileage: 2570
Engine No: R16B25502840

Document No: SVO19040010
Printed By: SHNG
Order Date: 24. June 2019
Order Time: 2:30:23 PM
Service Advisor: NG SIN HAI

BMA01D	1438 REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)	1	330.00	330.00	23.10	353.10
BMU12R	1438 REMOVE & REPLACE FR UNDERCARRIAGE PARTS.(N)	1	560.00	560.00	39.20	599.20
BKBH01R	1466 REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS INCLUDING FITTING ON ATTACHMENT ITEMS	1	2,240.00	2,240.00	158.80	2,398.80
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,250.00	2,250.00	157.50	2,407.50
BG02R	1438 REPLACE RR. WINDSCREEN.(N)	1	560.00	560.00	39.20	599.20
BODAMKIT	1438 WINDSCREEN DAM KIT.	1	100.00	100.00	7.00	107.00
BA02R	1466 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	180.00	12.60	192.60
BOJSE	1718 SEALANT FOR RHR FENDER	1	80.00	80.00	5.60	85.60
BML02I	1438 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	180.00	12.60	192.60
BMI02D	1438 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00	560.00	39.20	599.20
BKRP02M	1466 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	4,480.00	4,480.00	313.60	4,793.60
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	3,600.00	3,600.00	252.00	3,852.00
BKOT00R	1466 REMOVE AND RENEW TRUNK SPOILER	1	150.00	150.00	10.50	160.50
BKBU01R	1438 REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00	480.00	33.60	513.60
BKBU01R	1438 REMOVE AND RENEW WHEELS/RIMS	1	100.00	100.00	7.00	107.00
BKDR21R	1466 REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	560.00 (A)	560.00	39.20	599.20
BKDR11R	1466 REMOVE & TRANSFER ITEMS TO NEW FR L DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITES.(N)	1	560.00 (A)	560.00	39.20	599.20
BKDR22R	1466	1	560.00 (A)	560.00	39.20	599.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZM003 / MSIG INSURANCE	Document No:	SVO19040010
Chassis No:	MRHF-C565UJT002418	Printed By:	SHNG
License No:	SMH4398E	Order Date:	24. June 2019
Mileage:	2570	Order Time:	2:30:23 PM
Engine No:	R16B25502840	Service Advisor:	NG SIN HAI

BML12R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)				
	1466	1	560.00	(A)	560.00 39.20 599.20
	REMOVE & RENEW WIRE HARNESS. RESET ECU MEMORIES				
			SUM LABOUR:	19,200.00	1,344.00 20,544.00
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00		250.00 17.50 267.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00 12.60 192.60
			SUM EXT SERVICE:	430.00	30.10 460.10
			TOTAL SGD	27,034.08	1,892.38 28,926.46
			Total Payable (SGD)		28,926.46

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****1669H / ANGELA TAN CHYE
Chassis No: MRHFC5650JT002418
License No: SMH4398E
Mileage: 2570
Engine No: R16B25502840

Document No: SVO19040010
Printed By: SKHO
Order Date: 24. June 2019
Order Time: 2:30:23 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	SUPPLEMENTARY LABOUR AND ITEMS						
67550-TEA-T00ZZ	PANELL RR.DOOR <i>bf</i>	1	717.50	25	538.12	37.67	575.79
60262-TBA-A00ZZ	STAYL.FENDER LOWER <i>re</i>	1	17.20	25	12.90	0.90	13.80
72950-TEA-T01	MOLDING ASSY,L.RR.DOOR <i>re</i>	1	25.20	25	18.90	1.32	20.22
72965-TEA-T01	MOLDING ASSY,L.RR.DR INNER <i>re</i>	1	56.70	25	42.52	2.98	45.50
72970-TEA-T01	GARNISH ASSY,L.RR.DOOR SASH <i>re</i>	1	28.30	25	21.22	1.49	22.71
72368-TEA-T01	SEALL.FR.DOOR LOWER <i>re</i>	1	8.20	25	6.15	0.43	6.58
71850-TEA-T01ZB	GARNISH ASSY,L.SIDE SILL <i>re</i>	1	117.80	25	88.35	6.18	94.53
74552-TEA-T00	FENDERR.RR INNER <i>com</i>	1	63.00	25	47.25	3.31	50.56
77930-TEA-B21	SENSOR ASSYFR.CRASH <i>re</i>	1	71.40	25	53.55	3.75	57.30
17230-5FE-M00	CHAMBER ASSYRESONATOR <i>re</i>	1	51.00	25	38.25	2.68	40.93
42700-TEA-T61	DISKALUMINIUM WHEEL <i>re</i>	2	297.80	25	446.70	31.27	477.97
32108-TEA-N20	WIRE HARNESS REAR <i>cut</i>	1	116.80	25	87.60	6.13	93.73
51216-TEA-T10	KNUCKLEL.FR. <i>bf</i>	1	141.10	25	105.82	7.41	113.23
51360-TEA-T02	ARM COMP,L.FR.LOWER <i>bf</i>	1	233.90	25	175.42	12.28	187.70
44300-TEA-T51	BEARING ASSYFR.HUB <i>re</i>	1	73.90	25	55.42	3.88	59.30
44600-TBC-A00	HUB ASSYFR. <i>bf</i>	1	73.90	25	55.42	3.88	59.30
33505-TEA-T01	REFLECTOR ASSYR.RR. <i>com</i>	1	7.20	25	5.40	0.38	5.78
71504-TBA-A00	COVERR.FINISHER <i>com</i>	1	11.90	25	8.92	0.62	9.54
	SUM PARTS:				1,807.91	126.56	1,934.47
BKDR21R	1466 REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	560.00		560.00	39.20	599.20
BKDR11R	1466 REMOVE & TRANSFER ITEMS TO NEW FR L DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITES.(N)	1	560.00		560.00	39.20	599.20
BKDR22R	1466 REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	560.00		560.00	39.20	599.20
BML12R	1466 REMOVE & RENEW WIRE HARNESS. RESET ECU MEMORIES	1	560.00		560.00	39.20	599.20
	SUM LABOUR:				2,240.00	156.80	2,396.80
	TOTAL SGD				4,047.91	283.36	4,331.27

Total Payable (SGD)

4,331.27

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 18 July 2019 4:28 PM
To: Ng Sin Hai; SUR
Subject: RE: Submission Pre-Invoice for vehicle SMH4398E

Dear Sin Hai,

WITHOUT PREJUDICE

Confirmed amount \$27,034.08 (before GST)

No of working days : 23 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Thursday, 18 July 2019 10:34 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SMH4398E

Dear Veron,

Kindly assist.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 18 July 2019 10:24 AM
To: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>; SUR <sur@lkkauto.com>
Subject: FW: Submission Pre-Invoice for vehicle SMH4398E

Dear Sin Hai,

Missing of 1 page (Total amount), please re-send.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Wednesday, 17 July 2019 5:17 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SMH4398E

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$27,034.08 (before GST)

No of working days : 23 days. (LOU)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy.

Thank you and have a nice day, ☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2019		18 Jun 2019 14:23 Edit Adj Rpt	S\$27,034.08 Edit Estimates	S\$27,034.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	BlueCar East Asia Pte Ltd , Co. Reg. No.: 201617259H								
Main Claimant:	ANGELA TAN CHYE YUN , ID: S7341669H								
Vehicle Reg. No.:	SMH4398E	Date of Loss:	15/06/2019 00:00 - :59 [4 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 597053	Policy/Cover Note No.:	29112616MCY (Comprehensive) Coverage: 30/01/2019 - 31/12/2019						
Vehicle Reg. No. (Insured):	SMH7196B	Policy No. (Claimant):							
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/07/2019]								
Adj Asg. Remarks:	Car in, request survey ASAP. Liab: dispute (OI NR) Contact: Sin Hai @ 6471 5419 on WP. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMH4398E (597053)
[SMH7196B]
TP
ANGELA TAN CHYE YUN
Jun 15 2019 12:00AM
[BlueCar East Asia Pte Ltd]
Kah Motor Co Sdn Bhd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/06/19 14:33	SMH4398E - video 1		Load AVI	
2	24/06/19 14:33	SMH4398E - video 2		Load AVI	
3	24/06/19 14:34	SMH4398E - video 3		Load AVI	
4	24/06/19 14:34	SMH4398E - video 4		Load AVI	
5	24/06/19 14:34	SMH4398E - video 5		Load AVI	
6	24/06/19 14:34	SMH4398E - video 6		Load AVI	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/06/19 17:01	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/06/19 16:57	General View		Load JPG	
2	19/06/19 16:57	General View		Load JPG	
3	19/06/19 16:57	General View		Load JPG	
4	19/06/19 16:57	General View		Load JPG	
5	19/06/19 16:57	General View		Load JPG	
6	19/06/19 16:57	General View		Load JPG	
7	19/06/19 16:57	General View		Load JPG	
8	19/06/19 16:57	General View		Load JPG	
9	19/06/19 16:57	General View		Load JPG	
10	19/06/19 16:57	General View		Load JPG	
11	19/06/19 16:57	General View		Load JPG	
12	19/06/19 16:57	General View		Load JPG	
13	19/06/19 16:57	General View		Load JPG	
14	19/06/19 16:57	General View		Load JPG	
15	19/06/19 16:57	General View		Load JPG	
16	19/06/19 16:57	General View		Load JPG	
17	19/06/19 16:57	General View		Load JPG	
18	19/06/19 16:57	General View		Load JPG	
19	19/06/19 16:57	General View		Load JPG	
20	19/06/19 16:57	General View		Load JPG	
21	19/06/19 16:57	General View		Load JPG	
22	19/06/19 16:57	General View		Load JPG	
23	19/06/19 16:57	General View		Load JPG	
24	19/06/19 16:57	General View		Load JPG	
25	19/06/19 16:57	General View		Load JPG	
26	19/06/19 16:57	General View		Load JPG	

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
27	19/06/19 16:57	General View	 Load JPG	☒
28	19/06/19 16:57	General View	 Load JPG	☒
29	19/06/19 16:57	General View	 Load JPG	☒
30	19/06/19 16:57	General View	 Load JPG	☒
31	19/06/19 16:57	General View	 Load JPG	☒
32	19/06/19 16:57	General View	 Load JPG	☒
33	19/06/19 16:57	General View	 Load JPG	☒
34	19/06/19 16:57	General View	 Load JPG	☒
35	19/06/19 16:57	General View	 Load JPG	☒
36	19/06/19 16:57	General View	 Load JPG	☒
37	19/06/19 16:57	General View	 Load JPG	☒
38	19/06/19 16:57	General View	 Load JPG	☒
39	19/06/19 16:57	General View	 Load JPG	☒
40	19/06/19 16:57	General View	 Load JPG	☒
41	19/06/19 16:57	General View	 Load JPG	☒
42	19/06/19 16:57	General View	 Load JPG	☒
43	19/06/19 16:57	General View	 Load JPG	☒
44	19/06/19 16:57	General View	 Load JPG	☒
45	19/06/19 16:57	General View	 Load JPG	☒
46	19/06/19 16:57	General View	 Load JPG	☒
47	19/06/19 16:57	General View	 Load JPG	☒
48	19/06/19 16:57	General View	 Load JPG	☒
49	19/06/19 16:57	General View	 Load JPG	☒
50	19/06/19 16:57	General View	 Load JPG	☒
51	19/06/19 16:57	General View	 Load JPG	☒
52	19/06/19 16:57	General View	 Load JPG	☒
53	19/06/19 16:57	General View	 Load JPG	☒
54	19/06/19 16:57	General View	 Load JPG	☒
55	19/06/19 16:57	General View	 Load JPG	☒
56	19/06/19 16:57	General View	 Load JPG	☒
57	19/06/19 16:57	General View	 Load JPG	☒
58	19/06/19 16:57	General View	 Load JPG	☒
59	19/06/19 16:57	General View	 Load JPG	☒
60	19/06/19 16:57	General View	 Load JPG	☒
61	19/06/19 16:57	General View	 Load JPG	☒
62	19/06/19 16:57	General View	 Load JPG	☒
63	19/06/19 16:57	General View	 Load JPG	☒
64	19/06/19 16:57	General View	 Load JPG	☒
65	19/06/19 16:57	General View	 Load JPG	☒
66	19/06/19 16:57	General View	 Load JPG	☒
67	19/06/19 16:57	General View	 Load JPG	☒
68	19/06/19 16:57	General View	 Load JPG	☒
69	19/06/19 16:57	General View	 Load JPG	☒
70	19/06/19 16:57	General View	 Load JPG	☒
71	19/06/19 16:57	General View	 Load JPG	☒
72	19/06/19 16:57	General View	 Load JPG	☒
73	19/06/19 16:57	General View	 Load JPG	☒
74	19/06/19 16:57	General View	 Load JPG	☒
75	19/06/19 16:57	General View	 Load JPG	☒
76	19/06/19 16:57	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
77	19/06/19 16:57	General View	 Load JPG	☒
78	19/06/19 16:57	General View	 Load JPG	☒
79	19/06/19 16:57	General View	 Load JPG	☒
80	19/06/19 16:57	General View	 Load JPG	☒
81	19/06/19 16:57	General View	 Load JPG	☒
82	19/06/19 16:57	General View	 Load JPG	☒
83	19/06/19 16:57	General View	 Load JPG	☒
84	19/06/19 16:57	General View	 Load JPG	☒
85	19/06/19 16:57	General View	 Load JPG	☒
86	19/06/19 16:57	General View	 Load JPG	☒
87	19/06/19 16:57	General View	 Load JPG	☒
88	19/06/19 16:57	General View	 Load JPG	☒
89	19/06/19 16:57	General View	 Load JPG	☒
90	19/06/19 16:57	General View	 Load JPG	☒
91	19/06/19 16:57	General View	 Load JPG	☒
92	19/06/19 16:57	General View	 Load JPG	☒
93	19/06/19 16:57	General View	 Load JPG	☒
94	19/06/19 16:57	General View	 Load JPG	☒
95	19/06/19 16:57	General View	 Load JPG	☒
96	19/06/19 16:58	General View	 Load JPG	☒
97	19/06/19 16:58	General View	 Load JPG	☒
98	19/06/19 16:58	General View	 Load JPG	☒
99	19/06/19 16:58	General View	 Load JPG	☒
100	19/06/19 16:58	General View	 Load JPG	☒
101	19/06/19 16:58	General View	 Load JPG	☒
102	19/06/19 16:58	General View	 Load JPG	☒
103	19/06/19 16:58	General View	 Load JPG	☒
104	19/06/19 16:58	General View	 Load JPG	☒
105	19/06/19 16:58	General View	 Load JPG	☒
106	19/06/19 16:58	General View	 Load JPG	☒
107	19/06/19 16:58	General View	 Load JPG	☒
108	19/06/19 16:58	General View	 Load JPG	☒
109	19/06/19 16:58	General View	 Load JPG	☒
110	19/06/19 16:58	General View	 Load JPG	☒
111	19/06/19 16:58	General View	 Load JPG	☒
112	19/06/19 16:58	General View	 Load JPG	☒
113	19/06/19 16:58	General View	 Load JPG	☒
114	19/06/19 16:58	General View	 Load JPG	☒
115	19/06/19 16:58	General View	 Load JPG	☒
116	19/06/19 16:58	General View	 Load JPG	☒
117	19/06/19 16:58	General View	 Load JPG	☒
118	19/06/19 16:58	General View	 Load JPG	☒
119	19/06/19 16:58	General View	 Load JPG	☒
120	19/06/19 16:58	General View	 Load JPG	☒
121	19/06/19 16:58	General View	 Load JPG	☒
122	19/06/19 16:58	General View	 Load JPG	☒
123	19/06/19 16:58	General View	 Load JPG	☒
124	19/06/19 16:58	General View	 Load JPG	☒
125	19/06/19 16:58	General View	 Load JPG	☒
126	19/06/19 16:58	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
127	19/06/19 16:58	General View	 Load JPG	☒
128	19/06/19 16:58	General View	 Load JPG	☒
129	19/06/19 16:58	General View	 Load JPG	☒
130	19/06/19 16:58	General View	 Load JPG	☒
131	19/06/19 16:58	General View	 Load JPG	☒
132	19/06/19 16:58	General View	 Load JPG	☒
133	19/06/19 16:58	General View	 Load JPG	☒
134	19/06/19 16:58	General View	 Load JPG	☒
135	19/06/19 16:58	General View	 Load JPG	☒
136	19/06/19 16:58	General View	 Load JPG	☒
137	19/06/19 16:58	General View	 Load JPG	☒
138	19/06/19 16:58	General View	 Load JPG	☒
139	19/06/19 16:58	General View	 Load JPG	☒
140	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
141	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
142	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
143	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
144	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
145	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
146	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
147	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
148	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
149	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
150	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
151	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
152	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
153	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
154	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
155	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
156	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
157	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
158	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
159	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
160	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
161	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
162	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
163	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
164	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
165	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
166	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
167	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
168	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
169	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
170	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
171	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
172	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
173	18/07/19 16:26	Reinspection Photo	Load JPG	☒
174	18/07/19 16:26	Reinspection Photo	Load JPG	☒
175	18/07/19 16:26	Reinspection Photo	Load JPG	☒
176	18/07/19 16:26	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
177	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
178	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
179	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
180	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
181	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
182	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
183	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
184	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
185	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
186	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
187	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
188	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
189	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
190	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
191	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
192	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
193	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
194	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
195	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
196	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
197	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
198	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
199	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
200	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
201	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
202	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
203	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
204	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
205	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
206	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
207	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
208	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
209	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
210	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
211	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
212	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
213	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
214	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
215	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
216	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
217	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
218	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
219	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
220	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
221	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
222	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
223	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
224	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
225	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
226	18/07/19 16:26	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
227	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
228	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
229	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
230	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
231	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
232	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
233	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
234	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
235	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
236	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
237	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
238	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
239	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
240	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
241	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
242	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
243	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
244	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
245	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
246	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
247	18/07/19 16:26	Reinspection Photo	 Load JPG	☒
248	18/07/19 16:27	Reinspection Photo	 Load JPG	☒
249	18/07/19 16:27	Reinspection Photo	 Load JPG	☒
250	18/07/19 16:27	Reinspection Photo	 Load JPG	☒
251	18/07/19 16:27	Reinspection Photo	 Load JPG	☒
252	18/07/19 16:27	Reinspection Photo	 Load JPG	☒
253	18/07/19 16:27	Reinspection Photo	 Load JPG	☒
254	18/07/19 16:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/06/19 12:22	estimate repair	 Load PDF	
2	18/06/19 12:35	Ack PRI	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/19 09:37	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010795/R1VD3E2

Date: 13/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29112616MCY

Claimant Vehicle No : SMH4398E

Insured Vehicle No : SMH7196B

Date of Loss: 15/06/2019

Nature of Claim: TP

Claim No: 597053

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMH4398E

Make & Model: HONDA CIVIC, 1.6 L VTI (A)

Engine No: R16B25502840

Reg. Date: 23/01/2019 (Man. Year: 2018)

Chassis No: MRHFC5650JT002418

Colour: Blue

Odometer: 6511 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,240.51	7,454.08	22,786.43	75.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	34,100.00	19,580.00	14,520.00	42.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	64,340.51	27,034.08	37,306.43	57.98
+ GST 7.00/7.00% (S\$)	4,503.84	1,892.39	2,611.45	57.98
Nett Amount (S\$)	68,844.35	28,926.47	39,917.88	57.98

INSPECTION

Date of Assignment: 18/06/2019

Date Inspected: 18/06/2019 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)
NO. 255 ALEXANDRA ROAD
SINGAPORE 159937

Estimated Period of Repair: 23.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2019)
Parts: 143	HONDA CIVIC 1.6 L VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMH4398E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANELL.FENDER	Buckled	248.90 FS	*186.67 FS
2	1		*FENDERL.FR.INNER	Deformed	51.10 FS	*38.32 FS
3	1		*BRACKET AL.FR.FENDER	Necessary	29.40 FS	*22.05 FS
4	1		*STAY,L.FR. FENDER UPPER	Necessary	18.10 FS	*13.57 FS
5	1		*ENCLOSUREL.FR.FENDER	Necessary	8.90 FS	*6.67 FS
6	1		*PADL.FR.FENDER PARTITION	Serviceable	44.10 FS	*- FS
7	1		*CLIP, INNER FENDER (22PCS)	Necessary	61.60 FS	*46.20 FS
8	1		*HEADLIGHT ASSYL	Cracked	585.70 FS	*439.27 FS
9	1		*LIGHT ASSYL.SIDE TURN	Scratched	33.10 FS	*24.82 FS
10	1		*FACEFR.BUMPER	Deformed	579.90 FS	*434.92 FS
11	1		*GRILLEFR.BUMPER LOWER	Serviceable	36.10 FS	*- FS
12	1		*BEAML.FR.BUMPER UPPER	Bent	26.70 FS	*20.02 FS
13	1		*BEAMR.FR.BUMPER UPPER	Serviceable	26.70 FS	*- FS
14	1		*SPACERL.FR.BUMPER SIDE	Necessary	10.40 FS	*7.80 FS
15	1		*SPACERR.FR.BUMPER SIDE	Necessary	10.40 FS	*7.80 FS
16	1		*PLATEL.FR.BUMPER SIDE INDUCTN	Serviceable	44.00 FS	*- FS
17	1		*GARNISHL.FR.BUMPER SIDE	Scratched	18.00 FS	*13.50 FS
18	1		*CLIP,BUMPER (16PCS)	Necessary	36.80 FS	*27.60 FS
19	1		*BEAM COMPFR.BUMPER	Serviceable	345.90 FS	*- FS
20	1		*BEAM COMPFR.BUMPER CENTER UPP	Serviceable	214.80 FS	*- FS
21	1		*BULKHEAD ASSYFR.	Bent	525.90 FS	*394.42 FS
22	1		*SUPPORTL.FR.SIDE FRAME	Serviceable	31.10 FS	*- FS
23	1		*BRACKETL.FR.SUB FRAME FR.	Serviceable	32.60 FS	*- FS
24	1		*FLANGEL.FR.BUMPER BEAM EXTENS	Serviceable	34.20 FS	*- FS
25	1		*PLATEL.FR.SIDE FRAME	Serviceable	31.10 FS	*- FS
26	1		*EXTENSION ASSYL.FR.GRILLE	Serviceable	85.60 FS	*- FS
27	1		*BASE,FR.GRILLE CHROME	Cut	73.80 FS	*55.35 FS
28	1		*MOLDINGFR.GRILLE	Serviceable	100.40 FS	*- FS
29	1		*EMBLEM	Necessary	15.00 FS	*11.25 FS
30	1		*NUTPUSH 3MM (2PCS)	Necessary	4.20 FS	*3.15 FS
31	1		*DRIVESHAFT ASSY,R.	Serviceable	927.90 FS	*- FS
32	1		*ABSORBER UNITR.FR.SHOCK	Serviceable	231.60 FS	*- FS
33	1		*RUBBERR.FR.SPRING MOUNT LOWER	Serviceable	4.20 FS	*- FS
34	1		*SPRING,R.FR.	Serviceable	44.30 FS	*- FS
35	1		*RUBBER COMPFR.SHOCK ABS MTG	Serviceable	38.20 FS	*- FS
36	1		*RUBBERR.FR.SPRING MOUNT UPPER	Serviceable	7.70 FS	*- FS
37	1		*ARM COMPR.FR.LOWER	Serviceable	215.40 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*JOINT COMPFR.LOWER BALL	Bent	47.70 FS	*35.77 FS
39	1		*KNUCKLER.FR	Serviceable	141.10 FS	*- FS
40	1		*LINK COMP,FR.STABILIZER	Serviceable	21.70 FS	*- FS
41	1		*STABILIZER COMPFR.	Serviceable	141.10 FS	*- FS
42	1		*BRACKETSTABILIZER HOLD	Serviceable	4.10 FS	*- FS
43	1		*BOX ASSY, POWER STEERING GEAR	Serviceable	1,916.10 FS	*- FS
44	1		*NUMBER PLATE WITH CASING-L	Serviceable	45.00 FS	*- FS
45	1		*SUB CORDRR.BUMPER CORNER SENS	Serviceable	28.10 FS	*- FS
46	1		*SENSOR UNITPARKING	Serviceable	62.50 FS	*- FS
47	4		*SENSOR ASSY, PARKING	Serviceable	583.20 FS	*- FS
48	1		*TAILLIGHT ASSYR.	Missing	261.40 FS	*196.05 FS
49	1		*TAILLIGHT ASSYL.	Serviceable	281.30 FS	*- FS
50	1		*LIGHT ASSYR.LID	Serviceable	122.30 FS	*- FS
51	1		*LIGHT ASSYL.LID	Serviceable	122.30 FS	*- FS
52	1		*LID COMP TRUNK	Repair	486.20 FS	*- FS
53	1		*HINGE COMPR.TRUNK	Serviceable	44.80 FS	*- FS
54	1		*HINGE COMPL.TRUNK	Serviceable	44.80 FS	*- FS
55	1		*LOCK ASSYTRUNK	Serviceable	74.30 FS	*- FS
56	1		*WEATHERSTRIPTRUNK LID	Serviceable	70.00 FS	*- FS
57	1		*GARNISH ASSYRR.LICENSE	Repair	100.60 FS	*- FS
58	1		*EMBLEM SETRR.	Necessary	11.80 FS	*8.85 FS
59	1		*EMBLEMRR.	Necessary	11.00 FS	*8.25 FS
60	1		*FACE ASSY,RR.BUMPER	Torn	617.20 FS	*462.90 FS
61	1		*GARNISH,RR.BUMPER LOWER	Cracked	36.40 FS	*27.30 FS
62	1		*GARNISH R.RR.BUMPER SIDE	Missing	8.40 FS	*6.30 FS
63	1		*BRACKETR.RR.BUMPER SIDE	Necessary	2.30 FS	*1.72 FS
64	1		*GARNISHL.RR.BUMPER SIDE	Serviceable	7.80 FS	*- FS
65	1		*BEAM COMPRR.BUMPER	Serviceable	164.70 FS	*- FS
66	1		*BRACKETL.RR.BUMPER SIDE	Serviceable	2.30 FS	*- FS
67	1		*SPACERR.RR.BUMPER SIDE	Necessary	11.50 FS	*8.62 FS
68	1		*SPACERL.RR.BUMPER SIDE	Necessary	11.50 FS	*8.62 FS
69	1		*CLIP, BUMPER (7PCS)	Necessary	16.10 FS	*12.07 FS
70	1		*PANEL SETRR.	Repair	243.10 FS	*- FS
71	1		*PAN COMPSPARE TIRE	Serviceable	216.70 FS	*- FS
72	1		*LINING ASSYRR.PANEL	Serviceable	50.30 FS	*- FS
73	1		*LID ASSYSPARE TIRE	Serviceable	60.20 FS	*- FS
74	1		*BOX COMPTOOL	Serviceable	38.00 FS	*- FS
75	1		*LINING ASSYR.TRUNK SIDE	Serviceable	48.90 FS	*- FS
76	1		*LINING ASSYL.TRUNK SIDE	Serviceable	48.90 FS	*- FS
77	3		*OILSHEET	Serviceable	122.10 FS	*- FS
78	1		*STIFFENER,R.RR.PANEL SIDE	Serviceable	26.70 FS	*- FS
79	1		*FACEFR.BUMPER	Repeated	579.90 FS	*- FS
80	1		*GRILLEFR.BUMPER LOWER	Repeated	36.10 FS	*- FS
81	1		*GARNISHR.FR.BUMPER SIDE	Scratched	18.00 FS	*13.50 FS
82	1		*GARNISHL.FR.BUMPER SIDE	Repeated	18.00 FS	*- FS
83	1		*SPACERR.FR.BUMPER SIDE	Repeated	10.40 FS	*- FS
84	1		*SPACERL.FR.BUMPER SIDE	Repeated	10.40 FS	*- FS
85	16		*CLIP, BUMPER	Repeated	36.80 FS	*- FS
86	1		*BASE,FR.GRILLE CHROME	Repeated	73.80 FS	*- FS
87	1		*EXTENSION ASSYR.FR.GRILLE	Repeated	85.60 FS	*- FS
88	1		*MOLDINGFR.GRILLE	Repeated	100.40 FS	*- FS
89	1		*EXTENSION ASSYL.FR.GRILLE	Repeated	85.60 FS	*- FS
90	1		*RUBBERHOOD SEAL	Necessary	27.60 FS	*20.70 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*EMBLEM	Repeated	15.00 FS	*- FS
92	2		*NUTPUSH 3MM	Repeated	4.20 FS	*- FS
93	1		*COVER ASSY, ENGINE UNDER	Serviceable	213.20 FS	*- FS
94	1		*BEAM COMPFR.BUMPER	Serviceable	345.90 FS	*- FS
95	1		*BEAM COMPFR.BUMPER CENTER UPP	Serviceable	214.80 FS	*- FS
96	1		*BULKHEAD ASSYFR.	Repeated	525.90 FS	*- FS
97	1		*CONDENSER ASSY	Serviceable	704.40 FS	*- FS
98	1		*RADIATOR COMP	Serviceable	1,100.50 FS	*- FS
99	6		*COOLANT ANTI-FREEZE TYPE 2	Necessary	139.20 FS	*104.40 FS
100	1		*SENSOR ASSYAMBIENT	Serviceable	40.10 FS	*- FS
101	1		*CLIPAMBIENT SENSOR	Serviceable	5.40 FS	*- FS
102	1		*HOOD COMPENGINE	Bent	598.70 FS	*449.02 FS
103	1		*LABEL AIR CON	Necessary	0.80 FS	*0.60 FS
104	1		*LABEL, COOLANT INFORMATION	Necessary	10.00 FS	*7.50 FS
105	1		*BEAMR.FR.BUMPER UPPER	Serviceable	26.70 FS	*- FS
106	1		*HEADLIGHT ASSY,R.	Serviceable	585.70 FS	*- FS
107	1		*BEAML.FR.BUMPER UPPER	Serviceable	26.70 FS	*- FS
108	1		*HEADLIGHT ASSYL.	Repeated	585.70 FS	*- FS
109	1		*PANELR.FENDER	Buckled	248.90 FS	*186.67 FS
110	1		*BRACKET AR.FR.FENDER	Necessary	29.40 FS	*22.05 FS
111	1		*PANELL.FENDER	Repeated	248.90 FS	*- FS
112	1		*BRACKET AL.FR.FENDER	Repeated	29.40 FS	*- FS
113	1		*RIVET4.8MM (10PCS)	Necessary	19.00 FS	*14.25 FS
114	1		*FENDERR.FR.INNER	Serviceable	51.10 FS	*- FS
115	1		*FENDERL.FR.INNER	Repeated	51.10 FS	*- FS
116	1		*CLIP,INNER FENDER (22PCS)	Repeated	61.60 FS	*- FS
117	1		*PANEL COMPR.FR.DOOR	Repair	784.20 FS	*- FS
118	1		*HINGER.FR.DOOR UPPER	Serviceable	38.40 FS	*- FS
119	1		*HINGER.FR.DOOR LOWER	Serviceable	39.30 FS	*- FS
120	1		*CHECKER COMPFR.DOOR	Serviceable	13.50 FS	*- FS
121	1		*SEALR.FR.DOOR LOWER	Serviceable	8.20 FS	*- FS
122	1		*SEALR.FR.DOOR FR.GAP	Serviceable	12.50 FS	*- FS
123	1		*MOLDING ASSYR.FR.DOOR SASH	Serviceable	26.50 FS	*- FS
124	1		*GARNISH ASSYR.FR.DOOR SASH	Serviceable	13.70 FS	*- FS
125	1		*GARNISH ASSYR.FR.DOOR SASH	Serviceable	13.70 FS	*- FS
126	1		*MOLDING ASSYR.FR.DOOR	Cut	24.00 FS	*18.00 FS
127	1		*MIRROR ASSY,R.	Scratched	254.30 FS	*190.72 FS
128	1		*CAP,R.SKULL	Serviceable	59.90 FS	*- FS
129	1		*PANEL COMPL.FR.DOOR	Bent	784.20 FS	*588.15 FS
130	1		*MOLDING ASSYL.FR.DOOR SASH	Cut	26.50 FS	*19.87 FS
131	1		*GARNISHR.FR.CENTER CORNER	Serviceable	1.60 FS	*- FS
132	1		*GARNISH ASSYL.FR.DOOR SASH	Cut	13.70 FS	*10.27 FS
133	1		*MOLDING ASSYL.FR.DOOR	Cut	24.00 FS	*18.00 FS
134	1		*PANELR.RR.DOOR	Buckled	717.50 FS	*538.12 FS
135	2		*SEALRR.DOOR LOWER	Necessary	9.30 FS	*9.30 FS
136	1		*MOLDING ASSYR.RR.DOOR	Necessary	25.20 FS	*18.90 FS
137	1		*MOLDING ASSYR.RR.DOOR SASH	Necessary	29.20 FS	*21.90 FS
138	1		*GARNISH ASSYR.RR.DOOR SASH	Cut	28.30 FS	*21.22 FS
139	1		*GARNISHR.RR.DOOR QUARTER OUT	Serviceable	23.50 FS	*- FS
140	1		*GARNISHR.RR.CENTER CORNER	Serviceable	1.30 FS	*- FS
141	1		*FRAME COMP,R.RR.FLOOR	Serviceable	685.90 FS	*- FS
142	1		*FRAME COMP,L.RR.FLOOR	Serviceable	685.90 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
143	1		*SUPPORT COMPR.RR.SHELF	Serviceable	48.90 FS	*- FS
144	1		*SUPPORT COMPL.RR.SHELF	Serviceable	48.90 FS	*- FS
145	1		*WHEELHOUSE COMPR.RR	Repair	256.30 FS	*- FS
146	1		*WHEELHOUSE COMPL.RR	Serviceable	256.30 FS	*- FS
147	1		*PANELR.RR.INSIDE	Serviceable	212.00 FS	*- FS
148	1		*PANELL.RR.INSIDE	Serviceable	211.80 FS	*- FS
149	1		*EXTSN COMPR.RR.W/ARCH RFCMNT	Serviceable	37.10 FS	*- FS
150	1		*EXTSN COMPL.RR.W/ARCH RFCMNT	Serviceable	37.10 FS	*- FS
151	1		*STIFFENERRR.SHELF FR.	Serviceable	42.40 FS	*- FS
152	1		*SHELF COMPRR.PARCEL	Serviceable	244.50 FS	*- FS
153	6		*BOLT FLANGE 6X15	Serviceable	12.00 FS	*- FS
154	1		*PAN COMSPARE TIRE	Serviceable	216.70 FS	*- FS
155	1		*PANEL SETRR.	Repeated	243.10 FS	*- FS
156	1		*STIFFENER,R.RR.PANEL SIDE	Repeated	26.70 FS	*- FS
157	1		*STIFFENERL.RR.PANEL SIDE	Serviceable	26.70 FS	*- FS
158	1		*GUTTERR.RR.UPPER	Serviceable	29.40 FS	*- FS
159	1		*ADAPTERR.RR.COMBINATION LIGHT	Serviceable	60.70 FS	*- FS
160	1		*GUTTERL.RR.UPPER	Serviceable	29.40 FS	*- FS
161	1		*ADAPTERL.RR.COMBINATION LIGHT	Serviceable	60.70 FS	*- FS
162	1		*PANEL SETR.RR.OUTSIDE	Cracked	711.60 FS	*533.70 FS
163	1		*PANEL SETL.RR.OUTSIDE	Serviceable	711.60 FS	*- FS
164	1		*OUTLET ASSYRR.AIR	Cracked	8.10 FS	*6.15 FS
165	1		*LID COMP TRUNK	Repeated	486.20 FS	*- FS
166	1		*HINGE COMPR.TRUNK	Repeated	44.80 FS	*- FS
167	1		*HINGE COMPL.TRUNK	Repeated	44.80 FS	*- FS
168	2		*CUSHIONHOOD	Serviceable	7.40 FS	*- FS
169	2		*STOPPER TRUNK LID	Serviceable	9.20 FS	*- FS
170	1		*LOCK ASSYTRUNK	Repeated	74.30 FS	*- FS
171	1		*STRIKERTRUNK LID	Serviceable	7.10 FS	*- FS
172	1		*WEATHERSTRIPTRUNK LID	Repeated	70.00 FS	*- FS
173	1		*SPRINGR.TRUNK OPEN	Serviceable	35.40 FS	*- FS
174	1		*SPRINGL.TRUNK OPEN	Serviceable	35.40 FS	*- FS
175	1		*CLIPTRUNK OPEN STAY GATE	Serviceable	2.00 FS	*- FS
176	1		*CABLETRUNK OPEN	Serviceable	19.80 FS	*- FS
177	1		*GARNISH ASSYRR.LICENSE	Repeated	100.60 FS	*- FS
178	1		*GARNISH ASSYR.TRUNK HINGE	Serviceable	15.40 FS	*- FS
179	1		*GARNISH ASSYL.TRUNK HINGE	Serviceable	15.40 FS	*- FS
180	1		*EMBLEM,H-MARK	Not Necessary	12.20 FS	*- FS
181	2		*BOLT-WASHER6X16	Not Necessary	5.00 FS	*- FS
182	1		*BOLTWASHER 5X12	Not Necessary	2.00 FS	*- FS
183	4		*BOLT FLANGE 6X15	Not Necessary	8.00 FS	*- FS
184	4		*BOLT SPECIAL	Not Necessary	8.40 FS	*- FS
185	2		*NUTPUSH 3MM	Not Necessary	4.20 FS	*- FS
186	1		*NUTGARNISH	Not Necessary	3.90 FS	*- FS
187	2		*CLIP, TRIM, 7MM NH900L	Not Necessary	5.20 FS	*- FS
188	1		*PLUGTRUNK DRAIN	Not Necessary	0.40 FS	*- FS
189	1		*GLASS SET,RR.WINDSHIELD	Not Necessary	932.10 FS	*- FS
190	1		*RUBBER CWINDSHIELD DAM	Necessary	17.20 FS	*12.90 FS
191	3		*RUBERRR QTR W/SHIELD	Not Necessary	29.10 FS	*- FS
192	1		*FASTENER BW/SHIELD (2PCS)	Necessary	10.60 FS	*7.95 FS
193	2		*FASTENER AW/SHIELD	Necessary	7.60 FS	*5.70 FS
194	1		*CLIP,WINDSHIELD UPPER (2PCS)	Necessary	5.80 FS	*4.35 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
195	1		*RUBBER,W/SHIELD	Not Necessary	12.60 FS	*- FS
196	1		*RUBBER,W/SHIELD	Not Necessary	14.40 FS	*- FS
197	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
198	1		*GLASS ASSYR.QUARTER WINDSHIEL	Necessary	136.60 FS	*102.45 FS
199	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
200	1		*PANELL.RR.DOOR	Bent	538.12 FS	*538.12 FS
201	1		*STAYL.FENDER LOWER	Necessary	12.90 FS	*12.90 FS
202	1		*MOLDING ASSY,L.RR.DOOR	Necessary	18.90 FS	*18.90 FS
203	1		*MOLDING ASSY,L.RR.DR INNER	Necessary	42.52 FS	*42.52 FS
204	1		*GARNISH ASSYL.RR.DOOR SASH	Necessary	21.22 FS	*21.22 FS
205	1		*SEALL.FR.DOOR LOWER	Necessary	6.15 FS	*6.15 FS
206	1		*GARNISH ASSY,L.SIDE SILL	Scratched	88.35 FS	*88.35 FS
207	1		*FENDERR.RR INNER	Cracked	47.25 FS	*47.25 FS
208	1		*SENSOR ASSYFR.CRASH	Not Working	53.55 FS	*53.55 FS
209	1		*CHAMBER ASSYRESONATOR	Cracked	38.25 FS	*38.25 FS
210	2		*DISKALUMINIUM WHEEL	Scratched	446.70 FS	*446.70 FS
211	1		*WIRE HARNESS REAR	Cut	87.60 FS	*87.60 FS
212	1		*KNUCKLE.FR.	Bent	105.82 FS	*105.82 FS
213	1		*ARM COMP,L.FR.LOWER	Bent	175.42 FS	*175.42 FS
214	1		*BEARING ASSYFR.HUB	Necessary	55.42 FS	*55.42 FS
215	1		*HUB ASSYFR.	Bent	55.42 FS	*55.42 FS
216	1		*REFLECTOR ASSYR.RR.	Cracked	5.40 FS	*5.40 FS
217	1		*COVERR.FINISHER	Cracked	8.92 FS	*8.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	30,240.51	7,454.08
--------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS	New	250.00	250.00
2	WHEEL ALIGNMENT X4	New	180.00	180.00
3	REPLACE RR.R QTR GLASS	New	320.00	320.00
4	TOWING SERVICES (MBBS) (AFTER OFFICE HOUR)	New	180.00	180.00
5	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	180.00
6	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	380.00	380.00
7	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	330.00	330.00
8	REMOVE & REPLACE FR UNDERCARRIAGE PARTS	New	1,680.00	560.00
9	REMOVE & REPLACE RR UNDERCARRIAGE PARTS	New	1,680.00	0.00
10	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS	New	5,000.00	2,240.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	New	3,000.00	2,250.00
12	REPLACE RR.WINDSCREEN	New	560.00	560.00
13	WINDSCREEN DAM KIT	New	100.00	100.00
14	REMOVE & RENEW REVERSE SENSORS - 4PCS	New	180.00	180.00
15	SEALANT FOR RHR FENDER	New	80.00	80.00
16	SEALANT FOR LHR FENDER	New	80.00	0.00
17	SEALANT FOR RHS SILL PANEL	New	80.00	0.00
18	SEALANT FOR REAR END PANEL	New	80.00	0.00
19	SEALANT FOR REAR FLOOR PANEL	New	80.00	0.00
20	SEALANT FOR TAILGATE	New	80.00	0.00
21	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	180.00	180.00
22	REMOVE & INSTALL SPEAKER BOARD RR SEATS	New	1,120.00	560.00
23	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	0.00
24	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	560.00	0.00
25	CUT OFF & RENEW RR PANEL	New	9,000.00	4,480.00
26	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	New	5,000.00	3,600.00
27	REMOVE AND RENEW TRUNK SPOILER	New	180.00	150.00
28	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	New	560.00	480.00
29	REMOVE AND RENEW WHEELS/RIMS	New	200.00	100.00
30	REMOVE & TRANSFER ITEMS TO NEW RR L DR.ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS	New	560.00	560.00
31	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITES	New	560.00	560.00
32	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS	New	560.00	560.00
33	REMOVE & RENEW WIRE HARNESS. RESET ECU MEMORIES	New	560.00	560.00
Gross Labour Cost (\$\$)			34,100.00	19,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >