

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

TP III  
 Xiao Tony

Contact : 66550005 82820430

## ESTIMATE

Repair Code : CLM15306

Date in : 15/06/2019

Vehicle Num. : SLK2878X

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104558319/1ZRY333552

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE Bent	1	2355.00	2,355.00 ✓
REAR BUMPER Rehd	1	486.00	486.00 ✓
REAR BUMPER END SEAL COVER RH tom	1	96.50	96.50 ✓
REAR BUMPER REFLECTOR RH New	1	83.00	83.00 +
REAR BUMPER SIDE RETAINER L/R Rit could	2	69.00	<del>138.00</del> 69.
REAR RH DOOR Dented	1	1195.00	1,195.00 ✓
REAR RH DOOR BLACK TAPE new	1	63.00	63.00 ✓
REAR RH DOOR CHECKER New	1	127.00	127.00 +
REAR RH DOOR GLASS CHANNEL New	1	115.00	115.00 +
REAR RH DOOR GLASS REGULATOR Rehd	1	213.00	213.00 ✓
REAR RH DOOR GLASS REGULATOR MOTOR New	1	547.00	547.00 +
REAR RH DOOR HINGE (LOWER) 2 New	1	67.00	67.00 x
REAR RH DOOR HINGE (TOP) New	1	67.00	67.00 x
REAR RH DOOR INNER RUBBER SIDE GUIDE STOPPER New	2	25.00	50.00 +
REAR RH DOOR INNER TRIM BOARD cracked	1	1325.00	698 <del>1,325.00</del>
REAR RH DOOR MECHANISM LOCK Rehd	1	477.00	477.00 ✓
REAR RH DOOR WEATHER STRIP at	1	121.00	121.00 ✓
REAR RH FENDER Dented	1	971.00	971.00 ✓

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

Contact : 66550005 82820430

## ESTIMATE

Repair Code : CLM15306  
 Date in : 15/06/2019  
 Vehicle Num. : SLK2878X  
 Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT  
 Chassis/Eng# : MR053REH104558319/1ZRY333552

REAR RH SHOCK ABSORBER	<i>Best</i>		1	268.00	268.00 ✓
REAR RH SPORT RIM	<i>cut</i>	7649.80	1	1375.00	<del>500(SN)</del> 1,375.00 ✓
REAR RH WHEEL BEARING	<i>new</i>	5737.35	SN 500 1	562.00	562.00 ✓
REAR WINDSCREEN SEAL	<i>all</i>		1	75.30	75.30 ✓
				Subtotal before discount	10,776.80
Percentage discount 25%					2,694.20
				<b>Sub-total 1</b>	<b>8,082.60</b>
REAR BUMPER CLIPS - SET	<i>all</i>		1	80.00	<del>30</del> 80.00 ✓
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	<i>all</i>	120	1	50.00	<del>30</del> 50.00 ✓
REAR RH TYRE 205/55R16	<i>new</i>		1	380.00	+ 380.00 ✓
REAR WINDSCREEN SEALANT	<i>all</i>		1	80.00	<del>60</del> 80.00 ✓
				Subtotal before discount	590.00
Percentage discount 0%					0.00
				<b>Sub-total 2</b>	<b>590.00</b>
				<b>Parts-total</b>	<b>8,672.60</b>

## LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.		50	<del>100.00</del>
to remove, reinstall windscreen (REAR)		120	<del>150.00</del>
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.		280	<del>350.00</del>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

Contact : 66550005 82820430

## ESTIMATE

Repair Code : CLM15306  
 Date in : 15/06/2019  
 Vehicle Num. : SLK2878X  
 Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT  
 Chassis/Eng# : MR053REH104558319/1ZRY333552

To road test driving, check and resetting wheel alignments system.	80	<del>140.00</del>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	<del>140.00</del>
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	✓ 80	80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700	<del>1,000.00</del>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2230	800 <del>1,000.00</del>
To apply anti-rust chemical on repaired and replaced panel.	60	<del>120.00</del>
<b>Labour Total</b>		<b>3,080.00</b>
<b>Parts &amp; Labour Total</b>		<b>11,752.60</b>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian Lj  
 L/s 18/06/19  
 07 Days  
 total - 8587.35  
 L/s: 6.8k

**KIM HOE TYRE & BATTERY**  
**KAKI BUKIT AUTOHUB**  
**01-10 SINGAPORE 417921**  
**TEL:67472427**

Customer

Vehicle ident no.

Repair order no.  
**R000927**

Technician

Date  
**18.6.19**

License plate no.  
**SLK2878X**

First reg. date

Model

**Toyota : Corolla Altis : 1ZZ-FE : 2009-**

Odometer reading: km/miles

**Complaints or reason for alignment check**

			Before	Target Data	Actual	
Rear axle	Camber	left		-1°26' +/-0°30'	-1°11'	
		right			-6°53' *	
		cross		0°00' +/-0°30'	5°42' *	
	Toe	left		0°06' +/-0°08'	0°16' *	
		right			1°53' *	
		total		0°12' +/-0°16'	2°09' *	
Geometrical driving axis				0°00'	-0°48'	
Front axle	Camber	left		-0°25' +/-0°45'	-0°29'	
		right			-1°11' *	
		cross		0°00' +/-0°30'	0°42' *	
	Caster	left		2°52' +/-0°45'		
		right				
		cross		0°00' +/-0°30'		
	SAI	left		12°12'		
		right				
		cross		0°00'		
	Track differential angle					
	Toe	left		0°00' +/-0°06'	0°41' *	
		right			-0°30' *	
total			0°00' +/-0°12'	0°11'		
Setback				0°00'		
Max steering lock	left steer	left		-38°30' +/-2°00'		
		right		33°04' +/-2°00'		
	right steer	left		33°04' +/-2°00'		
		right		-38°30' +/-2°00'		

\* This value is not within specification. Tire wear, handling and safety problems may result.