

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0759/2019/TG
Date	:	18-Jun-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Kng Yau (Lin GuangYao)
Address	:	77 Flora Drive
	:	#08-23
	:	Singapore 50684
Telephone	:	96426011
Type of Claim	:	Own damage Claim
Policy No.	:	
Vehicle No	:	SLR 5653 X
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	18/8/2017
Engine No	:	CVN 040756
Chassis No	:	WAUZZZF48HA177989
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	9-Jun-19
Place of Accident	:	Slip Road At Tampines Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 5653 X

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray front bumper.	\$ 900.00 550	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,310.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 5653 X

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPR <i>torn</i>	\$ 1,946.00	x ✓ 1556.80
2	FRONT BUMPER FIXING PARTS <i>Ne me</i>	\$ 258.00	x
3	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	\$ 178.00	+ ✓ 142.40
4	CLOSING ELEMENT <i>Ne me</i>	\$ 191.00	✓
5	FRONT BUMPER AIR GUIDE - RH <i>Ne me</i>	\$ 56.00	+
6	RADIATOR GRILLE <i>crushed</i>	\$ 1,053.00	✓ 942.40
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Ne me</i>	\$ 123.00	x
8	FRONT BUMPER CARRIER <i>Best</i>	\$ 733.00	+ ✓ 586
9	FOAM FILLER PIECE <i>behind</i>	\$ 113.00	+ ✓ 90.40
10	BUMPER COVER	\$ 116.00	+
11	WARINING SIGN STICKER	\$ 13.00	x
12	STICKER FOR AIR CONDITIONER <i>HP</i>	\$ 7.00	x
13	HORN FANFARE - RH	\$ 262.00	x
14	SPRING SHACKLE - RH	\$ 26.00	x
15	LIFT CYLINDER - RH	\$ 192.00	x
16	AIR DUCT COVER - RH	\$ 25.00	x
17	INNER DUCT COVER - RH <i>behind</i>	\$ 11.00	+ ✓ 8.32
18	AIR DUCT COVER - UPPER <i>Ne me</i>	\$ 15.00	+
19	AIR DUCT COVER - LOWER	\$ 19.00	+
20	FRONT NUMBER PLATE <i>Ne</i>	\$ 40.00	✓
21	SUNDRIES <i>Ne</i>	\$ 200.00	? ✓ 52.24
TOTAL SPARE PARTS CHARGES		\$5,577.00	
TOTAL LABOUR CHARGES		\$ 2,310.00	
GRAND TOTAL		\$7,887.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Net.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian King

Surveyed Date

: 18/06/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repairs, 03 Days.

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No: 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0759/2019/TC

3-Jul-19

Kee Siang

1 of 1

SLR 5653 X

Audi A4 Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
Parts			
1	Bracket lock carrier	\$ 125.00	106
2	Bumper carrier support LHS	\$ 26.00	20.32
3	Bumper carrier support RHS	\$ 26.00	20.32
4	Bowden cable	\$ 53.00	41.68
5	Bracket for external temperature sensor	\$ 17.00	13.04
6	LED headlight RHS	\$ 7,087.00	X Not N/C
7	Radiator air guide LHS	\$ 11.00	8.32
8	Air-cond condenser	\$ 568.00	454.00
Labour			
1	To remove and renew air-cond condenser. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✓
		\$ 1,200.00	Repeat.
2	To renew rhs headlight. To remove and reinstall front lock carrier and align to position.	\$ 3,150.00	X
3	To respray front bonnet.	\$ 800.00	✓
GRAND TOTAL		\$ 14,263.00	

Auto Consultants hence notify
 Repairer of the following:
 • Survey before/after spray painting
 • Survey any damaged part(s) during resurvey
 • Prices are subject to confirmation
 • Survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

For Premium Automobiles Pte Ltd



Authorised Signature