

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 5653 X

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray front bumper.	\$ 900.00 550	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,310.00	

2,502

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 5653 X

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPR <i>torn</i>	\$ 1,946.00	x ✓ 1556.80
2	FRONT BUMPER FIXING PARTS <i>Ne Me</i>	\$ 258.00	x
3	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	\$ 178.00	x ✓ 142.40
4	CLOSING ELEMENT <i>Ne Me</i>	\$ 191.00	✓
5	FRONT BUMPER AIR GUIDE - RH <i>Ne Me</i>	\$ 56.00	+
6	RADIATOR GRILLE <i>crushed</i>	\$ 1,053.00	✓ 942.40
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Ne Me</i>	\$ 123.00	x
8	FRONT BUMPER CARRIER <i>Best</i>	\$ 733.00	x ✓ 586
9	FOAM FILLER PIECE <i>behind</i>	\$ 113.00	x ✓ 90.40
10	BUMPER COVER	\$ 116.00	x
11	WARINING SIGN STICKER	\$ 13.00	x
12	STICKER FOR AIR CONDITIONER	\$ 7.00	x
13	HORN FANFARE - RH	\$ 262.00	x
14	SPRING SHACKLE - RH	\$ 26.00	x
15	LIFT CYLINDER - RH	\$ 192.00	x
16	AIR DUCT COVER - RH	\$ 25.00	x
17	INNER DUCT COVER - RH	\$ 11.00	x ✓ 8.32
18	AIR DUCT COVER - UPPER	\$ 15.00	x
19	AIR DUCT COVER - LOWER	\$ 19.00	x
20	FRONT NUMBER PLATE <i>Ne</i>	\$ 40.00	✓
21	SUNDRIES <i>Ne</i>	\$ 200.00	? ✓ 52.24
TOTAL SPARE PARTS CHARGES		\$5,577.00	
TOTAL LABOUR CHARGES		\$ 2,310.00	
GRAND TOTAL		\$7,887.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Net.

8,079.00

22,173.68#