

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0761/2019/TG
Date : 18-Jun-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
5 days exclude 1 Sunday
jb 24 Aug 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Lee Pui Lee
Address : 25 Miltonia Close
#06-12
: Singapore 768060
Telephone : 96426011
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SGC 2223 L**
Model Code : Audi Q2 1.4 TFSI COD S TR
Model / Year : 11/14/2018
Engine No : CZE 835657
Chassis No : WAUZZZGA0JA119885
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jun-19
Place of Accident : Car Park Of International Plaza

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGC 2223 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,400.00	\$ 750.00
3	To remove and reinstall rear bumper.	\$	600.00	\$ 500.00
5	To respray front bumper, and rhs front fender.	\$	2,200.00	\$ 550.00
6	Added labour	\$	1,200.00	\$ 550.00
7	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,952.00	\$ 2,902.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 2223 L

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPR	\$	1,705.00	\$ 1,364.00
2	FRONT BUMPER FIXING PARTS	\$	314.00	
3	FRONT BUMPER GRILLE - CENTER	\$	179.00	
4	FRONT BUMPER AIR GUIDE GRILLE - RH	\$	154.00	\$ 122.80
5	END CAP	\$	31.00	\$ 24.40
6	SPOILER	\$	273.00	\$ 218.00
7	CLOSING ELEMENT	\$	142.00	\$ 113.20
8	WHEEL SPOILER - RH	\$	31.00	
9	ADAPTER - RH	\$	38.00	
10	RADIATOR GRILLE	\$	1,301.00	
11	STRIKER PLATE	\$	114.00	
12	FOAM FILLER PIECE	\$	71.00	
13	FRONT BUMPER CARRIER	\$	625.00	
14	FRONT BUMPER TOP COVER	\$	91.00	\$ 72.56
15	GUIDE SECTION - RH	\$	32.00	
16	FRONT FENDEER - RH	\$	1,047.00	
17	FRONT FENDER ATTACHMENT PARTS	\$	36.00	
18	BRACKET - RH	\$	14.00	
19	BRACKET - RH	\$	43.00	
20	BRACKET - RH	\$	14.00	
SUB-TOTAL SPARE PARTS		:	\$ 6,255.00	\$ 1,914.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 2223 L

S/N	Parts Description		Damage Pa	
			S/NETT	RE
		<i>c/f</i>		
21	POP RIVET	6	\$	18.00
22	BRACE - RH		\$	29.00
23	INSULATION FOR WING		\$	69.00
24	WHEEL HOUSING LINER - UPPER		\$	33.00
25	BRACKET		\$	21.00
26	WHEEL HOUSING LINER - RH		\$	183.00
27	WHEEL HOUSING ATTACHMENT PARTS		\$	56.00
28	CAUTION STICKER		\$	13.00
29	A/C STICKER		\$	7.00
30	HEADLIGHT MOUNTING - RH		\$	107.00
31	LED HEADLIGHT -RH		\$	4,491.00
32	LIFT CYLINDER - RH		\$	128.00
33	AIR GUIDE FOR RADIATOR		\$	27.00
34	FRONT WHEEL COVER - LH		\$	294.00
35	FRONT WHEEL COVER - RH		\$	294.00
36	REAR BUMPER SPOILER		\$	259.00
37	REAR WHEEL ARCH COVER - LH		\$	156.00
38	REAR WHEEL ARCH COVER - RH		\$	156.00
39	FRONT NO. PLATE	S/N	\$	40.00
41	Added parts - see attached		\$	1,074.00
42	SUNDRIES		\$	300.00
	TOTAL SPARE PARTS	:	\$	12,936.00
	TOTAL LABOUR CHARGES	:	\$	6,952.00
	GRAND TOTAL	:	\$	19,888.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Parts & Prices

MARKS

\$ 1,914.96

\$ 9.76

\$ 5.12

\$ 3,592.80

\$ 234.80

\$ 234.80

\$ 207.20

\$ 124.40

\$ 124.40

\$ 859.20

\$ 57.00

\$ 7,364.44

\$ 2,902.00

\$ 10,266.44

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0761/2019/TG 11-Jul-19 Glory Tan 1 OF 1 SGC 2223 L Audi Q2 1.4 TFSI COD S TR
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Rear bumper	\$ 1,074.00	\$ 859.20
		\$ 1,074.00	\$ 859.20
<u>LABORS</u> 1	To respray rear bumper.	\$ 1,200.00	\$ 550.00
	TOTAL	\$ 2,274.00	\$ 1,409.20

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant