Mumen	marcus on pauline son	ASSIGNM	MSIG	D + 67"	19/6/190 10 Ham
Estimated Co		00	Bill to:		FILOURIE TO
	STTP RES / OD RES /	EVA/INV/MV		60	
To Inspect Ve		SKV		Insured:	
at Workshop		Trynse	sublears	Tel: '812	28 9802 .
of		5 ubi (108	K		
Policy No:	B29083884	PMY	Claim No:		7 11 11 11 11 11 11 11 11 11 11 11 11 11
Sum Insured;			Excess;	\$1,500.0	D
Make of Veh (Client's Record				D.O.A	17/6/19
CA / REV	/ REP. / REV 24 HRS			H.O.D. I	ndorsement:
Date/Time:	11.17um@19/6/1A	Person Contacted	Jes -	Vehicl (IF	YOUT
Date/Time	Action/Instruction				
	SKN 83P-CS	CHIEWER	12/4gbn2	ě	70A:13/4/18
	-				
1					

ASSIGNMENT ASSIGNMENT To Inspect Vehicle No: Colour Low A AC: Insured Isted ININA So, Reading 93 C 23 Tradicional Insured Isted ININA So, Reading 93 C 23 Tradicional Insured Isted ININA So, Reading 93 C 23 Tradicional Insured Isted Inina To Insured Isted Inina To Insured Isted Inina Soenic Insured Isted Inina Soenic Insured Isted Inina To Insured Ist	08/11/13) wef REF:	MS(le)
From: Catimated Cost:	ASS. REC. BY: Marcus	SSIGNMENT
Type: WCR/ M.Cycle / Bus / Vah / Lorry / Taxi / Prime Mover / Truck / Trailer or / Truck / Trailer or / Truck / Trailer or / ACC: Insured / Stal / NI / NA / Sp. Reading / S.S. /	285	C/11/220 73/6/15
Truck/Trailer or 4 Truck/Trailer or 4 Truck/Trailer or 4 Make: Matt 4 6	From: Date:	Veh No: / V J I regil. / Prime Mover /
To Inspect Weihicle No: Name No. Sk. Sk	Estimated Cost:	
To Inspect Vehicle No: at Workshop mis of Insured: Policy No. Claims No. Surn insured: (Claim's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repaire the time of inspection. Bal or Market Value: IDAC Accident Rport: Consistent?: Yes or No Est Repairs: CA / REV / REP. / 12 4 HRS AP (CASO) Date: Person Contacted: Date / Time Action / Instruction Gan. Colour AC: Insured Std Nil Nil Sp. Reading 3 (* 2) Tiradio: Insured Std Nil Nil Conor Sp. Reading 3 (* 2) Tiradio: Insured Std Nil Nil Conor Sp. Reading 3 (* 2) Tiradio: Insured Std Nil Nil Conor Sp. Reading 3 (* 2) Tiradio: Insured Std Nil Nil EngNo: Conor Gold Fair / Poor / Burnt Stepfing: Jammed Leaked Burnt or Bal or Market Value: Invision! Std Alkin or Tyre Size: F: 2 2 / (5 - 7) Remark: Toyol / YoKo or Foors Ribal mm Libal mm Toyol / YoKo or Foors Ribal mm Libal mm Libal mm Libal mm Doul. 9 (6 / 1) Toyol / YoKo or Foors Ribal mm Libal mm Doul. 9 (6 / 1) Toyol / YoKo or Foors Ribal mm Libal mm Doul. 9 (6 / 1) Toyol / YoKo or Foors Ribal mm Libal mm Doul. 9 (6 / 1) Toyol / YoKo or Foors Ribal mm Libal mm Doul. 9 (6 / 1) Toyol / YoKo or Foors Ribal mm Libal mm Doul. 9 (6 / 1) Doul. 9 (6 / 1) Doul. 9 (6 / 1) The UIC Chassis frame Body Structure affected due to collision. The UIC Chassis frame Body Structure affected due to collision. The UIC Chassis frame Body Structure affected due to collision. The UIC Chassis frame Body Structure affected due to collision. The UIC Chassis frame Body Structure affected due to collision. The UIC Chassis frame Body Structure affected due to collision. The UIC Chassis frame Body Structure affected due to collision. The UIC Chassis frame Body Structure affected due to collision. The U	6D) TP / WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or A
at Workshop mis of Insured: Insured: Policy No. Claims No. Sum Insured: (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: DAC Accident Rport: Consistent?: Yes or No CBL / Type Sear: Consistent?: Yes or No CBL / Type Sear: CA / REV / REP. / 24 HRS Description Date / Time Action / Instruction Gyr. Description Date / Time Action / Instruction Gyr. Description Date / Time Action / Instruction Gyr. Description Size of Danages: Frt / Rear / OIS / NIS / UIC / Rooftop or NIS / Size of Danages: Frt / Rear / OIS / NIS / UIC / Rooftop or NIS / Size of No Date / Time Action / Instruction Gyr. Description CA / REV / REP. / 24 HRS Description Date / Time Action / Instruction Gyr. Description CA / Rev. Size of No CA / Re	To Inspect Vehicle No: SkJ89	ALC Laured / Chd / NI / NA
Insured: Policy No. Claim's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: DAC Accident Rport: Consistent?: Yes or No CLA Rev Rep. 24 HRS AA COO Date: Person Contacted: Date / Time Action / Instruction Action / Inst	7. ()	Colour Coo C
Insured: Policy No. Claims No. Sum Insured: (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No Est Repairs: Cays Res.: Yes or No Lum Sum: CA I REV I REP. I 24 HRS Date: Person Contacted: Person Contacted:		Sp.Reading 935'23 T/Radio: Insured / Std / NI / NA
Gen. Cond. G66d Fair Poor Burnt Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN STD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN STD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN STD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN STD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN STD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN STD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN StD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN StD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN StD ARRIM or Tyre Size: F: 2 2 FS - N - Street Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN StD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN StD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN StD ARRIM or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Modi: Nil JERRIN Jesked Burnt or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Tyre Size: F: 2 2 FS - N - Steering: Ingright Jammed Leaked Burnt or Tyre Size: F: 2 2 FS - N -		Eng/No:
Claims No. Sum Insured: (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: (DAC Accident Rport: Claims No. Sum insured: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: (DAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est Repairs: Cay Ress: Yes or No CLUM Sum: CA / REV / REP. 12 4 HRS Application of North Vehicle: IN / OUT Date: Person Contacted: Date / Time Action / Instruction Cay Not on the provided of the p		C/NO: JM66J1032602017859
Steering: Ingrafer Leaked Burnt or Brake: Ingrafer Jammed Leaked Burnt or Brake: Ingrafer Jammed Leaked Burnt or Modi: NII Riting Jammed Leaked Burnt or Riting Jammed Leaked Jammed Leaked Jammed Leaked Burnt or Riting Jammed Leaked Burnt or Riting Jammed Leaked Jammed		
(Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal or Market Value: IDAC Accident Rport: Consistent?: Yes or No Est. Repairs: Cays Res.: Yes or No Lum Sum: Date / Time Action / Instruction Gyr, Quy / OSDD MS Market. In 106/19 @ 14:37 pm rewised pm to Pauline Such A Psy Vis market. Soh A: Ping Vis market. Date / Time, File Pyss pm / Sold Prolit. Date / Time, File Repairs: Confirmed file Pyss pm / Sold Prolit. Peroll. Report Soh A: Ping Vis market. Add Fee: Site Insp (\$) Salves of Dears Interview (\$) Photos Interview (\$) Photos Lum Sum! File Pyss pm / Sold Prolit. Report Format: Librative in profer in profess in possible. Resurvey No. of Trip: Survey Fee: Transpostation: Add Fee: Site Insp (\$) Salves Survey Fee: Transpostation: Add Fee: Lum Sum! Site Insp (\$) Salves Survey Fee: Transpostation: The Uic / Chasals frame / Body Structure affected due to collision. Add Fee: Site Insp (\$) Salves Survey Fee: Transpostation: Transpostation: Trach. Invs (\$) Others Lum Sum / I.B.I. (\$ 8.265.50 P/P) Weekend (\$) Weekend (\$)		7 Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Acoident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Lum Sum: CA / REV / REP. / 24 HRS Date / Time Action / Instruction CA / Time Action / Instruction CA / Rev / Sap	35000-1100-11-12-12-12-12-12-12-12-12-12-12-12-12-	
Type Size: F: 225/CC-11 Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Lum Sum: / 2 / % 3 Val.: Yes or No CA / REV / REP. / 24 HRS	Control of the Contro	
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal or Market Value: IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Lum Sum: Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. RECEIVED 2 & JUL 2019 RECEIVED 2 & JUL 2019 RECEIVED 2 & JUL 2019 Confirmed final of a factory of contacted authorize report to Pauline Sub Library of Survey Resurvey Substitution authorize report to Pauline Substitution authorize report to Pauline Substitution of Survey Resurvey Substitution of Trip: Date: Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. RECEIVED 2 & JUL 2019 RECEIVED 2 & JUL 2019 RECEIVED 2 & JUL 2019 Confirmed final of a factory of Contacted authorize report to Pauline Substitution report to Pauline		Tyre Size: F: 225/55-24
Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: C days Res.: Yes or No LUBal. LUBal. D.O.A. / 7 6 1		
TOYO/YOKO OR Ball or Market Value: DAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repears: C days Res.: Yes or No Lum Sum: 72 % 3 Val.: Yes or No Date: Person Contacted: Described: IN/OUT Date: Person Contacted: Date / Time Action / Instruction Gyr. 0500 Ms Market 1366/19 Market Market Market 1466/19 Market Market Market 15 Market Market Market 166/19 Market Market 176/19 Market 186/19 Market	117.00	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR/ SUMI /
Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Low Sum: Low Sum: CA / REV / REP. / 24 HRS Date: Person Contacted: Date: Person Contacted: Date: Date / Time Action / Instruction 6 yr. 0xp / 0500 No market. Plant. Plant. The UIC / Chassis frame / Body Structure affected due to collision. RECEIVED 2 & JUL 2018 The UIC / Chassis frame / Body Structure affected due to collision. RECEIVED 2 & JUL 2018 CA / REV STOPM Action / Instruction 6 yr. 0xp / 0500 No market. Plant.	Remark: The ven had commenced its	
Ball of manker value. IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: C days Res.: Yes or No Lum Sum: /2/ % 3 Val.: Yes or No CA / REV / REP. / 24 HRS	71/,	
IDAC Accident Rport: GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Lays Res.: Yes or No Lum Sum: / 2 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Person Contacted: Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: P	o transfer version New or No.	
Est. Repairs:	IDAC Accident reports	101
Est. Repairs: Lum Sum: / 3 / 8 7 8 5 1 1 1 1 1 1 1 1 1	GIA / FIX dean.	011
Date: Person Contacted: Person Contacted: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time	Est. Repairs. Z days	11/6/4
Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. RECEIVED 2 & JUL 2019 13/06/19 @ 14:37 pm revised pn to Pauline Soh L. Ping Vic minimal following report to Pauline Soh L. Ping Vic minimal. 13/06/19 @ 14:37 pm revised pn to Pauline Soh L. Ping Vic minimal sold in report to Pauline Soh L. Ping Vic minimal. 13/06/19 @ 14:37 pm revised pn to Pauline Soh L. Ping Vic minimal sold in report to Pauline Soh L. Ping Vic minimal. 13/06/19 @ 14:37 pm revised pn to Pauline Soh L. Ping Vic minimal sold in report to Pauline Soh L. Ping Vic minimal sold in report Confirme. 13/06/19 @ 14:37 pm revised pn to Pauline Soh L. Ping Vic minimal sold in report to Pauline Soh L. Ping Vic minimal sold in report Confirme. 13/06/19 @ 14:37 pm revised pn to Pauline Soh L. Ping Vic minimal sold in report to Pauline Soh L. Ping Vic minimal sold in report Sold Interview (\$) Survey Fee: Transportation: 14/10 Confirme, File Pass to 72 Ping Vic minimal sold in report Sold Interview (\$) Photos 15/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 15/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 16/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 17/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minimal sold in report Sold Interview (\$) Photos 18/06/19 End Vic minterview (\$) Photos 18/06/19 End Vic minimal sold Interview (\$	Lum Sum: /3./ % 3 Val.: Yes or No	
Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time	CA REV REP. 24 HRS LTA S 6250	
Date / Time Action / Instruction 6 yr. Dep / OSDD MD Mg. P. ? RECEIVED 2 & JUL 2019 19/06/19 @ 14:37 pm revised pn to Pauline Sub L. Ping Via maining 19/06/19 @ 14:50 pm maining required authorius report to Pauline Sub L: Ping Via maining. 25 / Yill Confirmed fine of \$1265-50 Will Coffwine. C\$ 15, #49.72 Peak 65% Date/Time, File Pass 10? 25/07/19 1) Typit Dete/Time, File Return to? Add Fee: Site Insp (\$)_\$+R\$_51 200 Report Format: Lump Sum/1.B.: (\$ 3.265.50 P/P) Weekend (\$) Others	Venicle: IN	1001
RECEIVED 2 & JUL 2019 19/06/19 @ 14:37 pm revised pn to Pauline Roh L. Ping Via mainine 19/06/19 @ 14:37 pm naidle required authorie report to Pauline Soh L.: Ping Via mainine. 25/19 Confirmat fine of \$265-50 With Coffirme. C\$ 15,449.72 Red 65%) Date/Time, File Pass 10? 25/07/19 D: Final Report Days Of Repair: Dete/Time, File Return to? Add Fee: Site Insp (\$		The O/C / Chassis Haine / Body ordered another and
19/06/19 @ 14:37 pm revised PN to Pauline Soh L. Ping Via mainer 19/06/19 @ 14:50 pm mainer required authorius report to Pauline Soh L.: Ping Via mainer. 15/19 Confirmed fine of \$1265-50 With Coffwine. (\$ 15,449.72 Red 65%) Date/Time, File Pass ip? 25/04/19 Pine Report Days Of Repair: 1) Typist Date/Time, File Return to? Add Fee: Site Insp (\$)_s+RS_SI 11 Report Format: Lump Sum / B): (\$ 8.265.50 P/P) Survey Fee: Transportation: 11 12 13 14 15 16 17 17 18 19 10 10 10 10 10 10 10 10 10		50 7
Confirmal fine	,	NEOE I I
Confirmation Grant	salable a 14: 37 am revised	PA to Paulae Soh L. Ping Via mainer
Confirmal fine	18/1/10 P 14:00 PM mandre	removed authorice report to Paulere
Confirmal fine	Col Li Pine Vis m	wimu.
Date/Time, File Pass, to? Survey Fee: Transportation: Days Of Repair: Survey Fee: Date/Time, File Return to? Survey Fee: Date/Time, File Return to? Add Fee: Site Insp (\$)S+RSSI	11	moneto
Date/Time, File Pass, to? Survey Fee: Transportation: Days Of Repair: Survey Fee: Date/Time, File Return to? Survey Fee: Date/Time, File Return to? Add Fee: Site Insp (\$)S+RSSI	25/2/18 confirmed fine 4 &	8265-50 with cofferme.
Date/Time, File Pass, to? Sepair: Survey Fee: Transportation: Days Of Repair: Survey Fee: Date/Time, File Return to? Survey Fee: Date/Time, File Return to? Add Fee: Site Insp (\$)S+RSSI	(\$ 15, 449.72 Red	65%)
1 Typ:st : Final Report Resurvey No. of Trip: Survey Fee: Transportation: 200		
Transportation: 200	35/07/19 Final Bonort	
2) Add Fee: : Site Insp (\$)S+RSSI		
: Interview (\$) Photos : Tech. Invs (\$) Others : Weekend (\$) :	hΔ	
Tech. Invs (\$) Others Lump Sum 1.B : (\$ 8.26r-50 P) Weekend (\$)	2)	
Lump Sum (1.B): (\$ 8.26r-50 P/P) :Weekend (\$		
	Report Format	
	Lump Sum 1.81: (\$ 8,265.50 P/P)	TOTAL 211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Pauline Soh Li Ping

Date:

19 Jun 2019

Preliminary Advice

Vehicle No

: SKV83P

Accident Date

: 17/06/2019

Make

: MAZDA 6

Policy No.

: B29083884QMY

Assignment Date

: 19/06/2019

Excess

: \$\$1,500.00

Date of Inspection

: 19/06/2019

Est. Duration of Repair

Inspection At

: Trans Eurokars Pte Ltd (HQ)

5 Ubi Close

Singapore 408605

:S\$

: 5 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,715.22
Revised Amount	:S\$	8,265.50
Check Items (Estimated)	:S\$	283.70
Total	:S\$	8,549.20

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	71,000.00
COE / PARF Rebate	:S\$	56,250.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,750.00

Remarks

- The vehicle is economical for repair. According to the Jess (repairer), Owner din't write down the story of how the accident happened in sketch plan. Just only drawing showed in the sketch plan. Based on our surveyor, the damages of the n/s front portion is consistent with the accident.
- The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Ad) Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status			
Main	19 Jun 2019 10:33	No Street of the street	19 Jun 2019 11:56 Assign				New Assignment Cancel Case			
	Main	Ref	erence	Clain	n Details	Documen	ts	Show All		
LAIM S	UBFOLDER DE		Delinder at the Control of the Control	and the same of the same			ted by insurer	1		
nsured: ehicle Re	eg. No.:	SKV8	ONG JIN, ID: S		el: +6596790032, E e of Loss:	17/06 [5 Mo Reg D	/2019 16:00 - :5 nths and 16 Day: ate (Man Yr)]	s From LTA		
laim Typ	oe:	OD		Poli	cy/Cover Note No.:	B29083884QMY (Compreh Coverage: 23/06/2018 - 22/06/2019				
				Exc		S\$1,5	00.00			
epairer:			Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:							
andling	Insurer:	MSIG I	nsurance (Singa	pore) Pte. Ltd	re) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Pauline Soh Li					
djuster:		LKK Au	to Consultants F	Pte Ltd (HQ) - Tel: 6256-3561 [Imm.Advice due 20/06/2019]						
river/Cu	istodian:				1548829H, Tel: +6					
dj Asg. I	Remarks:		Survey & revert. P email on 19/06/2		is ASAP if you cannot	attend this assign	ment. Manually a	assigned to		
SSOCI	ATED MAIL REG	CEIVED				View All	Compose C	ase Mail		
here are	no mail for this	case.								
=		888			V V		5-80 80 80 M			
ALL ASS	SOCIATED TAS	KS			View All Search	Tasks Crea	te New Task	Complete		
Due Da		Type Task G	roup Subject	Handler	Assigned By	Completed On	Created On	Done?		

Nivitha (LKK Auto)

From:

Crystal Lee <crystal_lee@sg.msig-asia.com>

Sent:

Wednesday, 19 June 2019 10:21 AM

To:

assignments@lkkauto.com; admin-d@lkkauto.com

Cc:

Ong Zi Hui

Subject:

Survey Request - Manual Assigned

Attachments:

3002_190618175847_001.pdf

Importance:

High

SKV83P - Own damage claim PRI

Manual Assigned

Dear LKK.

Refer to the email below and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards, Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg









A Member of MS&AD INSURANCE GROUP

From: Motor Survey

Sent: Wednesday, 19 June, 2019 9:36 AM

To: Pauline Soh <pauline soh@sg.msig-asia.com>

Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>;

jess.francis@eurokars.com.sg

Subject: FW: SKV83P - Own damage claim PRI. The car is in UBI now. (URGENT) Manual assignment,

outsource, pend OD folder.

Importance: High

Dear ladies.

Please help to outsource this case. Meeting today. Tks.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey) Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

(O)

A Member of MS&AD INSURANCE GROUP

From: Agnes Lee

Sent: Tuesday, 18 June 2019 5:52 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Subject: FW: SKV83P - Own damage claim PRI. The car is in UBI now.

Importance: High

From: jess.francis@eurokars.com.sg < jess.francis@eurokars.com.sg>

Sent: Tuesday, 18 June 2019 5:42 PM

To: Claims < claims@sg.msig-asia.com >; Crystal Lee < crystal lee@sg.msig-asia.com >; Pauline Tham

<pauline tham@sg.msig-asia.com> Ce: ronald.yap@eurokars.com.sg

Subject: SKV83P - Own damage claim PRI. The car is in UBI now.

Importance: High

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

URGENT!!!

Dear Motor Claims,

Please arrange the PRI to your insured's vehicle on June 19, 2019.

Regards.

Jess Francis Carlos Insurance Claims Executive Trans Eurokars Pte Ltd 5 Ubi Close Singapore 408605 Tel no.: 8128 9802

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>

Sent: 18 June 2019 5:59 PM

To: Jess Francis Amurao Carlos < jess.francis@eurokars.com.sg>

Subject: Attached Image

.

CONFIDENTIALITY NOTICE
This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SGCARMART.COM

Login 5

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Swee becomes a hero - Disclosed should multiply

the income for 92% of Singaporeans alpinegrace.today

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Up To 100% Loan, 1 Owner, Under Agent Warranty.



SKL Automobile StarAd

PRIME MOT ICHENG YONG CREDIT ENTERPRISES With over 200 units of vehi to choose from, ranging fr all European to Japanese

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

mazda 6

Price

Depreciation

Eng Cap

Mileage

Sort by Date Posted

Search Selection

12 vehicles

mazda 6

Any

Anv

62,000 km

Any



Mazda 6 2.0A

Model

\$62,800

\$10,000 /yr

30-Apr-2015

2015

1,998 cc

1 Owner, Beautiful Condition, 90% Loan Of The Car Price Available. Free Servicing Package And Warranty, Call Now For Viewing.

Posted: 18-Jun-2019 Tags: 2015 Mazda 6, 2015 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda



Mazda 6 2.0A Executive

\$67,800

\$10,440 /yr

17-Jun-2015

1,998 cc

66,500 km

New 2 Months Old Tryes. Enjoy Loan Interest Rate At 2.28%, Financing Possible. Trade In Welcome. 100% Accident-Free. View To Belk This Red Beast, Call/SMS To Arrange A Viewing Now. View...

Posted: 18-Jun-2019 Tags: 2015 Mazda 6, 2015 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda



Mazda 6 2.0A

\$64,800

\$10,160 /yr

18-Jun-2015

1,998 cc

75,781 km

Rare! Fully Maintained At Eurokars Since Day 1 With History. Genuine Low Mileage Done 75781km. Like Brand New Condition, See To B Banker Owner, 100% Accident Free, Price Negotiable, Call Now!

Posted: 16-Jun-2019 Tags: 2015 Mazda 6, 2015 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda



Mazda 6 2.0A

\$65,800

\$10,470 /yr

11-May-2015

1,998 cc

71,000 km

1 Owner Unit, Low Mileage Done, Agent Serviced And Maintained, View To Believe, Reliable Japanese Car To Own, Spacious And Comfo For You And Your Family. Loan And Trade In Available.

Posted: 15-Jun-2019 Tags: 2015 Mazda 6, 2015 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda



Focal Component Kit

This 2-way component kit can be installed at the front instead of the original speakers of the Volkswagen Golf 6, 3/5 d

Find out more!



Mazda 6 2.5A Premium

\$72,800

\$11,350 /yr

06-Jan-2015

2,488 cc

20,000 km

1 Owner! AA Trust Certified Quality Pre-Owned Vehicle! Stunning Red With Light Interior! The Grand Luxury Of Mazda Sedan Line! Trav Comfort That Suits Every Occasion! Maintained By Agen...

Automotive

ed: 15-Jun-2019 Tags: 2015 Mazda 6, 2015 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Thursday, 20 June 2019 10:28 AM

To:

jess.francis@eurokars.com.sg SUR; ronald.yap@eurokars.com.sg

Cc: Subject:

SKV 83P OD (MSIG) DOA - 17/06/2019

Hi Jess,

As instructed by our client, please proceed to repair the insured vehicle SKV 83P (Excess \$ 1,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with:

*SKV83P (597025)

OD Jun 17 2019 4:00PM [TAN KEONG JIN] Trans Eurokars Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/06/2019 18:48 PM.

To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8265.50) - SKV83P - Claim Handler: Pauline Soh Li Ping

Approved:8265.50:a if c

DOCUMENTS SUMMARY
There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8829H
Vehicle Details	CHANGE SHAWAI SEE
Vehicle No.:	SKV83P
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR LED
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	PY20579400
Chassis No.:	JM6GJ1032G0207989
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$21,939.00
Original Registration Date:	23 Jun 2015
First Registration Date:	23 Jun 2015
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$17,715.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2025
PARF Rebate Amount: Intended COE Rebate Details	\$13,286.00
COE Expiry Date:	22 Jun 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,509.00
COE Rebate Amount:	\$42,964.00
Total Rebate Amount:	\$56,250.00

The information contained herein is correct as at 19 Jun 2019

ОК

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	18/06/2019 09:50
Date Of Accident	17/06/2019 16:05
Exact Location Of Accident	TANAH MERAH FERRY ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKV83P
Insured/Policyholder	
Name Of Registered Owner	TAN KEONG JIN
NRIC No	S1548829H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96790032
Alternative Phone No	OFFICE-96790032
Vehicle Particulars	
Manufacturer	MAZDA
Model	6-2.0 V SDN (GH) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29083884 QMY
Cover Note Number	
Driver	
Name of Driver	TAN KEONG JIN
NRIC No	S1548829H
Date Of Birth	22/09/1962
Occupation	INDOOR

08/07/2000

18 YEARS AND 11 MONTHS **Driving Experience** MALE Gender

(LOCAL) +65-96790032 Mobile Number

Fax Number

Date Of Driving Pass

OFFICE-96790032 Contact Number

EMail Address NOEMAIL Address

99 PASIR RIS HEIGHTS #14-29 VUE8 RESIDENCE

Postcode

519291

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

d OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

CONTRACTOR A

Number of vehicles (including own vehicle) involved in the accident

2

NO

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

one service

ambulance?

NO

Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: FONGSEOW KIEN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SBS3209Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

Page 2 of 24

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1



Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to regudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any fulse reporting may be refused to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you berely consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consont under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to callect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information. provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) tobo have insured vehicle(s) involved in this accident (all insurer(s) who have insured valuitle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' invyers/iaw firms, the Monetury Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by mu;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or (c) agents(induding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, 18-6-1019 regulators, law enforcement and government agencies as reasonably required for the purposus stated, or

Reporting Control/prisonner's Sympton

NRIC/FIN No.:

(II) for confiplying with requirements under any regulations, laws or court orders.

Policyholder's Signafuré


Date & Time:

Driver's Signature (If driver is not the palicyholder)

Date & Time:

galatina deprotessions VI










.

TAN KEONG JIN

Pace CHINESE Data of SV Ti 22-D9-1082 Soundy of SVTI SINGAPORE









MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807 Tel +65 6827 7888, Fax +65 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Cortificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1 Individual Ownership MOTOR MAX PLUS

Certificate No. B 29083884 QMY

Excess: SGD1,500

Windscreen Excess: SGD100

- Index Mark and Registration Number of Vehicle SKV83P
- 2. Name of Policyholder

Tan Keong Jin

- Effective Date of the Commencement of Insurance for the purposes of the Act 23/06/2018
- Date of Expiry of Insurance 22/06/2019
- 5. Persons or Classes of Persons entitled to drive*

Tan Keong Jin
Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

- * Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

 Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer





SGX CENTRE 2

SINGAPORE 068807

4 SHENTON WAY #21-01

TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

ADDRESS : 99 Pasir Ris Heights

Mr Tan Keong Jin

Singapore 519291

#14-29 VUE8 RESIDENCE

EXCESS :

18-Jun-19 DATE:

\$ 8265.50

MOTOR CLAIMS ATTN. :

MSIG INSURANCE SINGAPORE P/L

TEL: 96790032

NAME :

FAX :

VEH NO :	SKV83P	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6GJ1032G0207989	MILEAGE :	000000000000000000000000000000000000000	TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA6	DATE REG.	23-Jun-15	POLICY NO. :	

NATURE OF WORKS Parts Description PRICES REVISED OTY \$ 1,211.90 MGMV8-50-031CBB # 205 FRONT BUMPER 1 14.70 -MGHP9-50-0U1C 1 (na RETAINER LHS 77.00 MG461-50-1T1A 11 MESH, FRONT BUMPER 1 2 \$ 77.00 MGHP9-50-111 11 1 FOAM, FRONT REINFORCEMENT 4 \$ 12.40 2 MFD01-68-AC3 17 FASTENER, FOAM 5 101.90 11 1 MG46L-50-C22 CHROME LHS, FOGLAMP 6 \$ 22.70 MG46L-50-C21A Un 1 COVER LHS, FOGLAMP 17 S 18.20 1 MKD47-67-UC5A53 RETAINER SIDE, SENSOR 8 11 56.20 S MKD47-67-UC1 53 SENSOR SIDE, ULTRASONIC Q 33.40 5 TOWING COVER 1 MG46L-50-A11 BB vi.s 3.00 50 RIVET, FRONT BUMPER 1 ML33X-13-209 nu 11 3.00 5_ ML33X-13-209 RIVET, FRONT BUMPER 1 14 5.80 2 MGHP9-50-025 GROMMET, FRONT BUMPER 13 ne MC274-50-133 5-22.20 14 CLIP, FRONT BUMPER 6 ruc 19.20 MGD7A-50-EA1 ner FASTENER, FRONT BUMPER 6 15 32.00 -SI MS51S-51-833 16 RIVET, FRONT BUMPER 8 M 29.40 ne 51 RIVET, FRONT BUMPER 6 MGHP9-50-355 17 15.40 nu 5/ 1 MG46L-50-131 BRACKET SIDE LHS, GRILLE TOP 18 11 S 144,60 MG46L-50-7K1 19 CHROME LHS 1 37.20 20 BRACKET LHS, CHROME MG46L-50-161 S 1 11 nu 5 / 3.40 CLIP, BRACKET MGHP9-50-EB1A 21 52.70 SIL 5 . MG46L-50-B51 PROTECTOR LHS, CHROME 1 22 5 1 9.40 23 CLIP, FRONT GRILLE MG46L-50-EB1 ner 24 RIVET, FRONT GRILLE ner \$-16.00 2 MEA01-50-037 ner \$, 2.70 MG46L-50-2G1 RUBBER SEAL, FRONT GRILLE 1 25 MKD45-50-1K5A \$. 5.80 PIN LOCATOR, FRONT GRILLE 2 nes \$ -5.80 GROMMET, FRONT GRILLE 2 MKD45-50-ES1 27 ne 383.70 MGHP9-52-211A 5, FRONT FENDER LHS 1 28 22/Bu 48.30 \$ -1 MGHP9-52-240D STAY LHS, FENDER 30 102.90 MGHP9-56-140J \$. MUDGUARD LHS 31 51.00 32 RIVET, MUDGUARD 17 ML33X-13-209 50 ne C 3,369.80 MGML8-51-041E 33 HEADLAMP LHS 1 SCA 211.40 1 MGMG9-51-0K6 CORD SHORT, HEADLAMP 11 34 NI CLIP, HEADLAMP MFB01-50-133C \$ 8.00 36 MB092-51-833 nec 3.50 RIVET, HEADLAMP

8	CAPACITOR, I-	STOP	1	MG46L-67-ZCOA	11	-	,122.50
9	BLOCK, PELAY		1	MKD45-66-750	11	ş	49.80
0	BRACKET, RELA	Y	1	MKD45-67-B1XA	11	\$	15.40
1	HARNESS, FRON	T	1	MG46G-67-010A	11	\$ 5	5,706.50
				TOTAL PARTS		S 16	5,105.80
				LESS 10%			1,610.58
				TOTAL PARTS COST			1,495.22
		Labou	r Descri	ption			
	MZ-BR-FRONT7	O REPLACE FRONT BUMPER AND FRONT FEN LL AREAS AFFECTED BY THE ACCIDENT.	DER LH. TO	REPAIR HEADLAMP PANEL LH	1320	s -	1,980.00
	MZ-SP-SFRT01	1575		2,520.00			
3	MZ-BR-I-STOPT	O REPLACE I-STOP CAPACITOR.			11 >	\$	1,320.00
	MZ-BR-HARNES TO REMOVE & REPLACE THE WIRE HARNESS ASSY.					\$	1,320.00
5		11)	\$	450.00			
ŝ	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL	BALANCING.	NIX	NETT	ş	120.0
7	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT	FULL WHEEL	ALIGNMENT. /50	NETT	. \$	560.0
	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION	l.	So		\$	250.0
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER	FUNCTION	NG. / 20	n .	\$	250.0
0	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REP	PAIR WORKS.	150		\$	350.0
1	MZ-BR-SUNDRI	LKK Auto Consultants nence notify		n1X	NETT	\$	100.0
		the Repairer of the following: To receive unforelater spray painting		TOTAL LABOUR	\$ -		9,220.0
		. To ulcolar damaged part(s) during resurvey		TOTAL PARTS	\$ -	-	4,495.2
		 Parts prices are subject to confirmation Third curty Furney is on a "Without Prejudice" to 	vasis	TOTAL	\$ -		3,715.2
		No site or the processing its allowed.	25/15	LESS EXCESS	\$ -	\$	(=)
		. Supplementary demonstrated be required an	d	TOTAL AFTER EXCESS	\$ -	1	
		is subject to linal approval from Insurance Con	ipany :	GST 7%	\$ -	\$	-
		Acknowledged by Repairer		GRAND TOTAL	\$ -	\$	-
		Signature:		TRANS EURO			

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION
AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE
PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE
THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT
SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS,
A QUOTATION FEE OF \$400 WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR

PARTS PRICE AS WELL AS LABOUR CHARGES

Authorised Signature



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

MSIG INSURANCE SINGAPORE P/L

NAME:

Mr Tan Keong Jin

4 SHENTON WAY #21-01

ADDRESS: 99 Pasir Ris Helghts

WIP: EXCESS:

55116 \$ 1,500.00

SGX CENTRE 2

#14-29 VUE8 RESIDENCE

18-Jun-19

SINGAPORE 068807

Singapore 519291

DATE:

ATTN.:

MOTOR CLAIMS

MAZDA6

TEL:

96790032

FAX:

Jess 63957874 CONTACT PERSON: DATE IN: SKV83P VEH NO: OWN DAMAGED CLAIM TYPE OF CLAIM: MILEAGE: JM6GJ1032G0207989 CHASSIS NO:

MODEL:

POLICY NO. : DATE REG.: 23-Jun-15

MODE	L: MAZUAG	NATURE OF WORK	S				
_		Parts Description			EVISED		
NO		дту				PRICES	
1	FRONT BUMPER	1	MGMV8-50-031CBB	\$	2,222		1,211.90
2	RETAINER LHS	1	MGHP9-50-0U1C	\$	-	\$	14.70
3	MESH, FRONT BUMPER	1	MG46L-50-1T1A			\$	77.00
4	FOAM, FRONT REINFORCEMENT	1	MGHP9-50-111			\$	77.00
5	FASTENER, FOAM	2	MFD01-68-AC3	_		\$	12.40
6	CHROME LHS, FOGLAMP	1	MG46L-50-C22			\$	101.90
7	COVER LHS, FOGLAMP	1	MG46L-50-C21A			\$	22.70
8	RETAINER SIDE, SENSOR	1	MKD47-67-UC5A53			\$	18.20
9	SENSOR SIDE, ULTRASONIC	1	MKD47-67-UC1 53			\$	56.20
10	TOWING COVER	1	MG46L-50-A11 BB	\$	33.40	\$	33.40
11	RIVET, FRONT BUMPER	1	ML33X-13-209	\$	3.00	\$	3.00
12	RIVET, FRONT BUMPER	1	ML33X-13-209	\$	3.00	\$	3.00
13	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$	5.80	\$	5.80
14	CLIP, FRONT BUMPER	6	MC274-50-133	\$	22.20	\$	22.20
15	FASTENER, FRONT BUMPER	6	MGD7A-50-EA1	\$	19.20	\$	19.20
-	RIVET, FRONT BUMPER	8	MS51S-51-833	\$	32.00	\$	32.00
16	RIVET, FRONT BUMPER	6	MGHP9-50-355	\$	29.40	\$	29.40
17	BRACKET SIDE LHS, GRILLE TOP	1	MG46L-50-131	\$	15.40	\$	15.40
18		1	MG46L-50-7K1			\$	144.60
20	THE PROPERTY OF THE PARTY OF TH	1	MG46L-50-161			\$	37.20
		1	MGHP9-50-EB1A	\$	3.40	\$	3.40
21		1	MG46L-50-B51	\$	52.70	\$	52.70
22		2	MG46L-50-EB1	\$	9.40	\$	9.40
23	TO CHE COURT COURT	2	MEA01-50-037	\$	16.00	\$	16.00
24	THE PERSON STATE OF THE PERSON	1	MG46L-50-2G1	\$	2.70	\$	2.70
25	THE PARTY OF TRANSPORT CRILLE	2	MKD45-50-1K5A		5.80	\$	5.8
26	THE PROPERTY OF THE PARTY OF TH	2	MKD45-50-ES1		5.80	\$	5.8
27	AN OUT SEMBER IME	1	MGHP9-52-211A		383.70	\$	383.7
28	CTAVALUS SENDED	1	MGHP9-52-240D		48.30	\$	48.3
30		1	MGHP9-56-140J	1	102.90	\$	102.9
31	MUDGUARD LHS 2 RIVET, MUDGUARD	17	ML33X-13-209		\$ 51.00	\$	51.0

33 [HEADLAMP LHS		1	MGML8-51-041E	\$	7.00	-	3,369.80
C (S)	CORD SHORT, HEAD	LAMP	1	MGMG9-51-0K6			\$	211.40
-	CLIP, HEADLAMP		2	MFB01-50-133C			\$	8.00
-	RIVET, HEADLAMP		1	MB092-51-833	\$	3.50	\$	3.50
56.00	CAPACITOR, I- STOP		1	MG46L-67-ZC0A			_	4,122.50
	BLOCK, RELAY		1	MKD45-66-750			\$	49.80
39 40	BRACKET, RELAY		1	MKD45-67-B1XA			\$	15.40
41	HARNESS, FRONT		1	MG46G-67-010A	-		\$	5,706.50
-	,				-			C 105 90
				TOTAL PARTS	\$	5,445.00	_	1,610.58
				LESS 10%	\$	544.50	\$	1,610.58
				TOTAL PARTS COST	\$	4,900.50	\$	14,495.22
			Labour Descrip	otion				
1		O REPLACE FRONT BUMPER AND FRONT FENDER LH. TO REPAIR AREAS AFFECTED BY HE ACCIDENT.				1,320.00	\$	1,980.00
2	MZ-SP-SFRT01	O RESPRAY FRONT BUMPER, FRONT FENDER LH AND FRONT DOOR LH.					\$	2,520.00
3	MZ-BR-I-STOP	TO REPLACE I-STOP CAPACITOR.					\$	1,320.00
4	MZ-BR-HARNES	TO REMOVE & REPLACE THE WIRE HARNESS ASSY.					\$	1,320.00
5		TO SUPPLY 1 PC TIRE.	O SUPPLY 1 PC TIRE.				\$	450.00
6	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND COND	UCT WHEEL BALA	NCING.			\$	120.00
7	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY	& CONDUCT FULL	WHEEL ALIGNMENT.	\$	150.00	\$	560.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PR	ESERVATION.			\$ 50.0	0 \$	250.0
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM	FOR PROPER FUN	CTIONING.		\$ 120.0	0 5	250.0
1	0 MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$ 150.0	0 5	350.0
1	1 MZ-BR-SUNDR	SUNDRIES.		7			-	\$ 100.0
_				TOTAL LABOUR		\$ 3,365.0		\$ 9,220.
				TOTAL PARTS	_	\$ 4,900.	min =	\$ 14,495.
				TOTAL		\$ 8,265.		\$ 23,715.
				LESS EXCESS		\$ 1,500.	00	\$.
				TOTAL AFTER EXCESS		\$ 6,765.	-	10
				GST 7%		\$ 473.	-	\$
				GRAND TOTAL		\$ 7,239.	09	\$

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG19010838/USD3N2

Date:

30/07/2019

REFERENCE

Insured/Claimant: Date of Loss:

TAN KEONG JIN 17/06/2019

Policy No:

Nature of Claim:

B29083884QMY

OD

Claim No:

597025

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKV83P

Make & Model:

MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)

Engine No:

PY20579400

93523 km

Reg. Date:

23/06/2015 (Man. Year: 2015)

Chassis No: Odometer:

JM6GJ1032G0207989

Colour:

Brown

Engine Capacity: Market Value/New Car 2488 cc

Price:

S\$71,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

225/55R17

Rear Tyre Size:

225/55R17

Front Left Side: Front Right Side: Pirelli 6 mm Pirelli 6 mm Rear Left Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Item		Repairer's 15,045.22 0.00	Adjuster's 4,900.50 0.00	Difference 10,144.72 0.00	Diff % 67.43
Labour Paintwork Labour		8,670.00 0.00	3,365.00 0.00	5,305.00 0.00	61.19
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	23,715.22	8,265.50	15,449.72	65.15
	- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
	(S\$)	22,215.22	6,765.50	15,449.72	69.55
	+ GST 7.00/7.00% (S\$)	1,555.07	473.59	1,081.48	69.55
	Nett Amount (S\$)	23,770.29	7,239.09	16,531.20	69.55

INSPECTION

Date of Assignment:

19/06/2019

Date Inspected:

19/06/2019

Inspected At:

Trans Eurokars Pte Ltd (HQ)

5 Ubi Close

Singapore 408605

Estimated Period of Repair:

5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jul 2019)

Parts: 143 MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV83P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,211.90 FL	*1,211.90 FL
2	1		*RETAINER LHS	Cracked	14.70 FL	*14.70 FL
3	1		*MESH,FRONT BUMPER	Not Necessary	77.00 FL	*-FL
4	1		*FOAM, FRONT REINFORCEMENT	Not Necessary	77.00 FL	*-FL
5	2		*FASTENER,FOAM	Not Necessary	12.40 FL	*-FL
6	1		*CHROME LHS,FOGLAMP	Not Necessary	101.90 FL	*-FL
7	1		*COVER LHS,FOGLAMP	Not Necessary	22.70 FL	*-FL
8	1		*RETAINER SIDE, SENSOR	Not Necessary	18.20 FL	*-FL
9	1		*SENSOR SIDE,ULTRASONIC	Not Necessary	56.20 FL	*-FL
10	1		*TOWING COVER	Missing	33.40 FL	*33.40 FL
11	1		*RIVET,FRONT BUMPER	Necessary	3.00 FL	*3.00 FL
12	1		*RIVET,FRONT BUMPER	Necessary	3.00 FL	*3.00 FL
13	2		*GROMMET,FRONT BUMPER	Necessary	5.80 FL	*5.80 FL
14	6		*CLIP,FRONT BUMPER	Necessary	22.20 FL	*22.20 FL
15	6		*FASTENER,FRONT BUMPER	Necessary	19.20 FL	*19.20 FL
16	8		*RIVET,FRONT BUMPER	Necessary	32.00 FL	*32.00 FL
17	6		*RIVET,FRONT BUMPER	Necessary	29.40 FL	*29.40 FL
18	1		*BRACKET SIDE LHS,GRILLE TOP	Necessary	15.40 FL	*15.40 FL
19	1		*CHROME LHS	Not Necessary	144.60 FL	*-FL
20	1		*BRACKET LHS,CHROME	Not Necessary	37.20 FL	*-FL
21	1		*CLIP,BRACKET	Necessary	3.40 FL	*3.40 FL
22	1		*PROTECTOR LHS,CHROME	Scratched	52.70 FL	*52.70 FL
23	2		*CLIP,FRONT GRILLE	Necessary	9.40 FL	*9.40 FL
24	2		*RIVET,FRONT GRILLE	Necessary	16.00 FL	*16.00 FL
25	1		*RUBBER SEAL, FRONT GRILLE	Necessary	2.70 FL	*2.70 FL
26	2		*PIN LOCATOR,FRONT GRILLE	Necessary	5.80 FL	*5.80 FL
27	2		*GROMMET,FRONT GRILLE	Necessary	5.80 FL	*5.80 FL
28	1		*FRONT FENDER LHS	Dented/Buckled	383.70 FL	*383.70 FL
29	1		*STAY LHS,FENDER	Bent	48.30 FL	*48.30 FL
30	1		*MUDGUARD LHS	Torn	102.90 FL	*102.90 FL
31	17		*RIVET,MUDGUARD	Necessary	51.00 FL	*51.00 FL
32	1		*HEADLAMP LHS	Scratched	3,369.80 FL	*3,369.80 FL
33	1		*CORD SHORT,HEADLAMP	Not Necessary	211.40 FL	*-FL
34	2		*CLIP,HEADLAMP	Not Necessary	8.00 FL	*-FL
35	1		*RIVET,HEADLAMP	Necessary	3.50 FL	*3.50 FL
36	1		*CAPACITOR,I-STOP	Not Necessary	4,122.50 FL	*-FL
37	1		*BLOCK,RELAY	Not Necessary	49.80 FL	*- FL
38	1		*BRACKET,RELAY	Not Necessary	15.40 FL	*-FL
39	1		*HARNESS,FRONT	Not Necessary	5,706.50 FL	*-FL
40	1		*SUNDRIES	Not Necessary	100.00 FS	*-FS
41	1		*TIRE	Not Necessary	450.00 FS	*- FS
F=Fr	anchise	part. S=SpcN	lett. L=ListItemDisc.		Websers	27724-32
			- List Item Discount on L I	Sub Total (S\$) tems 10.00/10.00% (S\$)	16,655.80 1,610.58	5,445.00 544.50

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	15,045.22	4,900.50
			Report was ur	nsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Desembered	-41-	haur
Recommend	eu La	DOUL

rs	Lab.Type	Repairer's	Amount
ACE FRONT BUMPER AND FRONT FENDER EPAIR HEADLAMP PANEL LH ALL AREAS ED BY THE ACCIDENT	New	1,980.00	1,320.00
RAY FRONT BUMPER,HEADLAMP PANEL IT FENDER LH AND FRONT DOOR LH	New	2,520.00	1,575.00
ACE I-STOP CAPACITOR	New	1,320.00	0.00
OVE & REPLACE THE WIRE HARNESS ASSY	New	1,320.00	0.00
NT SPORT RIM AND CONDUCT WHEEL ING	New	120.00	0.00
CK STEERING GEOMETRY & CONDUCT FULL ALIGNMENT	New	560.00	150.00
RY-OUT BODY CAVITY PRESERVATION	New	250.00	50.00
CK ELECTRICAL SYSTEM FOR PROPER ONING	New	250.00	120.00
OGRAMME AFTER THE ACCIDENT REPAIR	New	350.00	150.00
Gross Lab	our Cost (S\$)	8,670.00	3,365.00
	5355125m195	Gross Labour Cost (S\$) Report was unsubmitted during this print-out.	5002.012 communication 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000

< END OF ESTIMATES >