

ASS. REC. BY:

REF: CS/SMD/9010841 / L2d3n4

Special Instruction:

Surveyor: Kenneth

## ASSIGNMENT (Office)

From (Person): Huang Shiang Yi of SMD

Date/Time: 19-6-19 9:32a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5492 U

Insured: SLG 9095 M

at Workshop n/s Trans-Cab

Tel: 621 30 998

of 2 AMK Street 63

Policy No: DIBMIRENT000819

Claim No: CMTD1902919

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 19.6.19 11:00a.m.

Person Contacted: Zh. Wei

Vehicle (IN) / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 5492 U - (C4) Ax A 160/9193 / KY1742 DOA - 10/11/2015
	SLG 9095 M - X
20/6/19 @ 2:38pm	revised to Huang Shiang Yi via Weimer.

Kennerth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: Tans Cob  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SHC 5492U Yr Regn: 07 14  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or \_\_\_\_\_  
 Make: Renault Latitude c.c. 1995  
 Colour: M. White / Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 278 295 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VFIABL15AUC 278814  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inop / Jammed / Leaked / Burnt or  
 Brake: Inop / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rlm / STD A/Rlm or  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or GTti

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 03 days Res.: Yes or No  
 Lum Sum: 20% 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front 7 mm R/Bal. 6 mm  
 L/Bal. 7 mm L/Bal. 6 mm  
 D.O.A. 15/6/19 D.O.I. 19/6/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
O/S Rear body  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>
	<u>6/1 Pym 83150 (Red to 42971.46, 53%)</u>

RECEIVED 20 JUN 2019

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time, File Return to?

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech Invs (\$ )  
 : Weekend (\$ )

Survey Fee:

Transportation:	<u>450</u>
S - RS. St	<u>11</u>
Other	
TOTAL	<u>461</u>

Report Format: MEP-9A  
 Lump Sum / I.B.I. (\$) 3150

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 20 Jun 2019

**Preliminary Advice**

Insured Vehicle No	: SLG9095M	Accident Date	: 15/06/2019
TP Vehicle No	: SHC5492U	Assignment Date	: 19/06/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 3.00
Date of Inspection	: 19/06/2019		
Inspection At	: TRANS-CAB SERVICES PTE LTD (HQ) 2 ANG MO KIO STREET 63 SINGAPORE 569111		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s rear body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,141.46
Revised Amount	:S\$	3,925.19
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,925.19
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2019		19 Jun 2019 09:38 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>SAN'S TOURS &amp; CAR RENTALS</b> , Co. Reg. No.: 08516300K								
Main Claimant:	<b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	<b>SHC5492U</b>	Date of Loss:	15/06/2019 14:00 - 59						
Claim Type:	<b>TP / CMTD1902919</b>	Policy/Cover Note No.:	D18MTRENT000819 (Third Party Only)						
Vehicle Reg. No. (Insured):	<b>SLG9095M</b>	Policy No. (Claimant):							
Repairer:	<b>Trans-Cab Services Pte Ltd (HQ)</b> 2 Ang Mo Kio Street 63, S69111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Hwang Shiang Yi</b> - 6329 5205]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 28/06/2019]								
Adj. Asp. Remarks:	WS: ZHEWEI 62130998 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a>   <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Thursday, 20 June 2019 3:19 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: TP VEHICLE SHB 7652S (DOA: 16/06/2019)--AAD1906-143 & SHC 5492U (DOA: 15/06/2019)--AAD1906-142  
**Attachments:** image001.wmz

Hi Shiau Chan

1. SHB7652S amount confirm \$714.45 (b4 GST)
2. SHC5492U amount confirm \$3,150 (b4 GST)

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAuto) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Thursday, 20 June, 2019 2:34 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHB 7652S (DOA: 16/06/2019) & SHC 5492U (DOA: 15/06/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation of repair cost of above vehicles are as below:

1. SHB 7652S at final fig \$714.45 before GST and 1 repair day
2. SHC 5492U at Lump Sum \$3,150.00 before GST and 3 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/06/2019 09:06
Date Of Accident	15/06/2019 14:05
Exact Location Of Accident	TANGLIN ROAD TOWARDS ORCHARD ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5492U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	SEE HUA TONG
NRIC No	S1216021F
Date Of Birth	08/12/1956
Occupation	OUTDOOR
Date Of Driving Pass	02/07/1976
Driving Experience	42 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96517157
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 157C RIVERVALE CRESCENT #08-635
Postcode	543157
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20190616/2017

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG9095M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JAE YONG CHOI
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name SEE HUA TONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5492U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Refer to attached sketch plan.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20190616/3017

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

*Daniel Lee*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


*Zhou*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Map of Accident

DAE: 15 JUNE 19.

PLACE: TANGLIN RD.

Time: 1405 hrs.



A-SHC-5492-U  
B-SLG-9095-M

Jae Lam Choi  
+80 4088910833

Others are  
subordinates





Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

CONTINUATION OF REPORT

**Brief Details.**

On 15/06/2019 at about 1400hrs, I was driving my Transcab taxi bearing registration number SHC5492U along Tanglin Rd towards Orchard Rd on the 3rd lane of a 4-lane Rd and nothing was amiss. There was a male passenger in my vehicle at that point of time.

60 HOUGANG AVE 9  
SINGAPORE 538775  
TEL: 1800-4890999

On the same day at about 1405hrs, there was a Toyota vehicle bearing registration number SLG9095M that was moving on the 2nd lane and wanted to change into the 3rd lane abruptly. As I was unable to swerve my vehicle away, the said vehicle then got collided onto my right side portion of vehicle.

Thus I then went down to make a check. There was several scratches and dents on my right side passenger and driver's door. The driver of the said vehicle was one namely Jae Youn Choi (HP: +804088480833). Both of the driver then agreed to pursue insurance claims. My passenger at that instance left from scene as he was in a rush. I was unable to ascertain my passenger details and was unsure on his conditions. No one was injured.

There was no police or ambulance attended. There is an in-built CCTV installed in my vehicle but was not operating.

On 16/06/2019, I have sought further medical assistance as I felt pain on my shoulder and neck. I was given 5-days medical leave.

As such I am making this report for Traffic Police assistance.




Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sgt 3 ASHLEY TOH	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 16/06/2019 10:21
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168 Singapore Police Force	

**Trans-cab Auto Services Pte Ltd**

AAD1906-142

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5492U***Not Authorized  
L1 Sing @ 31501**19/6/19*

Vehicle No.:	<b>SHC 5492U</b>
Chassis No.:	VF1ABL15AUC278814
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	15.6.19
Third Party Insurer :	<b>SOMPO</b>
Date of Registration:	11/7/2014

	<b>PART</b>		<b>LIST</b>	
1	DOOR PANEL REAR RH	\$	<i>Del/way</i> 2,844.66	✓
1	DOOR GUIDE REAR RH	\$	<i>Pr</i> 176.82	} X
1	DOOR HINGE UPPER RH	\$	<i>Pr</i> 274.50	
1	DOOR HINGE LOWER RH	\$	<i>Pr</i> 300.55	
1	DOOR CHECK REAR RH	\$	<i>Pr</i> 203.06	
1	DOOR LOCK REAR RH	\$	<i>Pr</i> 908.75	
1	DOOR HANDLE OUTER REAR RH	\$	<i>Pr</i> 126.49	
1	DOOR HANDLE CAP REAR RH	\$	<i>Pr</i> 35.52	
1	DOOR HANDLE SEAL REAR RH	\$	<i>Pr</i> 7.89	
1	DOOR HANDLE COVER REAR RH	\$	<i>Pr</i> 13.22	
1	DOOR HANDLE MODULE REAR RH	\$	<i>Pr</i> 133.60	
1	DOOR REGULATOR REAR RH	\$	<i>Pr</i> 1,135.10	
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>Pr</i> 893.75	
1	DOOR REGULATOR NUT REAR RH	\$	<i>Pr</i> 12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Pr</i> 6.31	
1	DOOR FINISHER REAR RH	\$	<i>Pr</i> 423.10	
1	DOOR MOULDING REAR RH	\$	<i>Pr</i> 176.82	
1	DOOR MOULDING CLIP L70Y	\$	<i>Pr</i> 5.92	
1	DOOR MOULDING SCREW L70Y	\$	<i>Pr</i> 6.91	
1	DOOR CASING REAR RH	\$	<i>Pr</i> 1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	<i>Pr</i> 30.39	
1	DOOR CASING CLIP	\$	<i>Pr</i> 12.63	
1	DOOR CASING LIGHT L70Y	\$	<i>Pr</i> 48.74	
1	DOOR FINISHER INNER REAR RH	\$	<i>Pr</i> 323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Pr</i> 46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Pr</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Pr</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Pr</i> 20.33	
1	DOOR GRAB HANDLE REAR RH	\$	<i>Pr</i> 210.96	
1	DOOR BLIND REAR RH	\$	<i>Pr</i> 741.80	

**Trans-cab Auto Services Pte Ltd**

AAD1906-142

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5492U**

1	DOOR WHEATHESTRIIP REAR RH	\$	Sn	410.66
1	DOOR SEAL REAR RH	\$	Sn	162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Sn	229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	Sn	334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	Sn	115.64
1	ROCKER PANEL INNER GARNISH RH	\$	Sn	466.51
1	ROCKER PANEL INNER RH	\$	R	1,024.79
1	ROCKER PANEL OUTER RH	\$	R	1,184.99
1	ROCKER PANEL CENTER RH	\$	R	990.25
1	BOOT REAR	\$	R	2,872.68
1	BOOT REFLECTOR LAMP RH	\$	Sn	493.35
1	FENDER PANEL REAR RH	\$	R	3,299.13
1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45
1	WHEELARCH REAR RH	\$	Sn	543.47
1	BUMPER COVER REAR	\$	R	1,108.46
1	BUMPER LOWER REAR	\$	Sn	768.84
1	BUMPER BRACKET CTR REAR	\$	Sn	113.47
1	BUMPER BRACKET SIDE RH REAR	\$	Sn	135.97
1	BUMPER RETAINER RH REAR	\$	Sn	44.99
1	BUMPER REFLECTOR RH	\$	Sn	43.61
1	BUMPER BEAM REAR	\$	R	777.52
1	BUMPER BEAM BRACKET RH REAR	\$	R	225.95
1	TAILLAMP RH	\$	Sn	552.55
1	TAILLAMP PANEL RH	\$	R	986.70
1	DOOR PANEL FRONT RH	\$	R	2,844.66

} X

<b>TOTAL</b>	<b>\$</b>	<b>31,072.03</b>
<b>10%</b>	<b>\$</b>	<b>3,107.20</b>
	<b>\$</b>	<b>27,964.83</b>

**Special Nett**

1	REAR DOOR STICKER '6555-3333'	\$	na	80.00	6555
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	6555
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	1555
1	FENDER INNER TRIM CLIP RH	\$	na	28.00	X
1	TAILLAMP CLIP RH	\$	na	5.00	X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
2	REAR WINDSCREEN SEALANT	\$	na	80.00	X
1	WINDSCREEN MOULDING	\$	na	100.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1906-142**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5492U**

1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	}
1	REAR RIGHT TYRE	\$	su	300.00	
1	REAR RIGHT TYRE RIM	\$	su	380.00	
1SET	PARKING AID	\$	su	700.00	
1SET	REAR BUMPER CLIP	\$	na	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	
1SET	BUMPER RETAINER CLIP RH RR	\$	na	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
<b>TOTAL</b>		<b>\$</b>		<b>2,286.63</b>	
<b>TOTAL PARTS</b>		<b>\$</b>		<b>30,251.46</b>	

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	400
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	na	380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na	170.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1906-142

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5492U

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X
Putty and spray painting of the affected portion.	\$		6,000.00	<i>664</i>
To rust-proofing of the affected areas.	\$		170.00	<i>34</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i>	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>24</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$		380.00	<i>64</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i>	170.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	<i>4</i>	380.00	X
To transfer of bootlid fittings, attachment and perform water seepage test.	\$	<i>4</i>	380.00	X
<b>TOTAL</b>	<b>\$</b>		<b>15,890.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>46,141.46</b>	

**LUMP SUM (REPAIR DAY)***20 DAYS  
3 days*

<p>Must also consistently hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To remove materials for spray painting</li> <li>• To display damaged parts during recovery</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party access is on a "Without Prejudice" basis</li> <li>• No single endorsement is allowed</li> <li>• Supplementary charges must be recovered and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer: Signature: Date:</p>
---

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19010841/KQD3N2

Date: 21/06/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte Ltd.	Policy No:	D18MTRENT000819
Claimant Vehicle No :	SHC5492U	Insured Vehicle No :	SLG9095M
Date of Loss:	15/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1902919

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC5492U	Engine No:	M9R8839C001892
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC278814
Reg. Date:	11/07/2014 (Man. Year: 2014)	Odometer:	278295 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	30,251.45	2,695.19	27,556.26	91.09	
Miscellaneous Items	0.00	0.00	0.00		
Labour	15,890.00	1,230.00	14,660.00	92.26	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>46,141.45</b>	<b>3,925.19</b>	<b>42,216.26</b>	<b>91.49</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,150.00</b>			
	(S\$)	46,141.45	3,150.00	42,991.45	93.17
<b>+ GST 7.00/7.00% (S\$)</b>	3,229.90	220.50	3,009.40	93.17	
<b>Nett Amount (S\$)</b>	<b>49,371.35</b>	<b>3,370.50</b>	<b>46,000.85</b>	<b>93.17</b>	

## INSPECTION

Date of Assignment:	19/06/2019	Inspected At:	Trans-Cab Services Pte Ltd (HQ)
Date Inspected:	19/06/2019		2 Ang Mo Kio Street 63
			Singapore 569111
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC5492U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*DOOR PANEL REAR RH	Dented / Warped	2,844.66 FL	*2,844.66 FL
2	1	*DOOR GUIDE REAR RH	Serviceable	176.82 FL	*- FL
3	1	*DOOR HINGE UPPER RH	Repair	274.50 FL	*- FL
4	1	*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
5	1	*DOOR CHECK REAR RH	Serviceable	203.06 FL	*- FL
6	1	*DOOR LOCK REAR RH	Repair	908.75 FL	*- FL
7	1	*DOOR HANDLE OUTER REAR RH	Serviceable	126.49 FL	*- FL
8	1	*DOOR HANDLE CAP REAR RH	Serviceable	35.52 FL	*- FL
9	1	*DOOR HANDLE SEAL REAR RH	Serviceable	7.89 FL	*- FL
10	1	*DOOR HANDLE COVER REAR RH	Serviceable	13.22 FL	*- FL
11	1	*DOOR HANDLE MODULE REAR RH	Serviceable	133.60 FL	*- FL
12	1	*DOOR REGULATOR REAR RH	Serviceable	1,135.10 FL	*- FL
13	1	*DOOR REGULATOR MOTOR REAR RH	Serviceable	893.75 FL	*- FL
14	1	*DOOR REGULATOR NUT REAR RH	Serviceable	12.43 FL	*- FL
15	1	*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*- FL
16	1	*DOOR FINISHER REAR RH	Serviceable	423.10 FL	*- FL
17	1	*DOOR MOULDING REAR RH	Serviceable	176.82 FL	*- FL
18	1	*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
19	1	*DOOR MOULDING SCREW L70Y	Not Necessary	6.91 FL	*- FL
20	1	*DOOR CASING REAR RH	Serviceable	1,509.06 FL	*- FL
21	1	*DOOR WATER SHIELD REAR RH	Serviceable	30.39 FL	*- FL
22	1	*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
23	1	*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
24	1	*DOOR FINISHER INNER REAR RH	Serviceable	323.44 FL	*- FL
25	1	*DOOR FINISHER BRACKET INNER REAR RH	Repair	46.97 FL	*- FL
26	1	*DOOR FINISHER BRACKET INNER REAR RH	Repair	20.33 FL	*- FL
27	1	*DOOR FINISHER BRACKET INNER REAR RH	Repair	20.33 FL	*- FL
28	1	*DOOR FINISHER BRACKET INNER REAR RH	Repair	20.33 FL	*- FL
29	1	*DOOR GRAB HANDLE REAR RH	Serviceable	210.96 FL	*- FL
30	1	*DOOR BLIND REAR RH	Serviceable	741.80 FL	*- FL
31	1	*DOOR WEATHESTRIIP REAR RH	Serviceable	410.66 FL	*- FL
32	1	*DOOR SEAL REAR RH	Serviceable	162.02 FL	*- FL
33	1	*DOOR GLASS RUNNER SEAL REAR RH	Serviceable	229.31 FL	*- FL
34	1	*DOOR WAIST SEAL OUTER REAR RH	Serviceable	334.69 FL	*- FL
35	1	*DOOR WAIST SEAL INNER REAR RH	Serviceable	115.64 FL	*- FL
36	1	*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
37	1	*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
38	1	*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
39	1	*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
40	1	*BOOT REAR	Repair	2,872.68 FL	*- FL
41	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
42	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
43	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
44	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*-FL
46	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*-FL
47	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*-FL
48	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*-FL
49	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*-FL
50	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*-FL
51	1		*BUMPER BEAM REAR	Repair	777.52 FL	*-FL
52	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*-FL
53	1		*TAILLAMP RH	Serviceable	552.55 FL	*-FL
54	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*-FL
55	1		*DOOR PANEL FRONT RH	Repair	2,844.66 FL	*-FL
56	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS
57	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
58	1		*FRONT DOOR STICKER CLASSIS	Necessary	80.00 FS	*15.00 FS
59	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*-FS
60	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
61	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*-FS
62	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
63	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
64	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
65	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*-FS
66	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*-FS
67	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
68	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*-FS
69	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*-FS
70	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
71	1		*SET BUMPER RETAINER CLIP RH RR	Not Necessary	20.00 FS	*-FS
72	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
73	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*-FS
74	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*-FS
75	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*-FS
76	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*-FS
77	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*-FS
78	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*-FS
79	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*-FS
80	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*-FS
81	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	<b>Sub Total (\$)</b>	<b>33,358.65</b>	<b>2,979.66</b>
	<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	<b>3,107.20</b>	<b>284.47</b>
	<b>Total Parts (\$)</b>	<b>30,251.45</b>	<b>2,695.19</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	6,000.00	400.00
2	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	60.00
4	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
5	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	660.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	30.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
10	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
12	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	0.00
14	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
15	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>15,890.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >