



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. BICYCLE

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SET CAMPAGNOLO SUPER RECORD 11 GROUP	BENT	4,500.00	4,500.00
1	SAN MARCO A SPIDE 2 CARBON FX (WIDE) (SEAT)	CRUSHED	299.00	299.00
1	2016 SPECIALIZE TARMAC (FRAME)	BROKEN	5,200.00	5,200.00
1	SET FULCRUM RACING ZERO NITE H G 11S (RIM)	BENT	1,600.00	1,600.00
1	2015 CAMPAGNOLO SUPER RECORD CRANKSET H, 170MM, 52/36T	NOT NECESSARY	1,000.00	-
1	SET CAMPAGNOLO INTEGRATED BB CUPS, BB30, 68X42	NOT NECESSARY	68.00	-
1	SET CAMPAGNOLO CABLE BRAKE / SHIFT CABLES / HOUSINGS	NOT NECESSARY	85.00	-
2	VITTORIA TYRE OPERA CORSA CX 700 X 25C, BLACK @ \$75.00	NOT NECESSARY	150.00	-
1	3T AERONOVA TEAM 31.8 X 44	NOT NECESSARY	365.00	-
2	KENDA INNER TUBE, 700 X 23 / 25, PRESTA 48L @ \$10.00	NOT NECESSARY	20.00	-
1	SUPACAZ BARTAPE, STICKY KUSH, RED PAINT	NOT NECESSARY	40.00	-
			13,327.00	11,599.00
<b>GRAND TOTAL</b>			<b>13,327.00</b>	<b>11,599.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>9,000.00</b>

Report Ref No. CS1/FC119010848/Esd3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.