

INS. CASE OWNER:

Wongshin | CC 3, MG 190 10814, Jda3 9

LKK:
IDAC:

Surveyor:

OHJ

DOI:

ASSIGNMENT

18/6/19

Date / Time:

18/6/19

Registered in Merimen:

19/6/19

Pre-assign / CCU / FTE

SMD 689M



Insured Vehicle No. :

Claim No. :

Name of Insured :

Jonathan Michelangelo Hoon.

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A:

15/6/19

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L YES / NO)

Insured Liability :

%

Final ? Yes / No

SHF 138K



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMD 689M



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 3/9/19

Confirm with

Tan Lee Goh

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

SS 3700.00

Loss of Rental (LOR):

SS 838.88

(

7 days)

x \$119.84

Loss of Use (LOU):

SS -

(

5 x

days)

Loss of Income (LOI):

SS 350.00

(

50 x

7 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ (Tick only one)

GIA/LTA Search

SS 7.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

3320

Total:

SS 4895.88

Global Sum SS: 4800.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 4800.00

Payee 2:

Smeat Taxi Pte Ltd

Payee 3 (Strike If N/A):

SS

Payee 4:

Payee 5 (Strike If N/A):

SS

Payee 6:

427 579

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF138k Yr Regn: 13 Jun 2012Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Ssangyong c.c. 2696Colour: white A/C: Insured / Std / NI / NASp. Reading: 615210 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPTV0BIF5CLP066700Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / SRM / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/6/19 D.O.I. 18/6/19Survey held at SmartDes. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

06/19/2017

SMO689m

L/S - \$3700 (Red \$ 6150 / 621)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation:

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Jin Le

Section A - Accident Details

Registration Number	SHF138K
Case Reference Number	TAX/06/19/2057
Registration Date	13/6/2012
Company Type	SMRT Taxis Pte Ltd
Make	SSANGYONG
Model	RODIUS-SV270
Name of Driver	GOH SWEE CHOON
Type of Accident	Head to Rear
Accident Date and Time	15/6/2019 2:40 PM
Accident Reported Date and Time	17/6/2019 8:35 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101997
Special instruction to ARC, if any	REAR PORTION
Prepared Date and Time	17/6/2019 4:23 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$500.00
Total Spray Cost	\$1,959.00	\$500.00
Total Spare Part Cost	\$5,487.45	\$2,475.01
Total Other Cost	\$1,140.00	\$220.00
TOTAL COST	\$9,850.46	\$3,695.01
Lump Sum Total	\$9,850.00	\$3,700.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	18/06/2019 2:18 PM	18/06/2019 1:44 PM
Signature		
Remarks	L/S REPAIR, PHOTO AFTER REPAIR.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0108	Invoice Number	
Quotation Date	08.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$250.00	\$100.00
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
Total Labour	\$1,264.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$473.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$473.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$473.00	\$0.00
Total Spray Painting & Panel Beating	\$1,959.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$100.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,140.00	\$220.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		78521210 00	ABSORBER ENERGY RR BUMPER	0.00	\$111.73	0.00	\$0.00	Replace	Check
		78530210 00	BEAM ASSY-IMPACT RR BUMPER	0.00	\$513.97	0.00	\$0.00	Replace	Check
		64011210 00	REAR TAILGATE ASSY	1.00	\$1,355.08	10.00	\$1,219.57	Replace	Replace
			REAR NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given
			REAR NUMBER PLATE FRAME	0.00	\$35.00	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
85 Woodlands Industrial Park E4, Singapore 757105
Fax Number: 63910002
Estimator Telephone Number: 68632025
Accident Reporting Number: 68632012

Date Generated: 08/08/2018

User ID: Pchuan

	71410210 00	LATCH ASSY, T/GATE	0.00	\$59.98	0.00	\$0.00	Replace	Not Given	X	NN	
	83790210 01	LAMP ASSY-LICENSE PLATE	0.00	\$49.25	0.00	\$0.00	Replace	Not Given	X		NN
	71415210 00	STRIKER ASSY, T/GATE	0.00	\$9.89	0.00	\$0.00	Replace	Not Given	X		
	71450210 01	WEATHER STRIP T/GATE OPENING	1.00	\$87.87	10.00	\$87.90	Replace	Replace	X	NN	
	86174030 93	Handle assy-T/gate O/S	0.00	\$14.16	0.00	\$0.00	Replace	Not Given	X		NN
	73810210 02ABU	Trim assy-T/gate lwr	0.00	\$159.92	0.00	\$0.00	Replace	Not Given	X		
	79630210 02	Garnish assy-T/gate ctr	0.00	\$300.19	0.00	\$0.00	Replace	Not Given	X	NN	
	88370211 00	ACTUATOR ASSY, DR LOCK T/GATE	0.00	\$74.55	0.00	\$0.00	Replace	Not Given	X		NN
	83601212 01	COMBI LAMP ASYSRR T/GATE LH	0.00	\$288.57	0.00	\$0.00	Replace	Not Given	X		
	83602212 01	COMBI LAMP ASYSRR T/GATE RH	0.00	\$288.57	0.00	\$0.00	Replace	Not Given	X	NN	
		EMBLEM REAR	1.00	\$46.94	10.00	\$44.05	Replace	Replace	X		NN
	7881A21 000	Rear Bumper Assy	1.00	\$925.27	10.00	\$832.74	Replace	Replace	X		
		REAR BUMPER CLIP	6.00	\$4.25	10.00	\$22.95	Replace	Replace	X	NN	
	83901211 00	LAMP ASSY, REFLEX REFLECTOR LH	0.00	\$10.52	0.00	\$0.00	Replace	Check	X		NN
	83902211 00	LAMP ASSY, REFLEX REFLECTOR RH	0.00	\$10.52	0.00	\$0.00	Replace	Check	X		
		REVERSE SENSOR	1.00	\$165.10	10.00	\$148.59	Replace	Replace	X	NN	
	78821210 00	ABSORBER ENERGY RR BUMPER	0.00	\$111.73	0.00	\$0.00	Replace	Not Given	X		NN
		EMBLEM RODUIS	1.00	\$32.08	10.00	\$28.87	Replace	Replace	X		
		EMBLEM RV270	1.00	\$20.00	10.00	\$18.00	Replace	Replace	X	NN	
		EMBLEM SSANYONG	1.00	\$34.56	10.00	\$31.10	Replace	Replace	X		NN
		STICKER PRESTIGE	1.00	\$60.00	0.00	\$60.00	Replace	Replace	X		
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X	NN	
	79340210 01	RUBBERSEAL GLASS RR QTR	2.00	\$11.04	10.00	\$19.87	Replace	Replace	X		NN
		SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace	X		
		PANEL END INNER	0.00	\$239.33	0.00	\$0.00	Replace	Not Given	X	NN	
		PANEL END OUTER	0.00	\$105.74	0.00	\$0.00	Replace	Check	X		NN
		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	X		
	77460210 01ABU	TRIM ASSY, RR TRANSVERSE	0.00	\$32.95	0.00	\$0.00	Replace	Check	X	NN	
	83601213 01	COMBI LAMP ASSYRR QTR LH	0.00	\$288.57	0.00	\$0.00	Replace	Not Given	X		NN
	52511210 60	REAR FENDER LH	0.00	\$1,300.95	0.00	\$0.00	Replace	Not Given	X		
		STICKER PRESTIGE	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X	NN	
Total				\$6,956.88		\$2,632.44					

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		78830210 00	BEAM ASSY-IMPACT RR BUMPER	1.00	\$513.97	10.00	\$462.57	Replace	Replace
Total					\$13.97		462.57		



Case Details

Case Reference Number : TAX/06/19/2057
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF138K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7340-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 15/06/2019 06:40 AM
 Vehicle Age(In Months) : 84

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Parts Cost Detail

SMRT Recommendation												Surveyor Approval		
RCM Type	Coating Type	Partion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ABSORBER ENERGY RR BUMPER	1	111.72	111.72	10.00	100.55	Replace	0	0	Check	X / M1
One Time Key In	Main			BEAM ASSY- IMPACT RR BUMPER	1	512.97	512.97	10.00	461.67	Replace	0	0	Check	X / M1
One Time Key In	Main			REAR TAILGATE ASSY	1	1,353.08	1,353.08	10.00	1,217.57	Replace	1	1,219.57	Replace	/ DD
One Time Key In	Main			REAR NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	} ~ X
One Time Key In	Main			REAR NUMBER PLATE FRAME	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	
One Time Key In	Main			LATCH ASSY- T/GATE	1	55.98	55.98	10.00	50.38	Replace	0	0	Not Give	
One Time Key In	Main			LAMP ASSY- LICENSE PLATE	2	49.25	98.50	10.00	88.65	Replace	0	0	Not Give	
One Time Key In	Main			STRIKER ASSY- T/GATE	1	9.89	9.89	10.00	8.90	Replace	0	0	Not Give	
One Time Key In	Main			WEATHER STRIP T/GATE OPENING	1	97.87	97.87	10.00	88.08	Replace	1	87.80	Replace	/ TAI
One Time Key In	Main			Handle assy- T/gate ORS	1	14.16	14.16	10.00	12.74	Replace	0	0	Not Give	X ~

Total Spare Part Cost 5,398.75

Surveyor Total 2,632.44

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 30

Final Spare Part Cost 5,117.40

Final Sur Total 2,105.36

SMRT Recommendation											Surveyor Approval		
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			Trim assy-Tigate lwr	1	199.92	199.92	10.00	179.93	Replace	0	0	Not Give *
One Time Key In	Main			Garnish assy-Tigate ctr	1	300.19	300.19	10.00	270.17	Replace	0	0	Not Give *
One Time Key In	Main			ACTUATOR ASSY, OR LOCK TIGATE	1	74.55	74.55	10.00	67.09	Replace	0	0	Not Give *
One Time Key In	Main			COMB LAMP ASSY RH TIGATE LH	1	258.57	258.57	10.00	232.71	Replace	0	0	Not Give *
One Time Key In	Main			COMB LAMP ASSY RH TIGATE RH	1	258.57	258.57	10.00	232.71	Replace	0	0	Not Give *
One Time Key In	Main			EMBLEM REAR	1	44.94	44.94	10.00	40.45	Replace	1	44.95	Replace * / nec
One Time Key In	Main			Rear Bumper Assy	1	825.27	825.27	10.00	742.74	Replace	1	822.74	Replace * / DEF
One Time Key In	Main			REAR BUMPER CLIP	6	4.35	26.10	10.00	23.49	Replace	6	22.95	Replace * / nec
One Time Key In	Main			LAMP ASSY, REFLEX REFLECTOR LH	1	10.52	10.52	10.00	9.47	Replace	0	0	Check * X N/A
One Time Key In	Main			LAMP ASSY, REFLEX REFLECTOR RH	1	10.52	10.52	10.00	9.47	Replace	0	0	Check * X N/A
One Time Key In	Main			REVERSE SENSOR	1	145.10	145.10	10.00	130.59	Replace	1	145.59	Replace * / Shorted
One Time Key In	Main			ABSORBER ENERGY RH BUMPER	1	111.73	111.73	10.00	100.56	Replace	0	0	Not Give * X 4m
One Time Key In	Main			EMBLEM RODING	1	22.98	22.98	10.00	20.68	Replace	1	22.97	Replace * / nec
One Time Key In	Main			EMBLEM RV270	1	20.00	20.00	10.00	18.00	Replace	1	18.00	Replace * / nec
One Time Key In	Main			EMBLEM SSANYONG	1	34.96	34.96	10.00	31.46	Replace	1	31.10	Replace * / nec
One Time Key In	Main			STICKER PRESTIGE	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace * / nec

Total Spare Part Cost 6,396.75

Surveyor Total 2,632.44

Lump Sum Discount (%) 25.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,117.40

Final Sur Total 2,105.95

SMRT Recommendation													Surveyor Approval	
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	• / nec
One Time Key In	Main			RUBBERSEAL GLASS RR QTR	2	11.04	22.08	10.00	19.87	Replace	2	19.87	Replace	• / nec
One Time Key In	Main			SEALANT WISCREEN	2	37.00	74.00	0.00	74.00	Replace	2	74.00	Replace	• / nec
One Time Key In	Main			PANEL END INNER	1	238.33	238.33	10.00	214.40	Replace	0	0	Not Give	• X hu
One Time Key In	Main			PANEL END OUTER	1	105.74	105.74	10.00	95.17	Replace	0	0	Check	• X NAI
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	• 3 / NK
One Time Key In	Main			TRIM ASSY, RR TRANSVERSE	1	32.86	32.86	10.00	29.56	Replace	0	0	Check	• X NAI
One Time Key In	Main			COMBI LAMP ASSYRR QTR LH	1	288.57	288.57	10.00	259.71	Replace	0	0	Not Give	• X hu
One Time Key In	Main			REAR FENDER LH	1	1,200.86	1,200.86	10.00	1,079.86	Replace	0	0	Not Give	• X hu
One Time Key In	Main			STICKER PRESTIGE	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	• X hu

Total Spare Part Cost 6,396.75

Surveyor Total 2,632.44

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,117.40

Final Sur Total 2,105.96

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	473.00	200	
Total:			1,779.00	400.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	473.00	200	
4	Main	TO RESPRAY REAR PANEL	180.00	0	
5	Main	TO RESPRAY REAR FENDER LH	473.00	0	
Total:			1,779.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	APC
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	APC
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	APC
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	125.00	30	APC
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	
6	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	125.00	0	
7	Main	TO REMOVE AND REFIT WIRE HARNESS	300.00	0	
8	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	100	APC
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,140.00	220.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,117.40	2,106.95
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,779.00	400.00
Other	1,140.00	220.00
Overall Total	9,050.40	3,126.95
Lump Sum Repair Option		

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Total	9,090.00	3,150.00
Surveyor Approved Amount		3,150.00
No of Repair Days	7	4
Remarks		L/S REPAIR, PHOTO AFTER REPAIR
Surveyor Name		Hwee Jie
Signature		
Survey Date	18/06/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To deduct damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	704/06/19/2057	Date of Collection	19/6/19
Vehicle No	S4F 138K	Date of Request	20/6/19
Vehicle Model	SSANG YONG	Number of Days to Extend (If any)	13 DAYS

S/N	Part Number	Part Description	Quantity	Unit Price
	3224,25,26,27	Beam Assy Impact RL Bumper		\$513.97
	3253,54,55,56	To Repair Panel End Outer		\$250.00
	57	To Repair Panel End Outer		\$180.00

DD \$46257
\$100
\$100

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA
(Position) _____

I do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.
 Signature of person making this declaration
 [To be signed in front of an authorised witness]
 I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff		
Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



Case Details

Case Reference Number : TAX/06/19/2057
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF13BK

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7340-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 15/06/2019 08:40 AM
 Vehicle Age(In Months) : 84

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BDM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			ABSORBER ENERGY RR BUMPER	1	111.73	111.73	10.00	100.56	Replace	0	0	Check	*
One Time Key In	Main			BEAM ASSY- IMPACT RR BUMPER	1	513.97	513.97	10.00	462.57	Replace	0	0	Check	*
One Time Key In	Main			REAR TAILGATE ASSY	1	1,355.08	1,355.08	10.00	1,219.57	Replace	1	1,219.57	Replace	*
One Time Key In	Main			REAR NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	*
One Time Key In	Main			REAR NUMBER PLATE FRAME	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	*
One Time Key In	Main			LATCH ASSY. T/GATE	1	59.98	59.98	10.00	53.98	Replace	0	0	Not Give	*
One Time Key In	Main			LAMP ASSY- LICENSE PLATE	2	49.25	98.50	10.00	88.65	Replace	0	0	Not Give	*
One Time Key In	Main			STRIKER ASSY. T/GATE	1	9.89	9.89	10.00	8.90	Replace	0	0	Not Give	*
One Time Key In	Main			WEATHER STRIP T/GATE OPENING	1	87.67	87.67	10.00	87.90	Replace	1	87.90	Replace	*
One Time Key In	Main			Handle assy- T/gate O/S	1	14.16	14.16	10.00	12.74	Replace	0	0	Not Give	*

Total Spare Part Cost 6,396.75

Surveyor Total 2,532.44

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,117.40

Final Sur Total 2,105.95

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			Trim assy- T/gate lwr	1	199.92	199.92	10.00	179.93	Replace	0	0	Not Give *	} hy
One Time Key In	Main			Garnish assy- T/gate ctr	1	300.19	300.19	10.00	270.17	Replace	0	0	Not Give *	
One Time Key In	Main			ACTUATOR ASSY, DR LOCK T/GATE	1	74.55	74.55	10.00	67.09	Replace	0	0	Not Give *	
One Time Key In	Main			COMBI LAMP ASYSRR T/GATE LH	1	288.57	288.57	10.00	259.71	Replace	0	0	Not Give *	
One Time Key In	Main			COMBI LAMP ASYSRR T/GATE RH	1	288.57	288.57	10.00	259.71	Replace	0	0	Not Give *	
One Time Key In	Main			EMBLEM REAR	1	48.94	48.94	10.00	44.05	Replace	1	44.05	Replace *	nec
One Time Key In	Main			Rear Bumper Assy	1	925.27	925.27	10.00	832.74	Replace	1	832.74	Replace *	DEF
One Time Key In	Main			REAR BUMPER CLIP	6	4.25	25.50	10.00	22.95	Replace	6	22.95	Replace *	nec
One Time Key In	Main			LAMP ASSY, REFLEX REFLECTOR LH	1	10.52	10.52	10.00	9.47	Replace	0	0	Check *	
One Time Key In	Main			LAMP ASSY, REFLEX REFLECTOR RH	1	10.52	10.52	10.00	9.47	Replace	0	0	Check *	
One Time Key In	Main			REVERSE SENSOR	1	145.10	145.10	10.00	148.59	Replace	1	148.59	Replace *	Shorted
One Time Key In	Main			ABSORBER ENERGY RR BUMPER	1	111.73	111.73	10.00	100.56	Replace	0	0	Not Give *	yn
One Time Key In	Main			EMBLEM RODUIS	1	32.08	32.08	10.00	28.87	Replace	1	28.87	Replace *	nec
One Time Key In	Main			EMBLEM RV270	1	20.00	20.00	10.00	18.00	Replace	1	18.00	Replace *	nec
One Time Key In	Main			EMBLEM SSANYONG	1	34.56	34.56	10.00	31.10	Replace	1	31.10	Replace *	nec
One Time Key In	Main			STICKER PRESTIGE	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace *	nec
Total Spare Part Cost									6,396.75	Surveyor Total 2,632.44				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									5,117.40	Final Sur Total 2,105.95				

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	hel
One Time Key In	Main			RUBBERSEAL GLASS RR QTR	2	11.04	22.08	10.00	19.87	Replace	2	19.87	Replace	hel
One Time Key In	Main			SEALANT W/SCREEN	2	37.00	74.00	0.00	74.00	Replace	2	74.00	Replace	hel
One Time Key In	Main			PANEL END INNER	1	229.33	229.33	10.00	215.40	Replace	0	0	Not Give	hu
One Time Key In	Main			PANEL END OUTER	1	105.74	105.74	10.00	95.17	Replace	0	0	Check	
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	
One Time Key In	Main			TRIM ASSY, RR TRANSVERSE	1	32.95	32.95	10.00	29.66	Replace	0	0	Check	
One Time Key In	Main			COMBI LAMP ASSYRH QTR LH	1	288.57	288.57	10.00	259.71	Replace	0	0	Not Give	mm
One Time Key In	Main			REAR FENDER LH	1	1,300.95	1,300.95	10.00	1,170.86	Replace	0	0	Not Give	mm
One Time Key In	Main			STICKER PRESTIGE	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	mm
Total Spare Part Cost									6,396.75	Surveyor Total		2,632.44		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									5,117.40	Final Sur Total		2,105.95		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	473.00	200	
Total:			1,779.00	400.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	473.00	200	
4	Main	TO RESPRAY REAR PANEL	180.00	0	
5	Main	TO RESPRAY REAR FENDER LH	473.00	0	
Total:			1,779.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	
6	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
7	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
8	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	150	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,140.00	220.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,117.40	2,105.95
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,779.00	400.00
Other	1,140.00	220.00
Overall Total	9,050.40	3,125.95
Lump Sum Repair Option		

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Total	9,050.00	3,150.00
Surveyor Approved Amount		3,150.00
No of Repair Days*	7	4
Remarks		L/S REPAIR, PHOTO AFTER REPAIR.
Surveyor Name		Hwee Jie
Signature		
Survey Date	18/06/2019	

LKK Auto Consultants hereby notify the Repairer of the following:

- To re-survey before after spray painting
- To replace damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHF138K
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	SSANGYONG
Vehicle Model:	RODIUS AUTO TAXI
Primary Colour:	Beige
Manufacturing Year:	2011
Engine No.:	66592622546459
Chassis No.:	KPTV0B1F5CP066700
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$21,115.00
Original Registration Date:	13 Jun 2012
First Registration Date:	13 Jun 2012
Transfer Count:	0
Actual ARF Paid:	\$21,115.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2020
PARF Rebate Amount:	\$12,669.00

Intended COE Rebate Details

COE Expiry Date:	12 Jun 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$46,801.00
COE Rebate Amount:	\$5,746.00
Total Rebate Amount:	\$18,415.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Jun 2019

OK

Jia Le (LKK Auto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Monday, 2 September 2019 11:05 AM
To: CS A Team; Admin A
Subject: LOD Re: Accident on 15/6/2019 involving SHF 138K & SMD 689M (AIG's insured)
Our Ref: TAX/06/19/2057/lg
Attachments: TAX 06 19 2057.pdf

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$3700.00
Loss of Rental	\$928.76 (7.75 days x \$119.84)
Loss of Income	\$465.00 (7.75 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$5100.76

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) Police/GIA reports
- 4) Accident vehicle laid-up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Our hirer engaged his own lawyer to claim for his injury only.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19010854/Jda3

26 JUNE 2019

JONATHAN MICHELANGELO HACON
973 BUKIT TIMAH RD
#08-25
SINGAPORE 589648

Dear Sir/Madam,

**ACCIDENT INVOLVING SMD 689M & SHF 138K ALONG/AT LOWER DELTA RD ON
15/06/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SHF 138K against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: jiaLe@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, SMRT TAXIS PTE LTD (the third party claimant") of BLK 60 WOODLANDS INDUSTRIAL PARK E4 (S) 757705 (address), owner of SHF 138K (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHF 138K that was damaged pursuant to the accident which occurred on 15/06/2019 (date) along KAMPONG BHARU ROAD TOWARDS VIVO CITY (location) involving vehicle no/s SMD 689M ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 2 (day) of Sept (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,800.00 (Global Sum) for vehicle no. SHF 138K that was damaged pursuant to the accident which occurred on 15/06/2019 (date) along KAMPONG BHARU ROAD TOWARDS VIVO CITY involving vehicle no/s SMD 689M.

This is pursuant to the inspection conducted on 18/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT TAXIS PTE LTD ("the third party claimant") of vehicle no. SHF 138K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHF 138K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 3 (day) of Sept (month) 2019 (year)



OKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

*** This Discharge Voucher applies only to the claimant's claim or his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV190800308
Date : 20.08.2019
Vehicle No. : SHF138K
Your Ref No. : TAX/06/19/2057
Our Ref No. : 24101997
Terms : 30 Days

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



Description	Qty	Unit Cost	Add / (Discount) \$ Amount	Amount
LUMP SUM AMOUNT FOR REPAIR. AS PER SURVEYOR'S RECOMMENDATION	1.00			\$ 3,700.00
GRAND TOTAL				\$ 3,700.00

Remark :

Make/Model : SSANGYONG PREMIER RO
Accident Date : 15.06.2019

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/06/19/2057

From: SMRT Taxis Pte Ltd

Date: 20/6/2019

**ACCIDENT INVOLVING SHF138K AND SMD689M ON 15/6/2019
2:40 PM ALONG KAMPONG BHARU ROAD TOWARDS VIVO CITY.**

This is to confirm that the daily rental rate for SHF138K is \$119.84 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 01/06/2019
Accident End Date : 31/08/2019

Date Generated : 31/08/2019
User Name : OngHuaYan

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX06/18/2057	SHF138K	SMART Taxis Pte Ltd	SSANGYONG	RODUS-SV270	24101967	17/06/2019 8:38 AM	24/06/2019 3:54 PM

Enquire Transaction History

Log Date/Time	18 Jun 2019 / 09:17:43	Transaction Amount:	\$7.69
Asset Type:	Vehicle	Channel:	External Agency
Asset ID:	SMD889M	Business Transaction Reference No:	20190618091743181814
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)		
User ID:	ESASBAHD - BALQISH BINTE ABDUL HALIL		
Search Date / Time:	15 Jun 2019 14:40:00		
Insurance Company:	AIG ASIA PACIFIC INSURANCE PTE. LTD		
Information displayed is correct as at the log date and time.			

11/11/19

Enquire Related Logs

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2019 Edit Reg		18 Jun 2019 00:00 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	JONATHAN MICHELANGELO HAGON, ID: S7288233D								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHF138K	Date of Loss: 15/06/2019 14:00 - :59 [84 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 5871115887SG	Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured):	SMD689H	Policy No. (Claimant): D-19093197MFSH							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 28/06/2019]								
ASSOCIATED MAIL RECEIVED									
		View All Compose Case Mail							
• AIG_SG (20/06/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHF138K (5871115887SG)
[SMD689M]
TP
SMRT TAXIS PTE LTD
Jun 15 2019 2:00PM
[JONATHAN MICHELANGELO HACON]
SMRT Automotive Services Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	19/08/19 19:53	Odometer Reading		Load JPG	☒
2	19/08/19 19:53	Chassis Number		Load JPG	☒
3	19/08/19 19:53	General View		Load JPG	☒
4	19/08/19 19:53	General View		Load JPG	☒
5	19/08/19 19:53	General View		Load JPG	☒
6	19/08/19 19:53	General View		Load JPG	☒
7	19/08/19 19:53	General View		Load JPG	☒
8	19/08/19 19:53	General View		Load JPG	☒
9	19/08/19 19:53	General View		Load JPG	☒
10	19/08/19 19:53	General View		Load JPG	☒
11	19/08/19 19:53	General View		Load JPG	☒
12	19/08/19 19:53	General View		Load JPG	☒
13	19/08/19 19:53	General View		Load JPG	☒
14	19/08/19 19:53	General View		Load JPG	☒
15	19/08/19 19:53	General View		Load JPG	☒
16	19/08/19 19:53	Photographs of Damaged Items		Load JPG	☒
17	19/08/19 19:53	Photographs of Damaged Items		Load JPG	☒
18	19/08/19 19:53	Photographs of Damaged Items		Load JPG	☒
19	19/08/19 19:53	Photographs of Damaged Items		Load JPG	☒
20	19/08/19 19:53	Photographs of Damaged Items		Load JPG	☒
21	19/08/19 19:53	Photographs of Damaged Items		Load JPG	☒
22	19/08/19 19:53	Photographs of Damaged Items		Load JPG	☒
23	19/08/19 19:53	After Repair Photo		Load JPG	☒
24	19/08/19 19:53	After Repair Photo		Load JPG	☒
25	19/08/19 19:53	After Repair Photo		Load JPG	☒
26	19/08/19 19:53	After Repair Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	21/06/19 11:58	TP ESTIMATE - MARKED		Load PDF	
2	21/06/19 11:58	TP GIA REPORT		Load PDF	
3	27/09/19 10:15	WORKSHOP INVOICE		Load PDF	
4	27/09/19 10:15	AUTHORISATION TO ACT FORM		Load PDF	
5	27/09/19 10:15	Release Voucher		Load PDF	
6	27/09/19 10:15	RENTAL RECEIPT		Load PDF	
7	27/09/19 10:15	RENTAL MILEAGE		Load PDF	
8	27/09/19 10:15	LTA SEARCH		Load PDF	
9	27/09/19 10:15	LOD		Load PDF	
10	27/09/19 10:15	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	20/06/19 09:17	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMD689M (Insd veh)	Model:	SSANGYONG RODIUS 2.7
	SHF138K (TP veh)		(A)
Date of Accident:	15/06/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	11,903.14
Final Repair Cost	:	\$	4,800.00
Loss of Use	:	\$	7.00 days at \$50.00 per day
Rental (if any)	:	\$	7 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,800.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	:	\$ 4,800.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

27 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19010854/JDA3Q2

Date: 27/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SHF138K

Insured Vehicle No : SMD689M

Date of Loss: 15/06/2019

Nature of Claim: TP

Claim No: 5871115887SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF138K

Make & Model: SSANGYONG RODIUS, 2.7 (A)

Engine No: 66592622546459

Reg. Date: 13/06/2012 (Man. Year: 2011)

Chassis No: KPTV0B1FSCP066700

Colour: White

Odometer: 615210 km

Engine Capacity: 2696 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,540.14	3,095.01	4,445.13	58.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,363.00	1,220.00	3,143.00	72.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,903.14	4,315.01	7,588.13	63.75
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	11,903.14	3,700.00	8,203.14	68.92
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Car Rental (7.0 x S\$119.84/day) (S\$)		838.88		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,895.88		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 18/06/2019

Date Inspected: 18/06/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE ASSY (DISC 10%)	Dented	1,355.08 F	*1,219.57 F
2	1		*WEATHER STRIP T/GATE OPENING (DISC 10%)	Torn	97.67 F	*87.90 F
3	1		*EMBLEM REAR (DISC 10%)	Necessary	48.94 F	*44.05 F
4	1		*REAR BUMPER ASSY (DISC 10%)	Deformed	925.27 F	*832.74 F
5	1		*REAR BUMPER CLIP (DISC 10%) (6 PCS)	Necessary	25.50 F	*22.95 F
6	1		*REVERSE SENSOR (DISC 10%)	Shorted	165.10 F	*148.59 F
7	1		*EMBLEM RODUIS (DISC 10%)	Necessary	32.08 F	*28.87 F
8	1		*EMBLEM RV270 (DISC 10%)	Necessary	20.00 F	*18.00 F
9	1		*EMBLEM SSANYONG (DISC 10%)	Necessary	34.56 F	*31.10 F
10	1		*RUBBERSEAL GLASS RR QTR (DISC 10%) (2 PCS)	Necessary	22.08 F	*19.87 F
11	1		*BEAM ASSY -IMPACT RR BUMPER (DISC 10%)	Necessary	513.97 F	*462.57 F
12	1		*STICKER PRESTIGE (SN)	Necessary	60.00 F	*60.00 F
13	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
14	2		*SEALANT W/SCREEN (SN)	Necessary	74.00 F	*74.00 F
15	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
16	1		*ABSORBER ENERGY RR BUMPER	Not Necessary	111.73 F	*- F
17	1		*BEAM ASSY -IMPACT RR BUMPER	Not Necessary	513.97 F	*- F
18	1		*REAR NUMBER PLATE	Not Necessary	15.00 F	*- F
19	1		*REAR NUMBER PLATE FRAME	Not Necessary	35.00 F	*- F
20	1		*LATCH ASSY ,T/GATE	Not Necessary	59.98 F	*- F
21	1		*LAMP ASSY -LICENSE PLATE	Not Necessary	49.25 F	*- F
22	1		*STRIKER ASSY ,T/GATE	Not Necessary	9.89 F	*- F
23	1		*HANDLE ASSY -T/GATE O/S	Not Necessary	14.16 F	*- F
24	1		*TRIM ASSY -T/GATE LWR	Not Necessary	199.92 F	*- F
25	1		*GARNISH ASSY -T/GATE CTR	Not Necessary	300.19 F	*- F
26	1		*ACTUATOR ASSY ,DR LOCK T/GATE	Not Necessary	74.55 F	*- F
27	1		*COMBI LAMP ASYSRR T/GATE LH	Not Necessary	288.57 F	*- F
28	1		*COMBI LAMP ASYSRR T/GATE RH	Not Necessary	288.57 F	*- F
29	1		*LAMP ASSY ,REFLEX REFLECTOR LH	Not Necessary	10.52 F	*- F
30	1		*LAMP ASSY ,REFLEX REFLECTOR RH	Not Necessary	10.52 F	*- F
31	1		*ABSORBER ENERGY RR BUMPER	Not Necessary	111.73 F	*- F
32	1		*PANEL END INNER	Not Necessary	239.33 F	*- F
33	1		*PANEL END OUTER	Not Necessary	105.74 F	*- F
34	1		*TRIM ASSY ,RR TRANSVERSE	Not Necessary	32.95 F	*- F
35	1		*COMBI LAMP ASSYRR QTR LH	Not Necessary	288.57 F	*- F
36	1		*REAR FENDER LH	Not Necessary	1,300.95 F	*- F
37	1		*STICKER PRESTIGE	Not Necessary	60.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					7,540.14	3,095.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,264.00	500.00
2	SPRAY PAINT	New	1,959.00	500.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	20.00
5	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	50.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
8	TO INSPECT RR LIGHTING ,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
9	TO REMOVE AND REFIT WIRE HARDESS	New	200.00	0.00
10	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	100.00
11	TO REPLACE SUNDRY PARTS	New	100.00	0.00
12	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			4,363.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >