

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

18-Jun-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1077 P

1 pc	Bootlid emblem	X	\$	27.00
1 pc	Bootlid CRDi	X	\$	29.00
1 pc	End panel inner garnish	X	\$	74.00
1 pc	Rear bumper	X	\$	696.00
1 pc	Rear bumper lower cover	X	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00		\$	58.00
1 pc	Rear bumper inner sponge	X	\$	114.00
1 pc	Rear bumper reinforcement	X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00		\$	92.00

### S/NETT

1 set	Rear bumper clips	X	\$	48.00
1 set	End panel inner garnish clips	X	\$	30.00
1 set	Bootlid stickers	X	\$	100.00
1 set	Reverse sensor	X	\$	280.00
1 pc	Rear bumper top protector		\$	80.00
	Sundry		\$	50.00 X
	Towing Fee		\$	50.00 X
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.		\$	800.00
	To putty and spray painting on bootlid lower garnish, rear bumper, end panel, boot lid		\$	800.00
	To apply rustproofing on the repaired and replaced panels.		\$	120.00
			\$	4,532.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to be repaired
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: *Kahri Chetty*  
Date: *18/6/19*

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.