

ASS. REC. BY:

REF: 08/FCI19010868/Ked3⁷²

Special Instruction:

Survey:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Henry Kuo

of

FCI

Date/Time:

9.29am 19/6/19

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SICU 26232

Insured:

SHA 09972

at Workshop m/s

city Auto

Tel:

64531235

of

160 Sin Ming Drive # 05-01

Policy No:

Claim No:

D1900 3931 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/6/19

CA / REV / REP. / REV 24 HRS

QDS

H.O.D. Endorsement:

Date/Time:

12.11pm 19/6/19

Person Contacted:

Vivian

Vehicle IN / OUT

Date/Time	Action/Instruction
	SICU 26232-X
	SHA 09972-CC1/11/8010857/Dhb372
21/6/19	@ 15:51pm revised PA to Henry via email.
4/7	@ 8050.73 email & confirmed (\$ 3,666.74 Red - 31%)

ASS. REC. BY:

REF:

1021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7-9

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

RECEIVED 08 JUL 2019

Veh No:

SKU 20236

Yr Regn:

07.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Hammer

C.C

1986

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

53956

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

85460

0049307

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

3

mm

L/Bal.

9

mm

L/Bal.

3

mm

D.O.A.

13/6/19

D.O.A.

19/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

08/07/19

1)

Type

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

8

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

F. & T.S

Others

TOTAL

170+15

50

50+50

43

378

Report Format:

Lump Sum / I.B.I. (\$

8,050.73

P/P



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003931MFSH

Date: 21 June 2019

Our Ref: CS/FCI19010868/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKU 2623Z

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/06/2019 at the premises of M/s City Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 11,717.47
Revised Estimate Amount	: S\$ 7,891.84
"Check" Items Amount	: S\$ 3,751.07
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 7 - 9 days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-06-2019	Our Ref No.	D19003931MFSH
Accident Date	13-06-2019	Claim Type.	Third Party
Insured Vehicle	SHA0997Z	Third Party Vehicle.	SKU2623Z
Survey Location	BLK 160, SIN MING DRIVE, SIN MING AUTO CITY #05-01		
Contact Person.	VRONICA LAW		
Contact No.	64531235/ 0	Fax No.	64537944
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	HENRY KAO		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1535G

Vehicle Details

Vehicle No.:	SKU2623Z
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	3ZRB588548
Chassis No.:	ZSU600049307
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$26,335.00
Original Registration Date:	14 Jul 2015
First Registration Date:	14 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$23,869.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2025
PARF Rebate Amount:	\$17,901.00

Intended COE Rebate Details

COE Expiry Date:	13 Jul 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,501.00
COE Rebate Amount:	\$39,693.00
Total Rebate Amount:	\$57,594.00

The information contained herein is correct as at 21 Jun 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 21 June 2019 3:51 PM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003931MFSH/1
Attachments: SKU 2623Z - Preli Advise .pdf

Dear Henry,

Enclosed preliminary revised of vehicle SKU 2623Z.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 19 June 2019 12:13 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003931MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 19 June 2019 9:29 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie

<HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19003931MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201906-000338(00)

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD #06-01

CITY HOUSE

SINGAPORE 068877

Contact : 62208751/62208751

Fax No. : 65073849

Date : 18/06/2019

Vehicle No. : SKU2623Z

Make/Model : TOYOTA HARRIER ELEGANCE 2.0 A

Mileage (km) : 0

Chassis No. : ZSU600049307

Accident Date : 13/06/2019 00:00:00

Claim No. : SHA997Z

Reference : SKU2623Z

Policy No. : J30004590MCY

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Tailgate	1.0	1,492.70	B ₁ 1,492.70 ✓
2	Tailgate lock	1.0	651.40	R 651.40 X
3	Tailgate weatherstrip	1.0	403.21	201-605m 403.21 502m
4	Tailgate emblem - harrier	1.0	74.80	M 74.80 —
5	Tailgate glass moulding	1.0	166.49	M 166.49 —
6	Tailgate lock cover	1.0	42.70	SL 42.70 X
7	Tailgate trim	1.0	697.43	L 697.43 X
8	Tailgate inner handle	2.0	49.67	SL 99.34 X
9	Rear bumper	1.0	1,495.30	B ₁ 1,495.30 —
10	Rear bumper retainer	2.0	69.70	D ₁₇ 139.40 —
11	Rear Bumper Lower lid	1.0	397.60	B ₁ 397.60 —
12	Rear bumper reflector	2.0	87.90	CR ₁ 175.80 —
13	Rear Bumper clips	8.0	3.89	M 31.12 —
14	Rear bumper sponge	1.0	157.60	CM 157.60 —
15	Rear keyless entry antenna	1.0	186.70	CM 186.70 —
16	Rear keyless entry buzzer	1.0	140.20	SL 140.20 X
17	Rear end panel	1.0	791.20	B ₁ 791.20 —
18	Rear end panel top garnish	1.0	367.40	RL 367.40 —
19	Rear floor pan	1.0	897.70	R 897.70 X
20	Rear floor pan reinforcement	1.0	321.30	R 321.30 X
21	Rear floor pan trim	1.0	691.70	SL 691.70 X
22	Deck floor box RH	1.0	422.60	CM 422.60 —
23	Deck floor box LH	1.0	472.70	CM 472.70 —
24	Exhaust silencer (Rear end)	1.0	854.10	B ₁ 854.10 —
25	Exhaust mounting	2.0	39.70	SL 79.40 X

List Total :

25% Discount S\$

11,249.89

2,812.42

8,437.47

41

SPECIAL NET :

1	Tailgate glass sealant	1.0	40.00	M 40.00 ✓
2	Reverse sensor	1.0	250.00	Short 250.00 200m
SPECIAL NET Total S\$:				290.00

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36
ROBINSON RD #06-01
CITY HOUSE
SINGAPORE 068877

Contact : 62208751/62208751

Fax No. : 65073849

Estimate : QUOT201906-000338(00)

Date : 18/06/2019

Vehicle No. : SKU2623Z

Make/Model : TOYOTA HARRIER ELEGANCE 2.0
A

Mileage (km) : 0

Chassis No. : ZSU600049307

Accident Date : 13/06/2019 00:00:00

Claim No. : SHA997Z

Reference : SKU2623Z

Policy No. : J30004590MCY

S/No	Particular	Quantity	Unit Price	Amount S\$
LABOUR :				
	* To remove and refit rear windscreen glass	1.0	150.00	150.00 ¹²⁰¹
	* Pull and realign rear chassis member	1.0	180.00	180.00 ⁿⁿ
	* To supply panel sealant and to seal off all weld seam and gaps	1.0	90.00	90.00 ³⁰¹
	* To check and repair wiring and lighting	1.0	60.00	60.00 ²⁰¹
	* To spray under coating	1.0	120.00	120.00 ⁶⁰¹
	* To remove and refit exhaust silencer	1.0	90.00	90.00 ⁶⁰¹
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	1,300.00	1,300.00 ⁹⁰⁰¹
	- Spray painting on affected & replace parts	1.0	1,000.00	1,000.00 ⁹⁰⁰¹
				<u>2,990.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

11717.42

E. & O.E.

Total S\$: 11,717.47

GST 7% S\$: 820.22

Amount Due S\$: 12,537.69

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19010868/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 997Z	Veh. Inspected	SKU 2623Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003931MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	19/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZSU600049307	Colour	METALLIC PEARL WHITE	
Odometer	53956	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	MICHELIN	9 mm	
L/H Front Tyre	225/65 R17	MICHELIN	9 mm	
R/H Rear Tyre	225/65 R17	MICHELIN	3 mm	
L/H Rear Tyre	225/65 R17	MICHELIN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2019	Inspection Date	19/06/2019	
Survey held at	160 SIN MING DRIVE# 05-01			
Repairer	CITY AUTO PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 2623Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BENT	1,492.70	1,492.70
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	651.40	-
1	TAILGATE EMBLEM-HARRIER	NECESSARY	74.80	74.80
1	TAILGATE GLASS MOULDING	NECESSARY	166.49	166.49
1	TAILGATE LOCK COVER	SERVICEABLE	42.70	-
1	TAILGATE TRIM	SERVICEABLE	697.43	-
2	TAILGATE INNER HANDLE @\$49.67	SERVICEABLE	99.34	-
1	REAR BUMPER	BENT	1,495.30	1,495.30
2	REAR BUMPER RETAINER @\$69.70	DISTORTED	139.40	139.40
1	REAR BUMPER LOWER LID	BENT	397.60	397.60
2	REAR BUMPER REFLECTOR @\$87.90	CRACKED	175.80	175.80
8	REAR BUMPER CLIPS @\$3.89	NECESSARY	31.12	31.12
1	REAR BUMPER SPONGE	CRACKED	157.60	157.60
1	REAR KEYLESS ENTRY ANTENNA	CRACKED	186.70	186.70
1	REAR KEYLESS ENTRY BUZZER	SERVICEABLE	140.20	-
1	REAR END PANEL	BENT	791.20	791.20
1	REAR END PANEL TOP GARNISH	DENTED	367.40	367.40
1	REAR FLOOR PAN	TO REPAIR SEE LABOUR	897.70	-
1	REAR FLOOR PAN REINFORCEMENT	TO REPAIR SEE LABOUR	321.30	-
1	REAR FLOOR PAN TRIM	SERVICEABLE	691.70	-
1	DECK FLOOR BOX RH	CRACKED	422.60	422.60
1	DECK FLOOR BOX LH	CRACKED	472.70	472.70
1	EXHAUST SILENCER (REAR END)	BENT	854.10	854.10
2	EXHAUST MOUNTING @\$39.70	SERVICEABLE	79.40	-
	LESS 25% DISCOUNT		-2,711.67	-1,806.38
			8,135.01	5,419.13
1	TAILGATE WEATHERSTRIP (50%)(SN)	DISTORTED / DENTED	403.21	201.60

Report Ref No. CS/FC19010868/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-100.80	-
			302.41	201.60
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			290.00	240.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		150.00	120.00
	PULL AND REALIGN REAR CHASSIS MEMBER.	NOT NECESSARY	180.00	-
	TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WELD SEAM AND GAPS.		90.00	30.00
	TO CHECK AND REPAIR WIRING AND LIGHTING.		60.00	20.00
	TO SPRAY UNDER COATING.		120.00	60.00
	TO REMOVE AND REFIT EXHAUST SILENCER.		90.00	60.00
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK,REAR FLOOR PAN AND REAR FLOOR PAN REINFORCEMENT.		1,300.00	900.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,000.00	1,000.00
			2,990.00	2,190.00
	GRAND TOTAL		11,717.42	8,050.73
	RECOMMENDED COST OF REPAIRS			8,050.73

Report Ref No. CS/FCI19010868/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.