

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMK5148M	MODEL : XV 2.0I-S EYESIGHT AWD CVT
REF NO:INS/IC/CHI/0254/2019	YEAR: 12-APR-2019
ENGINE NO: FB20CE15838	CHASSIS NO: JF1GT7KL5KG062254
DOA: 10/06/2019	TOA: 1725HRS
TYPE OF CLAIM: 3 RD PARTY	INS COMPANY: NTUC

S/N	NATURE OF JOB	AMOUNT	
1.	REPAIR/REPLACE REAR BUMPER,ENDPANEL,RH REAR FENDER & TAILGATE	\$3360.00	2520
2.	RESPRAY REAR BUMPER,ENDPANEL,RH REAR FENDER & TAILGATE	\$2520.00	1680
3.	DISMENTLE & REFIX UNDERCARRAIGE TO FACILITATE REPAIR	\$900.00	2
4.	REMOVE & REFIX EXHAUST	\$150.00	X
5.	TRANSFER TAILGATE MECHANISM	\$150.00	X
6.	WHEEL ALIGNMENT	\$200.00	X
7.	REMOVE & REFIX CARPET,SEATS TO FACILITATE RERAIRS	\$400.00	280
8.	REMOVE & REFIX REAR BOOT GARNISH& TRIM TO FACILITATE REPAIRS	\$150.00	X
9.	REMOVE & INSTALL REAR WINDSCREEN	\$300.00	X
10.	REMOVE & INSTALL RH REAR QUARTER GLASS	\$180.00	X
11.	TO REMOVE & REFIX FUEL TANK	\$200.00	X
12.	TO CONDUCT REAR LIGHTING TEST	\$50.00	30
13.	TO CONDUCT PROTECTANT COATING	\$1500.00	280
14.	TO CONDUCT ANTI RUST COATING	\$580.00	280
15.	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	\$300.00	X
16.	TO SUPPLY & INSTALL REAR RH QUARTER GLASS & REAR WINDSCREEN TINTED FILM	\$290.00	250
17.	SUNDRIES	\$100.00	X
Total Labour		\$11330.00	

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Mennery (L/LC)
HP / EMAIL:	968106831
BEFORE PAINT:	Yes
DAYS GIVEN:	12 days

12 Not within
Mennery B4 paint

Estimate

Date 06 / 11 / 2019

002 / 003

Name	QUOTATION FOR SMK5148M	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG062254

Part Number	Part Code Name	Part Code	Q'ty	Price	
57707FL400	BRACKET-REAR BUMPER SIDE,RIGHT	FIG-591 57707H	1	12.10	✓
57707FL410	BRACKET-REAR BUMPER SIDE,LEFT	FIG-591 57707I	1	12.10	X
57707FL510	BRACKET-REAR BUMPER,LOWER	FIG-591 57707N	2	25.20	?
57731FL570NN	COVER-REAR BUMPER	FIG-591 57731C	1	6.50	X
52129FL0209P	FLOOR PAN COMPLETE-REAR,REAR	FIG-505 52110	1	432.00	X
52401FL0209P	SKIRT COMPLETE-REAR	FIG-505 52411	1	288.00	?
84912FL041	LENS & BODY-REAR COMBINATION LAMP RIGHT	FIG-842 84912B	1	378.00	✓
84912FL061	LENS & BODY-REAR FINISHER LAMP ,RIGHT	FIG-842 84912OA	1	193.90	✓
84940FL030	PACKING-REAR FINISHER RIGHT	FIG-842 84940UA	1	18.00	?
84913AL120	LENS & BODY-FOG LIGHT,REAR RIGHT	FIG-845 84912XA	1	129.60	✓
84913AL140	REFLEX REFLECTOR ASSEMBLY LEFT	FIG-845 84281A	1	64.20	✓
91111FL030NN	GARNISH ASSEMBLY-REAR GATE,B	FIG-914 91111P	1	173.90	?
91713FL000	PROTECTOR-REAR GARNISH	FIG-914 91713	1	7.20	?
91713FL020	PROTECTOR-REAR GARNISH	FIG-914 91713D	1	3.60	?
91713FL010	PROTECTOR-REAR GARNISH	FIG-914 91713C	1	3.60	?
91713FL030	PROTECTOR-REAR GARNISH A	FIG-914 91713A	1	3.60	?
		Page-Total		1,751.50	

Memo

Grand Total
5,853.20

--

Tel

Estimate

Date 06 / 11 / 2019

001 / 003

Name	QUOTATION FOR SMK5148M	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG062254

Part Number	Part Code Name	Part Code	Q'ty	Price	
65209FL040	GLASS-REAR QUARTER,RIGHT	FIG-652 65210A	1	842.40	?
65245FL010	DAM RUBBER-REAR QUARTER	FIG-652 65245	1	10.00	?
65277FL000	SEAL-WINDOW REAR QUARTER	FIG-652 65277A	1	4.30	?
63019FL030	GLASS-REAR GATE	FIG-621 63011	1	1,062.00	✓
65245FL000	DAM RUBBER-REAR GATE GLASS	FIG-621 63232C	1	18.00	✓
51439FL1609P	REAR QUARTER COMPLETE-OUTER,RIGHT	FIG-522 51410	1	945.60	✓
51445FL0209P	REAR QUARTER END COMPLETE-RIGHT	FIG-522 51410B	1	53.70	?
59122FL020	MUD GUARD,REAR RIGHT	FIG-541 59112	1	64.80	✓
63516FL000	WEATHER STRIP-REAR GATE	FIG-901 63516	1	108.00	✓
63032FG102	LATCH & ACTUATOR-REAR GATE	FIG-622 63176A	1	144.00	X
63264AG100	STRIKER-REAR GATE	FIG-622 63264	1	21.60	X
94026FL010VH	TRIM PANEL-REAR SKIRT	FIG-943 94046	1	108.00	?
57704FL250	BUMPER-FACE,REAR	FIG-591 57704A	1	401.10	✓
57711FL0419P	BACK BEAM COMPLETE-REAR	FIG-591 57711D	1	203.00	✓
57707FL460	BRACKET-REAR BUMPER CORNER,RIGHT	FIG-591 57707AC	1	21.60	✓
57707FL470	BRACKET-REAR BUMPER CORNER,LEFT	FIG-591 57707AD	1	21.60	X
		Page-Total		4,029.70	

Memo

Grand Total
5,853.20

--

Tel

Estimate

Date 06 / 11 / 2019

003 / 003

Name	QUOTATION FOR SMK5148M	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG062254

Part Number	Part Code Name	Part Code	Q'ty	Price
91713FL040	PROTECTOR-REAR GARNISH B	FIG-914 91713B	1	3.60
91174SA181	ORNAMENT	FIG-915 93033D	1	68.40
		Page-Total		72.00
		Sub-Total		5,853.20
		Total		5,853.20
		Tax		0.00
		Grand Total		5,853.20

Memo

Grand Total
5,853.20

--

Tel



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SMK 5148 MM

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

<i>Kuan</i> 1 <u>FAULT DIAGNOSTIC TOOLS</u>	<u>\$ 300.00</u> ✓
2 _____	_____
3 _____	_____
4 _____	_____
5 _____	_____
6 _____	_____
7 _____	_____
8 _____	_____
9 _____	_____
10 _____	_____
11 _____	_____
12 _____	_____



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SMK-S148-M

Surveyor: _____

DESCRIPTION	PART NO	AMOUNT
1 REAR QUARTER EX- COMPLETE L	514457-L-0209-P	\$53.60
2 REAR GATE	608097-L-0009-P	\$940.00
3 GLASS REAR- QUARTER RIGHT	652097-L-040	\$842.40
4 DAM RUBBER REAR QUARTER	652457-L-010	\$10.00
5 SEAL WINDOW- REAR QUARTER	652777-L-000	\$24.30
6 COVER Bumper SIDE REAR- RIGHT	577317-L-508	\$20.90
7 GRILLE AIR- VENT ASSEMBLY	726517-L-001	\$39.60
8		
9		
10 LETTER MARK- R	930777-L-440	\$36.00
11 LETTER MARK- R	930777-L-100	\$90.00
12 EXHAUST MARK	LP1001035 EMB	\$23.20
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		

24/8/11P