

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Ave 4, #03-50, Premier @ KB, Singapore 415875

Tel : 62459655 / 9735 6016 (Tony) Fax : 6245 9678

Email : exclusiveenterprise50@gmail.com PA1111NV4018413384

TP INS : III

Veh No. : JRK 6627

TP III

Xiao Tony

Veh Model : Toyota Innova 2.0E

No.	List items	QTY	Amount
1	Bonnet <i>Agnt</i>	1	\$739.10 +
2	Bonnet Lock	1	\$93.10 +
3	Bonnet Outer Chrome Moulding	1	\$267.30 +
4	Bonnet Rubber Seal	1	\$39.10 +
5	Bonnet Hinge L/R	2	\$114.20 +
6	Frt Bumper <i>Del d</i>	1	\$573.10 -
7	Frt Bumper Side Retainer L/R <i>new</i>	2	\$146.20 -
8	Frt Bumper Fog Lamp Garnish L/R <i>new</i>	2	\$178.40 +
9	Frt Bumper Lower Grille <i>Del d</i>	1	\$188.30 -
10	Frt Bumper Reinforcement <i>new</i>	1	\$437.10 +
11	Frt Bumper Bracket <i>Del d</i>	1	\$113.40 -
12	Frt Grille <i>new</i>	1	\$362.10 -
13	Frt Grille Logo <i>new</i>	1	\$48.80 -
14	Headlamp L/R <i>Del d</i>	2	\$986.20 -
15	Support Panel <i>Agnt</i>	1	\$519.30 +
16	Brace Panel <i>Del d</i>	1	\$221.90 -
17	Radiator <i>new</i>	1	\$939.10 +
18	A/C Condenser	1	\$1,163.90 +
19	Tailgate <i>Del d</i>	1	\$1,391.60 1043
20	Tailgate Lock <i>Del d</i>	1	\$476.10 285
21	Tailgate W/strip <i>cut</i>	1	\$197.60 -
22	Tailgate Outer Garnish <i>new</i>	1	\$119.30 +
23	Tailgate Logo	1	\$69.30 -
24	Emblem "2.0" <i>new</i>	1	\$53.10 -
25	Emblem "E"	1	\$48.30 -
26	Tailgate Glass Moulding L/R <i>new</i>	1	\$79.20 -
27	Tailgate Inner Trimboard <i>new</i>	1	\$587.10 +
28	Tailgate Stopper L/R	1	\$78.80 +
29	Rear Bumper <i>Del d</i>	1	\$561.90 -
30	Rear Bumper Side Retainer L/R <i>new</i>	2	\$178.60 98
31	Rear Bumper Side Holder L/R <i>new</i>	2	\$187.20 +
32	Rear Bumper Side Reflector L/R <i>LH Del d</i>	2	\$183.60

91-80

33 Taillamp L/R	2	\$579.20	+
34 End Panel	1	\$811.60	+
35 End Panel Top Garnish	1	\$363.70	105
36 Rear Compartment Board	1	\$893.60	+
Sub-Total :		\$13,990.40	
Less 25% :		\$3497.60	
Total :		\$10,492.80	

5272.10

3954.15

S/N

Frt Bumper Clips	1Set	\$50.30
Frt Grille Clips	1Set	\$50.20
Coolant	1	\$80
Frt Number Plate	1	\$50
Rear Bumper Clips	1Set	\$50.30
Rear W/S Sealant	1	\$80.60
Tailgate Inner Trim Clips	1	\$50.20
Rear Number Clips	1Set	\$50
Reverse Sensor	1	\$300
S/N Total :		\$760

Labour

R&R Front Aircon Condenser & Radiator	\$180	+
Top up aircon gas	\$150	+
Wire-Checking (Front)	\$50	30
Labour (Front)	\$1,000	400
Painting (Front)	\$900	400
R&R Rear Windscreen	\$150	120
R&R Reverse Sensor	\$60	50
Wire-Checking (Rear)	\$50	30
R&R Rear Compartment & Trims	\$150	60
Transfer Rear Gate Component from old to new	\$100	80
Labour (Rear)	\$1,000	600
Painting (Rear)	\$900	600
Labour Total :		\$3790

2370

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj 96893735

H/s 19/06/19.

~~5821007~~

total: 6734.15

H/s: 5350

08 Days.